



U.S. Department
of Homeland Security
**United States
Coast Guard**

LOCAL NOTICE TO MARINERS

District: 17

Week: 10/21

-Navigation Information Service (NIS)-
Watchstander, 24 hours a day at (703) 313-5900
~Navcen Internet Address~
<https://www.navcen.uscg.gov>
-Local Notice to Mariners-
<https://www.navcen.uscg.gov/-pageName=lnmMain>

Issued by: Commander (DPW) Telephone: (907) 463-2269 (0800-1600)
Seventeenth Coast Guard District After Hours: (907) 463-2000 (1600-0800)
PO Box 25517, Juneau, AK 99802-5517
<http://www.uscg.mil/d17/D17%20Divisions/dpw/dpw.asp>

Questions, comments, or additional information on this Local Notice to Mariners should be sent to the address above or by E-mail to: D17-PF-D17-LNM@uscg.mil. You can get the U.S. Coast Guard 17th District Local Notice to Mariners via the Internet directly from the U.S. Coast Guard Navigation Center web site at <https://www.navcen.uscg.gov/-pageName=lnmDistrict®ion=17>.

REFERENCES: Light List, Vol. VI, Pacific Coast and Pacific Islands (COMDTPUB P16502.6).
U.S. Coast Pilot 8, Pacific Coast Alaska: Dixon Entrance to Cape Spencer, 42nd Edition.
U.S. Coast Pilot 9, Pacific and Arctic Coasts Alaska: Cape Spencer to Beaufort Sea, 37th Edition.

BROADCAST NOTICE TO MARINERS

Navigation information previously promulgated by CG Sector Juneau Broadcast Notice to Mariners through J033-21 and CG Sector Anchorage Broadcast Notice to Mariners through A018-21 that are still in effect are included in this notice.

Chart Corrections
<https://nauticalcharts.noaa.gov/charts/chart-updates.html>

Dates of Latest Editions, Nautical Charts, and Miscellaneous Maps
<https://nauticalcharts.noaa.gov/charts/list-of-latest-editions.html>

Light List/ Summary of Corrections
<https://www.navcen.uscg.gov/-pageName=lightListCorrections>

NOAA Chart Viewer (Posting of all up to date NOAA charts for viewing on Internet browser to be used for ready reference or planning)
<https://nauticalcharts.noaa.gov/>

NOAA Booklet Charts
<https://nauticalcharts.noaa.gov/charts/noaa-raster-charts.html#booklet-charts>

Coast Pilots, along with corrections, are available at:
<https://nauticalcharts.noaa.gov/publications/coast-pilot/index.html>

NOAA Weather Buoy Sites
<http://www.ndbc.noaa.gov/>

Tides online
<https://tidesandcurrents.noaa.gov/>

Tides, Currents, PORTS
<https://tidesandcurrents.noaa.gov/noaacurrents/Stations-g=693>

Weather
<http://www.nws.noaa.gov/om/marine/alaska.htm>

Vessel Traffic System Prince William Sound (VTSPWS) Users Manual
<https://homeport.uscg.mil/Lists/Content/DispForm.aspx-ID=2205&Source=https://>

ABBREVIATIONS

A through H

ADRIFT - Buoy Adrift

I through O

I - Interrupted

P through Z

PRIV - Private Aid

AICW - Atlantic Intracoastal Waterway
 Al - Alternating
 B - Buoy
 BKW - Breakwater
 bl - Blast
 BNM - Broadcast Notice to Mariner
 bu - Blue
 C - Canadian
 CHAN - Channel
 CGD - Coast Guard District
 C/O - Cut Off
 CONT - Contour
 CRK - Creek
 CONST - Construction
 DAYMK/Daymk - Daymark
 DBN/Dbn - Daybeacon
 DBD/DAYBD - Dayboard
 DEFAC - Defaced
 DEST - Destroyed
 DISCON - Discontinued
 DMGD/DAMGD - Damaged
 ec - eclipse
 EST - Established Aid
 ev - every
 EVAL - Evaluation
 EXT - Extinguished
 F - Fixed
 fl - flash
 FI - Flashing
 G - Green
 GIWW - Gulf Intracoastal Waterway
 HAZ - Hazard to Navigation
 HBR - Harbor
 HOR - Horizontal Clearance
 HT - Height

ICW - Intracoastal Waterway
 IMCH - Improper Characteristic
 INL - Inlet
 INOP - Not Operating
 INT - Intensity
 ISL - Islet
 Iso - Isophase
 kHz - Kilohertz
 LAT - Latitude
 LB - Lighted Buoy
 LBB - Lighted Bell Buoy
 LHB - Lighted Horn Buoy
 LGB - Lighted Gong Buoy
 LONG - Longitude
 LNM - Local Notice to Mariners
 LT - Light
 LT CONT - Light Continuous
 LTR - Letter
 LWB - Lighted Whistle Buoy
 LWP - Left Watching Properly
 MHz - Megahertz
 MISS/MSNG - Missing
 Mo - Morse Code
 MRASS - Marine Radio Activated Sound Signal
 MSLD - Misleading
 N/C - Not Charted
 NGA - National Geospatial-Intelligence Agency
 NO/NUM - Number
 NOS - National Ocean Service
 NW - Notice Writer
 OBSCU - Obscured
 OBST - Obstruction
 OBSTR - Obstruction
 Oc - Occulting
 ODAS - Anchored Oceanographic Data Buoy

Q - Quick
 R - Red
 RACON - Radar Transponder Beacon
 Ra ref - Radar reflector
 RBN - Radio Beacon
 REBUILT - Aid Rebuilt
 RECOVERED - Aid Recovered
 RED - Red Buoy
 REFL - Reflective
 RRL - Range Rear Light
 RELIGHTED - Aid Relit
 RELOC - Relocated
 RESET ON STATION - Aid Reset on Station
 RFL - Range Front Light
 RIV - River
 RRASS - Remote Radio Activated Sound Signal
 s - seconds
 SEC - Section
 SHL - Shoaling
 si - silent
 SIG - Signal
 SND - Sound
 SPM - Single Point Mooring Buoy
 SS - Sound Signal
 STA - Station
 STRUCT - Structure
 St M - Statute Mile
 TEMP - Temporary Aid Change
 TMK - Topmark
 TRLB - Temporarily Replaced by Lighted Buoy
 TRLT - Temporarily Replaced by Light
 TRUB - Temporarily Replaced by Unlighted Buoy
 USACE - Army Corps of Engineers
 W - White
 Y - Yellow

Additional Abbreviations Specific to this LNM Edition: None

SECTION I - SPECIAL NOTICES

This section contains information of special concern to the Mariner.

625 ALASKA

The Coast Guard's VHF-FM Remote Fixed Facility (RFF) reception capabilities on the following sites are degraded and calls on VHF-FM Channel 16 may not be received by the responsible Coast Guard Sector Communication Center within the stated coverage area:

- DECEPTION HILLS – The Gulf of Alaska near Cape Fairweather, Lituya Bay, and the Fairweather grounds.
- MOUNT MCARTHUR – Cape Decision, Southern Sumner Strait, Cape Omney, and the vicinity of Coronation Island.
- SUKKWAN ISLAND – Tlevak Strait, Hetta Inlet, Cordova Bay, and Western Dixon Entrance.
- CAPE GULL – Northwest Afognak Island, Cape Douglas, and Shelikof Strait to Cape Uyak.
- MANLEY – Central Chatham Strait from Peril Strait to Frederick Sound.
- RUGGED ISLAND – The area around Seward, Resurrection Bay, Southwestern Prince William Sound including Blying Sound.

If unable to reach the Coast Guard on VHF-FM Channel 16, mariners that are equipped with capable radios can contact the Coast Guard through Communications Detachment Kodiak via high frequency (HF) 4125Khz. Mariners can also contact the Coast Guard via cellular or satellite phone by calling JRCC Juneau at 907-463-2000, Sector Juneau Command Center at (907) 463-2980 or Sector Anchorage Command Center at (907) 428-4100. Mariners are reminded that Western and Northern Alaskan have no VHF-FM coverage. Contact in areas without VHF/FM coverage to the Coast Guard is via Communications Detachment Kodiak on HF or JRCC Juneau by phone. Mariners are requested to relay any unanswered calls for assistance to the Coast Guard.

LNM: 10/21

626 ALASKA – SOUTHEAST – STIKINE STRAIT/CHICHIGOF PASS

M/V CABLE INNOVATOR will be conducting a cable recovery and re-lay operation on the Seafast cable near Wrangell, Alaska from March 7th to 13th, 2021. Operations will be conducted 24 hours per day for the duration of the project. The M/V CABLE INNOVATOR is a special purpose cable laying ship, 477 feet long, with a dark hull and white superstructure and the bridge amidships. The M/V CABLE INNOVATOR will be transmitting on AIS and monitoring VHF/FM channels 13 and 16 and will be restricted in ability to manoeuvre while recovering/laying cable. A chartlet indicating the approximate route of the cable is included as an enclosure to this LNM. The M/V CABLE INNOVATOR will recover the existing cable in Stikine Strait (highlighted in red on the enclosed chartlet). Following the recovery operation, CABLE INNOVATOR will re-route the cable to Shoemaker Bay Harbor via Chichigof Pass (highlighted in blue). Questions/concerns should be directed to Alex Riddell at Alex.Riddell@oceaniq.co.uk or Steve Bennet at Steven.Bennett@globalmarine.co.uk.

LNM: 09/21

627 **CANCELLATION OF NOAA PAPER AND RASTER NAUTICAL CHARTS**

The National Oceanic and Atmospheric Administration (NOAA) is undertaking a multi-year program to end production and maintenance of its suite of over 1,000 traditional paper nautical charts and all associated raster chart products and services, including: Print-on-Demand (POD) paper nautical charts, Full-size chart PDF files, BookletChart™ PDF files, NOAA raster navigational charts (NOAA RNC®), the NOAA RNC tile service, and the online RNC viewer.

Six months notice of the intent to cancel a specific chart is provided in a "Last Edition" notice. The final cancellation of a chart is made in a "Canceled" notice. Both types of notices will appear in LNM Section IV, "Chart Correction." A comprehensive list of all canceled NOAA charts is available at: <http://www.charts.noaa.gov/MCD/Dole.shtml>.

Traditional paper nautical chart production is ending to enable the creation and maintenance of larger scale, more up-to-date, higher quality coverage of NOAA's electronic navigational chart (NOAA ENC®) product. This will significantly enhance the amount of charted detail available to mariners. More information about NOAA's program to sunset traditional paper charts is on the NOAA Coast Survey website at: <https://www.nauticalcharts.noaa.gov/farewell-to-traditional-nautical-charts.html>

An online NOAA Custom Chart application at: <https://devgis.charttools.noaa.gov/pod> is available to create chart images from ENC data, which may then be printed. Notices to Mariners will not be issued for NOAA Custom Charts.

LNM: 09/21

628 **ALASKA – COOK INLET**

The BAKER OIL PLATFORM warning lights (LLNR 26361) in position 60°49'45.390"N, 151°29'00.010"W and the DILLION OIL PLATFORM warning lights (LLNR 26361.5) in position 60°44'07.340"N, 151°30'42.610"W are experiencing intermittent outages. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Sector Anchorage Waterways Management at anchorage.waterways@uscg.mil or (907) 428-4189.

LNM: 08/21

633 **ALASKA – SOUTHCENTRAL – COOK INLET**

The U.S. Coast Guard Captain of the Port (COTP) for Western Alaska has implemented the Operating Guidelines for Ice Conditions for the Lower Cook Inlet, effective February 1st, 2021. All vessels arriving in Cook inlet destined for a port with an active ice condition must file a voyage plan with the COTP by email to sector.anchorage@uscg.mil or by fax to (907) 428-4114, no less than 24 hours prior to arrival at or abeam the Kachemak Bay pilot station. Additional information is included as an enclosure to this LNM. Questions/concerns should be directed to the Sector Anchorage Waterways Management Division at (907) 428-4189 or after normal business hours to the Sector Anchorage Command Center at (907) 428-4100.

LNM: 05/21

634 **ALASKA – SOUTHCENTRAL – PORT GRAVINA/ORCA BAY**

The University of Alaska, Fairbanks, has deployed an Autonomous Underwater Vehicle (AUV) in the vicinity of Port Gravina and Orca Bay. The AUV will be operating in the area from January 18th through April 18th, 2021. The AUV is 6 feet long, bright yellow and shaped like a torpedo with wings. It operates underwater but it will surface every two hours to transmit data. If sighted please avoid the AUV and do not try to recover it. Additional information including a photo of the AUV and a chartlet depicting the area of operation are included as an enclosure to this LNM. Questions/concerns should be directed to Hank Statscewich at (907) 322-3470 or by email to hstatscewich@alaska.edu or Mary Anne Bishop at (907) 424-5800 or by email to mbishop@pwssc.org.

LNM: 04/21

645 **CANADA – SOUTHEASTERN GULF OF ALASKA/DIXON ENTRANCE – HAIDA GWAI**

A Voluntary Protection Zone (VPZ) for shipping was established for a 14-month trial period along the West coast of Haida Gwaii by the Government of Canada, the Haida Nation, and multiple maritime and shipping industry partners. The program asks vessels to voluntarily increase the sailing distance off Haida Gwaii when transiting along the West coast of the archipelago. The goal of the VPZ is to reduce the risk of groundings and oil spills, by allowing more time to address any mechanical casualties, and the effectiveness of the VPZ will be assessed during this trial period, which runs until October 31st, 2021. An enclosure to this LNM has additional information. For more information, and to download a descriptive brochure, visit www.haidagwaii-vpz.ca or email info@haidagwaii-vpz.ca.

LNM: 50/20

651 **ALASKA – SOUTHCENTRAL – COOK INLET**

The U.S. Coast Guard Captain of the Port (COTP) for Western Alaska has implemented the Operating Guidelines for Ice Conditions for the Upper Cook Inlet, effective November 20, 2020. All vessels arriving in Cook Inlet destined for a port with an active ice condition must file a voyage plan with the COTP by email: Sector.Anchorage@uscg.mil or by fax: (907) 428-4114, no less than 24 hours prior to arrival at or abeam the Kachemak Bay pilot station. The Navigation Advisory containing additional details is included as an enclosure to this LNM. Questions/concerns should be directed to the Sector Anchorage Waterways Management Division during regular business hours at (907) 428-4189. After hours, contact the Sector Anchorage Command Center at (907) 428-4100 or on VHF/FM channel 16.

LNM: 47/20

656 **ALASKA – SOUTHCENTRAL – VALDEZ**

The new Valdez South Boat Harbor has been completed. The Coast Guard has established four lights, one light at the end of each breakwater to mark the harbor entrance and two lights on piles marking either side of the entrance channel. Those lights have been established or reconfigured as follows:

25822.2 Valdez South Boat Harbor Entrance Channel LT 1 – On a pile in position 61°07'21.023"N, 146°19'57.351"W

25822.3 Valdez South Boat Harbor Entrance Channel LT 2 – On a pile in position 61°07'20.974"N, 146°19'54.202"W

25822.4 Valdez South Boat Harbor Entrance Channel LT 3 – On end of breakwater in position 61°07'23.699"N, 146°19'56.213"W

25822.6 Valdez South Boat Harbor Entrance Channel LT 4 – On end of breakwater in position 61°07'20.632"N, 146°19'51.688"W

Chart and Light List corrections will be issued once the positions have been verified. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 46/20

661 **ALASKA**

The Coast Guard will be using AIS Broadcasts to relay some marine information, primarily ATON Discrepancies, VHF/FM Hi-site outages, active subsistence whaling, Gunnery and Pyrotechnics Exercises, and similar Notices directly relating to safe navigation. The Coast Guard's access to AIS transmitters is limited so not all areas might be covered at any given time and the locations of the active transmitters will be determined by the priority of the messages being broadcast from them. All information broadcast by AIS will also be published by the more conventional methods of BNM and LNM. Feedback is desired and should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 43/20

663 **ALASKA – SOUTHCENTRAL – KODIAK**

Hamilton Construction Company will be conducting repair and repainting of the Kodiak Harbor Bridge which spans between Near Island and Kodiak Island in approximate position 57°47.3022'N, 152°23.8332'W, from October 23rd, 2020 through July 15th, 2021. The work will consist of bridge re-painting which requires a temporary containment structure that will hang down from the bridge over the waterway, no more than 15 feet. All equipment will be staged on top of the bridge deck. Questions/concerns should be directed to Austin Dukowitz at (907) 723-0383 or by email to adukowitz@hamil.com.

LNM: 42/20

692 **ALASKA – SOUTHEAST – DIXON ENTRANCE TO KETCHIKAN**

Ketchikan Public Utilities has installed a submarine fiber optic cable from Prince Rupert, Canada to Ketchikan, Alaska. A chartlet indicating it's approximate route and positions indicating the "As Laid" route of the cable are included as an enclosure to this LNM. The positions have been submitted to NOAA and a chart correction will be issued in the near future. Mariners are requested to not anchor near or conduct operations that may impact the cable. Questions/concerns should be directed to Edward Cushing, KPU's Division Manager, at (907) 228-6001 or by email to edc@city.ketchikan.ak.us.

LNM: 38/20

694 **ALASKA – SOUTHCENTRAL – COOK INLET NAVIGATION CHANNEL**

The U.S. Army Corps of Engineers (USACE), Alaska District conducted a project condition survey for Cook Inlet Navigation Channel on August 18th, 2020 in which the following controlling depths in feet (FT) mean lower low water (MLLW) were recorded:

Left Outside Quarter 61°12'02.03"N, 150°05'42.26"W, -36.4 FT MLLW

Left Inside Quarter 61°12'00.14"N, 150°05'42.25"W, -39.7 FT MLLW

Right Inside Quarter 61°11'51.14"N, 150°05'56.92W, -40.9 FT MLLW

Right Outside Quarter 61°11'44.04"N, 150°06'15.51"W, -38.1 FT MLLW

A chartlet of the controlling depths as well as survey data are available on the U.S. Army Corps of Engineers (USACE) Navigation Portal website at: <http://navigation.usace.army.mil/Survey/Hydro>. The Cook Inlet Navigation Channel was dredged during the summer of 2014 to a project depth of -38 FT MLLW. At this time, no maintenance dredging is scheduled for this channel during 2020. The next project condition survey for this channel is tentatively scheduled for May 2021. BE ADVISED: The information depicted on maps, charts, drawings, navigation notices, etc., for the subject project, represents the results of a survey conducted on the date(s) indicated and can only be considered to represent the general condition existing at that time. The survey data was collected under a USACE contract for the purpose of characterizing the condition of the navigation channel, and the area for placement of dredged material for future channel maintenance operations. As such, the information is only valid for its intended use. This information can be used to supplement existing published navigation charts. The user is responsible for the results of any application of the survey data for other than its intended purpose and should consider the contents, timeframe of data collection, and accuracy specifications for survey data collection/processing. Additionally, bathymetry in Cook Inlet is subject to drastic and continuing change. Prudent mariners should not rely solely upon this information. Questions/concerns should be directed to Donna West with the USACE Anchorage office at (907) 753-2761 or by email to Donna.L.West@usace.army.mil.

LNM: 37/20

751 **ALASKA – SOUTHCENTRAL – PRINCE WILLIAM SOUND – BARRY ARM**

The State of Alaska has issued a press release indicating that a potential landslide caused tsunami may occur in Barry Arm in Northwestern Prince William Sound. It is uncertain if and when this might occur and until additional testing and analysis is conducted a more accurate timetable cannot be developed. The geologic makeup of the area is similar to Alaskan locations where two previous landslides caused tsunamis occurred, in Lituya Bay (1958) and Icy Bay (2015), both causing extremely large but localized tsunamis. Mariners should maintain vigilance when in the vicinity of Barry Arm or nearby waters and be prepared to depart the area if any unusual geologic activity is observed. Additional information is available at the following website:

<https://www.adfg.alaska.gov/sf/EONR/index.cfm?ADFG=region.NR&Year=2020&NRID=2935>

LNM: 20/20

782 **ALASKA – SOUTHEAST – DIXON ENTRANCE**

Tree Point LT (LLNR 21840) has been relocated to a new steel structure approximately 100 yards Southeast of the existing lighthouse structure. The approximate position for the new light is 54°48'10"N, 130°56'04"W. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 11/20

784 **ALASKA**

The outbreak of respiratory illness caused by the COVID-19 virus may affect mariners and maritime commerce transiting to or near Alaska. Additional interim guidance for ships on managing suspected coronavirus disease concerns is available at <https://www.cdc.gov/quarantine/maritime/recommendations-for-ships.html>. Two enclosures to this LNM include additional information as well as a number of links to websites where additional information regarding this illness can be obtained. Mariners with questions/concerns while transiting to or near Alaska should contact the Coast Guard Sector Anchorage Command Center at (907) 428-4100 or the Coast Guard Sector Juneau Command Center at (907) 463-2980.

LNM: 11/20

807 **ALASKA – SOUTHWESTERN – BRISTOL BAY – PORT MOLLER**

The Coast Guard has decommissioned the Port Moller Harbor Spit DBN (LLNR 27850). Chart and Light List corrections will be issued in a subsequent LNM. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 04/20

832 **ALASKA – SOUTHWESTERN – ALEUTIAN PENINSULA AND ISLANDS**

The Captain of the Port (COTP), Western Alaska, through consultation with marine pilot associations, vessel operators, and port authorities, developed operating procedures for vessels in port or at anchor in the Aleutian or Pribilof Islands, with an emphasis on Dutch Harbor, Alaska. Those procedures were developed to address the frequent and severe storms that impact both the Aleutian and Pribilof Islands and have been published as a Navigation Advisory and is available online at https://ba5d8e27-22a6-4c7e-bfd1-86a9416f28e1.filesusr.com/ugd/cd25fe_5daa0bb144324e6b9abe6e5c5305492c.pdf. Questions/concerns should be directed to LT Mateusz Lemanski at (907) 463-4189 or by email to Mateusz.j.lemanski@uscg.mil or the Coast Guard Sector Anchorage Command Center at (907) 428-4100.

LNM: 48/19

836 **ALASKA – SOUTHEAST – TONGASS NARROWS**

OBSTRUCTION TO NAVIGATION: A 24' Bayliner has sunk in 22 feet of water in approximate position 55°20.79'N, 131°40.36'W, approximately 50 yards offshore from Bar Harbor. The vessel is marked by an orange float. Mariners are requested to use caution when transiting the area. Questions/concerns should be directed to the Coast Guard Sector Juneau Command Center at (907) 463-2980 or on VHF/FM channel 16.

LNM: 48/19

916 **ALASKA – GULF OF ALASKA**

NOAA DLB 46001 (LLNR 984) has been replaced with a 3-meter buoy and relocated to 56°13'56.000"N, 147°56'57.000"W. Chart and Light List corrections were issued in LNM 32/19 but gave an incorrect position for NOAA DLB 46001 (LLNR 984). The chart and Light List corrections have been reissued in this LNM. The previous 6-meter buoy was not recovered, has been temporarily renamed 46X01, and remains in position 56°18'16.000"N, 147°55'13.000"W. Mariners are requested to transit the area with caution until the previous buoy is recovered. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 35/19

918 **ALASKA – GULF OF ALASKA**

NOAA DLB 46085 (LLNR 984.15) has been replaced with a 3-meter buoy and relocated to 55°53'18.000"N, 142°50'48.000"W. Chart and Light List corrections have been issued. The previous 6-meter buoy was not recovered and remains in position 55°52'05.000"N, 142°33'31.000"W. Mariners are requested to transit the area with caution until the previous buoy is recovered. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 33/19

930 **ALASKA – SOUTHCENTRAL – SHELIKOF STRAIT – KINAK BAY**

An uncharted rock has been reported in Kinak Bay in position 58°03.8'N, 154°25.3'W at a depth of approximately 3 fathoms. Mariners are advised to transit the area with extreme caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 28/19

937 **ALASKA – SOUTHCENTRAL – PRINCE WILLIAM SOUND – UNAKWIK INLET**

An uncharted and dangerous rock has been reported in Unakwik Inlet in approximate position 61°08.045'N, 147°32.665'W. Mariners should transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 25/19

939 **ALASKA – SOUTHEAST – WRANGELL NARROWS**

OBSTRUCTION TO NAVIGATION: The P/C HEATHER ANN has sunk in Wrangell Narrows on the East side of the channel approximately 330 yards South of Wrangell Narrows Channel LT 16 (LLNR 22955). The most recent reported position was 56°37.25'N, 132°57.64'W. The P/C HEATHER ANN is a 52' wood vessel and may be awash and barely visible at higher tides, exposed at lower tides, or relocated by the extreme current in the area. The vessel was marked with a single orange float. Mariners are requested to transit the area with extreme caution and report any changes in position to the Coast Guard Sector Juneau on VHF/FM channel 16 or by phone to (907) 463-2980.

LNM: 25/19

946 **ALASKA – SOUTHEAST – FRESHWATER BAY**

An uncharted rock shoal has been reported in Cedar Cove centered in approximate position 57°52.405'N, 135°03.694'W with an approximate 75 foot radius. The rocks were approximately 1 foot below a 0' tide. The location of the reported shoal has a charted depth of 12 fathoms. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 24/19

960 **ALASKA – SOUTHEAST – STARRIGAVAN BAY**

Blasting will be conducted for construction of the Katlian Bay road from Starrigavan Bay to Katlian Bay beginning May 15, 2019 through September 1, 2021. Blasting will begin in approximate position 57° 08' 09" N, 135°22'12"W and end in approximate position 57°09'43" N, 135°17'18" W, with a danger radius of 1,000 feet. Blasting may take place during daylight hours 7 days per week. Blasting will be preceded by a series of long audible signals 5 minutes prior to blasting, a series of short audible signals 1 minute prior to blasting, and one long audible signal when the blast is complete. Mariners are advised to avoid transiting within the danger radius when blasting is taking place. Blasting near the coastline will be announced on the VHF/FM channel 16 one hour prior to blasting, and blasting personnel will maintain lookouts for watercraft within the danger radius before the blast is initiated. Questions/concerns should be directed to Ken Kirschenman at (916) 218-2729 or by email to superiorblasting@yahoo.com.

LNM: 18/19

964 **ALASKA – SOUTHEAST – FARRAGUT BAY – FRANCIS ANCHORAGE**

Uncharted shoaling was observed in Francis Anchorage on February 14th, 2019 in position 57°08.95'N, 133°10.03'W. The charted depth for this location is 15 fathoms and the observed depths rapidly shallowed from 120 feet and ranged from 8 to 10 feet. The navigational charts for Francis Anchorage are based on pre-1900 Partial Bottom Coverage Surveys and in 1976 'shoaling to bare' was reported further into the anchorage. Mariners should transit this area with extreme caution and be aware of areas that may not be adequately charted. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 08/19

970 **ALASKA – SOUTHCENTRAL – PRINCE WILLIAM SOUND – ESTHER ISLAND**

OBSTRUCTION TO NAVIGATION: The 32' F/V SONG II has been reported sunk in position 60°47.76'N, 148°03.31'W. Mariners are requested to transit the area with caution and report any sightings to the Coast Guard Sector Anchorage Command Center at (907) 428-4100 or on VHF/FM channel 16.

LNM: 34/18

971 **ALASKA - CENTRAL – BETHEL**

OBSTRUCTION: The barge SHANKS ARK has been reported sunken and abandoned in Steamboat Slough on the Kuskokwim River, approximate position 60°47'15"N, 161°41'52"W. A portion of the vessel remains visible above the level of high-tide, but the majority of the vessel remains below the waterline. The vessel is marked by an all-round white light and one ball dayshape when Steamboat Slough is ice free but the markers are removed during freeze up as no hazards exists. The Coast Guard has actively monitored the proper marking of the vessel by the vessel's owner and operator since September 10, 2016. Coast Guard pollution investigators confirmed the vessel does not pose a substantial pollution threat to the environment. Mariners are requested to transit the area with caution and report any discrepancies with the vessel's marking to the Coast Guard. Questions/concerns should be directed to LT David Parker, Sector Anchorage Waterways Management, at (907) 428-4189.

LNM: 11/17

972 **ALASKA – ALEUTIAN ISLANDS – AKUTAN ISLAND – AKUTAN HARBOR**

UNKNOWN MARINE ANOMALY: An unknown marine anomaly was discovered during underwater survey operations in Akutan Harbor in position 54°07.70889'N, 165°46.38298'W on the sea floor at a depth of 138 feet. This anomaly has not been positively identified. Mariners are requested to transit the area with caution. Questions/concerns should be directed to LT David Parker with the Coast Guard Sector Anchorage Waterways Management Branch at (907) 428-4189 or by email to david.n.parker@uscg.mil.

LNM: 03/18

974 **ALASKA – SOUTHWESTERN – ALEUTIAN PENINSULA – BECHEVIN BAY**

Shoaling has been reported at the bar along the Northern entrance to Bechevin Bay by a vessel with a draft of 10 feet that reported briefly grounding in seas running 6-8 feet. Mariners should take into account their vessel's draft, charted depth of water, tides and sea state when determining an appropriate under-keel clearance for a safe transit of this waterway. Mariners are requested to report any future groundings or significant variations from charted depth to the Coast Guard Sector Anchorage Command Center at (907) 428-4100 or on VHF/FM channel 16.

LNM: 17/18

976 **ALASKA – WESTERN – YUKON RIVER**

The Yukon River South Entrance LT (LLNR 27860) has been rebuilt but the position has not been verified. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 37/17

977 **ALASKA – SOUTHEAST – ICY STRAIT – NORTH INIAN PASSAGE**

The currents in North Inian Passage and Glacier Bay have been observed at up to 3 knots above the NOAA published current predictions. Mariners should exercise caution when transiting the area. Questions/concerns should be directed to LT Bart Buesseler at (907) 271-3327 or by email to bart.o.buesseler@noaa.gov.

LNM: 36/17

978 **ALASKA – GULF OF ALASKA**

NOAA DLB 46001 (LLNR 984) has been replaced with a 3-meter buoy and relocated to 56°13'56"N, 147°56'57"W. Chart and Light List corrections have been issued. The previous 6-meter buoy was not recovered due to weather and remains in position 56°19'33.962"N, 147°57'01.382"W. Mariners are requested to transit the area with caution until the previous buoy is recovered. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 35/17

980 **ALASKA – U.S. COAST GUARD MEDIUM FREQUENCY (MF) DISTRESS WATCHKEEPING**

Mariners are advised that calls to the U.S. Coast Guard on the international radiotelephone distress frequency 2182 kHz or the Digital Selective Calling (DSC) frequency 2187.5 kHz may not be heard or may be severely degraded. Instead of using 2182 kHz for distress calls, mariners should use high frequency (HF) radiotelephone or DSC in the 4, 6, 8, and 12 MHz distress or calling bands. Additional information concerning U.S. Coast Guard HF watchkeeping is posted on the U.S. Coast Guard's Navigation Center website (<https://www.navcen.uscg.gov/?pageName=cgcommsCall>).

LNM: 08/17

983 **ALASKA – SOUTHEAST**

The U.S. Coast Guard has VHF Digital Selective Calling (DSC) capability with limited coverage in Southeast Alaska. The initial coverage areas are Ketchikan, Juneau and Yakutat. Mariners are reminded to ensure that they have properly connected their GPS units to their DSC equipped marine VHF radios and registered for their Maritime Mobile Service Identity (MMSI) to utilize the DSC distress function. Additional information is available through the Alaska Outdoors Forum at [http://forums.outdoorsdirectory.com/showthread.php/142083-Digital-Selective-Calling-\(DSC\)](http://forums.outdoorsdirectory.com/showthread.php/142083-Digital-Selective-Calling-(DSC)) or by contacting Mike Folkerts with the Coast Guard District 17 Boating Safety Office at (907) 463-2297 or by email to Michael.r.folkerts@uscg.mil.

LNM: 15/15

984 **ALASKA – SOUTHCENTRAL**

The U.S. Coast Guard has VHF Digital Selective Calling (DSC) capability with limited coverage in Southcentral Alaska. The initial coverage areas are Upper Cook Inlet, Kodiak and Valdez Arm. Mariners are reminded to ensure that they have properly connected their GPS units to their DSC equipped marine VHF radios and registered for their Maritime Mobile Service Identity (MMSI) to utilize the DSC distress function. Additional information is available through the Alaska Outdoors Forum at [http://forums.outdoorsdirectory.com/showthread.php/142083-Digital-Selective-Calling-\(DSC\)](http://forums.outdoorsdirectory.com/showthread.php/142083-Digital-Selective-Calling-(DSC)) or by contacting Mike Folkerts with the Coast Guard District 17 Boating Safety Office at (907) 463-2297 or by email to Michael.r.folkerts@uscg.mil.

LNM: 15/15

985 **ALASKA – SOUTHEAST – WESTERN BEHM CANAL**

The U.S. Navy has established a temporary data collection buoy in Western Behm canal approximately 5,000 yards North of Betton Island within 400 yards of position 55°35.684'N, 131°46.503'W. The buoy is described as a 3 foot diameter yellow sphere, with the marking "Wave Buoy", with an attached telemetry whip antenna and a night time warning light that flashes 5 times at 1 second intervals with a period of 20 seconds between each series, Fl(5) Y 25s. Questions/concerns should be directed to Mr. Bill Harney at (907) 247-6289.

LNM: 05/15

986 **ALASKA**

The Alaska Marine Safety Education Association (AMSEA) will be offering AMSEA Marine Safety Instructor Training and AMSEA Drill Conductor Courses in various locations within Alaska. The specific locations, dates, and course information can be found in an enclosure to this LNM. For more information contact AMSEA at (907) 747-3287 or view their website at www.amsea.org.

LNM: 12/14

988 **ALASKA – ALEUTIAN ISLANDS – ADAK – SWEEPER COVE**

The East side of the Pier 5 Dock located in Sweeper Cove is closed to moorage without prior approval from the Adak Harbormaster due to loose and missing pilings. Questions/concerns should be directed to Jim Fleming at (907) 277-7527 or the Port of Adak office at (907) 592-0185. The Adak harbormaster can also be contacted on VHF/FM channel 16.

ALASKA – SUBSURFACE AND SURFACE BUOYS

Locations of all subsurface and surface oceanographic moorings that have been reported to the U.S. Coast Guard District 17 Waterways Branch are included in an enclosure to the Local Notice to Mariners. The name, type, location, depth, water depth, and a Point of Contact for all data buoys, surface and subsurface, shall be reported as quickly as is practical if they are placed within the navigable waters (within 200 nm) of the United States. Data buoys placed in the Arctic region but outside of 200 nm of the United States may be reported and will be included in this compilation (for informational purposes only). This notification process is for inclusion in the Local Notice to Mariners to provide navigational information to mariners and does not supersede any permission or permitting requirements. Any notifications, corrections, additions, deletions, or comments for the Alaska region (Coast Guard District 17) or the Arctic region should be submitted via e-mail to D17-PF-D17-LNM@uscg.mil or to Todd Buck, USCG D17(dpw), at (907) 463-2269 or by email to todd.r.buck@uscg.mil. This compilation is as current as the Local Notice to Mariners (LNM) as included in an enclosure. The referenced LNM may have additional information and indicates the last time an entry was updated.

SECTION II - DISCREPANCIES

This section lists all reported and corrected discrepancies related to Aids to Navigation in this edition. A discrepancy is a change in the status of an aid to navigation that differs from what is published or charted.

DISCREPANCIES (FEDERAL AIDS)

LLNR	Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM End
1045	Star Rock Bell Buoy SR	OFF STA	17303	J097-20	37/20	
1150	Seal Rocks Light	LT EXT/DAYMK MISSING	16682	A112-20	41/20	
1260	Cape Greig Light	DAYMK DMGD	16338	A067-20	24/20	
22670	Blake Channel Light 1	STRUCT DEST/LT EXT	17385	J124-20	48/20	
23305.1	Keku Strait Entrance Light	STRUCT DEST	17368	J069-19	38/19	
23305.7	Keku Strait Daybeacon 10	MISSING	17368	J148-13	32/13	
23305.9	Keku Strait Daybeacon 13	STRUCT DEST	17368	J103-15	23/15	
23306.7	Keku Strait Daybeacon 25	STRUCT DEST	17368	J071-20	28/20	
23307	Keku Strait Daybeacon 30	STRUCT DEST	17368	J075-20	29/20	
23307.05	Keku Strait Daybeacon 31	STRUCT DEST	17372	J072-20	28/20	
23355	Portage Pass Daybeacon 11	STRUCT DEST	17368	J077-18	26/18	
23510	Point Ellis Light	LT EXT	17376	J028-21	08/21	
23520	Hoggatt Bay Light	LT EXT	17336	J018-21	07/21	
23665	Sheep Creek Light 2	LT EXT	17315	J004-21	03/21	
23895	Letnikof Cove Light 2	DAYMK DMGD	17317	J021-21	07/21	
24260	Elfin Cove Daybeacon 5	STRUCT DEST	17302	J017-18	36/19	
24790	Dry Pass Daybeacon 3	STRUCT DEST	17387	J072-18	23/18	
24948	Indian River Flats Lighted Buoy 2	LT EXT	17327	J032-20	09/20	
25025.51	Japonski Island Buoy 2	OFF STA	17327	J030-21	09/21	
25335	Klag Bay Entrance Daybeacon 1	STRUCT DEST	17322	J047-19	30/19	
25355	Dippy Island Rock Daybeacon 3	DAYMK DMGD	17321	J216-15	51/15	
25615.1	Orca Inlet South Channel Buoy 2	MISSING	16709	A108-20	40/20	
25615.85	Orca Inlet South Channel Buoy 16	MISSING	16709	A100-20	37/20	
25665	Glacier Island Light	LT EXT	16713	A121-20	43/20	
25824	Valdez Security Zone Lighted Buoy B	LT EXT	16707	A007-21	04/21	
25975	Lonetree Point Light	LT EXT	16702	A134-20	49/20	
25982	NOAA Data Lighted Buoy 46076	OFF STA	16700	A060-20	23/20	
26020	Seward East Breakwater Light 2	DAYMK DMGD	16682	A018-21	10/21	
26330	Nikiski Sector Light	LT EXT	16665	A047-20	19/20	

26435	Point Woronzof Range Front Light	LT EXT	16665	A033-20	14/20
26440	Point Woronzof Range Rear Light	LT EXT	16665	A010-21	07/21
26910	Aiaktalik Island Light 5	DAYMK DMGD	16590	A133-20	49/20
26925	Lazy Bay Light 2	DAYMK DMGD	16591	A132-20	49/20
27105	Humboldt Harbor Breakwater Light 2	STRUCT DEST	16553	A026-19	08/19
27190	King Cove Harbor Entrance Light 2	STRUCT DEST	16549	A015-21	10/21
27300	Chunak Point Daybeacon 2	STRUCT DEST	16535	A093-20	33/20
27345	St. Catherine Cove Daybeacon 4	STRUCT DEST	16535	A094-20	33/20
27505	Bailey Ledge Light	LT EXT/STRUCT DMGD	16529	A122-20	43/20

DISCREPANCIES (FEDERAL AIDS) CORRECTED

LLNR	Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM End
24005	Killisnoo Harbor Entrance Lighted Buoy 2	WATCHING PROPERLY	17339	J031-21	07/21	10/21
25000	Makhnati Rock Lighted Whistle Buoy 2	WATCHING PROPERLY	17327	J033-21	08/21	10/21
27185	King Cove Harbor Entrance Light 1	WATCHING PROPERLY	16549	A014-21	09/21	10/21

DISCREPANCIES (PRIVATE AIDS)

LLNR	Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM End
22201	Bar Harbor Breakwater East Light	STRUCT DEST	17430	J202-15	47/15	
22202	Bar Harbor Breakwater Middle Light	STRUCT DEST	17430	J203-15	47/15	
22203	Bar Harbor Breakwater West Light	STRUCT DEST	17430	J204-15	47/15	
23804.5	Auke Bay Speed Limit Lighted Buoy	LT EXT	17315	J051-20	16/20	
23908	Port Chilkoot Mooring Dolphin Lights (2)	LT EXT	17317	J175-14	38/14	
25822	Port Valdez Servs Dock Lights (2)	OFF STA	16707	A067-19	24/19	
25893	Whittier Passenger Dock Lights (2)	LT EXT	16706	A031-10	20/10	
26361	Baker Oil Platform Light	LT EXT	16662	A012-21	08/21	
26361.5	Dillon Oil Platform Light	LT EXT	16662	A011-21	07/21	

DISCREPANCIES (PRIVATE AIDS) CORRECTED

LLNR	Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM End
------	----------	--------	-----------	----------	--------	---------

None

PLATFORM DISCREPANCIES

Name	Status	Position	BNM Ref.	LNM St	LNM End
------	--------	----------	----------	--------	---------

None

PLATFORM DISCREPANCIES CORRECTED

Name	Status	Position	BNM Ref.	LNM St	LNM End
------	--------	----------	----------	--------	---------

None

SECTION III - TEMPORARY CHANGES and TEMPORARY CHANGES CORRECTED

This section contains temporary changes and corrections to Aids to Navigation for this edition. When charted aids are temporarily relocated for dredging, testing, evaluation, or marking an obstruction, a temporary correction shall be listed in Section IV giving the new position.

TEMPORARY CHANGES

LLNR	Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM End
23355	Portage Pass Daybeacon 11	TRUB	17368	J093-18	30/18	
23790	Horse Shoal Light 1	DISCONTINUED	17315	J102-19	51/19	
24957	Mitchell Rock Daybeacon	DISCONTINUED	17327	J022-17	04/17	

25025.5	Japonski Island Daybeacon 2	DISCONTINUED	17327	J196-16	49/16
25647	NOAA Data Lighted Buoy 46081	DISCONTINUED	16705	A126-19	46/19
25805	Port Valdez Coast Guard Mooring Buoy	DISCONTINUED	16707	A095-18	33/18

TEMPORARY CHANGES CORRECTED

LLNR	Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM End
------	----------	--------	-----------	----------	--------	---------

None

PLATFORM TEMPORARY CHANGES

Name	Status	Position	BNM Ref.	LNM St	LNM End
------	--------	----------	----------	--------	---------

None

PLATFORM TEMPORARY CHANGES CORRECTED

Name	Status	Position	BNM Ref.	LNM St	LNM End
------	--------	----------	----------	--------	---------

None

SECTION IV - CHART CORRECTIONS

None

OIL RIG MOVEMENT

Drill Rigs/Vessels Removed

Latitude	Longitude	Block	Rigs/Vessel	Chart	Type	Status
----------	-----------	-------	-------------	-------	------	--------

None

Drill Rigs/Vessels Established

Latitude	Longitude	Block	Rigs/Vessel	Chart	Type	Status
----------	-----------	-------	-------------	-------	------	--------

None

SECTION V - ADVANCE NOTICES

This section contains advance notice of approved projects, changes to aids to navigation, or upcoming temporary changes such as dredging, etc. Mariners are advised to use caution while transiting these areas.

SUMMARY OF ADVANCED APPROVED PROJECTS

<u>Approved Project(s)</u>	<u>Project Date</u>	<u>Ref. LNM</u>
----------------------------	---------------------	-----------------

None

Advance Notice(s)

690 **ALASKA – SOUTHEAST – SITKA**

The Coast Guard intends to rename and upgrade Japonski Island Buoy 2 (LLNR 25025.51) to Japonski Island Lighted Buoy 2 (LLNR 25025.51) with a red flash every 4 seconds (R 4s). Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 38/20

ALASKA – SOUTHEAST – TONGASS NARROWS – WARD COVE

The Coast Guard will be establishing Bolle Ledge LB 2 (LLNR 22253) in Ward Cove in approximate position 55°24'13.860"N, 131°43'33.540"W in 33 feet of water. Bolle Ledge LB 2 will be a red buoy with a red quick flashing light. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 38/20

SECTION VI - PROPOSED CHANGES

Periodically, the Coast Guard evaluates its system of aids to navigation to determine whether the conditions for which the aids to navigation were established have changed. When changes occur, the feasibility of improving, relocating, replacing, or discontinuing aids are considered. This section contains notice(s) of non-approved, proposed projects open for comment. SPECIAL NOTE: Mariners are requested to respond in writing to the District office unless otherwise noted (see banner page for address).

PROPOSED WATERWAY PROJECTS OPEN FOR PUBLIC COMMENT

Proposed Project(s)

Closing

Docket No.

Ref. LNM

None

Proposed Change Notice(s)

ALASKA – WESTERN – NORTON SOUND – GOLOVIN BAY

The Coast Guard is proposing adding navigational aids within Golovin Bay. These aids may include Lights, Daybeacons, or buoys. Mariners are requested to provide recommendations on locations that would facilitate safe navigation within Golovin Bay. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 26/18

SECTION VII - GENERAL

This section contains information of general concern to the Mariners. Mariners are advised to use caution while transiting these areas.

None

SECTION VIII - LIGHT LIST CORRECTIONS

An Asterisk *, indicates the column in which a correction has been made to new information

(1) No.	(2) Name and Location	(3) Position	(4) Characteristic	(5) Height	(6) Range	(7) Structure	(8) Remarks
------------	--------------------------	-----------------	-----------------------	---------------	--------------	------------------	----------------

None

PUBLICATION CORRECTIONS

None

ENCLOSURES

ALASKA

[1120 MSIB-06-20.pdf](#)

Vessel Reporting Requirements for Illness or Death

LNM: 11/20

ALASKA

[1120 MSIB-02-20.pdf](#)

Novel Coronavirus – Update (Change 3)

LNM: 11/20

ALASKA

[4220Subsurface Buoys.pdf](#)

Compilation of Subsurface and Surface oceanography moorings properly reported to U.S. Coast Guard District 17.

LNM: 42/20

ALASKA

[2320 MSIB 17-20.pdf](#)

Coast Guard Marine Safety Information Bulletin

LNM: 23/20

ALASKA – SOUTHCENTRAL – COOK INLET

[4720 Ice Advisory.pdf](#)

USCG COTP Ice Guidelines

LNLM: 47/20

CANADA – SOUTHEASTERN GULF OF ALASKA/DIXON ENTRANCE – HAIDA GWAI

[5020 Haida Gwaii VPZ.pdf](#)

Additional information about a Voluntary Protection Zone (VPZ) for shipping that was established for a 14-month trial period along the West coast of Haida Gwaii.

LNLM: 50/20

ALASKA – SOUTHCENTRAL – COOK INLET

[0521 NavAdvisory Ice Guidelines.pdf](#)

NavAdvisory 16710 – Operating Guidelines for Ice Conditions for the Lower Cook Inlet

LNLM: 05/21

ALASKA – SOUTHEAST – STIKINE STRAIT/CHICHIGOF PASS

[0921 Seafast Cable Replacement.pdf](#)

Seafast Cable recovery/relay

LNLM: 09/21

ALASKA

[1021 AMSEA.pdf](#)

AMSEA Maritime Training

LNLM: 10/21

ALASKA – SOUTHCENTRAL – PORT GRAVINA/ORCA BAY

[0421 Autonomous Submersible.pdf](#)

Information about an Autonomous Underwater Vehicle deployed in the vicinity of Port Gravina and Orca Bay.

LNLM: 04/21

ALASKA – SOUTHEAST – DIXON ENTRANCE TO KETCHIKAN

[3820 KPU Telecom Cable As Laid.pdf](#)

As Laid location of submarine fiber optic cable from Prince Rupert, Canada to Ketchikan, Alaska.

LNLM: 38/20

Michael D. Newell
Waterways Management Branch
Seventeenth Coast Guard District
OPERATIONAL EXCELLENCE THROUGH LEADERSHIP, TEAMWORK, AND INNOVATION.



Marine Safety Information Bulletin

Commandant
U.S. Coast Guard
Inspections and Compliance Directorate
2703 Martin Luther King Jr Ave SE, STOP 7501
Washington, DC 20593-7501

MSIB Number: 06-20
Date: March 13, 2020

E-Mail: OutbreakQuestions@uscg.mil

Vessel Reporting Requirements for Illness or Death

An outbreak of respiratory illness caused by novel coronavirus (COVID-19) is affecting mariners and maritime commerce. This MSIB serves as a reminder that the illness of persons on board a vessel must be reported to both the Coast Guard and the Centers for Disease Control and Prevention (CDC). Reporting delays create significant challenges to protect persons on board vessels and, more broadly, maintain an effective Marine Transportation System. Vessels or masters that do not immediately report illness or death among passengers or crew may face delays and disruption to passenger and cargo operations including a requirement to return to the previous port after sailing. Additionally, vessels and masters are subject to Coast Guard enforcement action, which include civil penalties, vessel detentions, and criminal liability.

Illness of a person onboard a vessel that may adversely affect the safety of a vessel or port is a hazardous condition per 33 CFR 160.216 and the owner, agent, master, operator, or person in charge **must immediately** notify the nearest Coast Guard Captain of the Port (COTP). It is critical to report persons who exhibit symptoms consistent with COVID-19 or other illness to the COTP.

42 CFR 71.1 defines an ill person onboard a vessels as one that has:

(A) **Fever (has a measured temperature of 100.4 °F [38 °C] or greater; or feels warm to the touch; or gives a history of feeling feverish) accompanied by one or more of the following:**

- skin rash,
- **difficulty breathing** or suspected or confirmed pneumonia,
- **persistent cough** or cough with bloody sputum,
- decreased consciousness or confusion of recent onset,
- new unexplained bruising or bleeding (without previous injury),
- persistent vomiting (other than sea sickness)
- headache with stiff neck;

(B) **Fever that has persisted for more than 48 hours;**

(C) Acute gastroenteritis, which means either:

- diarrhea, defined as three or more episodes of loose stools in a 24-hour period or what is above normal for the individual, or
- vomiting accompanied by one or more of the following: one or more episodes of loose stools in a 24-hour period, abdominal cramps, headache, muscle aches, or fever (temperature of 100.4 °F [38 °C] or greater);

Additionally, as required by [42 CFR 71.21](#), the master of a ship destined for a U.S. port shall report *immediately* to the quarantine station at or nearest the port at which the ship will arrive, the occurrence, on board, of any death or any ill person among passengers or crew (including those who have disembarked or have been removed) during the 15-day period preceding the date of expected arrival or during the period since departure from a U.S. port (whichever period of time is shorter). Guidance and forms to report deaths and illnesses to the CDC can be found at: <https://go.usa.gov/xdjnj>.

Richard Timme, RDML, U.S. Coast Guard, Assistant Commandant for Prevention Policy sends.



Marine Safety Information Bulletin

Commandant
U.S. Coast Guard
Inspections and Compliance Directorate
2703 Martin Luther King Jr Ave SE, STOP 7501
Washington, DC 20593-7501

MSIB Number: 02-20 (Change 3)
Date: March 16, 2020

E-Mail: OutbreakQuestions@uscg.mil

Novel Coronavirus – Update (Change 3)

An outbreak of respiratory illness caused by a novel coronavirus (COVID-19) may affect mariners and maritime commerce. The Centers for Disease Control and Prevention (CDC) has updated their Interim Guidance for Ships on Managing Suspected Coronavirus Disease 2019 (see <https://go.usa.gov/xdfyG>) and Cruise Ship Travel (see <https://go.usa.gov/xdfVP>).

Illness of a person onboard any vessel that may adversely affect the safety of a vessel or port facility is a hazardous condition per 33 CFR 160.216 and must be reported **immediately** to the U.S. Coast Guard Captain of the Port (COTP). Cases of persons who exhibit symptoms consistent with COVID-19 must be reported to the COTP.

The Coast Guard considers it a hazardous condition under 33 CFR 160.216 if anyone, regardless of where they have been or who they have interacted with, shows symptoms of COVID-19 or other flu like illness. This requires immediate notification to the nearest Coast Guard COTP.

Per 42 CFR 71.21, vessels destined for a U.S. port are required to report to the CDC any sick or deceased crew/passengers during 15 days prior to arrival at the U.S. port. Guidance to vessels to report deaths and illnesses to the CDC can be found at: <https://go.usa.gov/xdjmj>. U.S. flagged commercial vessels are also advised to report ill crewmembers in accordance with the requirements of each foreign port called upon.

Presidential Proclamations have placed entry restrictions from persons arriving from or through the following countries: Iran, China (excluding Hong Kong and Macau), the European states within the Schengen Area (Austria, Belgium, Czech Republic, Denmark, Estonia, Finland, France, Germany, Greece, Hungary, Iceland, Italy, Latvia, Liechtenstein, Lithuania, Luxembourg, Malta, Netherlands, Norway, Poland, Portugal, Slovakia, Slovenia, Spain, Sweden, and Switzerland), and beginning at 11:59 p.m. eastern standard daylight savings time on March 16, 2020, United Kingdom and Republic of Ireland.

Vessel owners/operators and local stakeholders should be aware of the following:

1. On March 13, 2020, Cruise Lines International Association (CLIA) announced that member companies were voluntarily suspending cruise ship operations from U.S. ports of call for 30 days. The CDC issued a [No Sail Order](#) on March 14, 2020 to all cruise ships that had not voluntarily suspended operations. The Coast Guard will closely coordinate with CDC to facilitate a safe and expeditious return of passengers onboard cruise ships that are underway and bound for U.S. ports.
2. Maritime commerce is vital to the U.S. economy and the Coast Guard has the responsibility to safely enable the uninterrupted flow of maritime cargo.
 - Non-passenger commercial vessels that have been to the countries noted above or embarked crewmembers from the countries noted above within the last 14 days, with no sick crewmembers, will be permitted to enter the U.S. and conduct normal operations, provided that crewmembers remain aboard the vessel except to conduct specific activities directly related to vessel cargo or

provisioning operations. U.S. citizens or any other persons listed in Section 2 of Presidential Proclamation “[Suspension of Entry as Immigrants and Nonimmigrants of Certain Additional Persons Who Pose a Risk of Transmitting 2019 Novel Coronavirus](#)”, for example crewmembers with a transit and/or crewmember visa, may be permitted to disembark the vessel to conduct vessel operations pier side or for the immediate and continuous transit through the U.S. to another country. When entering the U.S. all persons must be cleared by Customs and Border Protection (CBP) and, if applicable, CDC. Crewmembers without the appropriate visas will generally be required to remain onboard unless otherwise cleared for entry by CBP and, if applicable, CDC.

- Non-passenger commercial vessels that have been to the countries noted above or embarked crewmembers from the countries noted above within the last 14 days, and do have sick crewmembers should expect delays and need to work with local health and port officials prior to entry.
3. All persons that have been in or through a country listed above may be subject to CDC screening prior to disembarkation.

Vessel owners and operators should be aware of the following:

- The Coast Guard will continue to review all “Notice of Arrivals” in accordance with current policies and will communicate any concerns stemming from sick or deceased crew or passengers to their Coast Guard chain of command and the cognizant CDC quarantine station, who will coordinate with local health authorities.
- All commercial vessel operators and mariners are encouraged to exercise due diligence during daily operations and highly encouraged to follow the CDC [Interim Guidance for Ships on Managing Suspected Coronavirus Diseases 2019](#).
- Vessel masters shall inform Coast Guard boarding teams of any ill crewmembers on their vessel prior to embarking the team.
- Local industry stakeholders, in partnership with their Coast Guard COTP, should review and be familiar with section 5310 Procedures for Vessel Quarantine and Isolation, and Section 5320 - Procedures for Security Segregation of Vessels in their Area Maritime Security Plan.
- Local industry stakeholders, in partnership with their Coast Guard COTP, should review and be familiar with their Marine Transportation System Recovery Plan.
- **Maritime facility operators are reminded that they are not permitted to impede the embarkation/ disembarkation of crew members as permitted under Seafarer's access regulations.** This authority resides with CBP, Coast Guard, or the CDC for medical matters. Facility operators should contact their local CBP, Coast Guard, or CDC/health department offices if they have a specific request to restrict a crew member’s access.
- The Coast Guard recommends that people review the CDC travel guidance (see <https://www.cdc.gov/coronavirus/2019-ncov/travelers/index.html>) and the U.S. Department of State (DoS) Travel Advisories related to COVID-19 at <https://travel.state.gov/content/travel/en/traveladvisories/traveladvisories.html/> .

Richard Timme, RDML, U. S. Coast Guard, Assistant Commandant for Prevention Policy sends

This is the current compilation of all subsurface and surface oceanographic moorings that have been reported to the U.S. Coast Guard District 17 Waterways Branch. The name, type, location, depth, water depth, and a Point of Contact for all data buoys, surface and subsurface, shall be reported as quickly as is practical if they are placed within the navigable waters (within 200 nm) of the United States. Data buoys placed in the Arctic region but outside of 200 nm of the United States may be reported and will be included in this compilation (for informational purposes only). This notification process is for inclusion in the Local Notice to Mariners to provide navigational information to mariners and does not supersede any permission or permitting requirements. Any notifications, corrections, additions, deletions, or comments for the Alaska region (Coast Guard District 17) or the Arctic region should be submitted via e-mail to D17-PF-D17-LNM@uscg.mil or to Todd Buck, USCG D17(dpw), at (907) 463-2269 or by email to todd.r.buck@uscg.mil. This compilation is as current as the Local Notice to Mariners (LNM) included in as an enclosure. The referenced LNM may have additional information and indicates the last time an entry was updated.

ALASKA – ARCTIC OCEAN

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
N/A	72°27.655'N, 157°23.774'W	780 feet	731 feet	39/10	Ethan Roth ehroth@ucsd.edu
N/A	72°47.939'N, 158°23.941'W	1,066 feet	1,017 feet	39/10	Ethan Roth ehroth@ucsd.edu
N/A	72°07.275'N, 160°29.698'W	131 feet	115 feet	35/12	Thomas Weingartner (907) 474-7993
N/A	72°09.747'N, 159°07.349'W	167 feet	85 feet	35/12	Thomas Weingartner (907) 474-7993
N/A	72°10.875'N, 159°33.117'W	184 feet	95 feet	35/12	Thomas Weingartner (907) 474-7993
N/A	72°41.745'N, 164°31.935'W	N/A	151 feet	35/12	N/A
N/A	72°31.517'N, 164°05.944'W	N/A	164 feet	35/12	N/A
N/A	72°16.850'N, 163°32.034'W	N/A	131 feet	35/12	N/A
HARP C2	72°48.154'N, 158°25.384'W	1,062 feet	979 feet	48/15	Josh Jones (858) 822-1836
HARP D	72°36.925'N, 158°42.177'W	323 feet	237 feet	48/15	Josh Jones (858) 822-1836
AIM16-1	75°06.003'N, 168°00.004'W	535 feet	142 feet	44/16	Dr. Humfrey Melling (250) 363-6552
20CKP9A	72°28.210'N, 156°33.510'W	3,199 feet	1,280 feet	38/20	David Strausz (206) 526-4510
NAP-20t	74°31.370'N, 161°55.880'W	5,528 feet	141 feet	42/20	Motoyo ITOH +81-46-867-9488

CANADA – BEAUFORT SEA

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
ACW16-30	68°59.173'N, 105°53.030'W	242 feet	231 feet	44/16	Dr. Humfrey Melling (250) 363-6552
CB12	70°33.770'N, 127°41.710'W	125 feet	116 feet	44/16	Dr. Humfrey Melling (250) 363-6552
IBO16-1a	70°20.031'N, 133°44.369'W	180 feet	171 feet	44/16	Dr. Humfrey Melling (250) 363-6552
IBO16-1b	70°20.035'N, 133°44.452'W	180 feet	171 feet	44/16	Dr. Humfrey Melling (250) 363-6552
IBO16-2	70°59.359'N, 133°44.636'W	365 feet	146 feet	44/16	Dr. Humfrey Melling (250) 363-6552
IBO16-9a	70°03.534'N, 133°42.918'W	116 feet	106 feet	44/16	Dr. Humfrey Melling (250) 363-6552
IBO16-9b	70°03.501'N, 133°42.937'W	116 feet	106 feet	44/16	Dr. Humfrey Melling (250) 363-6552
SIC16-11	69°46.483'N, 137°02.757'W	117 feet	107 feet	44/16	Dr. Humfrey Melling (250) 363-6552
HI16	69°39.284'N, 138°55.279'W	134 feet	125 feet	44/16	Dr. Humfrey Melling (250) 363-6552

ALASKA – BEAUFORT SEA

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
N/A	71°35.980'N, 161°30.3221'W	151 feet	111 feet	48/14	David Leech (907) 224-4319
AON-BS3	71°23.659'N, 152°03.046'W	482 feet	115 feet	49/14	Dr. Robert Pickart (508) 289-2858
UPW80	71°14.670'N, 150°32.750'W	262 feet	236 feet	49/17	Steve Okkonen (907) 283-3234
UPW120	71°16.000'N, 150°41.640'W	354 feet	328 feet	49/17	Steve Okkonen (907) 283-3234
UPE80	71°11.673'N, 148°43.424'W	262 feet	236 feet	49/17	Steve Okkonen (907) 283-3234
UPE120	71°12.338'N, 148°48.018'W	400 feet	374 feet	49/17	Steve Okkonen (907) 283-3234
WAVE SS-1	70°29'16.8864"N, 147°30'00.3528"W	UNK	Surface	29/18	Jeremy Kasper (907) 371-6510
ODAS-1	70°24.889'N, 147°39.206'W	26 feet	24 feet	30/19	Carmen Lawrence (902) 405-3336
ODAS-2	70°16.663'N, 147°35.493'W	19 feet	17 feet	30/19	Carmen Lawrence (902) 405-3336
BCE-19	71°40.368'N, 154°59.923'W	344 feet	131 feet	42/19	Motoyo ITOH +81-46-867-9488
BCC-19	71°44.049'N, 155°09.624'W	951 feet	131 feet	42/19	Motoyo ITOH +81-46-867-9488
BCW-19	71°47.766'N, 155°20.777'W	554 feet	131 feet	42/19	Motoyo ITOH +81-46-867-9488
AL20-AU-BF2	71°45.220'N, 154°28.070'W	335 feet	308 feet	38/20	Catherine Berchok (206) 526-6331

ALASKA – CHUKCHI SEA

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
E. Barrow Canyon	71°22.569'N, 156°53.710'W	236 feet	226 feet	49/14	Steve Okkonen (907) 283-3234
Unnamed	71°14.459'N, 164°18.067'W	138 feet	Surface	28/15	Noah Lawrence (206) 526-6209
2015MARU_2	71°29.792'N, 163°11.449'W	144 feet	140 feet	40/15	Catherine Berchok (206) 526-6331
CEM1-19	71°35.971'N, 161°30.419'W	154 feet	108 feet	35/19	Peter Shipton (907) 224-4319
CEM2-19	71°35.979'N, 161°31.648'W	154 feet	108 feet	35/19	Peter Shipton (907) 224-4319
19CKP-5A	71°12.212'N, 158°00.722'W	157 feet	131 feet	35/19	David Strausz (206) 525-4510
19CKP-4A	71°02.591'N, 160°29.706'W	171 feet	138 feet	35/19	David Strausz (206) 525-4510
19CKP-3A	71°49.486'N, 166°03.560'W	151 feet	125 feet	35/19	David Strausz (206) 525-4510
AL19-AU-PB1	71°12.346'N, 158°00.660'W	161 feet	131 feet	35/19	Catherine Berchok (206) 526-6331
AL19-AU-WT1	71°02.623'N, 160°30.201'W	171 feet	141 feet	35/19	Catherine Berchok (206) 526-6331
AL19-AU-IC2	71°13.005'N, 164°15.110'W	148 feet	118 feet	35/19	Catherine Berchok (206) 526-6331
AL19-AU-IC3	71°49.728'N, 166°03.993'W	151 feet	121 feet	35/19	Catherine Berchok (206) 526-6331

ALASKA – CHUKCHI SEA (Continued)

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
20CKP-12A	67°54.820'N, 168°11.830'W	195 feet	161 feet	38/20	David Strausz (206) 526-4510
20CKITAER-12A	67°54.290'N, 168°11.510'W	196 feet	115 feet	38/20	David Strausz (206) 526-4510
20CK-1A	70°00.000'N, 163°00.000'W	125 feet	112 feet	38/20	David Strausz (206) 526-4510
20CKP-2A	71°13.180'N, 164.14.830'W	146 feet	128 feet	38/20	David Strausz (206) 526-4510
AL20-AU-CL1	69°18.880'N, 167°36.650'W	167 feet	141 feet	38/20	Catherine Berchok (206) 526-6331
AL20-AU-IC1	70°50.160'N, 163°07.100'W	148 feet	121 feet	38/20	Catherine Berchok (206) 526-6331

ALASKA – KOTZEBUE SOUND

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
OTZ-N	67°6.791'N, 163°46.328'W	37 feet	27 feet	48/14	Dr. Manuel Castellote (206) 526-6866
OTZ-M	67°5.148'N, 163°48.282'W	58 feet	48 feet	48/14	Dr. Manuel Castellote (206) 526-6866
OTZ-S	67°3.365'N, 163°48.699'W	60 feet	50 feet	48/14	Dr. Manuel Castellote (206) 526-6866
OTZ-Ch	66°14.346'N, 166°51.926'W	51 feet	41 feet	48/14	Dr. Manuel Castellote (206) 526-6866

ALASKA – BERING STRAIT

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
AOOS-AXYS	65°00.700'N, 169°27.23'W	-----	Surface	30/15	Darcy Dugan (907) 644-6718
NB-17t	65°03.884'N, 169°38.045'W	171 feet	89 feet	29/17	Makoto Sampei +81-138-40-8844
BS-17t	66°16.075'N, 168°54.098'W	187 feet	105 feet	29/17	Makoto Sampei +81-138-40-8844
A2-19	65°46.860'N, 168°34.070'W	184 feet	26 feet	37/18	Rebecca Woodgate (206) 221-3268
A3-19	66°19.600'N, 168°57.050'W	184 feet	49 feet	37/18	Rebecca Woodgate (206) 221-3268
A4-19	65°44.750'N, 168°15.770'W	157 feet	49 feet	37/18	Rebecca Woodgate (206) 221-3268
A2-20	65°46.860'N, 168°34.600'W	184 feet	148 feet	37/20	Rebecca Woodgate (206) 221-3268
A3-20	66°19.600'N, 168°57.600'W	194 feet	138 feet	37/20	Rebecca Woodgate (206) 221-3268
A4-20	65°44.750'N, 168°16.310'W	161 feet	118 feet	37/20	Rebecca Woodgate (206) 221-3268

ALASKA – NORTON SOUND

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
Station-241	64°28.365'N, 165°28.525'W	66 feet	Surface	36/20	James Behrens (858) 534-3032

ALASKA – BERING SEA

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
GPS Tide Buoy	58°28.015'N, 162°04.779'W	126 feet	Surface	25/19	NOAAS FAIRWEATHER (401) 378-4022
AL19-AU-BS6	53°37.775'N, 167°23.945'W	312 feet	282 feet	28/19	Catherine Berchok (206) 526-6331
19BS-5A	59°54.220'N, 171°41.890'W	233 feet	30 feet	40/19	Geoff Lebon (206) 526-6884
19BSP-5A	59°54.220'N, 171°41.890'W	233 feet	30 feet	40/19	Geoff Lebon (206) 526-6884
19BS-8A	62°12.000'N, 174°40.770'W	243 feet	177 feet	40/19	Geoff Lebon (206) 526-6884
19BS-2C	56°51.884'N, 164°02.601'W	236 feet	203 feet	40/19	Geoff Lebon (206) 526-6884
19BSP-2B	56°51.494'N, 164°02.724'W	236 feet	33 feet	40/19	Geoff Lebon (206) 526-6884
19BSP-8A	61°11.760'N, 174°40.470'W	243 feet	30 feet	40/19	Geoff Lebon (206) 526-6884
19SHP-1A	54°50.970'N, 158°59.890'W	243 feet	207 feet	40/19	Geoff Lebon (206) 526-6884
AL19-AU-BS10	56°09.603'N, 166°34.646'W	390 feet	361 feet	40/19	Catherine Berchok (206) 526-6331
20BSP-4A	57°51.894'N, 168°52.759'W	233 feet	203 feet	38/20	David Strausz (206) 526-4510
20BSP-8A	62°11.540'N, 174°40.310'W	241 feet	210 feet	38/20	David Strausz (206) 526-4510
20BSP-14A	64°00.156'N, 167°56.043'W	125 feet	102 feet	38/20	David Strausz (206) 526-4510
20BSIP-14A	63°59.950'N, 167°55.690'W	125 feet	102 feet	38/20	David Strausz (206) 526-4510
AL20-AU-BS11	61°04.714'N, 170°16.565'W	164 feet	138 feet	38/20	Catherine Berchok (206) 526-6331

ALASKA – GULF OF ALASKA – SANAK TROUGH (NORTH OF SANAK ISLAND)

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
TRBM-1	54°42.606'N, 162°37.872'W	407 feet	405 feet	48/16	Chris Wilson (206) 526-6435
TRBM-2	54°37.151'N, 162°35.695'W	489 feet	487 feet	48/16	Chris Wilson (206) 526-6435

ALASKA – COOK INLET – KAMISHAK BAY

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
ADCP-A	59°16'34.5168"N, 154°07'03.6837"W	16 feet	13 feet	03/18	Jason Crockett (907) 315-6513
ADCP-B	59°15'24.7255"N, 154°02'45.7066"W	43 feet	39 feet	03/18	Jason Crockett (907) 315-6513

ALASKA – GULF OF ALASKA – KODIAK ISLAND – CHINIAK BAY

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
19CB-1A	57°43.223'N, 152°17.531'W	640 feet	587 feet	28/19	David Strausz (206) 526-4510

ALASKA – GULF OF ALASKA

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
UAF GAK4M	59°24.231'N, 149°00.731'W	656 feet	328 feet	45/16	Dr. Andrew McDonnell (907) 474-7529
WAVE YB-1	59°27'22.248"N, 139°45'02.088"W	UNK	Surface	29/17	Jeremy Kasper (907) 371-6510

ALASKA – GULF OF ALASKA (Continued)

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
WAVE YB-2	59°26'58.7349"N, 139°47'46.3194"W	UNK	Surface	29/17	Jeremy Kasper (907) 371-6510
GEO1-2019	59°00.850'N, 148°41.410'W	722 feet	Surface	29/19	Seth Danielson (907) 474-7834
GEO2-2019	59°00.917'N, 148°41.604'W	722 feet	72 feet	29/19	Seth Danielson (907) 474-7834
GEO3-2019	59°00.988'N, 148°41.797'W	722 feet	Surface	29/19	Seth Danielson (907) 474-7834
GA20-AU-BT01	57°01.790'N, 152°59.620'W	269 feet	243 feet	40/20	Catherine Berchok (206) 526-6331

ALASKA – GULF OF ALASKA – RESURRECTION BAY

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
GAKOA	59°54'39.55"N, 149°20'57.47"W	171 feet	Surface	13/19	Natalie Monacci (907) 474-7956
GAKI	59°51'11.952"N, 149°30'03.96"W	869 feet	66 feet	13/19	Peter Shipton (907) 224-4319

ALASKA – PRINCE WILLIAM SOUND

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
PST1	60°39.100'N, 146°16.682'W	154 feet	138 feet	18/09	Mary Anne Bishop (907) 424-5800 x228
PST2	60°39.338'N, 146°17.353'W	226 feet	210 feet	18/09	Mary Anne Bishop (907) 424-5800 x228
PST3	60°39.568'N, 146°18.040'W	390 feet	374 feet	18/09	Mary Anne Bishop (907) 424-5800 x228
PST4	60°39.798'N, 146°18.726'W	427 feet	410 feet	18/09	Mary Anne Bishop (907) 424-5800 x228
PST5	60°40.028'N, 146°19.413'W	420 feet	404 feet	18/09	Mary Anne Bishop (907) 424-5800 x228
PST6	60°40.257'N, 146°20.100'W	410 feet	394 feet	18/09	Mary Anne Bishop (907) 424-5800 x228
PST7	60°40.487'N, 146°20.786'W	295 feet	279 feet	18/09	Mary Anne Bishop (907) 424-5800 x228
PST8	60°40.717'N, 146°21.473'W	233 feet	217 feet	18/09	Mary Anne Bishop (907) 424-5800 x228
PST9	60°40.947'N, 146°22.160'W	194 feet	177 feet	18/09	Mary Anne Bishop (907) 424-5800 x228
PST10	60°41.176'N, 146°22.846'W	141 feet	125 feet	18/09	Mary Anne Bishop (907) 424-5800 x228
LHRT1	60°22.6596'N, 147°51.147'W	225 feet	209 feet	11/14	Mary Anne Bishop (907) 424-5800 x228
LHRT2	60°22.6482'N, 147°50.7522'W	364 feet	348 feet	11/14	Mary Anne Bishop (907) 424-5800 x228
LHRT3	60°22.668'N, 147°50.5116'W	382 feet	366 feet	11/14	Mary Anne Bishop (907) 424-5800 x228
WTRT1	60°44.253'N, 147°59.5596'W	504 feet	488 feet	11/14	Mary Anne Bishop (907) 424-5800 x228
WTRT2	60°44.0994'N, 147°59.086'W	504 feet	488 feet	11/14	Mary Anne Bishop (907) 424-5800 x228
WTRT3	60°43.938'N, 147°59.448'W	316 feet	300 feet	11/14	Mary Anne Bishop (907) 424-5800 x228
PWSSC-15	60°36.791'N, 147°11.996'W	722 feet	197 feet (Surfacing 2X per day)	15/16	R. W. Campbell (907) 424-5800 x241
H01	60°20.550'N, 146°43.824'W	98 feet	66 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
HA	60°20.274'N, 146°43.248'W	591 feet	532 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H02	60°20.400'N, 146°44.520'W	879 feet	791 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
HB	60°20.094'N, 146°43.974'W	830 feet	747 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H03	60°20.250'N, 146°45.246'W	886 feet	797 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H04	60°20.112'N, 146°45.966'W	886 feet	797 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H05	60°19.968'N, 146°46.710'W	886 feet	797 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H06	60°19.812'N, 146°47.418'W	896 feet	806 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H07	60°19.668'N, 146°48.138'W	909 feet	818 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H08	60°19.470'N, 146°48.954'W	935 feet	842 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H09	60°19.320'N, 146°49.782'W	1007 feet	906 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H10	60°19.188'N, 146°50.508'W	1060 feet	954 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H11	60°19.008'N, 146°51.228'W	1135 feet	1022 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H12	60°18.888'N, 146°51.930'W	1194 feet	1075 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H13	60°18.738'N, 146°52.656'W	909 feet	818 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H14	60°18.588'N, 146°53.340'W	522 feet	470 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H15	60°18.468'N, 146°53.994'W	276 feet	244 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
HC	60°18.120'N, 146°53.568'W	449 feet	404 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
H16	60°18.540'N, 146°54.552'W	85 feet	53 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
HD	60°17.982'N, 146°54.336'W	151 feet	119 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
M01	59°55.482'N, 147°48.630'W	295 feet	263 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
MA	59°55.146'N, 147°49.092'W	220 feet	188 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
M02	59°55.848'N, 147°49.074'W	446 feet	401 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
MB	59°55.512'N, 147°49.512'W	420 feet	378 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
M03	59°56.178'N, 147°49.518'W	509 feet	458 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
M04	59°56.556'N, 147°49.956'W	577 feet	519 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
M05	59°56.886'N, 147°50.382'W	640 feet	576 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
M06	59°57.222'N, 147°50.826'W	705 feet	635 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
M07	59°57.546'N, 147°51.234'W	741 feet	667 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
M08	59°57.864'N, 147°51.636'W	768 feet	691 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
M09	59°58.152'N, 147°52.008'W	784 feet	706 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
M10	59°58.536'N, 147°52.458'W	778 feet	700 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
MC	59°58.182'N, 147°52.872'W	745 feet	671 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
M11	59°58.842'N, 147°52.866'W	472 feet	425 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
MD	59°58.518'N, 147°53.352'W	614 feet	553 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
LP01	59°58.854'N, 148°01.920'W	112 feet	80 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
LPA	59°58.488'N, 148°02.286'W	98 feet	66 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
EP04	59°59.700'N, 148°06.072'W	276 feet	244 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
EPB	59°59.364'N, 148°06.492'W	246 feet	214 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
POWP05	60°02.778'N, 148°07.470'W	312 feet	280 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
LPB	59°58.758'N, 148°02.676'W	289 feet	257 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
EP03	59°59.472'N, 148°05.802'W	240 feet	208 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
EPA	59°59.064'N, 148°05.952'W	331 feet	299 feet	09/17	Mary Anne Bishop (907) 424-5800 x228

ALASKA – PRINCE WILLIAM SOUND (Continued)

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
PWA	60°02.394'N, 148°07.698'W	289 feet	257 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
LP02	59°59.082'N, 148°02.208'W	148 feet	116 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
POWP06	60°02.796'N, 148°07.902'W	177 feet	145 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
PWB	60°02.418'N, 148°08.208'W	266 feet	234 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
BP07	60°06.906'N, 148°14.118'W	174 feet	142 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
BPA	60°07.128'N, 148°13.458'W	167 feet	135 feet	09/17	Mary Anne Bishop (907) 424-5800 x228
Grav-1	60°41.370'N, 146°23.956'W	16 feet	Surface	16/17	Mary Anne Bishop (907) 424-5800 x228
Grav-2	60°41.454'N, 146°23.496'W	75 feet	55 feet	16/17	Mary Anne Bishop (907) 424-5800 x228
Grav-3	60°40.925'N, 146°23.018'W	146 feet	126 feet	16/17	Mary Anne Bishop (907) 424-5800 x228
Grav-4	60°40.696'N, 146°22.561'W	195 feet	176 feet	16/17	Mary Anne Bishop (907) 424-5800 x228
Grav-5	60°41.257'N, 146°24.580'W	7 feet	Surface	16/17	Mary Anne Bishop (907) 424-5800 x228
Grav-6	60°41.033'N, 146°24.109'W	53 feet	34 feet	16/17	Mary Anne Bishop (907) 424-5800 x228
Grav-7	60°40.811'N, 146°23.633'W	128 feet	108 feet	16/17	Mary Anne Bishop (907) 424-5800 x228
Grav-8	60°40.580'N, 146°23.148'W	158 feet	138 feet	16/17	Mary Anne Bishop (907) 424-5800 x228
Grav-9	60°40.362'N, 146°22.692'W	212 feet	192 feet	16/17	Mary Anne Bishop (907) 424-5800 x228
Grav-10	60°40.970'N, 146°23.557'W	106 feet	86 feet	16/17	Mary Anne Bishop (907) 424-5800 x228
Grav-RT1	60°41.053'N, 146°24.004'W	59 feet	40 feet	16/17	Mary Anne Bishop (907) 424-5800 x228
Grav-RT2	60°41.071'N, 146°23.896'W	72 feet	53 feet	16/17	Mary Anne Bishop (907) 424-5800 x228
Grav-RT3	60°41.090'N, 146°23.765'W	74 feet	55 feet	16/17	Mary Anne Bishop (907) 424-5800 x228
RH1	60°36.987'N, 146°37.412'W	213 feet	203 feet	28/18	Mary Anne Bishop (907) 424-5800 x228
RH2	60°38.175'N, 146°29.837'W	223 feet	223 feet	28/18	Mary Anne Bishop (907) 424-5800 x228
NMS1	60°18.476'N, 147°40.044'W	131 feet	131 feet	28/18	Mary Anne Bishop (907) 424-5800 x228
NMS2	60°18.280'N, 147°25.330'W	154 feet	154 feet	28/18	Mary Anne Bishop (907) 424-5800 x228
NMS3	60°22.657'N, 147°08.341'W	118 feet	118 feet	28/18	Mary Anne Bishop (907) 424-5800 x228
GISL1	60°51.782'N, 147°13.369'W	164 feet	154 feet	28/18	Mary Anne Bishop (907) 424-5800 x228
MR1	59°58.586'N, 147°53.254'W	607 feet	597 feet	28/18	Mary Anne Bishop (907) 424-5800 x228
MR2	59°58.655'N, 147°53.160'W	581 feet	571 feet	28/18	Mary Anne Bishop (907) 424-5800 x228
MR3	59°58.738'N, 147°53.030'W	564 feet	554 feet	28/18	Mary Anne Bishop (907) 424-5800 x228
HRT1	60°18.058'N, 146°54.282'W	112 feet	102 feet	28/18	Mary Anne Bishop (907) 424-5800 x228
HRT2	60°18.135'N, 146°54.227'W	121 feet	111 feet	28/18	Mary Anne Bishop (907) 424-5800 x228
HRT3	60°18.226'N, 146°54.145'W	151 feet	141 feet	28/18	Mary Anne Bishop (907) 424-5800 x228
KIP1	60°18.121'N, 148°00.944'W	344 feet	324 feet	39/18	Mary Anne Bishop (907) 424-5800 x228
KIP2	60°18.050'N, 147°55.640'W	344 feet	324 feet	39/18	Mary Anne Bishop (907) 424-5800 x228
CP1	60°32.465'N, 146°08.652'W	106 feet	81 feet	39/18	Mary Anne Bishop (907) 424-5800 x228
CP2	60°32.733'N, 146°06.749'W	151 feet	126 feet	39/18	Mary Anne Bishop (907) 424-5800 x228
CEDAR1	60°33.568'N, 146°01.978'W	110 feet	85 feet	39/18	Mary Anne Bishop (907) 424-5800 x228
JP1	60°29.366'N, 146°35.524'W	74 feet	71 feet	10/20	Mary Anne Bishop (907) 424-5800 x228
PF1	60°48.720'N, 146°34.464'W	131 feet	128 feet	10/20	Mary Anne Bishop (907) 424-5800 x228

ALASKA – GULF OF ALASKA – YAKUTAT

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
Wave Buoy-1	59°270402'N, 139°44.982'W	Unknown	Surface	41/19	Jeremy Kasper (907) 371-6510
Wave Buoy-2	59°25.998'N, 139°48.366'W	Unknown	Surface	41/19	Jeremy Kasper (907) 371-6510

ALASKA – SOUTHEAST

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
Icy Strait	58° 14.6112'N, 136° 7.28972'W	614 feet	594 feet	35/09	Dave Carlile (907) 465-4216
Icy Strait	58° 14.5037'N, 136° 7.27185'W	541 feet	521 feet	35/09	Dave Carlile (907) 465-4216
Icy Strait	58° 14.3962'N, 136° 7.25398'W	522 feet	502 feet	35/09	Dave Carlile (907) 465-4216
Icy Strait	58° 14.2887'N, 136° 7.23611'W	358 feet	338 feet	35/09	Dave Carlile (907) 465-4216
Icy Strait	58° 14.1812'N, 136° 7.21824'W	266 feet	246 feet	35/09	Dave Carlile (907) 465-4216
Chatham Strait	56° 9.6115'N, 134° 33.78278'W	1814 feet	1795 feet	35/09	Dave Carlile (907) 465-4216
Chatham Strait	56° 9.6209'N, 134° 33.97584'W	1820 feet	1800 feet	35/09	Dave Carlile (907) 465-4216
Chatham Strait	56° 9.6303'N, 134° 34.1689'W	1811 feet	1791 feet	35/09	Dave Carlile (907) 465-4216
Chatham Strait	56° 9.6397'N, 134° 34.36195'W	1811 feet	1791 feet	35/09	Dave Carlile (907) 465-4216
Chatham Strait	56° 9.6491'N, 134° 34.55501'W	1798 feet	1778 feet	35/09	Dave Carlile (907) 465-4216
Chatham Strait	56° 8.6362'N, 134° 25.56783'W	1916 feet	417 feet	35/09	Dave Carlile (907) 465-4216
Chatham Strait	56° 8.655'N, 134° 25.95379'W	1930 feet	1910 feet	35/09	Dave Carlile (907) 465-4216
Chatham Strait	56° 8.6644'N, 134° 26.14676'W	1932 feet	1912 feet	35/09	Dave Carlile (907) 465-4216
Chatham Strait	56° 8.6738'N, 134° 26.3397'W	1936 feet	1916 feet	35/09	Dave Carlile (907) 465-4216
Chatham Strait	56° 8.6832'N, 134° 26.53272'W	1932 feet	1912 feet	35/09	Dave Carlile (907) 465-4216
Chatham Strait	56° 8.6926'N, 134° 26.7257'W	1932 feet	1912 feet	35/09	Dave Carlile (907) 465-4216
Frederick Sound	57° 3.34'N, 134° 15.64'W	1180 feet	928 feet	35/09	Dave Carlile (907) 465-4216
Frederick Sound	57° 3.1874'N, 134° 15.35938'W	1155 feet	1135 feet	35/09	Dave Carlile (907) 465-4216
Frederick Sound	57° 3.1111'N, 134° 15.21907'W	1155 feet	1135 feet	35/09	Dave Carlile (907) 465-4216
Frederick Sound	57° 3.0348'N, 134° 15.07877'W	1155 feet	1135 feet	35/09	Dave Carlile (907) 465-4216
Frederick Sound	57° 2.9584'N, 134° 14.93847'W	1158 feet	1138 feet	35/09	Dave Carlile (907) 465-4216
Ommaney	56° 5.1769'N, 134° 46.8910'W	1191 feet	1171 feet	33/10	Dave Carlile (907) 465-4216
Ommaney	56° 5.0755'N, 134° 46.8249'W	1200 feet	1180 feet	33/10	Dave Carlile (907) 465-4216
Ommaney	56° 4.9741'N, 134° 46.7587'W	1200 feet	1180 feet	33/10	Dave Carlile (907) 465-4216
Ommaney	55° 59.6327'N, 134° 57.3717'W	1214 feet	1194 feet	33/10	Dave Carlile (907) 465-4216
Ommaney	55° 59.5313'N, 134° 57.3057'W	1191 feet	1171 feet	33/10	Dave Carlile (907) 465-4216
Ommaney	55° 59.4298'N, 134° 57.2397'W	1191 feet	1171 feet	33/10	Dave Carlile (907) 465-4216

ALASKA – SOUTHEAST (Continued)

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
Ommaney	55° 59.3284'N, 134° 57.1737'W	1220 feet	1200 feet	33/10	Dave Carlile (907) 465-4216
Frederick Sound	57° 2.8821'N, 134° 14.79818'W	1158 feet	1138 feet	35/09	Dave Carlile (907) 465-4216
Ommaney	56° 5.4812' N, 134° 47.0895' W	1181 feet	912 feet	33/10	Dave Carlile (907) 465-4216
Ommaney	56° 5.3798'N, 134° 47.0233'W	1191 feet	1171 feet	33/10	Dave Carlile (907) 465-4216
Ommaney	56° 5.2783'N, 134° 46.9572'W	1191 feet	1171 feet	33/10	Dave Carlile (907) 465-4216
Ommaney	55° 59.2270'N, 134° 57.1077'W	1220 feet	1200 feet	33/10	Dave Carlile (907) 465-4216
Ommaney	55° 59.1256'N, 134° 57.0417' W	1220 feet	1200 feet	33/10	Dave Carlile (907) 465-4216
20CSP-4A	58°07.363'N, 136°35.604'W	1,099 feet	1,060 feet	06/20	David Strausz (206) 526-4510

ALASKA – NORTH PACIFIC OCEAN

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
HARP-CB	58°40.409'N, 148°00.546'W	2,877 feet	2,779 feet	49/14	Josh Jones (858) 822-1836
HARP-PT	56°14.635'N, 142°45.431'W	3,238 feet	3,140 feet	49/14	Josh Jones (858) 822-1836
MFM-A	49°58.60'N, 144°14.77'W	13,540 feet	49 feet	24/15	Gabriella Chavez (858) 822-4938
MFM-B	50°19.82'N, 144°23.90'W	13,599 feet	49 feet	24/15	Gabriella Chavez (858) 822-4938
GHPM-1	50°04.79'N, 144°48.18'W	13, 842 feet	483 feet	24/15	Gabriella Chavez (858) 822-4938



Marine Safety Information Bulletin

Commandant
U.S. Coast Guard
Waterways Policies and Activities Division (WWM-1)
2703 Martin Luther King Jr Ave SE, STOP 7501
Washington, DC 20593-7501

MSIB Number: 17-20
Date: 06/03/2020
Contact: LCDR John Downing
Phone: (202) 372-1568
E-Mail: cgwwm@uscg.mil

On-Water Mass Gatherings – Recreational, Sporting, or Cause-Related Events

On-water mass gatherings pose concerns due to the safety issues they create for the boating public and the Maritime Transportation System (MTS). Regardless of the nature of these gatherings, whether recreational, sporting or cause-related, they are primarily a boating safety issue. As these types of marine events continue to grow in popularity throughout the country, the Coast Guard will work together with its port partners to ensure the safety on the marine transportation system. These actions will take into account health and safety factors including but not limited to local COVID-19 and social distance guidelines as well as current unrest.

The Coast Guard issues permits for, and monitors marine events, to ensure safety of life at sea and on our waterways. Permits are required for powerboat races, sailing regattas, and other marine events that have the potential to draw an accumulation of spectator craft, may obstruct a waterway, or introduce extra or unusual hazards to the safety of human life on the navigable waters of the United States. A large gathering of recreational boaters would not necessarily meet the requirement for an event permit. It is recommended you contact your local Captain of the Port to determine if your event will require a permit.

The Coast Guard and our port partners are committed to ensuring the safety and security of the waterway. The Coast Guard and other local agencies will provide on-water safety and law enforcement assets. The goal of these patrols is to ensure mariners using the waterway are not negatively impacted due to the anticipated increase in vessel traffic and to ensure that commercial traffic can safely continue operations.

Regardless of the nature of the event, the Coast Guard's role is to ensure the safety and security of the maritime transportation system. The presence of the Coast Guard and its partners on the waterway is not to support the event itself, but to ensure the waterway is safe for all mariners due to the anticipated increase in traffic.

Boating accidents can occur quickly and without warning. To ensure a safe and enjoyable time on the water, the Coast Guard is asking boaters to ensure they have the necessary knowledge and safety equipment before getting underway. This includes a properly fitting life jacket for each passenger, a VHF radio, and flares. The Coast Guard regularly conducts recreational boating safety checks. Failure to have the necessary safety equipment may result in the termination of a voyage. Having the basic equipment can ensure a safe and enjoyable day on the water.

It is recommended participants in the event, and mariners in general, follow guidance from the CDC and local government health authorities to prevent the spread of coronavirus, including social distancing and the use of face coverings when social distance cannot be maintained.

Questions concerning this notice may be forwarded to Coast Guard Office of Waterways Policies and Activities Division (CG-WWM-1) by email to cgwwm@uscg.mil.

-uscg-

U.S. Department of
Homeland Security

United States
Coast Guard



Commander
United States Coast Guard
Sector Anchorage

PO Box 5800
JBER, AK 99505
Staff Symbol: s
Phone: 907-428-4200
FAX: 907-428-4218

16710
November 20, 2020

**CAPTAIN OF THE PORT, WESTERN ALASKA
NAVIGATION SAFETY ADVISORY**

Dear Mariner:

Cold temperatures are causing a significant buildup of ice in the upper Cook Inlet that poses extreme danger to vessels. To assist mariners, we are implementing the **Operating Guidelines for Ice Conditions for Upper Cook Inlet, effective November 20, 2020**. These guidelines were updated and signed on November 5, 2020.

All vessels scheduled to arrive in areas north of Homer, AK in Cook Inlet must submit a voyage plan no less than 24 hours prior to arrival at the Kachemak Bay Pilot Station. We have posted a voyage plan template and the Guidelines referenced above to the Sector Anchorage Homeport webpage.

Sector Anchorage Homeport webpage:

[https://homeport.uscg.mil/port-directory/western-alaska-\(anchorage\)](https://homeport.uscg.mil/port-directory/western-alaska-(anchorage))

While use of the voyage plan template is not mandatory, your voyage plan must include all information listed in the template. Voyage plans must be e-mailed to Sector.Anchorage@uscg.mil. Based on information in your voyage plan, we will determine if the vessel needs an exam prior to entry into Cook Inlet and will notify the submitter if an exam is required. Vessel agents can coordinate with Marine Safety Detachment Homer at (907) 235-3292 to schedule an exam.

The National Weather Service's Cook Inlet Sea Ice analysis:

<https://www.weather.gov/afc/ice>

Please direct questions regarding this advisory, or the Guidelines referenced above, to the Sector Anchorage Waterways Management Division at (907) 428-4189 or after hours (907) 428-4100.

Sincerely,

A handwritten signature in blue ink that reads "L. M. Lusk".

L. M. LUSK
Captain, U. S. Coast Guard
Captain of the Port, Western Alaska

Copy: Commander, Seventeenth Coast Guard District (dp)



Trial 2020/21

VOLUNTARY PROTECTION ZONE FOR SHIPPING

West Coast of Haida Gwaii

Haida Gwaii is a remote archipelago located on Canada's north Pacific Coast that is home to a rich abundance and diversity of marine life, lush rainforests, and the Haida people who have lived there for thousands of years. The lands and waters of the southern portion of the archipelago are protected as the Gwaii Haanas National Park Reserve, National Marine Conservation Area Reserve, and Haida Heritage Site, which includes the ancient Haida village site of SGang Gwaay, a UNESCO World Heritage Site.

Its remote location, rugged coastline, variable sea and weather conditions, and rich ecological and cultural heritage make Haida Gwaii vulnerable to the potential for pollution from shipping breakdowns and accidents. Increasing the distance vessels travel offshore can increase the amount of time available to address propulsion, steering or other issues, and the likelihood of a towing vessel being able to respond to a vessel that is disabled or drifting. This in turn reduces the risk of grounding and oil spills. To assess the effectiveness of such a measure, a 14-month trial of a Voluntary Protection Zone (VPZ) for Shipping is being implemented that asks vessels to observe greater distances when transiting on the west coast of Haida Gwaii.

The VPZ is based on the analysis of multi-year, large vessel traffic patterns and potential impacts to industry operations. The

project represents significant and unprecedented collaboration between the Council of the Haida Nation, the Government of Canada, and the maritime shipping industry, along with many other advisors and partners, and supports commitments made by the Government of Canada and the Council of the Haida Nation to advance collaboration in the spirit of reconciliation.


WHERE: West Coast of Haida Gwaii

A minimum 50 nautical mile (nm) VPZ applies to commercial vessels 500 tons gross tonnage or more transiting along the west coast of Haida Gwaii, with the following exceptions:

- Cruise vessels, who are asked to observe a minimum 12 nm distance from shore;
- Vessels transiting between Pacific Northwest ports (Washington, BC and Alaska), who are asked to observe a minimum 25 nm distance from shore;
- Tugs and barges (including pushing and towing alongside); and
- Fishing vessels.

Adherence to the VPZ will be undertaken on voluntary basis and only when it does not jeopardize the safety of navigation, the vessel, the persons aboard, and the cargo.

(Continued over)



For more information on the Voluntary Protection Zone project, visit haidagwaii-vpz.ca.

For questions, please contact us at info@haidagwaii-vpz.ca.

WHEN: September 1, 2020 – October 31, 2021

The trial will take place for a period of 14-months beginning on September 1, 2020.

The start and end date of the **VPZ** and measures will be communicated to vessel operators and mariners through industry associations' channels including, ships' agents, BC Coast Pilots, Puget Sound Pilots, Alaska Maritime Prevention & Response Network, and Canadian Coast Guard's Marine Communications and Traffic Services (MCTS).

MONITORING and EVALUATION

Traffic patterns will be monitored before, during and after the trial period using Automatic Identification System (AIS) data obtained from Transport Canada's Enhanced Maritime Situational Awareness (EMSA) system¹ and the Pacific Safety Initiative. Participation rates will be reviewed on a monthly basis to monitor the effectiveness of the trial measures and communications, and reasons for voluntary participation (or lack of participation) in the trial will be identified through a short questionnaire. We recognize that the pressures being faced by the marine industry due to COVID-19 may make it challenging to maintain high participation at all times and that the data collected during the trial period may reflect impacts to shipping and traffic patterns.


¹ <https://rb.gy/qzknk7>

**INFORMATION
and QUESTIONS**

For more information on the **VOLUNTARY PROTECTION ZONE**, visit haidagwaii-vpz.ca and download the booklet.

...

QUESTIONS?
Please contact us at info@haidagwaii-vpz.ca



WORKING TOGETHER TO IMPROVE SAFETY ON THE WEST COAST.



HAIDA NATION

Canada

U.S. Department of
Homeland Security

United States
Coast Guard



Commander
United States Coast Guard
Sector Anchorage

PO Box 5800
JBER, AK 99505
Staff Symbol: s
Phone: 907-428-4200
FAX: 907-428-4218

16710
February 1, 2021

CAPTAIN OF THE PORT, WESTERN ALASKA NAVIGATION SAFETY ADVISORY

Cold temperatures are causing a buildup of ice in lower Cook Inlet. To assist mariners with the dangers posed by ice and winter weather conditions, we are implementing Condition A of the Operating Guidelines for Ice Conditions in Lower Cook Inlet, **effective February 1, 2021**, of the Operating *Guidelines* for Ice Conditions in Cook Inlet signed November 5, 2020. Condition A specifies that there is ice present with no immediate impact to mooring and represents the lowest severity of ice present in lower Cook Inlet.

The National Weather Service (NWS) Cook Inlet Sea Ice analysis:

<https://www.weather.gov/afc/ice>

All vessels scheduled to arrive in Cook Inlet north of Homer, Alaska must submit a voyage plan no less than 24 hours prior to arrival at the Kachemak Bay Pilot Station. We have posted the *Guidelines* referenced above to the Sector Anchorage Homeport webpage. The Voyage Plan template is Enclosure (3) of the *Guidelines*.

Sector Anchorage Homeport webpage:

[https://homeport.uscg.mil/port-directory/western-alaska-\(anchorage\)](https://homeport.uscg.mil/port-directory/western-alaska-(anchorage))

While use of the voyage plan template is not mandatory, your voyage plan must include all information listed in the template. Voyage plans must be e-mailed to Sector.Anchorage@uscg.mil. Based on information in your voyage plan, we will determine if the vessel needs an exam prior to entry into Cook Inlet and will notify the submitter if an exam is required. Vessel agents can coordinate with Marine Safety Detachment Homer at (907) 235-3292 to schedule an exam.

Please direct questions regarding this advisory or the *Guidelines* referenced above to the Sector Anchorage Waterways Management Division at (907) 428-4189 or after hours at (907) 428-4100.

Sincerely,

A handwritten signature in blue ink that reads "L. M. Lusk".

L. M. LUSK
Captain, U.S. Coast Guard
Captain of the Port, Western Alaska

Copy: Commander, Seventeenth Coast Guard District (dp)

Seafast Cable Replacement

March 7th to 13th, 2021


Stikine Strait/Chichigof Pass

M/V CABLE INNOVATOR will be conducting a cable recovery and re-lay operation on the Seafast cable near Wrangell, Alaska from March 7th to 13th, 2021. Operations will be conducted 24 hours per day for the duration of the project. The M/V CABLE INNOVATOR is a cable laying ship, 477 feet long, with a dark hull and white superstructure and the bridge amidships. The M/V CABLE INNOVATOR will be transmitting on AIS and monitoring VHF/FM channels 13 and 16 and will be restricted in ability to manoeuvre while recovering/laying cable. CABLE INNOVATOR will recover the existing cable in Stikine Strait (highlighted in red on the chartlet). Following the recovery operation, CABLE INNOVATOR will re-route the cable to Shoemaker Bay Harbor via Chichigof Pass (highlighted in blue on the chartlet). Questions/concerns should be directed to Alex Riddell at Alex.Riddell@oceaniq.co.uk or Steve Bennet at Steven.Bennett@globalmarine.co.uk.

M/V CABLE INNOVATOR



SEAFAST seg 1 repair 3





Alaska Marine Safety Education Association

2924 Halibut Point Road, Sitka, Alaska 99835-9668
phone 907-747-3287 / fax 907-747-3259 / www.amsea.org

For Immediate Release

Date Issued: March 8, 2021

Kill Date: March 19, 2021

AMSEA Workshops of Interest to Mariners in District 17

The Alaska Marine Safety Education Association is offering a number of classes in U.S. Coast Guard District 17 that may be of interest to mariners. Many of these workshops are offered at reduced cost to commercial fishermen, thanks to support from the U.S. Coast Guard, the National Institute for Occupational Safety and Health, the Alaska Department of Commerce, Community and Economic Development, and AMSEA members.

Register online at www.amsea.org or call (907) 747-3287. All class participants must wear a cloth face mask, maintain six feet of physical distance from other participants, and follow any other required COVID-19 safety procedures.

Fishing Vessel Drill Conductor Workshops

These workshops give participants hands-on training with emergency equipment that should be onboard any commercial fishing vessel, such as PFDs, life rafts, immersion suits, EPIRBs, fire extinguishers. Participants practice emergency procedures like man overboard, abandon ship, firefighting, and flooding control.

The workshops are US Coast Guard-accepted and meet the training requirements for drill conductors on documented commercial fishing vessels operating beyond the federal boundary line. The workshops are open to all mariners and are recommended for captains and crew serving on any commercial vessel.

Start Date	End Date	Location	State
3/17/2021	3/17/2021	Sitka	AK
3/27/2021	3/27/2021	Homer	AK
4/3/2021	4/3/2021	Juneau	AK
4/25/2021	4/25/2021	Seward	AK
4/28/2021	4/28/2021	Homer	AK

Stability Awareness & Damage Control

This workshop is designed to provide practical information and hands on training on vessel stability and emergency responses to flooding problems which cause many stability casualties.

AMSEA is a 501(c)(3) non-profit educational institute. Support Organizations: Alaska Native Tribal Health Consortium / National Institute for Occupational Safety & Health / Southeast Alaska Regional Health Consortium / State of Alaska Chronic Disease Prevention & Health Promotion / State of Alaska Office of Boating Safety / University of Alaska Sea Grant, Marine Advisory Program / U.S. Coast Guard 17th District

This workshop is oriented towards the commercial fishing environment but can be adapted for other vessel types and activities. The course is designed to meet future training requirements for commercial fishermen. Topics covered include:

- Requirements & Responsibilities
- Stability Terminology
- Stability Principles & the Stability Curve
- Operational Considerations
- Understanding Stability Reports
- Flooding control & prevention

Start Date	End Date	Location	State
3/18/2021	3/18/2021	Sitka	AK
4/26/2021	4/26/2021	Seward	AK
4/27/2021	4/27/2021	Homer	AK

First Aid & CPR

AMSEA's First Aid & CPR workshop is designed to meet the unique needs of commercial fishermen and other mariners. Attendees receive a U.S. Coast Guard accepted two-year certificate issued by the American Safety & Health Institute. The cost for the workshop is \$100.00 including local sales tax. The topics covered include:

- CPR & automatic external defibrillators (AED)
- Treatment of choking
- Medical emergencies
- Trauma
- Environmental hazards
- Patient assessment
- Medical communications
- Drowning & hypothermia
- Common fishing injuries

Start Date	End Date	Location	State
3/13/2021	3/13/2021	Sitka	AK
3/20/2021	3/20/2021	Sitka	AK
4/10/2021	4/10/2021	Sitka	AK
5/8/2021	5/8/2021	Sitka	AK
6/19/2021	6/19/2021	Sitka	AK

AMSEA is a 501(c)(3) non-profit educational institute. Support Organizations: Alaska Native Tribal Health Consortium / National Institute for Occupational Safety & Health / Southeast Alaska Regional Health Consortium / State of Alaska Chronic Disease Prevention & Health Promotion / State of Alaska Office of Boating Safety / University of Alaska Sea Grant, Marine Advisory Program / U.S. Coast Guard 17th District

Marine Safety Instructor Training

The MSIT is an intensive train-the-trainer course that prepares individuals to effectively teach cold-water survival procedures, use of marine safety equipment, and vessel safety drills. Upon completion of the course, participants will be prepared to teach AMSEA's U.S. Coast Guard accepted Fishing Vessel Drill Conductor training, pending authorization from the Coast Guard. Topics covered during the course include:

- Preparation for emergencies
- Cold-water near drowning
- Hypothermia
- Cold-water survival
- Survival equipment, procedures & onboard drills
- Risk Assessment
- Ergonomics
- Methods of instructions

Start Date	End Date	Location	State
4/19/2021	4/21/2021	Seward	AK
06/07/2021	06/12/2021	Nome	AK
09/20/2021	09/25/2021	Sitka	AK


AMSEA is a 501(c)(3) non-profit educational institute. Support Organizations: Alaska Native Tribal Health Consortium / National Institute for Occupational Safety & Health / Southeast Alaska Regional Health Consortium / State of Alaska Chronic Disease Prevention & Health Promotion / State of Alaska Office of Boating Safety / University of Alaska Sea Grant, Marine Advisory Program / U.S. Coast Guard 17th District

NOTICE TO MARINERS

AUTONOMOUS UNDERWATER VEHICLE OPERATIONS – PORT GRAVINA AND ORCA BAY

From January 18 to April 18, 2021 an autonomous underwater glider will be navigating in the vicinity of Port Gravina and Orca Bay as part of an oceanographic research project. The glider is 6 feet long, bright yellow and shaped like a torpedo with wings, it surfaces every two hours to transmit data.

If sighted, please avoid the glider and do not try to recover it.



**Questions or comments? Please contact Hank Statscewicz (hstatscewicz@alaska.edu;
907.322.3470) or Mary Anne Bishop (mbishop@pwssc.org; 907.424.5800)**

Submarine Fiber Optic Cable

Ketchikan Public Utilities has installed a submarine fiber optic cable from Prince Rupert, Canada to Ketchikan, Alaska. It's approximate route are indicated on the following chartlet and positions indicating the "As Laid" route of the cable are also included. The positions have been submitted to NOAA and a chart correction will be issued in the near future. Mariners are requested to not anchor near or conduct operations that may impact the cable. Questions/concerns should be directed to Edward Cushing, KPU's Division Manager, at (907) 228-6001 or by email to edc@city.ketchikan.ak.us.



- | | | |
|-----------------------------------|-----------------------------------|-----------------------------------|
| 1: 54.23300987°N, 130.33355572°W | 21: 54.23376519°N, 130.33507142°W | 41: 54.22634008°N, 130.34917957°W |
| 2: 54.23301748°N, 130.33392420°W | 22: 54.23380016°N, 130.33516000°W | 42: 54.22476268°N, 130.35061915°W |
| 3: 54.23299928°N, 130.33418750°W | 23: 54.23382457°N, 130.33522830°W | 43: 54.22327626°N, 130.35203859°W |
| 4: 54.23300408°N, 130.33424136°W | 24: 54.23387951°N, 130.33562439°W | 44: 54.22275781°N, 130.35250329°W |
| 5: 54.23302590°N, 130.33430036°W | 25: 54.23394777°N, 130.33635846°W | 45: 54.22154773°N, 130.35340552°W |
| 6: 54.23305058°N, 130.33434412°W | 26: 54.23411032°N, 130.33701887°W | 46: 54.22022449°N, 130.35445891°W |
| 7: 54.23307438°N, 130.33438631°W | 27: 54.23434617°N, 130.33787804°W | 47: 54.21941540°N, 130.35511036°W |
| 8: 54.23310351°N, 130.33443482°W | 28: 54.23442111°N, 130.33833310°W | 48: 54.21868217°N, 130.35581028°W |
| 9: 54.23312829°N, 130.33446937°W | 29: 54.23437541°N, 130.33929210°W | 49: 54.21808412°N, 130.35655755°W |
| 10: 54.23315398°N, 130.33450395°W | 30: 54.23427941°N, 130.34016509°W | 50: 54.21744992°N, 130.35764102°W |
| 11: 54.23317352°N, 130.33452453°W | 31: 54.23412770°N, 130.34087517°W | 51: 54.21665061°N, 130.35901811°W |
| 12: 54.23323421°N, 130.33456331°W | 32: 54.23399044°N, 130.34141694°W | 52: 54.21618086°N, 130.36026182°W |
| 13: 54.23330733°N, 130.33461630°W | 33: 54.23372616°N, 130.34190394°W | 53: 54.21567409°N, 130.36199658°W |
| 14: 54.23334020°N, 130.33465112°W | 34: 54.23335490°N, 130.34247186°W | 54: 54.21532435°N, 130.36335613°W |
| 15: 54.23337936°N, 130.33468613°W | 35: 54.23267943°N, 130.34323855°W | 55: 54.21512382°N, 130.36455495°W |
| 16: 54.23345602°N, 130.33474384°W | 36: 54.23223163°N, 130.34373798°W | 56: 54.21500167°N, 130.36629157°W |
| 17: 54.23353619°N, 130.33480934°W | 37: 54.23151052°N, 130.34440495°W | 57: 54.21495123°N, 130.36796461°W |
| 18: 54.23359938°N, 130.33486661°W | 38: 54.23015679°N, 130.34562051°W | 58: 54.21504027°N, 130.36970054°W |
| 19: 54.23365183°N, 130.33491893°W | 39: 54.22912868°N, 130.34665175°W | 59: 54.21543551°N, 130.37161839°W |
| 20: 54.23371850°N, 130.33498553°W | 40: 54.22791723°N, 130.34776135°W | 60: 54.21619055°N, 130.37414175°W |

61: 54.21677218°N, 130.37594626°W 120: 54.23572117°N, 130.45242011°W 179: 54.29047455°N, 130.53603296°W
62: 54.21739369°N, 130.37779817°W 121: 54.23616282°N, 130.45358644°W 180: 54.29136504°N, 130.53704177°W
63: 54.21796460°N, 130.37951348°W 122: 54.23635784°N, 130.45411039°W 181: 54.29241059°N, 130.53822543°W
64: 54.21836404°N, 130.38105133°W 123: 54.23676161°N, 130.45513732°W 182: 54.29363221°N, 130.53962776°W
65: 54.21854163°N, 130.38179039°W 124: 54.23711180°N, 130.45598592°W 183: 54.29593100°N, 130.54226746°W
66: 54.21889716°N, 130.38323633°W 125: 54.23745573°N, 130.45683124°W 184: 54.29743561°N, 130.54395877°W
67: 54.21939756°N, 130.38521476°W 126: 54.23803240°N, 130.45827556°W 185: 54.29837747°N, 130.54502210°W
68: 54.21966415°N, 130.38634029°W 127: 54.23859370°N, 130.45965186°W 186: 54.29956448°N, 130.54638358°W
69: 54.21990833°N, 130.38722580°W 128: 54.23911704°N, 130.46104374°W 187: 54.30119828°N, 130.54822912°W
70: 54.22010200°N, 130.38812650°W 129: 54.23972497°N, 130.46264888°W 188: 54.30207632°N, 130.54921955°W
71: 54.22036659°N, 130.38918911°W 130: 54.24018673°N, 130.46377931°W 189: 54.30291473°N, 130.55021622°W
72: 54.22068542°N, 130.39077046°W 131: 54.24066629°N, 130.46499787°W 190: 54.30509822°N, 130.55271753°W
73: 54.22099256°N, 130.39234990°W 132: 54.24119549°N, 130.46634712°W 191: 54.30660779°N, 130.55443131°W
74: 54.22128104°N, 130.39406372°W 133: 54.24172017°N, 130.46769625°W 192: 54.30760933°N, 130.55559882°W
75: 54.22139726°N, 130.39481769°W 134: 54.24238313°N, 130.46935112°W 193: 54.30820910°N, 130.55627779°W
76: 54.22159123°N, 130.39591941°W 135: 54.24311564°N, 130.47119728°W 194: 54.30949126°N, 130.55777880°W
77: 54.22196386°N, 130.39858866°W 136: 54.24389239°N, 130.47317247°W 195: 54.30980226°N, 130.55819636°W
78: 54.22217914°N, 130.40032922°W 137: 54.24444648°N, 130.47453663°W 196: 54.31029360°N, 130.55884825°W
79: 54.22243411°N, 130.40205582°W 138: 54.24533170°N, 130.47675064°W 197: 54.31059391°N, 130.55925774°W
80: 54.22259100°N, 130.40309498°W 139: 54.24617882°N, 130.47891733°W 198: 54.31127029°N, 130.56019643°W
81: 54.22267747°N, 130.40493093°W 140: 54.24683945°N, 130.48060318°W 199: 54.31211278°N, 130.56059264°W
82: 54.22278167°N, 130.40655428°W 141: 54.24748516°N, 130.48225784°W 200: 54.31428734°N, 130.55932361°W
83: 54.22283233°N, 130.40791198°W 142: 54.24835476°N, 130.48441483°W 201: 54.31537922°N, 130.55843632°W
84: 54.22296390°N, 130.40911292°W 143: 54.24875734°N, 130.48515376°W 202: 54.31603327°N, 130.55790450°W
85: 54.22312398°N, 130.41048816°W 144: 54.24911780°N, 130.48566248°W 203: 54.31649509°N, 130.55770978°W
86: 54.22323913°N, 130.41178519°W 145: 54.24934542°N, 130.48600988°W 204: 54.31724045°N, 130.55762417°W
87: 54.22330775°N, 130.41290883°W 146: 54.24956506°N, 130.48634779°W 205: 54.31774256°N, 130.55792911°W
88: 54.22342210°N, 130.41365823°W 147: 54.24977992°N, 130.48671008°W 206: 54.31808994°N, 130.55845269°W
89: 54.22349056°N, 130.41441220°W 148: 54.25029158°N, 130.48756657°W 207: 54.31846553°N, 130.55915876°W
90: 54.22339384°N, 130.41537681°W 149: 54.25092389°N, 130.48869757°W 208: 54.31882549°N, 130.56016869°W
91: 54.22321570°N, 130.41715007°W 150: 54.25153325°N, 130.48979402°W 209: 54.31893029°N, 130.56096140°W
92: 54.22306771°N, 130.41941367°W 151: 54.25257481°N, 130.49148173°W 210: 54.31889947°N, 130.56202266°W
93: 54.22301667°N, 130.42061759°W 152: 54.25359410°N, 130.49307968°W 211: 54.31878155°N, 130.56279925°W
94: 54.22316236°N, 130.42198318°W 153: 54.25500910°N, 130.49523853°W 212: 54.31846602°N, 130.56377283°W
95: 54.22334046°N, 130.42334223°W 154: 54.25615615°N, 130.49703934°W 213: 54.31765613°N, 130.56550713°W
96: 54.22352602°N, 130.42422143°W 155: 54.25808226°N, 130.49979733°W 214: 54.31746478°N, 130.56591498°W
97: 54.22381804°N, 130.42559823°W 156: 54.25941839°N, 130.50149473°W 215: 54.31707160°N, 130.56705160°W
98: 54.22434227°N, 130.42785897°W 157: 54.26135195°N, 130.50393560°W 216: 54.31690430°N, 130.56789083°W
99: 54.22440352°N, 130.42815100°W 158: 54.26277181°N, 130.50576223°W 217: 54.31684999°N, 130.56861137°W
100: 54.22459873°N, 130.42904745°W 159: 54.26382098°N, 130.50711175°W 218: 54.31690735°N, 130.56931463°W
101: 54.22477832°N, 130.42982065°W 160: 54.26413239°N, 130.50751005°W 219: 54.31704921°N, 130.56994884°W
102: 54.22515261°N, 130.43130316°W 161: 54.26514323°N, 130.50876152°W 220: 54.31737650°N, 130.57083766°W
103: 54.22541637°N, 130.43232934°W 162: 54.26672463°N, 130.51074488°W 221: 54.31814694°N, 130.57200169°W
104: 54.22563760°N, 130.43322673°W 163: 54.26829198°N, 130.51270024°W 222: 54.31897319°N, 130.57246831°W
105: 54.22597709°N, 130.43445805°W 164: 54.26977512°N, 130.51455898°W 223: 54.31997206°N, 130.57293232°W
106: 54.22639587°N, 130.43604957°W 165: 54.27131720°N, 130.51651677°W 224: 54.32071924°N, 130.57325912°W
107: 54.22672635°N, 130.43728062°W 166: 54.27409908°N, 130.52001928°W 225: 54.32141023°N, 130.57355150°W
108: 54.22726399°N, 130.43915248°W 167: 54.27595615°N, 130.52236694°W 226: 54.32196560°N, 130.57369878°W
109: 54.22755065°N, 130.43998626°W 168: 54.27835722°N, 130.52540612°W 227: 54.32353832°N, 130.57385724°W
110: 54.22824382°N, 130.44147701°W 169: 54.28040575°N, 130.52802862°W 228: 54.32548193°N, 130.57362852°W
111: 54.22864238°N, 130.44227177°W 170: 54.28203450°N, 130.52993996°W 229: 54.32792809°N, 130.57194415°W
112: 54.22962615°N, 130.44388780°W 171: 54.28308399°N, 130.53039362°W 230: 54.32978017°N, 130.57121969°W
113: 54.23059370°N, 130.44490500°W 172: 54.28413820°N, 130.53104258°W 231: 54.33159967°N, 130.57071847°W
114: 54.23146685°N, 130.44569802°W 173: 54.28545271°N, 130.53186101°W 232: 54.33280196°N, 130.57053975°W
115: 54.23249645°N, 130.44656252°W 174: 54.28672382°N, 130.53262871°W 233: 54.33466756°N, 130.57015711°W
116: 54.23361003°N, 130.44776756°W 175: 54.28791701°N, 130.53337360°W 234: 54.33631253°N, 130.56987525°W
117: 54.23388482°N, 130.44831266°W 176: 54.28834058°N, 130.53371043°W 235: 54.33899590°N, 130.56929913°W
118: 54.23454171°N, 130.44959690°W 177: 54.28875604°N, 130.53411919°W 236: 54.34027192°N, 130.56891086°W
119: 54.23506780°N, 130.45077073°W 178: 54.28933232°N, 130.53474596°W 237: 54.34204055°N, 130.56817365°W

238: 54.34336738°N, 130.56754110°W 297: 54.45651571°N, 130.58191116°W 356: 54.64804292°N, 130.62406774°W
239: 54.34442169°N, 130.56692122°W 298: 54.45794524°N, 130.58284257°W 357: 54.65099441°N, 130.62696314°W
240: 54.34543547°N, 130.56616899°W 299: 54.46131010°N, 130.58499667°W 358: 54.65304456°N, 130.62950666°W
241: 54.34642257°N, 130.56553264°W 300: 54.46341455°N, 130.58607166°W 359: 54.65869916°N, 130.63476387°W
242: 54.34708289°N, 130.56521157°W 301: 54.46787210°N, 130.58769616°W 360: 54.66300599°N, 130.63738044°W
243: 54.34808549°N, 130.56483578°W 302: 54.47217880°N, 130.58855589°W 361: 54.66421348°N, 130.63841517°W
244: 54.34905226°N, 130.56451863°W 303: 54.47552736°N, 130.58879833°W 362: 54.66545488°N, 130.63946838°W
245: 54.34987502°N, 130.56435602°W 304: 54.47893494°N, 130.58858468°W 363: 54.66662201°N, 130.64056209°W
246: 54.35076717°N, 130.56445608°W 305: 54.48163531°N, 130.58842695°W 364: 54.66808900°N, 130.64194553°W
247: 54.35230355°N, 130.56533769°W 306: 54.48362484°N, 130.58825862°W 365: 54.66975105°N, 130.64365796°W
248: 54.35347458°N, 130.56645938°W 307: 54.48686534°N, 130.58803688°W 366: 54.67187461°N, 130.64580172°W
249: 54.35397491°N, 130.56703855°W 308: 54.48902264°N, 130.58789200°W 367: 54.67309607°N, 130.64712596°W
250: 54.35458683°N, 130.56774509°W 309: 54.49178881°N, 130.58758234°W 368: 54.67501452°N, 130.64934397°W
251: 54.35646571°N, 130.56979723°W 310: 54.49546894°N, 130.58714748°W 369: 54.67657917°N, 130.65120505°W
252: 54.35826711°N, 130.57123870°W 311: 54.49805862°N, 130.58686177°W 370: 54.67807182°N, 130.65293926°W
253: 54.35983641°N, 130.57200503°W 312: 54.50056332°N, 130.58654495°W 371: 54.67985769°N, 130.65518345°W
254: 54.36243466°N, 130.57237361°W 313: 54.50245212°N, 130.58631234°W 372: 54.68113250°N, 130.65687184°W
255: 54.36390866°N, 130.57224368°W 314: 54.50705180°N, 130.58552982°W 373: 54.68286409°N, 130.65893887°W
256: 54.36469042°N, 130.57205497°W 315: 54.50961122°N, 130.58508368°W 374: 54.68434304°N, 130.66087786°W
257: 54.36787789°N, 130.57093756°W 316: 54.51206602°N, 130.58466433°W 375: 54.68568024°N, 130.66292599°W
258: 54.36886146°N, 130.57057486°W 317: 54.51641493°N, 130.58381151°W 376: 54.68753088°N, 130.66593702°W
259: 54.37111702°N, 130.56985581°W 318: 54.51994959°N, 130.58301973°W 377: 54.68876448°N, 130.66806191°W
260: 54.37368300°N, 130.57007996°W 319: 54.52344008°N, 130.58216893°W 378: 54.69002403°N, 130.67006233°W
261: 54.37508168°N, 130.57041971°W 320: 54.52737914°N, 130.58124416°W 379: 54.69124308°N, 130.67167331°W
262: 54.37626558°N, 130.57075590°W 321: 54.53164596°N, 130.58013560°W 380: 54.69260550°N, 130.67376974°W
263: 54.37854035°N, 130.57146174°W 322: 54.53519841°N, 130.57914916°W 381: 54.69428611°N, 130.67618822°W
264: 54.38158051°N, 130.57226929°W 323: 54.54230393°N, 130.57588498°W 382: 54.69561645°N, 130.67838917°W
265: 54.38325936°N, 130.57249054°W 324: 54.54688700°N, 130.57250256°W 383: 54.69751462°N, 130.68151069°W
266: 54.38552743°N, 130.57260652°W 325: 54.55119154°N, 130.56868811°W 384: 54.69904006°N, 130.68421823°W
267: 54.38812055°N, 130.57240229°W 326: 54.55175272°N, 130.56838648°W 385: 54.70029042°N, 130.68647225°W
268: 54.39097961°N, 130.57213889°W 327: 54.55294113°N, 130.56747182°W 386: 54.70172501°N, 130.68911275°W
269: 54.39334955°N, 130.57223106°W 328: 54.55632500°N, 130.56554175°W 387: 54.70282676°N, 130.69125380°W
270: 54.39555021°N, 130.57248466°W 329: 54.55990147°N, 130.56456370°W 388: 54.70392244°N, 130.69350491°W
271: 54.39744301°N, 130.57277273°W 330: 54.56462767°N, 130.56440750°W 389: 54.70487700°N, 130.69543207°W
272: 54.39946788°N, 130.57327231°W 331: 54.56850006°N, 130.56521942°W 390: 54.70551547°N, 130.69669422°W
273: 54.40264468°N, 130.57386998°W 332: 54.56965340°N, 130.56555445°W 391: 54.70689046°N, 130.69940279°W
274: 54.40484645°N, 130.57417617°W 333: 54.57057969°N, 130.56586222°W 392: 54.70794182°N, 130.70147088°W
275: 54.40757164°N, 130.57438997°W 334: 54.57162520°N, 130.56633392°W 393: 54.70873544°N, 130.70313711°W
276: 54.41016766°N, 130.57410112°W 335: 54.57299950°N, 130.56709673°W 394: 54.70969214°N, 130.70528524°W
277: 54.41380521°N, 130.57532773°W 336: 54.57641975°N, 130.56915735°W 395: 54.71098430°N, 130.70786206°W
278: 54.41548080°N, 130.57278206°W 337: 54.57883245°N, 130.571128321°W 396: 54.71230194°N, 130.71066832°W
279: 54.41737263°N, 130.57217791°W 338: 54.58229184°N, 130.57537313°W 397: 54.71333612°N, 130.71285736°W
280: 54.41972141°N, 130.57140931°W 339: 54.58490255°N, 130.57864166°W 398: 54.71444316°N, 130.71516757°W
281: 54.42427215°N, 130.57010210°W 340: 54.58584284°N, 130.57938990°W 399: 54.71522983°N, 130.71686664°W
282: 54.42571828°N, 130.57004023°W 341: 54.58895823°N, 130.58048394°W 400: 54.71594677°N, 130.71860165°W
283: 54.42697353°N, 130.57028092°W 342: 54.59129922°N, 130.58086094°W 401: 54.71678457°N, 130.72182455°W
284: 54.42828616°N, 130.57060091°W 343: 54.59262885°N, 130.58138917°W 402: 54.71797120°N, 130.72642406°W
285: 54.42914860°N, 130.57084202°W 344: 54.59621977°N, 130.58433323°W 403: 54.71866986°N, 130.72905291°W
286: 54.43205396°N, 130.57157759°W 345: 54.60174698°N, 130.58862265°W 404: 54.71922513°N, 130.73127049°W
287: 54.43499426°N, 130.57245955°W 346: 54.60481918°N, 130.59094550°W 405: 54.71978699°N, 130.73296204°W
288: 54.43731493°N, 130.57315907°W 347: 54.60850855°N, 130.59376664°W 406: 54.72039756°N, 130.73470231°W
289: 54.44154318°N, 130.57459801°W 348: 54.61218612°N, 130.59659248°W 407: 54.72120529°N, 130.73666999°W
290: 54.44339456°N, 130.57530443°W 349: 54.61571967°N, 130.59929239°W 408: 54.72169069°N, 130.73798421°W
291: 54.44698142°N, 130.57664360°W 350: 54.62011651°N, 130.60256725°W 409: 54.72259163°N, 130.74034267°W
292: 54.44949565°N, 130.57779986°W 351: 54.62473539°N, 130.60603591°W 410: 54.72281320°N, 130.74174970°W
293: 54.45092821°N, 130.57857066°W 352: 54.62937571°N, 130.60950777°W 411: 54.72293154°N, 130.74264610°W
294: 54.45393905°N, 130.58023990°W 353: 54.63355539°N, 130.61266782°W 412: 54.72320206°N, 130.74427266°W
295: 54.45503612°N, 130.58095783°W 354: 54.63883523°N, 130.61669654°W 413: 54.72337663°N, 130.74507056°W
296: 54.45539299°N, 130.58123075°W 355: 54.64379183°N, 130.62069021°W 414: 54.72357276°N, 130.74593150°W

415: 54.72352651°N, 130.74633480°W 474: 54.71551028°N, 130.84099583°W 533: 54.75429957°N, 130.93491846°W
416: 54.72347083°N, 130.74651875°W 475: 54.71531354°N, 130.84264505°W 534: 54.75479481°N, 130.93694688°W
417: 54.72340295°N, 130.74661366°W 476: 54.71503136°N, 130.84494555°W 535: 54.75536839°N, 130.93918890°W
418: 54.72326193°N, 130.74679394°W 477: 54.71494365°N, 130.84604233°W 536: 54.75603074°N, 130.94206000°W
419: 54.72270927°N, 130.74853107°W 478: 54.71500446°N, 130.84824506°W 537: 54.75651859°N, 130.94386910°W
420: 54.72251882°N, 130.74908498°W 479: 54.71541054°N, 130.85173198°W 538: 54.75712240°N, 130.94578794°W
421: 54.72188674°N, 130.75059347°W 480: 54.71568797°N, 130.85351612°W 539: 54.75788758°N, 130.94778764°W
422: 54.72121256°N, 130.75190445°W 481: 54.71589321°N, 130.85473029°W 540: 54.75849944°N, 130.94925782°W
423: 54.72079246°N, 130.75267512°W 482: 54.71605265°N, 130.85594084°W 541: 54.75912211°N, 130.95083736°W
424: 54.72040347°N, 130.75346886°W 483: 54.71621293°N, 130.85785786°W 542: 54.75995242°N, 130.95275024°W
425: 54.71964745°N, 130.75509141°W 484: 54.71652033°N, 130.86061229°W 543: 54.76072135°N, 130.95456543°W
426: 54.71893642°N, 130.75701861°W 485: 54.71689752°N, 130.86227225°W 544: 54.76209289°N, 130.95752581°W
427: 54.71834789°N, 130.75886410°W 486: 54.71726211°N, 130.86322986°W 545: 54.76325284°N, 130.96016994°W
428: 54.71773878°N, 130.76076299°W 487: 54.71764623°N, 130.86408592°W 546: 54.76394812°N, 130.96169739°W
429: 54.71730435°N, 130.76226728°W 488: 54.71790566°N, 130.86451705°W 547: 54.76513770°N, 130.96417221°W
430: 54.71623753°N, 130.76676849°W 489: 54.71853827°N, 130.86552118°W 548: 54.76659194°N, 130.96717301°W
431: 54.71569140°N, 130.76920865°W 490: 54.71911878°N, 130.86623104°W 549: 54.76803207°N, 130.97009718°W
432: 54.71543377°N, 130.77047828°W 491: 54.71977294°N, 130.86682785°W 550: 54.76955083°N, 130.97310156°W
433: 54.71527888°N, 130.77123693°W 492: 54.72027524°N, 130.86718788°W 551: 54.77125597°N, 130.97657857°W
434: 54.71489519°N, 130.77319657°W 493: 54.72074391°N, 130.86751378°W 552: 54.77315057°N, 130.98039164°W
435: 54.71442950°N, 130.77578136°W 494: 54.72118051°N, 130.86764565°W 553: 54.77472675°N, 130.98355199°W
436: 54.71396461°N, 130.77849187°W 495: 54.72190878°N, 130.86798195°W 554: 54.77555102°N, 130.98514413°W
437: 54.71375226°N, 130.77991552°W 496: 54.72247865°N, 130.86827369°W 555: 54.77736982°N, 130.98852046°W
438: 54.71351775°N, 130.78174493°W 497: 54.72305735°N, 130.86857518°W 556: 54.77913054°N, 130.99110428°W
439: 54.71320169°N, 130.78422744°W 498: 54.72394543°N, 130.86927292°W 557: 54.78040642°N, 130.99255723°W
440: 54.71283550°N, 130.78724174°W 499: 54.72435979°N, 130.86979824°W 558: 54.78245366°N, 130.99372787°W
441: 54.71234698°N, 130.78885652°W 500: 54.72486167°N, 130.87041768°W 559: 54.78451313°N, 130.99546535°W
442: 54.71165365°N, 130.79088759°W 501: 54.72531228°N, 130.87115590°W 560: 54.78647889°N, 130.99781586°W
443: 54.71122596°N, 130.79257948°W 502: 54.72595997°N, 130.87246074°W 561: 54.78793253°N, 130.99965914°W
444: 54.71106415°N, 130.79628410°W 503: 54.72667552°N, 130.87402656°W 562: 54.78921267°N, 131.00128400°W
445: 54.71121243°N, 130.79786168°W 504: 54.72731114°N, 130.87576112°W 563: 54.79232804°N, 131.00504373°W
446: 54.71146014°N, 130.79952129°W 505: 54.72807300°N, 130.87804826°W 564: 54.79483946°N, 131.00786869°W
447: 54.71170840°N, 130.80078043°W 506: 54.72902710°N, 130.88074509°W 565: 54.79845704°N, 131.01190334°W
448: 54.71194546°N, 130.80212602°W 507: 54.72970097°N, 130.88244126°W 566: 54.80259309°N, 131.01593964°W
449: 54.71225531°N, 130.80371393°W 508: 54.73064430°N, 130.88437985°W 567: 54.80673892°N, 131.01970495°W
450: 54.71260273°N, 130.80549294°W 509: 54.73209357°N, 130.88724758°W 568: 54.81004607°N, 131.02254983°W
451: 54.71286317°N, 130.80683497°W 510: 54.73314147°N, 130.88921923°W 569: 54.81337011°N, 131.02540226°W
452: 54.71296294°N, 130.80755820°W 511: 54.73410333°N, 130.89071167°W 570: 54.81691915°N, 131.02796448°W
453: 54.71322967°N, 130.81094515°W 512: 54.73543175°N, 130.89261737°W 571: 54.82105907°N, 131.03093353°W
454: 54.71322486°N, 130.81198820°W 513: 54.73627831°N, 130.89395081°W 572: 54.82546925°N, 131.03359452°W
455: 54.71322540°N, 130.81315413°W 514: 54.73727536°N, 130.89548862°W 573: 54.82950871°N, 131.03622186°W
456: 54.71308364°N, 130.81451863°W 515: 54.73824404°N, 130.89705780°W 574: 54.83236076°N, 131.03831185°W
457: 54.71264633°N, 130.81593047°W 516: 54.73874320°N, 130.89801477°W 575: 54.83593157°N, 131.04063307°W
458: 54.71224948°N, 130.81728043°W 517: 54.73925660°N, 130.89915264°W 576: 54.83734770°N, 131.04130254°W
459: 54.71201230°N, 130.81865148°W 518: 54.73973981°N, 130.90038078°W 577: 54.83796434°N, 131.04162178°W
460: 54.71191861°N, 130.81986284°W 519: 54.74016457°N, 130.90178176°W 578: 54.83997265°N, 131.04267477°W
461: 54.71232961°N, 130.82194134°W 520: 54.74081810°N, 130.90360985°W 579: 54.84133240°N, 131.04322161°W
462: 54.71294599°N, 130.82333050°W 521: 54.74168507°N, 130.90609587°W 580: 54.84294738°N, 131.04382500°W
463: 54.71349623°N, 130.82451490°W 522: 54.74213903°N, 130.90735076°W 581: 54.84452788°N, 131.04439399°W
464: 54.71391276°N, 130.82538593°W 523: 54.74293152°N, 130.90948231°W 582: 54.84677257°N, 131.04528636°W
465: 54.71476477°N, 130.82765832°W 524: 54.74379681°N, 130.91166866°W 583: 54.84850378°N, 131.04624630°W
466: 54.71531271°N, 130.82958797°W 525: 54.74534982°N, 130.91526880°W 584: 54.85005068°N, 131.04726086°W
467: 54.71566557°N, 130.83104154°W 526: 54.74708690°N, 130.91904574°W 585: 54.85131012°N, 131.04810514°W
468: 54.71588619°N, 130.83232305°W 527: 54.74840053°N, 130.92162978°W 586: 54.85254209°N, 131.04897924°W
469: 54.71604328°N, 130.83423827°W 528: 54.74962343°N, 130.92426407°W 587: 54.85420311°N, 131.05004809°W
470: 54.71602142°N, 130.83550419°W 529: 54.75117370°N, 130.92744864°W 588: 54.85543783°N, 131.05086481°W
471: 54.71591862°N, 130.83694966°W 530: 54.75196302°N, 130.92902304°W 589: 54.85694139°N, 131.05183546°W
472: 54.71581756°N, 130.83798377°W 531: 54.75279051°N, 130.93090857°W 590: 54.85878419°N, 131.05320983°W
473: 54.71565969°N, 130.83967980°W 532: 54.75366130°N, 130.93295165°W 591: 54.86056167°N, 131.05461841°W

592: 54.86256984°N, 131.05631000°W 651: 54.93561127°N, 131.07383359°W 710: 55.07214038°N, 131.14819708°W
593: 54.86449251°N, 131.05784780°W 652: 54.93724751°N, 131.07418322°W 711: 55.07305028°N, 131.14945518°W
594: 54.86598011°N, 131.05906747°W 653: 54.93952306°N, 131.07467666°W 712: 55.07449760°N, 131.15132807°W
595: 54.86994678°N, 131.06192707°W 654: 54.94127248°N, 131.07503064°W 713: 55.07552446°N, 131.15262863°W
596: 54.87157247°N, 131.06295305°W 655: 54.94323609°N, 131.07547375°W 714: 55.07672853°N, 131.15407352°W
597: 54.87343574°N, 131.06396165°W 656: 54.94607586°N, 131.07635090°W 715: 55.07784902°N, 131.15505966°W
598: 54.87669245°N, 131.06495742°W 657: 54.94946143°N, 131.07758428°W 716: 55.07916025°N, 131.15608589°W
599: 54.87892038°N, 131.06540031°W 658: 54.95235216°N, 131.07900160°W 717: 55.08098249°N, 131.15703472°W
600: 54.87998820°N, 131.06571840°W 659: 54.95438118°N, 131.08003411°W 718: 55.08279321°N, 131.15756780°W
601: 54.88080488°N, 131.06611097°W 660: 54.95616451°N, 131.08097906°W 719: 55.08493754°N, 131.15783998°W
602: 54.88180385°N, 131.06672491°W 661: 54.95746165°N, 131.08181305°W 720: 55.08657909°N, 131.15777483°W
603: 54.88315037°N, 131.06767317°W 662: 54.95782682°N, 131.08206154°W 721: 55.08821488°N, 131.15727372°W
604: 54.88500241°N, 131.06891714°W 663: 54.95912109°N, 131.08295793°W 722: 55.08980171°N, 131.15689844°W
605: 54.88747925°N, 131.07047083°W 664: 54.96014613°N, 131.08367173°W 723: 55.09138625°N, 131.15660137°W
606: 54.88879706°N, 131.071109823°W 665: 54.96126767°N, 131.08441869°W 724: 55.09285174°N, 131.15652983°W
607: 54.89023064°N, 131.07173629°W 666: 54.96232127°N, 131.08530120°W 725: 55.09431890°N, 131.15641448°W
608: 54.89080184°N, 131.07197457°W 667: 54.96363065°N, 131.08641573°W 726: 55.09583392°N, 131.15659168°W
609: 54.89196465°N, 131.07236176°W 668: 54.96640284°N, 131.08871077°W 727: 55.09851179°N, 131.15718891°W
610: 54.89308243°N, 131.07270143°W 669: 54.96894457°N, 131.09123321°W 728: 55.10068064°N, 131.15759890°W
611: 54.89428602°N, 131.07301590°W 670: 54.97036716°N, 131.09266025°W 729: 55.10263319°N, 131.15834529°W
612: 54.89546637°N, 131.07332295°W 671: 54.97163802°N, 131.09392012°W 730: 55.10504490°N, 131.15920119°W
613: 54.89657538°N, 131.07359673°W 672: 54.97325100°N, 131.09551196°W 731: 55.10682212°N, 131.16030516°W
614: 54.89749377°N, 131.07397926°W 673: 54.97511105°N, 131.09742154°W 732: 55.10855063°N, 131.16136741°W
615: 54.89810830°N, 131.07436489°W 674: 54.97648095°N, 131.09877283°W 733: 55.11008451°N, 131.16250703°W
616: 54.89872823°N, 131.07480229°W 675: 54.97787589°N, 131.10007864°W 734: 55.11232730°N, 131.16442049°W
617: 54.90000454°N, 131.07564780°W 676: 54.97912410°N, 131.10092835°W 735: 55.11492153°N, 131.16724232°W
618: 54.90068109°N, 131.07598053°W 677: 54.98103429°N, 131.10258477°W 736: 55.11723527°N, 131.16955846°W
619: 54.90196201°N, 131.07650348°W 678: 54.98236121°N, 131.10371538°W 737: 55.11986318°N, 131.17224950°W
620: 54.90299036°N, 131.07665781°W 679: 54.98405249°N, 131.10493078°W 738: 55.12204622°N, 131.17458108°W
621: 54.90339011°N, 131.07661911°W 680: 54.98708939°N, 131.10702491°W 739: 55.12445574°N, 131.17711346°W
622: 54.90375215°N, 131.07657848°W 681: 54.99184503°N, 131.11009437°W 740: 55.12660849°N, 131.17937491°W
623: 54.90425992°N, 131.07611013°W 682: 54.99618929°N, 131.11226270°W 741: 55.12942188°N, 131.18253857°W
624: 54.90520684°N, 131.07445386°W 683: 54.99926120°N, 131.11404248°W 742: 55.13212296°N, 131.18559458°W
625: 54.90551958°N, 131.07366813°W 684: 55.00251672°N, 131.11616840°W 743: 55.13523027°N, 131.18884896°W
626: 54.90593634°N, 131.07279101°W 685: 55.00462958°N, 131.11809838°W 744: 55.13906745°N, 131.19284840°W
627: 54.90629044°N, 131.07210878°W 686: 55.00597362°N, 131.11937341°W 745: 55.14369909°N, 131.19874090°W
628: 54.90756501°N, 131.07036931°W 687: 55.00940853°N, 131.12259815°W 746: 55.14664298°N, 131.20291265°W
629: 54.90842687°N, 131.07006099°W 688: 55.01029550°N, 131.12348490°W 747: 55.14939622°N, 131.20713101°W
630: 54.90902596°N, 131.07014010°W 689: 55.01149203°N, 131.12440214°W 748: 55.15006354°N, 131.20830106°W
631: 54.90938207°N, 131.07018334°W 690: 55.01304143°N, 131.12523800°W 749: 55.15443189°N, 131.21597976°W
632: 54.911189072°N, 131.07002818°W 691: 55.01466648°N, 131.12611703°W 750: 55.15657483°N, 131.22071537°W
633: 54.91290536°N, 131.06966837°W 692: 55.01760945°N, 131.12749769°W 751: 55.15803658°N, 131.22380917°W
634: 54.91389049°N, 131.06887795°W 693: 55.02084891°N, 131.12888488°W 752: 55.15941570°N, 131.22723927°W
635: 54.91520156°N, 131.06763143°W 694: 55.02428703°N, 131.12970551°W 753: 55.16067243°N, 131.23032837°W
636: 54.91580261°N, 131.06733146°W 695: 55.02845595°N, 131.13078101°W 754: 55.16222503°N, 131.23369954°W
637: 54.91650139°N, 131.06725651°W 696: 55.03441738°N, 131.13251065°W 755: 55.16321802°N, 131.23547742°W
638: 54.91743662°N, 131.06776011°W 697: 55.03825268°N, 131.13364413°W 756: 55.16434120°N, 131.23706643°W
639: 54.91796544°N, 131.06816486°W 698: 55.04351297°N, 131.13527159°W 757: 55.16544652°N, 131.23845197°W
640: 54.91832433°N, 131.06846727°W 699: 55.04823952°N, 131.13745032°W 758: 55.16716073°N, 131.23976811°W
641: 54.91909141°N, 131.06913238°W 700: 55.05185454°N, 131.13884068°W 759: 55.16923150°N, 131.24207639°W
642: 54.91995788°N, 131.06981978°W 701: 55.05416234°N, 131.13968399°W 760: 55.17036582°N, 131.24364133°W
643: 54.92114756°N, 131.07063462°W 702: 55.05673806°N, 131.14031936°W 761: 55.17187696°N, 131.24704765°W
644: 54.92202479°N, 131.07121809°W 703: 55.06039303°N, 131.14076500°W 762: 55.17291862°N, 131.24924679°W
645: 54.92269005°N, 131.07168613°W 704: 55.06296209°N, 131.14142054°W 763: 55.17437627°N, 131.25155117°W
646: 54.92742110°N, 131.07245376°W 705: 55.06463841°N, 131.14198463°W 764: 55.17567144°N, 131.25354971°W
647: 54.92956383°N, 131.07277780°W 706: 55.06732549°N, 131.14349242°W 765: 55.17725887°N, 131.25563715°W
648: 54.93160122°N, 131.07311207°W 707: 55.06839836°N, 131.14437993°W 766: 55.17787437°N, 131.25642584°W
649: 54.93326586°N, 131.07337724°W 708: 55.06989199°N, 131.14561895°W 767: 55.17859004°N, 131.25796942°W
650: 54.93378187°N, 131.07347873°W 709: 55.07113871°N, 131.14704533°W 768: 55.17927724°N, 131.25959313°W

769: 55.17973733°N, 131.26018149°W 828: 55.24712465°N, 131.45715942°W 887: 55.29044620°N, 131.50529802°W
770: 55.18035498°N, 131.26065942°W 829: 55.24871210°N, 131.45782859°W 888: 55.29079903°N, 131.50514384°W
771: 55.18117260°N, 131.26140472°W 830: 55.24986911°N, 131.45840199°W 889: 55.29103726°N, 131.50509899°W
772: 55.18207758°N, 131.26257598°W 831: 55.25048768°N, 131.45884145°W 890: 55.29122823°N, 131.50507952°W
773: 55.18295030°N, 131.26417745°W 832: 55.25145544°N, 131.45948347°W 891: 55.29147591°N, 131.50509986°W
774: 55.18358901°N, 131.26589138°W 833: 55.25242126°N, 131.46013169°W 892: 55.29178231°N, 131.50523731°W
775: 55.18370071°N, 131.26645852°W 834: 55.25396244°N, 131.46113342°W 893: 55.29232357°N, 131.50575661°W
776: 55.18437648°N, 131.26898050°W 835: 55.25610582°N, 131.46262730°W 894: 55.29284248°N, 131.50635801°W
777: 55.18547125°N, 131.27216736°W 836: 55.25664969°N, 131.46329364°W 895: 55.29311605°N, 131.50686833°W
778: 55.18635209°N, 131.27510969°W 837: 55.25730357°N, 131.46483242°W 896: 55.29332714°N, 131.50735738°W
779: 55.18729285°N, 131.27840121°W 838: 55.25860371°N, 131.46739501°W 897: 55.29350350°N, 131.50783008°W
780: 55.18849151°N, 131.28308389°W 839: 55.26041091°N, 131.47003961°W 898: 55.29370856°N, 131.50848102°W
781: 55.18938791°N, 131.28695612°W 840: 55.26162275°N, 131.47172035°W 899: 55.29383414°N, 131.50906237°W
782: 55.19106599°N, 131.29456724°W 841: 55.26348986°N, 131.47446510°W 900: 55.29394865°N, 131.50970131°W
783: 55.19235811°N, 131.29850364°W 842: 55.26455910°N, 131.47577203°W 901: 55.29404783°N, 131.51029832°W
784: 55.19335352°N, 131.30077176°W 843: 55.26688070°N, 131.47852975°W 902: 55.29421424°N, 131.51147301°W
785: 55.19540520°N, 131.30355510°W 844: 55.26794127°N, 131.47981905°W 903: 55.29427825°N, 131.51220644°W
786: 55.19769641°N, 131.30464913°W 845: 55.26981509°N, 131.48213682°W 904: 55.29434692°N, 131.51301894°W
787: 55.19910497°N, 131.30597829°W 846: 55.27083887°N, 131.48320045°W 905: 55.29440697°N, 131.51376945°W
788: 55.19970671°N, 131.30752488°W 847: 55.27173063°N, 131.48399296°W 906: 55.29445006°N, 131.51468903°W
789: 55.20067141°N, 131.31074111°W 848: 55.27299210°N, 131.48512507°W 907: 55.29450841°N, 131.51539061°W
790: 55.20216705°N, 131.31543576°W 849: 55.27363882°N, 131.48581103°W 908: 55.29460270°N, 131.51705228°W
791: 55.20333529°N, 131.31871451°W 850: 55.27447926°N, 131.48695945°W 909: 55.29463729°N, 131.51877477°W
792: 55.20556975°N, 131.32448077°W 851: 55.27516390°N, 131.48794543°W 910: 55.29457702°N, 131.51973507°W
793: 55.20677257°N, 131.32725440°W 852: 55.27546391°N, 131.48844130°W 911: 55.29448012°N, 131.52081435°W
794: 55.20838903°N, 131.33119198°W 853: 55.27591541°N, 131.48931039°W 912: 55.29433970°N, 131.52147655°W
795: 55.21007439°N, 131.33490441°W 854: 55.27632478°N, 131.49004145°W 913: 55.29412823°N, 131.52200978°W
796: 55.21241449°N, 131.33981102°W 855: 55.27667864°N, 131.49076117°W 914: 55.29391136°N, 131.52245601°W
797: 55.21390830°N, 131.34374877°W 856: 55.27767018°N, 131.49353172°W 915: 55.29365983°N, 131.52292682°W
798: 55.21555646°N, 131.34909356°W 857: 55.27843561°N, 131.49685039°W 916: 55.29333312°N, 131.52355512°W
799: 55.21668879°N, 131.35423382°W 858: 55.27852123°N, 131.49868402°W 917: 55.29296859°N, 131.52436058°W
800: 55.21793510°N, 131.36104458°W 859: 55.27793975°N, 131.50315268°W 918: 55.29274759°N, 131.52487584°W
801: 55.21845032°N, 131.36507185°W 860: 55.27796432°N, 131.50878535°W 919: 55.29233579°N, 131.52587991°W
802: 55.21862074°N, 131.36763851°W 861: 55.27842561°N, 131.51140014°W 920: 55.29205503°N, 131.52684976°W
803: 55.21906503°N, 131.37225134°W 862: 55.27890329°N, 131.51264916°W 921: 55.29197880°N, 131.52770973°W
804: 55.21976378°N, 131.37509799°W 863: 55.27962928°N, 131.51401783°W 922: 55.29194668°N, 131.52826218°W
805: 55.22066682°N, 131.37802140°W 864: 55.28007009°N, 131.51469924°W 923: 55.29193870°N, 131.52929820°W
806: 55.22213666°N, 131.38183578°W 865: 55.28065234°N, 131.51571402°W 924: 55.29201391°N, 131.53070024°W
807: 55.22372864°N, 131.38633866°W 866: 55.28118256°N, 131.51663577°W 925: 55.29204418°N, 131.53097469°W
808: 55.22444502°N, 131.38845258°W 867: 55.28212319°N, 131.51766385°W 926: 55.29206604°N, 131.53126436°W
809: 55.22559996°N, 131.39272374°W 868: 55.28260989°N, 131.51755765°W 927: 55.29209141°N, 131.53160151°W
810: 55.22615298°N, 131.39546025°W 869: 55.28315970°N, 131.51726803°W 928: 55.29212337°N, 131.53196743°W
811: 55.22701043°N, 131.39953461°W 870: 55.28341798°N, 131.51707965°W 929: 55.29216403°N, 131.53239062°W
812: 55.22820552°N, 131.40521479°W 871: 55.28379184°N, 131.51673478°W 930: 55.29223729°N, 131.53267253°W
813: 55.22960795°N, 131.41057915°W 872: 55.28431124°N, 131.51595813°W 931: 55.29224199°N, 131.53322575°W
814: 55.23100412°N, 131.41533957°W 873: 55.28464631°N, 131.51544542°W 932: 55.29228186°N, 131.53368670°W
815: 55.23213915°N, 131.41920839°W 874: 55.28507922°N, 131.51472155°W 933: 55.29230266°N, 131.53419999°W
816: 55.23339805°N, 131.42280814°W 875: 55.28544135°N, 131.51420423°W 934: 55.29232817°N, 131.53466003°W
817: 55.23415529°N, 131.42496035°W 876: 55.28591103°N, 131.51344012°W 935: 55.29234865°N, 131.53501577°W
818: 55.23636734°N, 131.43196440°W 877: 55.28631051°N, 131.51276764°W 936: 55.29238281°N, 131.53514555°W
819: 55.23677430°N, 131.43409398°W 878: 55.28669589°N, 131.51203755°W 937: 55.29243020°N, 131.53537384°W
820: 55.23728346°N, 131.43866494°W 879: 55.28699195°N, 131.51141048°W 938: 55.29247617°N, 131.53571388°W
821: 55.23763873°N, 131.44179981°W 880: 55.28739796°N, 131.51050684°W 939: 55.29248781°N, 131.53588948°W
822: 55.23816533°N, 131.44450007°W 881: 55.28748848°N, 131.51030150°W 940: 55.29250582°N, 131.53606076°W
823: 55.24095339°N, 131.45186077°W 882: 55.28785695°N, 131.50934348°W 941: 55.29261276°N, 131.53675441°W
824: 55.24240518°N, 131.45404733°W 883: 55.28825633°N, 131.50836850°W 942: 55.29333141°N, 131.53816136°W
825: 55.24351323°N, 131.45499982°W 884: 55.28875938°N, 131.50724725°W 943: 55.29354040°N, 131.53844251°W
826: 55.24356900°N, 131.45504259°W 885: 55.28909616°N, 131.50669357°W
827: 55.24542096°N, 131.45632580°W 886: 55.28996271°N, 131.50559834°W