

U.S. Department of Homeland Security

United States Coast Guard

LOCAL NOTICE TO MARINERS

District: 17 Week: 36/24

58-Navigation Information Service (NIS)-Watchstander, 24 hours a day at (703) 313-5900 ~Navcen Internet Address~ https://www.navcen.uscg.gov -Local Notice to Marinershttps://www.navcen.uscg.gov/-pageName=InmMain

Issued by: Commander (DPW) Telephone: (907) 463-2269 (0800-1600) Seventeenth Coast Guard District After Hours: (907) 463-2000 (1600-0800) PO Box 25517, Juneau, AK 99802-5517

Questions, comments, or additional information on this Local Notice to Mariners should be sent to the address above or by E-mail to: SMB-D17Juneau-LNM@uscg.mil. You can get the U.S. Coast Guard 17th District Local Notice to Mariners via the Internet directly from the U.S. Coast Guard Navigation

Center web site at https://www.navcen.uscg.gov/-pageName=InmDistrict®ion=17.

REFERENCES: Light List, Vol. VI, Pacific Coast and Pacific Islands (COMDTPUB P16502.6).
U.S. Coast Pilot 8, Pacific Coast Alaska: Dixon Entrance to Cape Spencer, 46th Edition.
U.S. Coast Pilot 9, Pacific and Arctic Coasts Alaska: Cape Spencer to Beaufort Sea, 41st Edition.

BROADCAST NOTICE TO MARINERS

Navigation information previously promulgated by CG Sector Southeast Alaska Broadcast Notice to Mariners through SEAK314-24 and CG Sector Anchorage Broadcast Notice to Mariners through A154-24 that are still in effect are included in this notice.

Chart Corrections https://nauticalcharts.noaa.gov/charts/chart-updates.html

Dates of Latest Editions, Nautical Charts, and Miscellaneous Maps https://nauticalcharts.noaa.gov/charts/list-of-latest-editions.html

Light List/ Summary of Corrections https://www.navcen.uscg.gov/-pageName=lightListCorrections

NOAA Chart Viewer (Posting of all up to date NOAA charts for viewing on Internet browser to be used for ready reference or planning) https://nauticalcharts.noaa.gov/

NOAA Booklet Charts https://nauticalcharts.noaa.gov/charts/noaa-raster-charts.html#booklet-charts

Coast Pilots, along with corrections, are available at: https://nauticalcharts.noaa.gov/publications/coast-pilot/index.html

NOAA Weather Buoy Sites http://www.ndbc.noaa.gov/

Tides online https://tidesandcurrents.noaa.gov/

Tides, Currents, PORTS https://tidesandcurrents.noaa.gov/noaacurrents/Stations-g=693

Weather https://www.weather.gov/marine/alaskatext

Vessel Traffic System Prince William Sound (VTSPWS) Users Manual https://homeportr.uscg.mil/Lists/Content/DispForm.aspx-ID=2205&Source=https:

ABBREVIATIONS

A through H I through O

I - Interrupted

ICW - Intracoastal Waterway

PRIV - Private Aid Q - Quick

P through Z

Page 1 of 25 Coast Guard District 17

ADRIFT - Buoy Adrift

AICW - Atlantic Intracoastal Waterway

LNM: 36/24 04 September 2024 Al - Alternating B - Buoy BKW - Breakwater

bl - Blast

BNM - Broadcast Notice to Mariner bu - Blue C - Canadian CHAN - Channel

CHAN - Channel CGD - Coast Guard District

C/O - Cut Off CONT - Contour CRK - Creek CONST - Construction

DAYMK/Daymk - Daymark DBN/Dbn - Daybeacon DBD/DAYBD - Dayboard DEFAC - Defaced DEST - Destroyed

DISCON - Discontinued DMGD/DAMGD - Damaged ec - eclipse

EST - Established Aid ev - every

EVAL - Evaluation EXT - Extinguished

F - Fixed fl - flash Fl - Flashing

G - Green GIWW - Gulf Intracoastal Waterway

HAZ - Hazard to Navigation HBR - Harbor

HOR - Horizontal Clearance

HT - Height

IMCH - Improper Characteristic

INL - Inlet INOP - Not Operating INT - Intensity

ISL - Islet
Iso - Isophase
kHz - Kilohertz
LAT - Latitude
LB - Lighted Buoy
LBB - Lighted Bell Buoy
LHB - Lighted Horn Buoy
LGB - Lighted Gong Buoy
LONG - Longitude

LNM - Local Notice to Mariners

LT - Light

LT CONT - Light Continuous LTR - Letter

LWB - Lighted Whistle Buoy LWP - Left Watching Properly MHz - Megahertz MISS/MSNG - Missing

Mo - Morse Code

MRASS - Marine Radio Activated Sound Signal

MSLD - Misleading N/C - Not Charted

NGA - National Geospatial-Intelligence Agency

NO/NUM - Number

NOS - National Ocean Service

NW - Notice Writer OBSCU - Obscured OBST - Obstruction OBSTR - Obstruction Oc - Occulting

ODAS - Anchored Oceanographic Data Buoy

R - Red

RACON - Radar Transponder Beacon

Ra ref - Radar reflector RBN - Radio Beacon REBUILT - Aid Rebuilt RECOVERED - Aid Recovered

RED - Red Buoy REFL - Reflective RRL - Range Rear Light RELIGHTED - Aid Relit RELOC - Relocated

RELOC - Relocated RESET ON STATION - Aid Reset on Station

RFL - Range Front Light

RIV - River

RRASS - Remote Radio Activated Sound Signal

s - seconds SEC - Section SHL - Shoaling si - silent SIG - Signal SND - Sound

SPM - Single Point Mooring Buoy

SS - Sound Signal STA - Station STRUCT - Structure St M - Statute Mile

TEMP - Temporary Aid Change

TMK - Topmark

TRLB - Temporarily Replaced by Lighted Buoy TRLT - Temporarily Replaced by Light

TRUB - Temporarily Replaced by Unlighted Buoy

USACE - Army Corps of Engineers

W - White Y - Yellow

Additional Abbreviations Specific to this LNM Edition: None

SECTION I - SPECIAL NOTICES

This section contains information of special concern to the Mariner.

871 ALASKA

The Coast Guard's VHF-FM Remote Fixed Facility (RFF) reception capabilities on the following site is degraded and calls on VHF-FM Channel 16 may not be received by the responsible Coast Guard Sector Communication Center within the stated coverage area:

JUNEAU FEDERAL BUILDING – Gastineau channel.

PILLAR MOUNTAIN - Eastern Kodiak Island, Afognak Island, Chiniak Bay, and Womens Bay.

COLD BAY – The area around Cold Bay, Izembek Lagoon, Northeastern Morzhovoi Bay, King Cove, and the Shumagin Islands. If unable to reach the Coast Guard on VHF-FM Channel 16, mariners that are equipped with capable radios can contact the Coast Guard through Communications Detachment Kodiak via high frequency (HF) 4125Khz. Mariners can also contact the Coast Guard via cellular or satellite phone by calling JRCC Juneau at 907-463-2000, Sector Southeast Alaska Command Center at (907) 463-2980 or Sector Western Alaska and U.S. Arctic Command Center at (907) 428-4100. Mariners are reminded that Western and Northern Alaska have no VHF-FM coverage. Contact in areas without VHF/FM coverage to the Coast Guard is via Communications Detachment Kodiak on HF or JRCC Juneau by phone. Mariners are requested to relay any unanswered calls for assistance to the Coast Guard.

LNM: 36/24

872 ALASKA – SOUTHWESTERN – BERING SEA

HAZARDOUS OPERATIONS: A gunnery and pyrotechnics exercise will be conducted in position 55°05′N, 168°35′W, approximately 100 NM NW from Dutch Harbor, from 061500-070400 UTC which is 0700-2000 Alaska time on September 6th, 2024. Danger radius is 20,000 yards and danger altitude is 23,000 feet. Mariners are requested to remain clear of the hazard area during the exercise. Questions/concerns should be directed to the Coast Guard Sector Western Alaska and U.S. Arctic at 907-428-4100 or on VHF/FM channel 16. The unit conducting the exercise will also be monitoring VHF/FM channel 16 during the exercise.

LNM: 36/24

873 ALASKA – NORTH PACIFIC OCEAN

The following subsurface data moorings have been recovered:

TYPE/NAME: POSITION: HARP-CB 58°40.409′N, 148°00.546′W HARP-PT 56°14.635′N, 142°45.431′W

Page 2 of 25 Coast Guard District 17 Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 36/24

874 ALASKA – SOUTHCENTRAL – GULF OF ALASKA

The following subsurface data moorings have been recovered:

TYPE/NAME: POSITION: Wave Buoy-1 59°270402'N, 139°44.982'W Wave Buoy-2 59°25.998'N, 139°48.366'W

Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 36/24

ALASKA - SOUTHCENTRAL - PRINCE WILLIAM SOUND

Part 1 of 3

875

The following subsurface data moorings have been established:

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:
BP07	60°06.894′N, 148°14.118′W	171 feet	154 feet
POWP05	60°02.784'N, 148°07.482'W	315 feet	299 feet
POWP06	60°02.790'N, 148°07.789'W	154 feet	138 feet
EP03	59°59.466'N, 148°05.778'W	207 feet	190 feet
EP04	59°59.706'N, 148°06.060'W	276 feet	259 feet
LP01	59°58.848'N, 148°01.914'W	112 feet	95 feet
LP02	59°59.082'N, 148°02.219'W	144 feet	128 feet
M06	59°57.222'N, 147°50.838'W	702 feet	686 feet
M08	59°57.858'N, 147°51.630'W	758 feet	741 feet
M09	59°58.146'N, 147°52.008'W	643 feet	617 feet
M10	59°58.512'N, 147°52.434'W	784 feet	768 feet
H03	60°20.256'N, 146°45.264'W	876 feet	860 feet
H12	60°18.888'N, 146°51.918'W	1194 feet	1079 feet

Questions/concerns for these established moorings should be directed to Mary Anne Bishop by phone to 907-4245800 x228 or by email to mbishop@pwssc.org. Other questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 36/24

876 ALASKA – SOUTHCENTRAL – PRINCE WILLIAM SOUND

Part 2 of 3

The following subsurface data moorings have been recovered:

TYPE/NAME:	POSITION:
PST1	60°39.100'N, 146°16.682'W
PST2	60°39.338'N, 146° 17.353'W
PST3	60° 39.568'N, 146° 18.040'W
PST4	60° 39.798'N, 146° 18.726'W
PST5	60° 40.028'N, 146°19.413'W
PST6	60°40.257'N, 146°20.100'W
PST7	60°40.487'N, 146°20.786'W
PST8	60°40.717'N, 146°21.473'W
PST9	60°40.947'N, 146°22.160'W
PST10	60°41.176'N, 146°22.846'W
LHRT1	60°22.6596′N, 147°51.147′W
LHRT2	60°22.6482′N, 147°50.7522′W
LHRT3	60°22.668′N, 147°50.5116′W
WTRT1	60°44.253′N, 147°59.5596′W
WTRT2	60°44.0994′N, 147°59.086′W
WTRT3	60°43.938′N, 147°59.448′W
H03	60°20.250'N, 146°45.246'W
H12	60°18.888'N, 146°51.930'W
MA	59°55.146'N, 147°49.092'W
MB	59°55.512'N, 147°49.512'W
M06	59°57.222'N, 147°50.826'W
M08	59°57.864'N, 147°51.636'W
M09	59°58.152'N, 147°52.008'W
M10	59°58.536'N, 147°52.458'W
LP01	59°58.854'N, 148°01.920'W
LPA	59°58.488'N, 148°02.286'W

EP04	59°59.700'N, 148°06.072'W
EPB	59°59.364'N, 148°06.492'W
POWP05	60°02.778'N, 148°07.470'W
LPB	59°58.758'N, 148°02.676'W
EP03	59°59.472'N, 148°05.802'W
EPA	59°59.064'N, 148°05.952'W
PWA	60°02.394'N, 148°07.698'W
LP02	59°59.082'N, 148°02.208'W
POWP06	60°02.796'N, 148°07.902'W

Questions/concerns for these established moorings should be directed to Mary Anne Bishop by phone to 907-4245800 x228 or by email to mbishop@pwssc.org. Other questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 36/24

ALASKA - SOUTHCENTRAL - PRINCE WILLIAM SOUND

Part 3 of 3

877

The following subsurface data moorings have been recovered:

TYPE/NAME: POSITION:

PWB 60°02.418'N, 148°08.208'W BP07 60°06.906'N, 148°14.118'W BPA 60°07.128'N, 148°13.458'W 60°41.370′N, 146°23.956′W Grav-1 Grav-2 60°41.454′N, 146°23.496′W Grav-3 60°40.925′N, 146°23.018′W Grav-4 60°40.696′N, 146°22.561′W 60°41.257′N, 146°24.580′W Grav-5 Grav-6 60°41.033′N, 146°24.109′W 60°40.811′N, 146°23.633′W Grav-7 60°40.580′N, 146°23.148′W Grav-8 Grav-9 60°40.362′N, 146°22.692′W Grav-10 60°40.970′N, 146°23.557′W Grav-RT1 60°41.053′N, 146°24.004′W Grav-RT2 60°41.071′N, 146°23.896′W Grav-RT3 60°41.090′N, 146°23.765′W RH1 60°36.987′N, 146°37.412′W RH2 60°38.175′N, 146°29.837′W NMS1 60°18.476'N, 147°40.044'W 60°18.280′N, 147°25.330′W NMS2 60°22.657′N, 147°08.341′W NMS3 GISL1 60°51.782′N, 147°13.369′W MR1 59°58.586'N, 147°53.254'W 59°58.655′N, 147°53.160′W MR2 MR3 59°58.738'N, 147°53.030'W HRT1 60°18.058'N, 146°54.282'W HRT2 60°18.135′N, 146°54.227′W HRT3 60°18.226′N, 146°54.145′W KIP1 60°18.121′N, 148°00.944′W KIP2 60°18.050′N, 147°55.640′W CP1 60°32.465′N, 146°08.652′W CP2 60°32.733′N, 146°06.749′W CEDAR1 60°33.568'N, 146°01.978"W JP1 60°29.366'N, 146°35.524'W PF1 60°48.720'N, 146°34.464'W

Questions/concerns for these established moorings should be directed to Mary Anne Bishop by phone to 907-4245800 x228 or by email to mbishop@pwssc.org. Other questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 36/24

878 ALASKA – SOUTHCENTRAL – GULF OF ALASKA

The following subsurface data moorings have been recovered:

TYPE/NAME: POSITION:

WAVE YB-1 59°27′22.248″N, 139°45′02.088″W WAVE YB-2 59°26′58.7349″N, 139°47′46.3194″W

Other questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 36/24

ALASKA - SOUTHWESTERN - SANAK TROUGH 879

The following subsurface data moorings have been recovered:

TYPE/NAME: POSITION: TRBM-1 54°42.606′N, 162°37.872′W 54°37.151′N, 162°35.695′W TRBM-2

Other questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or

by email to todd.r.buck@uscg.mil.

880

881

LNM: 36/24

ALASKA - SOUTHWESTERN - UNIMAK PASS

The following subsurface data mooring has been recovered:

TYPE/NAME: POSITION: 54°26.150′N, 165°16.310′W AL22-AU-UN01

The following subsurface data mooring has been established:

TYPE/NAME: POSITION: WATER DEPTH: TOP FLOAT DEPTH: AL24-AU-UN01 54°26.220'N, 165°10.200'W 518 feet 492 feet

Questions/concerns for these established moorings should be directed to Catherine Berchok by phone to 206-526-6331 or by email to catherine.berchok@nooa.gov. Other questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways

Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 36/24

ALASKA - SOUTHWESTERN - BERING SEA

The following subsurface data moorings have been recovered:

TYPE/NAME: POSITION:

GPS Tide Buoy 58°28.015′N, 162°04.779′W AL19-AU-BS6 53°37.775′N, 167°23.945′W 22BSP-2A 56°51.818'N, 164°03.693W 56°07.760'N, 168°18.767'W AL22-AU-PC01 AL22-AU-UM01 53°37.870'N, 167°24.272'W 56°09.702'N, 166°34.707'W AL22-AU-BS10 AL23-AU-BS11 61°05.030′N, 170°15.850′W AL23-AU-NM01 64°51.481′N, 168°26.882′W

The following subsurface data moorings have been established:

TYPE/NAME: POSITION: WATER DEPTH: TOP FLOAT DEPTH: AL24-AU-NM01 64°51.480'N, 168°26.880'W 144 feet 118 feet AL24-AU-BS10 56°09.600'N, 166°34.920'W 384 feet 358 feet AL24-AU-BS11 61°05.040'N, 170°15.840'W 161 feet 135 feet AL24-AU-PC01 56°07.762'N, 168°18.780'W 561 feet 535 feet

Questions/concerns for these established moorings should be directed to Catherine Berchok by phone to 206-526-6331 or by email to catherine.berchok@nooa.gov. Other questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways

Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 36/24

882 ALASKA - WESTERN - NORTON SOUND

The following subsurface data mooring has been recovered:

TYPE/NAME: POSITION:

64°28.365'N, 165°28.525'W Station-241

Other questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 36/24

ALASKA - ARCTIC - CHUKCHI SEA 883

The following subsurface data moorings have been recovered:

TYPE/NAME: POSITION:

A2-21 65°46.850'N, 168°34.090'W 66°19.640'N, 168°56.990'W A3-21 A4-21 65°44.740'N, 168°15.770'W

The following subsurface data moorings have been established:

TYPE/NAME: POSITION: WATER DEPTH: TOP FLOAT DEPTH: 65°46.860'N, 168°34.060'W A2-23 184 feet 49 feet A3-23 66°19.600'N, 168°56.940'W 190 feet 23 feet A4-23 65°44.760'N, 168°15.760'W 161 feet 49 feet

Questions/concerns for these established moorings should be directed to Rebecca Woodgate by phone to 206-221-3268 or by email to woodgate@uw.edu.

Other questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or

Page 5 of 25 Coast Guard District 17

LNM: 36/24

ALASKA - ARCTIC - CHUKCHI SEA 884

The following subsurface data moorings have been recovered:

TYPE/NAME: POSITION:

Unnamed 71°14.459′N, 164°18.067′W 2015MARU_2 71°29.792′N, 163°11.449′W AL21-AU-PH1 67°54.507'N, 168°11.926'W W. Barrow Canyon 71°37.868′N, 157°19.576′W WhoopDeeDo 71°25.327′N, 152°44.103′W AL23-AU-PB01 71°12.258′N, 157°59.970′W AL23-AU-IC03 71°49.840′N, 166°01.090′W

The following subsurface data moorings have been established:

POSITION: WATER DEPTH: TOP FLOAT DEPTH: TYPE/NAME: AL24-AU-IC03 71°49.860'N, 166°01.080'W 148 feet 121 feet AL24-AU-PB01 71°12.240′N, 157°59.940′W 157 feet 131 feet

Questions/concerns for these established moorings should be directed to Catherine Berchok by phone to 206-526-6331 or by email to catherine.berchok@nooa.gov.

Other questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 36/24

ALASKA - ARCTIC - BEAUFORT SEA 885

The following subsurface data moorings have been recovered:

TYPE/NAME: POSITION: UPE120 71°12.338′N, 148°48.018′W WAVE SS-1 70°29′16.8864″N, 147°30′00.3528″W 71°40.368′N, 154°59.923′W BCE-19 BCC-19 71°44.049′N, 155°09.624′W BCW-19 71°47.766′N, 155°20.777′W 70°50.085′N, 146°23.564′W Prudhoe AL23-AU-BF02 71°45.243′N, 154°28.560′W

70°50.100′N, 163°07.540′W AL23-AU-IC01

The following subsurface data moorings have been established:

TOP FLOAT DEPTH: TYPE/NAME: POSITION: WATER DEPTH:

BCE-22 71°40.385'N, 154°59.988'W 384 feet 62 feet BCC-22 71°44.067'N, 155°09.840'W 951 feet 66 feet BCW-22 71°47.781′N, 155°20. 812′W 554 feet 115 feet

Questions/concerns for these established moorings should be directed to Motoyo ITOH by phone to +81-46-867-9488 or by email to

mr2406cs@mirai.jamstecfb.jp.

TYPE/NAME: POSITION: WATER DEPTH: TOP FLOAT DEPTH: AL24-AU-IC01 70°50.040'N, 163°07.560'W 148 feet 121 feet AL24-AU-BF02 71°45.240′N, 154°28.500′W 344 feet 312 feet

Questions/concerns for these established moorings should be directed to Catherine Berchok by phone to 206-526-6331 or by email to

catherine.berchok@nooa.gov.

Other questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or

by email to todd.r.buck@uscg.mil.

LNM: 36/24

ALASKA - ARCTIC - ARCTIC OCEAN 886

The following subsurface data moorings have been recovered:

TYPE/NAME: POSITION: HARP C2 72° 48.154'N, 158°25.384'W HARP D 72° 36.925'N, 158°42.177'W NAP-20t 74°31.370′N, 161°55.880′W

The following subsurface data moorings have been established:

TYPE/NAME: POSITION: WATER DEPTH: TOP FLOAT DEPTH: 74°31.375′N, 161°56.536′W 5.528 feet 115 feet

Questions/concerns should be directed to Motoyo ITOH by phone to +81-46-867-9488 or by email to mr2406cs@mirai.jamstecfb.jp.

Other questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 36/24

ALASKA - SOUTHEAST - STEPHENS PASSAGE

887

Sub-surface operations occasionally including divers will be conducted twenty-four hours a day, seven days a week beginning at 1700 UTC which is 0900 Alaska time on September 5th, 2024 in Stephens Passage between Tantallon Point and Green Cove. The sub-surface operations will continue until 1700 UTC which is 0900 Alaska time on October 5th, 2024. Vessels on scene will monitor VHF/FM channel 16 and respond to calls to "PACIFIC LIFTER" for communication with transiting vessels. DB PACIFIC LIFTER is restricted in ability to maneuver. Mariners are requested to transit the area with caution, maintain a 500 yard CPA and minimize wake when transiting nearby. Questions/concerns should be directed to Mr. Brad Pace at (415) 323-4466 or brad.pace@kennedyslaw.com.

LNM: 36/24

888 ALASKA – SOUTHEAST – GASTINEAU CHANNEL – AURORA HARBOR

A floating dock measuring 180'X24' is being temporarily moored in Gastineau channel adjacent to the Aurora Harbor breakwater. Two white quick flashing lights have been attached to the dock in the following approximate positions:

58°18′20.4962″N, 134°26′12.2197″W

58°18′18.4802″N, 134°26′10.4467″W

Mariners are requested to transit the area with caution. Questions/concerns should be directed to Jeremy Norbryhn, Deputy Harbormaster, at 907-586-0395 or by email to jeremy.norbryhn@juneau.gov.

LNM: 36/24

ALASKA - ARCTIC - BEAUFORT SEA - SIMPSON LAGOON

CORRECTION (Positions updated in 34/24) ConocoPhillips will be conducting marine ocean and seabed characterization studies near Oliktok Point. Studies will include buoy installation, tide gauge installation, an Acoustic Wave and Current (AWAC) profiler, bathymetric surveys, and navigational hazard surveys during the open water seasons of 2024-2027. Temporary monitoring equipment will be placed in the area to support the studies. During the 2024 open water season, roughly late July through mid October, three wave buoys and one tide gauge will be established off of Oliktok Point in the following approximate locations:

B1 70°32.2810'N, 149°51.3480'W

897

898

B2 70°34.5850'N, 150°00.2300'W

B3 70°31.4080′N, 150°04.7940'W

TG1 70°30.6228'N, 149°52.2870'W

TG2 70°30.4302′N, 149°51.5130′W

TG3 70°30.3294′N, 149°51.3366′W

TG4 70°30.3912′N, 149°51.4446′W

AWAC 70°30.6120'N, 149°50.7132'WAll buoys will consist of a spar buoy floating on the surface with an LED strobe light.

The tide gauges will consist of a pressure transducer attached to a ¾" pipe that sticks up above the water approximately 3 feet, located in a water depth of 3-5 feet, with a cable to shore connected to a data recorder. The tide gauges will be clearly marked for safety. The AWAC Profiler will be deployed in water approximately 6 to 7 feet deep about 2,000 feet east of the Oliktok Access Road. The AWAC profiler consists of an array of sensors mounted in a gimbaled tripod system with sides approximately 3 feet long. The weighted tripod will be deployed by vessel and sits directly on the seafloor. The AWAC is battery powered and does not require a cable connection to the shore. The surface location of the subsurface AWAC will be marked by an A1-sized buoy.Mariners are requested to transit the area with caution, maintain at least a 100 foot CPA from all equipment, and minimize their wake when passing nearby. Questions/concerns should be directed to Hannah Griego at 907-265-6163 or by email to Hannah.griego@conocophillips.com.

LNM: 30/24

ALASKA – SOUTHEAST – SAGINAW CHANNEL – FAVORITE REEF

Favorite Reef B 2, LLNR 23945.1 has been re-established in position 58°22′47.514″N, 134°51′46.790″W, and upgraded to a lighted buoy with a flash characteristic of Fl R 4s. Mariners are requested to transit the area with caution.

LNM: 34/24

911 ALASKA – SOUTHCENTRAL – PRINCE WILLIAM SOUND – ORCA INLET

Orca Inlet LT 12, LLNR 25575, has been replaced with a temporary replacement lighted buoy in position 60°37′35.256″N, 145°41′22.268″W. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 30/24

915 ALASKA – BERING SEA

The M/V INTREPID will be laying cable along the following trackline from July 25 through September 25, 2024:

59°32.10′N, 162°14.40′W,

59°18.50′N, 162°23.10′W,

58°50.90'N, 162°17.80'W,

58°47.50'N, 162°13.50'W,

58°36.90′N, 162°17.90′W,

58°30.30'N, 162°02.70'W,

58°12.00'N, 158°47.90'W,

58°27.40′N, 158°23.50′W,

58°34.30'N, 158°23.50'W.

Mariners are requested to remain clear during cable laying operations.

LNM: 29/24

919 ALASKA – SOUTHEAST – CRAIG

927

A 32 foot troller has sunk SE of Madre De Dios Island in position 55°23.6′N, 133°06.98′W. Debris including an inflatable skiff have been reported in the vicinity. Mariners are requested to transit the area with caution. Questions/concerns should be directed to the Sector Southeast Alaska Command Center at 907-463-2980.

LNM: 28/24

922 ALASKA – SOUTHEAST – ANNETTE ISLAND – CANOE COVE

The F/V JACI GRACE has sunk in Canoe Cove in position 55°03.00'N, 131°38.93'W. The F/V JACI GRACE is a 52 foot seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Mariners are advised to transit the area with caution. Questions/concerns should be directed to the Coast Guard Sector Southeast Alaska Command Center at 907-463-2980.

LNM: 27/24

ALASKA – NORTHWESTERN – KOTZEBUE SOUND

HYDROGRAPHIC SURVEY: TerraSond, under contract to NOAA's Office of Coast Survey, will be conducting a hydrographic survey in the vicinity of Kotzebue Sound, from approximately July 1 through October 15. The work is being done for the purpose of updating nautical charts in the region. The survey areas are distributed in Kotzebue Sound, from Kotzebue to Good Hope Bay, as well as the general area from Cape Espenberg to Kivalina. The survey will be accomplished by the R/V POSEIDON, a 135' vessel blue and white in color. A 25' vessel called the "ASV-LR1", red in color, will be also be deployed and will be operated primarily unmanned, remote controlled and monitored from the POSEIDON. Both vessels will work in close proximity to each other and will have limited maneuverability during survey operations. Mariners are requested to remain clear of the vessels while surveying is in progress. Any immediate navigation concerns should be directed to the POSEIDON, which will be monitoring VHF channel 16. General questions can be directed to the TerraSond Charting Program Manager, Andrew Orthmann, by email at andrew.orthmann@terrasond.com.

LNM: 27/24

930 ALASKA – SOUTHEAST – ANITA BAY

The F/V PAMELA RAE LADY has sunk in position 56°12.10′N, 132°29.68′W. The F/V PAMELA RAE LADY is a 58ft seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Mariners are advised to transit the area with caution. Questions/concerns should be directed to the Coast Guard Sector Southeast Alaska Command Center on VHF/FM channel 16 or by phone to 907-463-2980.

I NM: 26/24

932 ALASKA – SOUTHEAST – SITKA – SILVER BAY – HERRING COVE

The F/V DRAGON LADY, a 79' wooden fishing vessel, has sunk in approximate position 57°02.607'N, 135°12.358'W. Fishing gear and other debris may be attached to or in the vicinity of the wreck. Mariners are advised to transit the area with caution. Questions/concerns should be directed to the Coast Guard Sector Southeast Alaska Command Center on VHF/FM channel 16 or by phone to 907-463-2980.

LNM: 26/24

944 ALASKA – SOUTHWESTERN – ALEUTIAN PENINSULA – SHUMAGIN ISLANDS

Bluff point Shoal LGB 1 (LLNR 27140) has been relocated to 55°11′25.315″N, 161°52′25.171″W. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 24/24

945 ALASKA – SOUTHEAST – WRANGELL NARROWS

An 18ft aluminum skiff has sunk in the Wrangell Narrows near Wrangell Narrows Channel LB 26 (LLNR 22995) and Wrangell Narrows Channel LT 27 (LLNR 23000) in position 56°38.868′N, 132°55.258′W. All vessels are requested to transit this area with caution and account for the reduced depth of the channel due to the wreck. Questions/concerns should be directed to the Coast Guard Sector Southeast Alaska Command Center on VHF/FM channel 16 or by phone to 907-463-2980.

LNM: 24/24

948 ALASKA – SOUTHEAST – DUNCAN CANAL – WHISKEY PASS

A skiff was reported sunk in Whiskey Pass, Duncan Canal, in approximate position 56°32.586′N, 133°03.855′W. Mariners are requested to transit or anchor in the area with caution. Questions/concerns should be directed to the Coast Guard Sector Southeast Alaska Command Center on VHF/FM channel 16 or by phone to 907-463-2980.

LNM: 22/24

949 ALASKA – SOUTHEAST – FOGGY BAY

An uncharted dangerous rock has been reported in Foggy Bay in approximate position 54°57.501′N, 130°57.267′W. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 21/24

951 ALASKA – SOUTHEAST – ICY STRAIT/ICY PASSAGE

Dangerous shoaling was reported in position 58°18′08.1″N, 135°22′22.5″W. Mariners are advised to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 19/24

952 ****CANCELLATION OF NOAA PAPER AND RASTER NAUTICAL CHARTS****

Originally published in LNM 09/21 and updated in LNM 18/24 The National Oceanic and Atmospheric Administration (NOAA) is undertaking a multi-year program to end production and maintenance of its suite of over 1,000 traditional paper nautical charts and all associated raster chart products and services, including: Print-on-Demand (POD) paper nautical charts, Full-size chart PDF files, BookletChartTM PDF files, NOAA raster navigational charts (NOAA RNC®), the NOAA RNC tile service, and the online RNC viewer. Six months notice of the intent to cancel a specific chart is provided in a "Last Edition" notice. The final cancellation of a chart is made in a "Canceled" notice. Both types of notices will appear in LNM Section IV, "Chart Correction." Canceled charts do not meet USCG carriage requirements. A comprehensive list of all canceled NOAA charts is available at: http://www.charts.noaa.gov/MCD/Dole.shtml. Traditional paper nautical chart production is ending to enable the creation and maintenance of larger scale, more up-to-date, higher quality coverage of NOAA's electronic navigational chart (NOAA ENC®) product. This will significantly enhance the amount of charted detail available to mariners. More information about NOAA's program to sunset traditional paper charts is on the NOAA Coast Survey website at: https://nauticalcharts.noaa.gov/charts/farewell-to-traditional-nautical-charts.html An online NOAA Custom Chart application at: https://devgis.charttools.noaa.gov/pod is available to create chart images from ENC data, which may then be printed. Notices to Mariners will not be issued for NOAA Custom Charts.

LNM: 09/21

ALASKA - SOUTHCENTRAL - COOK INLET - ANCHORAGE

Dredging, pile driving and other miscellaneous marine construction will be conducted at the Port of Alaska from April 1st through October 31st, 2024. Three mooring buoys with quick flashing white lights will be established northwest of Terminal 3 in positions 61°15'3.25"N, 149°53'39.45"W; 61°15'14.56"N, 149°53'31.58"W; and 61°15'25.56"N, 149°53'33.24"W. During operations VHF/FM channel 8 will be monitored. Derrick barges will have anchors deployed and submerged anchor cables will be marked by crown buoys over each submerged anchor. Mariners are requested to maintain a minimum 1,000 foot CPA. Mariners should proceed with caution and are requested to operate at a slow speed when transiting in this area.

LNM: 13/24

ALASKA – SOUTHCENTRAL – ORCA BAY

The Coast Guard has temporarily established Orca Inlet Channel LB 12 to temporarily replace Orca Inlet Channel LT 12 in position 60°37′34.074″N, 145°41′27.078″W. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscq.mil.

I NM: 12/24

955 ALASKA – SOUTHEAST – WESTERN CHANNEL

Makhnati Rock LWB 2 (LLNR 25000) is missing. A red temporary replacement lighted buoy has been established in position 57°02.170′N, 135°23.759′W. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscq.mil.

LNM: 04/24

956 ALASKA – SOUTHEAST – GASTINEAU CHANNEL – DOUGLAS

OBSTRUCTION TO NAVIGATION: A 22' white sailboat has sunk in Gastineau Channel off of Sandy Beach on Douglas in approximate position 58°16.259'N, 134°22.227'W. Mariners are requested to transit the area with caution. Questions/concerns should be directed to the Coast Guard Sector Southeast Alaska Command Center on VHF/FM channel 16 or by phone to 907-463-2980.

LNM: 01/24

957 ALASKA – SOUTHEAST

953

954

The U.S. Coast Guard has VHF Digital Selective Calling (DSC) capability with limited coverage in Southeast Alaska. The initial coverage areas are Ketchikan, Juneau and Yakutat. Mariners are reminded to ensure that they have properly connected their GPS units to their DSC equipped marine VHF radios and registered for their Maritime Mobile Service Identity (MMSI) to utilize the DSC distress function. Additional information is available through the Alaska Outdoors Forum at

https://forums.outdoorsdirectory.com/threads/digital-selective-calling-dsc.140270/ or by contacting Mike Folkerts with the Coast Guard District 17 Boating Safety Office at (907) 463-2297 or by email to Michael.r.folkerts@uscq.mil.

LNM: 51/23

958 ALASKA – ALEUTIAN ISLANDS – ADAK – SWEEPER COVE

The East side of the Pier 5 Dock located in Sweeper Cove is closed to moorage without prior approval from the Adak Harbormaster due to loose and missing pilings. Questions/concerns should be directed to Jim Fleming at (907) 277-7527 or the Port of Adak office at (907) 592-0185. The Adak harbormaster can also be contacted on VHF/FM channel 16.

LNM: 20/13

959 ALASKA – SOUTHCENTRAL – KODIAK

OBSTRUCTION TO NAVIGATION: A submerged rock has been reported approximately 20' off of the K&I Pier, which is located just South of the Star of Kodiak Pier, in approximate position 57°47.150'N, 152°24.341'W. The rock was reported struck by a vessel with a 16' draft at low tide, approximately +.085'. Mariners are requested to transit the area with extreme caution. Questions/concerns should be directed to the Sector Anchorage Command Center on VHF/FM channel 16 or by phone to 907-428-4100.

LNM: 47/23

960 ALASKA – SOUTHEAST – HAINES – CHILKOOT INLET

OBSTRUCTION TO NAVIGATION: An anchor and 1 shot of chain from a 120 foot vessel was reported as lost and sitting on the sea floor in Chilkoot Inlet in position 59°14.420'N, 135°25.852'W. All vessels anchoring in the vicinity are requested to remain clear of the lost anchor. Questions/concerns should be directed to the Coast Guard Sector Juneau Command Center at 907-463-2980 or on VHF/FM channel 16.

LNM: 27/23

961 ALASKA – SOUTHWESTERN – ALASKA PENINSULA – BECHEVIN BAY

Bechevin Bay B 8 (LLNR 27290) has been relocated 136 yards to position 55°03′09.590″N, 163°25′26.656″W to best mark the channel. Mariners are requested to transit the area with caution. Chart and Light List corrections will be issued once the verification process has been completed. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscq.mil.

LNM: 26/23

ALASKA - SOUTHEAST - WRANGELL - STIKINE RIVER ENTRANCE

The Coast Guard received a report of a grounding due to uncharted shoaling in the vicinity of the Stikine River entrance. The grounding occurred on June 17th, 2023, in the vicinity of position 56°30.01′N, 132°27.28′W with an approximate charted depth of 140′. Mariners are advised to transit the area with extreme caution and report any observed uncharted shoaling. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscq.mil.

LNM: 26/23

963 ALASKA – SOUTHEAST – AUKE BAY/AUK REC

962

964

The U.S. Coast Guard has established a temporary mooring buoy in the cove where the Auk Recreation area is located between Point Louisa and Auke Bay in position 58°22′34.114″N, 134°43′23.448″W. The mooring buoy has been established for official use and should not be used without authorization from the Coast Guard. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 23/23

ALASKA – SOUTHEAST – FREDERICK SOUND

A 47 foot wood fishing vessel has been reported sunk in position 56°54.68'N, 132°56.69'W. Mariners are requested to transit the area with caution. Questions/concerns should be directed to the Sector Juneau Command Center at 907-463-2980.

LNM: 21/23

965 ALASKA – SOUTHEAST – SITKA SOUND – DOROTHY NARROWS

Elovoi Island Rock DBN 1 (LLNR 24900) has been rebuilt in position 56°49′17.695″N, 135°22′43.882″W and is watching properly. The temporary buoy marking the rock has been removed. Chart and Light List corrections will be issued once the verification process has been completed. Mariners are advised to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscq.mil.

LNM: 17/23

966 ALASKA – PRINCE WILLIAM SOUND – CAPE HINCHINBROOK

A submerged mooring has been reported lost in 315 feet of water in position 60°30.224′N, 146°30.821′W. This mooring may be an obstruction to operations on the sea floor. Questions/concerns should be directed to Todd Buck at the Coast Guard District 17 Waterways Management Office at 907-463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 6/23

967 ALASKA – SOUTHEAST – STEPHENS PASSAGE – HORSE ISLAND

Sea Quester Farms has established an aquatic farm just South of Horse Island in Stephens Passage. The aquatic farm is marked by buoys and three of the buoys are currently lighted with plans to add lights to two additional buoys. The extent of the aquatic farm is:

SSW - 58°14.575'N,134°43.980'W (Lighted buoy)

WSW - 58°14.587'N, 134°44.040'W (Lighted buoy)

WNW - 58°14.648'N, 134°44.077'W (Lighted buoy)

NNW - 58°14.684'N, 134°44.025'W (Light will be added to buoy)

ENE - 58°14.674'N, 134°43.888'W

ESE - 58°14.639'N, 134°43.862'W

SSE - 58° 14.597'N 134° 43.887'W (Light will be added to buoy)

Mariners are advised to transit the area with caution. Questions/concerns should be directed to Ilivia Duner at 530-414-3632 or by email to info@seaquesterfarms.com.

LNM: 05/23

968 ALASKA – SUBSURFACE AND SURFACE BUOYS

Locations of all subsurface and surface oceanographic moorings that have been reported to the U.S. Coast Guard District 17 Waterways Branch are included in an enclosure to the Local Notice to Mariners. The name, type, location, depth, water depth, and a Point of Contact for all data buoys, surface and subsurface, shall be reported as quickly as is practical if they are placed within the navigable waters (within 200 nm) of the United States. Data buoys placed in the Arctic region but outside of 200 nm of the United States may be reported and will be included in this compilation (for informational purposes only). This notification process is for inclusion in the Local Notice to Mariners to provide navigational

information to mariners and does not supersede any permission or permitting requirements. Any notifications, corrections, additions, deletions, or comments for the Alaska region (Coast Guard District 17) or the Arctic region should submitted via e-mail to D17-PF-D17-LNM@uscg.mil or to Todd Buck, USCG D17(dpw), at (907) 463-2269 or by email to todd.r.buck@uscg.mil. This compilation is as current as the Local Notice to Mariners (LNM) as included in an enclosure. The referenced LNM may have additional information and indicates the last time an entry was updated.

LNM: 38/11

ALASKA - SOUTHCENTAL - COOK INLET NAVIGATION CHANNEL

The U.S. Army Corps of Engineers (USACE), Alaska District conducted a project condition survey for Cook Inlet Navigation Channel on May 13th, 2022 in which the following controlling depths in feet (FT) mean lower low water (MLLW) were recorded:

Left Outside Quarter 61°12'30.93"N, 150°03'54.55"W, -39.5 FT MLLW

Left Inside Quarter 61°11'39.75"N, 150°07'00.55"W, -38.6 FT MLLW

Right Inside Quarter 61°11'37.86"N, 150°06'57.61"W, -39.4 FT MLLW

Right Outside Quarter 61°12'13.42"N, 150°04'19.01"W, -41.8 FT MLLW

A chartlet of the controlling depths as well as survey data are available on the U.S. Army Corps of Engineers (USACE) Navigation Portal website at: http://navigation.usace.army.mil/Survey/Hydro. The Cook Inlet Navigation Channel was dredged during the summer of 2014 to a project depth of -38 FT MLLW. At this time, no maintenance dredging is scheduled for this channel during 2022. The next project condition survey for this channel is tentatively scheduled for May 2023. BE ADVISED: The information depicted on maps, charts, drawings, navigation notices, etc., for the subject project, represents the results of a survey conducted on the date(s) indicated and can only be considered to represent the general condition existing at that time. The survey data was collected under a USACE contract for the purpose of characterizing the condition of the navigation channel, and the area for placement of dredged material for future channel maintenance operations. As such, the information is only valid for its intended use. This information can be used to supplement existing published navigation charts. The user is responsible for the results of any application of the survey data for other than its intended purpose and should consider the contents, timeframe of data collection, and accuracy specifications for survey data

collection/processing. Additionally, bathymetry in Cook Inlet is subject to drastic and continuing change. Prudent mariners should not rely solely upon this information. Questions/concerns should be directed to Jeremy Allen, Operations Project Manager at 907-753-2753 or by email to jeremy.m.allen@usace.army.mil.

LNM: 02/23

970 ALASKA – SOUTHEAST – TENAKEE INLET

969

Tenakee Inlet Entrance LT 1 (LLNR 24065) is destroyed and has been temporarily decommissioned and Tenakee Inlet Entrance LB 1 (LLNR 24065.1) has been established in position 57°46′19.284″N, 134°55′36.987″W. Tenakee Inlet Entrance LB 1 is a green can buoy with a green light flashing every 4 seconds. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 49/22

971 ALASKA – SOUTHEAST – FRESHWATER INLET – PAVLOF HARBOR

The F/V BAILEY BAY has sunk in position 57°50.985′N, 135°01.725′W in approximately 30 feet of water. The F/V BAILEY BAY is a 33′ fiberglass fishing vessel and there may be fishing gear or debris attached to or in the vicinity of the vessel. Mariners are advised to transit the area with caution.

LNM: 43/22

972 ALASKA – SOUTHEAST – ICY STRAIT – ICY PASSAGE

A kelp farm has been established in Icy Passage along the North shore of Pleasant Island in approximate position 58°21′30″N, 135°32′32″W. The kelp farm is marked with two private lighted buoys. Aquatic Plant Farm LB A (LLNR 24177) is a yellow buoy with a FI 4 second light and is located in position 58°21′16.980″N, 135°32′32.700″W. Aquatic Plant Farm LB B (LLNR 24278) is a yellow buoy with a FI 6 second light and is located in position 58°21′47.580″N, 135°32′32.500″W. Chart and Light List corrections will be published in a subsequent LNM. Questions/concerns should be directed to Brian Delay at 907-321-1952 or by email to rainydawnfarms@gmail.com.

LNM: 42/22

ALASKA - SOUTHCENTRAL - PRINCE WILLIAM SOUND - BARRY ARM

The State of Alaska is issuing routine updates on the Barry Arm Landslide Tsunami risk. This threat is located in Barry Arm, Northwestern Prince William Sound, and has the potential to create a tsunami when it falls into the water. It is uncertain if and when this might occur, but if it occurs localized wave heights will be very hazardous in Barry Arm and Harriman Fjord. Port Wells and Passage Canal will also see inundation and strong, unusual currents for hours following this event. The geologic makeup of the area is similar to Alaskan locations where two previous landslide caused tsunamis occurred, in Lituya Bay (1958) and Icy Bay (2015), both causing extremely large but localized tsunamis. Mariners should maintain vigilance when in the vicinity of Barry Arm or nearby waters and be prepared to depart the area if any unusual geologic activity is observed. Studies are being conducted and the situation is being monitored to allow for a better understanding of the potential results of a slide. Additional information is available at the following website: https://dggs.alaska.gov/hazards/barry-arm-landslide.html.

LNM: 40/22

974 SAFETY NOTICE - NAVIGATIONAL RANGE AND SECTOR LIGHTS ON ELECTRONIC CHARTS

The U.S. Coast Guard has become aware that the Range and Sector Light Characteristic labels are not displayed on Electronic Navigational Charts (ENCs) when used in an Electronic Chart Display and Information System (ECDIS) due to limitations of the S-52 ECDIS display specification. Mariners may query the ENC data directly within ECDIS or refer to the Light List for complete information on Range and Sector Light

973

Characteristics.

975

976

977

LNM: 39/22

ALASKA – SOUTHEAST – NECKER ISLANDS – HOT SPRINGS BAY

A 32' Sailboat has been reported sunk in Hot Springs Bay in approximate position 56°50.252'N, 135°23.574'W in approximately 84 feet of water. The sailboat has an estimated mast height of up to 50'. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 36/22

ALASKA - SOUTHEAST - DUNCAN CANAL - BUTTERWORTH ISLAND

OBSTRUCTION TO NAVIGATION: A 94 foot tug has been reported sunk in the vicinity of Butterworth Island in approximate position 56°32.586′N, 133°03.855′W. Vessels transiting in the vicinity are requested to remain clear of the reported wreck. Questions/concerns should be directed to the Coast Guard Sector Juneau Command Center at 907-463-2980 or on VHF/FM channel 16.

LNM: 34/22

ALASKA - U.S. COAST GUARD MEDIUM FREQUENCY (MF) AND HIGH FREQUENCY (HF) DISTRESS WATCHKEEPING

Mariners are advised that calls to the U.S. Coast Guard on the international radiotelephone distress frequency 2182 kHz or the Digital Selective Calling (DSC) frequency 2187.5 kHz may not be heard or may be severely degraded. Instead of using 2182 kHz for distress calls, mariners may use high frequency (HF) radiotelephone or DSC in the 4, 6, 8, and 12 MHz distress or calling bands. On February 7th, 2022, the U.S. Coast Guard will discontinue monitoring high frequency (HF) voice for all existing regions with the exception of Kodiak, Alaska, and Guam. All existing regions will also continue monitoring high frequency (HF) DSC in the 4, 6, 8, and 12 MHz distress or calling bands. Mariners may also use cellular, satellite or other methods of communications to speak directly to the nearest Coast Guard Command Center. Additional information concerning U.S. Coast Guard HF watchkeeping is posted on the U.S. Coast Guard's Navigation Center website

(https://www.navcen.uscg.gov/?pageName=cgcommsCall). The three U.S. Coast Guard Command Centers (CC) located in Alaska are: CG Sector Juneau CC, 907-463-2980; CG Sector Anchorage CC, 907-428-4100; CG District 17 CC, 907-463-2000. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 50/21

978 ALASKA – SOUTHCENTRAL – KODIAK ISLAND

A Waverider buoy approximately 29 nautical miles southeast of the City of Kodiak, Alaska in position 57° 28.8′ N, 151° 42.0′ W, has been decommissioned. The mooring remains on site and is marked with a cluster of unlit white floats. The mooring will be removed as operations permit. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 40/21

979 ALASKA – SOUTHEAST – BEHM CANAL – MOSER BAY

The Moser Bay Coast Guard Mooring Buoy (LLNR 22329) is missing and may be submerged and attached/entangled with a sunken vessel in the vicinity of its charted position. Mariners should transit the area with extreme caution because it may be suspended subsurface at an unknown depth. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscq.mil.

LNM: 38/21

980 ALASKA – SOUTHEAST – KLAG BAY

Klag Bay Entrance DBN 1 (LLNR 25335) has been rebuilt in position 57°36′42.318″N, 136°06′08.130″W and is watching properly. Chart and Light List corrections will be issued once the verification process has been completed. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 37/21

981 ALASKA – WESTERN – YUKON RIVER

OBSTRUCTION TO NAVIGATION: A 6' by 6' by 15' metal tower is partially submerged in the Yukon River in position 62°35.55'N, 164°54.48'W. Mariners are requested to transit the area with caution and make sighting reports to the Coast Guard Sector Anchorage Command Center at (907) 428-4100 with any updated positions.

LNM: 28/21

982 ALASKA – BRISTOL BAY – NORTHEAST KVICHAK BAY – NAKNEK RIVER

A potential obstruction to navigation exists in the Naknek River in position: 58°42.772'N, 157°02.045'W. A large metal ramp has been reported to be visible during low tide and completely submerged during high tide. All mariners should utilize caution and avoid transiting in close proximity to the object. Questions/concerns should be directed to Sector Anchorage Command Center at (907) 428-4100.

LNM: 27/21

ALASKA – ALEUTIAN ISLANDS – UNALASKA – CAPTAIN'S BAY

Bailey Ledge LT (LLNR 27505) in Captain's Bay has been temporarily replaced with an unlit red buoy in position 53°51.603'N, 166°33.103'W. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

983

LNM: 23/21

984 ALASKA – COOK INLET

The BAKER OIL PLATFORM warning lights (LLNR 26361) in position 60°49'45.390"N, 151°29'00.010"W and the DILLION OIL PLATFORM warning lights (LLNR 26361.5) in position 60°44'07.340"N, 151°30'42.610"W are experiencing intermittent outages. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Sector Anchorage Waterways Management at anchorage.waterways@uscg.mil or (907) 428-4189.

LNM: 08/21

985 ALASKA

986

989

The Coast Guard will be using AIS Broadcasts to relay some marine information, primarily ATON Discrepancies, VHF/FM Hi-site outages, active subsistence whaling, Gunnery and Pyrotechnics Exercises, and similar Notices directly relating to safe navigation. The Coast Guard's access to AIS transmitters is limited so not all areas might be covered at any given time and the locations of the active transmitters will be determined by the priority of the messages being broadcast from them. All information broadcast by AIS will also be published by the more conventional methods of BNM and LNM. Feedback is desired and should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscq.mil.

LNM: 43/20

ALASKA - SOUTHEAST - DIXON ENTRANCE

Tree Point LT (LLNR 21840) has been relocated to a new steel structure approximately 100 yards Southeast of the existing lighthouse structure. The approximate position for the new light is 54°48′10″N, 130°56′04″W. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscq.mil.

LNM: 11/20

987 ALASKA – GULF OF ALASKA

NOAA DLB 46085 (LLNR 984.15) has been replaced with a 3-meter buoy and relocated to 55°53′18.000″N, 142°50′48.000″W. Chart and Light List corrections have been issued. The previous 6-meter buoy was not recovered and remains in position 55°52′05.000″N, 142°33′31.000″W. Mariners are requested to transit the area with caution until the previous buoy is recovered. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 33/19

988 ALASKA – SOUTHCENTRAL

The U.S. Coast Guard has VHF Digital Selective Calling (DSC) capability with limited coverage in Southcentral Alaska. The initial coverage areas are Upper Cook Inlet, Kodiak and Valdez Arm. Mariners are reminded to ensure that they have properly connected their GPS units to their DSC equipped marine VHF radios and registered for their Maritime Mobile Service Identity (MMSI) to utilize the DSC distress function. Additional information is available through the Alaska Outdoors Forum at https://forums.outdoorsdirectory.com/threads/digital-selective-calling-dsc.140270/ or by contacting Mike Folkerts with the Coast Guard District 17 Boating Safety Office at (907) 463-2297 or by email to Michael.r.folkerts@uscg.mil.

LNM: 51/23

ALASKA – SOUTHCENTRAL – PRINCE WILLIAM SOUND – UNAKWIK INLET

An uncharted and dangerous rock has been reported in Unakwik Inlet in approximate position 61°08.045′N, 147°32.665′W. Mariners should transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 25/19

990 ALASKA

Coast Guard District 17 is using AIS broadcasts to notify mariners of CG VHF/FM Hi-Site outages. These are geographic broadcasts that should display on properly configured, AIS equipped, chart plotters. The broadcast will display with a 40NM range ring surrounding the inoperative Hi-Site and a message stating the name of the site, it's latitude/longitude, and the telephone number of the nearest CG Command Center. An example broadcast message is "CG DECEPTION HILLS VHF SITE AT 59-05N 138-13W INOP-RELAY DISTRESS CALLS TO 9074632980". The purpose of this notification is to ensure mariners are aware of problematic VHF/FM coverage and to encourage them to relay information to the nearest CG Command Center. When relaying a distress call the most critical piece of information is an accurate position. Additional valuable information is: Nature of distress; Number of persons on board; Vessel name; On scene weather; Crew's intentions (I.E. Abandon ship, Fight the fire, ETC.). The CG Command Center may request additional information depending on the specific situation. CG VHF/FM Hi-Site outages will also be listed in each weekly Local Notice to Mariners, announced over nearby Hi-Sites by Broadcast Notice to Mariners, listed on the Coast Guard NAVCEN website at https://www.navcen.uscg.gov/broadcast-notice-to-mariners. BNM texts can also be emailed to people who request it through the NAVCEN website. Sector Juneau Command Center is 907-463-2980. Sector Anchorage Command Center is 907-428-4100. Questions/concerns should be directed to Todd Buck with the CG District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscq.mil.

LNM: 04/23

991 ALASKA – SOUTHEAST – FRESHWATER BAY

An uncharted rock shoal has been reported in Cedar Cove centered in approximate position 57°52.405′N, 135°03.694′W with an approximate 75 foot radius. The rocks were approximately 1 foot below a 0′ tide. The location of the reported shoal has a charted depth of 12 fathoms. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by

LNM: 24/19

992 ALASKA – SOUTHEAST – FARRAGUT BAY – FRANCIS ANCHORAGE

Uncharted shoaling was observed in Francis Anchorage on February 14th, 2019 in position 57°08.95′N, 133°10.03′W. The charted depth for this location is 15 fathoms and the observed depths rapidly shallowed from 120 feet and ranged from 8 to 10 feet. The navigational charts for Francis Anchorage are based on pre-1900 Partial Bottom Coverage Surveys and in 1976 'shoaling to bare' was reported further into the anchorage. Mariners should transit this area with extreme caution and be aware of areas that may not be adequately charted. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 08/19

ALASKA - SOUTHCENTRAL - PRINCE WILLIAM SOUND - ESTHER ISLAND

OBSTRUCTION TO NAVIGATION: The 32' F/V SONG II has been reported sunk in position 60°47.76'N, 148°03.31'W. Mariners are requested to transit the area with caution and report any sightings to the Coast Guard Sector Anchorage Command Center at (907) 428-4100 or on VHF/FM channel 16.

LNM: 34/18

ALASKA - CENTRAL - BETHEL

993

994

995

996

998

OBSTRUCTION: The barge SHANKS ARK has been reported sunken and abandoned in Steamboat Slough on the Kuskokwim River, approximate position 60°47'15"N, 161°41'52"W. A portion of the vessel remains visible above the level of high-tide, but the majority of the vessel remains below the waterline. The vessel is marked by an all-round white light and one ball dayshape when Steamboat Slough is ice free but the markers are removed during freeze up as no hazards exists. The Coast Guard has actively monitored the proper marking of the vessel by the vessel's owner and operator since September 10, 2016. Coast Guard pollution investigators confirmed the vessel does not pose a substantial pollution threat to the environment. Mariners are requested to transit the area with caution and report any discrepancies with the vessel's marking to the Coast Guard. Questions/concerns should be directed to LT David Parker, Sector Anchorage Waterways Management, at (907) 428-4189.

LNM: 11/17

ALASKA – ALEUTIAN ISLANDS – AKUTAN ISLAND – AKUTAN HARBOR

UNKNOWN MARINE ANOMALY: An unknown marine anomaly was discovered during underwater survey operations in Akutan Harbor in position 54°07.70889'N, 165°46.38298W on the sea floor at a depth of 138 feet. This anomaly has not been positively identified. Mariners are requested to transit the area with caution. Questions/concerns should be directed to LT David Parker with the Coast Guard Sector Anchorage Waterways Management Branch at (907) 428-4189 or by email to david.n.parker@uscg.mil.

LNM: 03/18

ALASKA – SOUTHWESTERN – ALEUTIAN PENINSULA – BECHEVIN BAY

Shoaling has been reported at the bar along the Northern entrance to Bechevin Bay by a vessel with a draft of 10 feet that reported briefly grounding in seas running 6-8 feet. Mariners should take into account their vessel's draft, charted depth of water, tides and sea state when determining an appropriate under-keel clearance for a safe transit of this waterway. Mariners are requested to report any future groundings or significant variations from charted depth to the Coast Guard Sector Anchorage Command Center at (907) 428-4100 or on VHF/FM channel 16.

LNM: 17/18

997 ALASKA – SOUTHEAST – ICY STRAIT – NORTH INIAN PASSAGE

The currents in North Inian Passage and Glacier Bay have been observed at up to 3 knots above the NOAA published current predictions. Mariners should exercise caution when transiting the area. Questions/concerns should be directed to LT Bart Buesseler at (907) 271-3327 or by email to bart.o.buesseler@noaa.gov.

LNM: 36/17

ALASKA – SOUTHCENTRAL – SHELIKOF STRAIT – KINAK BAY

An uncharted rock has been reported in Kinak Bay in position 58°03.8′N, 154°25.3′W at a depth of approximately 3 fathoms. Mariners are advised to transit the area with extreme caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 28/19

999 ALASKA – SOUTHEAST – WRANGELL NARROWS

OSTRUCTION TO NAVIGATION: The P/C HEATHER ANN has sunk in Wrangell Narrows on the East side of the channel approximately 330 yards South of Wrangell Narrows Channel LT 16 (LLNR 22955). The most recent reported position was 56°37.25′N, 132°57.64′W. The P/C HEATHER ANN is a 52′ wood vessel and may be awash and barely visible at higher tides, exposed at lower tides, or relocated by the extreme current in the area. The vessel was marked with a single orange float. Mariners are requested to transit the area with extreme caution and report any changes in position to the Coast Guard Sector Juneau on VHF/FM channel 16 or by phone to (907) 463-2980.

LNM: 25/19

SECTION II - DISCREPANCIES

This section lists all reported and corrected discrepancies related to Aids to Navigation in this edition. A discrepancy is a change in the status of an aid to navigation that differs from what is published or charted.

DISCREPANCIES (FEDERAL AIDS)

LLNR	Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM End
984	NOAA Data Lighted Buoy 46001	ADRIFT	16013		50/21	
984.15	NOAA Data Lighted Buoy 46085	MISSING	16016	A121-23	29/23	
985	Cape Muzon Light	LT EXT	17400	J329-23	46/23	
1030	Cape Edgecumbe Light	LT EXT	17320	J099-23	14/23	
1105	Cape St. Elias Buoy 2	MISSING	16016	A175-23	41/23	
1131	NOAA Data Lighted Buoy 46061	MISSING	16700	A234-23	52/23	
1150	Seal Rocks Light	DAYMK MISSING	16680		44/21	
1260	Cape Greig Light	LT EXT/DAYMK DMGD	16011	A100-21	37/21	
1285	Cape Mohican Light	LT EXT	16006	A076-22	33/22	
1315	Point Romanof Light	STRUCT DEST		A153-24	36/24	
21850	Cape Chacon Light	DAYMK DMGD	17420	J095-22	31/22	
22025	Point McCartey Buoy 3	MISSING	17420	SEAK220-24	25/24	
22040	Nichols Passage East Channel Daybeacon 2	STRUCT DEST		J130-22	41/22	
22065	Metlakatla Boat Harbor Light 2	DAYMK DMGD	17420	J299-23	42/23	
22070	Metlakatla Inner Harbor Daybeacon 3	DAYMK DMGD	17420	J299-23	42/23	
22125	Walden Rock Light 6	REDUCED INT/STRUCT DMGD	17420	J292-23	42/23	
22150	California Rock Lighted Buoy 3	LT EXT		J335-23	47/23	
22155	Idaho Rock Lighted Buoy 4	LT EXT		J336-23	47/23	
22190	Pennock Island Reef Lighted Buoy PR	LT EXT		J339-23	47/23	
22195	Tongass Narrows Wreck Lighted Buoy WR6	OFF STA		SEAK239-24	27/24	
22270	Refuge Cove Daybeacon 3	STRUCT DEST		J143-22	43/22	
22430	Meyers Chuck Buoy 1	SINKING		SEAK235-24	27/24	
22510	Bushy Island Light	DAYMK DMGD		SEAK248-24	28/24	
22515	Snow Passage Lighted Buoy SP	LT EXT	17420	SEAK001	01/24	
22525	Bay Point Daybeacon BP	DAYMK DMGD	17360	J174-22	51/22	
22670	Blake Channel Light 1	STRUCT DEST/LT EXT	17360	J124-20	48/20	
22735	Mc Arthur Reef Lighted Bell Buoy MR	LT EXT	17360	SEAK245-24	28/24	
22863	Wrangell Narrows Daybeacon 4	STRUCT DEST		J113-21	41/21	
22875	Wrangell Narrows Tow Channel Buoy 1TC	MISSING		SEAK105-24	12/24	
22916	Wrangell Narrows Daybeacon 10A	STRUCT DEST		J128-21	47/21	
23210	Wrangell Narrows North Entrance Lighted Bell Buoy WN	LT EXT	17360	SEAK004-24	02/24	
23260	Cape Fanshaw Light	STRUCT DEST	17360	J081-22	26/22	
23280	Five Finger Light	LT EXT	17360	J010-23	02/23	
23285	Five Fathom Shoal Lighted Buoy F	LT EXT	17360	SEAK189-24	21/24	
23290	The Eye Opener Light	LT EXT	17360	SEAK296-24	34/24	
23305.1	Keku Strait Entrance Light	STRUCT DEST		J069-19	38/19	
23305.3	Keku Strait Daybeacon 4	STRUCT DEST		SEAK217-24	25/24	
23305.7	Keku Strait Daybeacon 10	MISSING		J148-13	32/13	
23305.9	Keku Strait Daybeacon 13	STRUCT DEST		J103-15	23/15	
23305.95	Keku Strait Buoy 14	MISSING		J288-23	41/23	
23306	Keku Strait Daybeacon 15	STRUCT DEST		J288-23	41/23	

23306.2	Keku Strait Daybeacon 18	STRUCT DEST		J288-23	41/23
23306.3	Keku Strait Daybeacon 19	STRUCT DEST		SEAK217-24	25/24
23306.7	Keku Strait Daybeacon 25	STRUCT DEST		J071-20	28/20
23306.8	Keku Strait Daybeacon 26	STRUCT DEST		SEAK217-24	25/24
23306.85	Keku Strait Daybeacon 27	STRUCT DEST		SEAK217-24	25/24
23307.05	Keku Strait Daybeacon 31	STRUCT DEST		J072-20	28/20
23307.6	Keku Strait Daybeacon 37	STRUCT DEST		J288-23	41/23
23307.7	Keku Strait Daybeacon 39	STRUCT DEST		J074-21	26/21
23307.8	Keku Strait Daybeacon 41	STRUCT DEST		SEAK217-24	25/24
23355	Portage Pass Daybeacon 11	STRUCT DEST	17360	J077-18	26/18
23455	Point Crowley Light	STRUCT DEST	17320	SEAK299-24	34/24
23510	Point Ellis Light	LT EXT	17320	J028-21	08/21
23530	Point Gardner Light	LT EXT	17320		34/24
23595	Hobart Bay Light 2	DAYMK MISSING	17360	J247-23	34/23
23600	Point Gambier Light	LT EXT	17360	J362-23	51/23
23785	Middle Point Light	LT EXT	17300	SEAK309-24	36/24
23860	Vanderbilt Reef Light	LT EXT	17300	SEAK305-24	35/24
23945.1	Favorite Reef B 2	MISSING	17300	SEAK281-24	33/24
24260	Elfin Cove Daybeacon 5	STRUCT DEST		J017-18	36/19
24300	Lisianski Inlet Daybeacon 4	STRUCT DEST	17300	J272/23	39/23
24330	Cape Muzon Light	LT EXT	17400	J329-23	46/23
24445	Tlevak Narrows Buoy 4	MISSING	17400	SEAK244-24	28/24
24545	Hermanos Islands Reef Lighted Buoy 8	LT EXT	17400	SEAK302-24	35/24
24575	Klawock Reef Lighted Buoy 1	LT EXT	17400	J017-23	03/23
24790	Dry Pass Daybeacon 3	STRUCT DEST		J072-18	23/18
24910	Cape Edgecumbe Light	LT EXT	17320	J099-23	14/23
24915	Vitskari Island Light	RAC INOP	17320	J211-23	29/23
24948	Indian River Flats Lighted Buoy 2	LT EXT		J032-20	09/20
25025	Sitka Breakwater Light 7	LT EXT		SEAK249-24	28/24
25355	Dippy Island Rock Daybeacon 3	STRUCT DEST		J112-22	35/22
25535	Johnstone Point Light	LT EXT		A073-23	17/23
25550	Hanks Island Rock Light 5	STRUCT DEST		A233-23	52/23
25575	Orca Inlet Channel Light 12	STRUCT DEST	16700	A020-24	06/24
25646	NOAA Data Lighted Buoy 46060	ADRIFT	16700	A009-23	04/23
25662	Bligh Reef Light	DAYMK DMGD		A071-24	17/24
25662	Bligh Reef Light	LT EXT		A150-24	36/24
25725	Entrance Point Light 12	LT EXT		A144-24	32/24
25735	Entrance Island Light 14	LT EXT	16700	A124-24	28/24
25823	Valdez Security Zone Lighted Buoy A	LT EXT		A230-23	01/23
25824	Valdez Security Zone Lighted Buoy B	LT EXT		A231-23	52/23
25982	NOAA Data Lighted Buoy 46076	OFF STA	16700	A 023-24	07/24
25982	NOAA Data Lighted Buoy 46076	OFF STA	16700	A060-20	23/20
26020	Seward East Breakwater Light 2	DAYMK DMGD		A146-24	34/24
26075	Chugach Passage Lighted Buoy 2	MISSING	16640	A047-24	13/24
26095	Perl Rock Light	LT EXT	16640	A085-24	19/24
26245	Halibut Point Daybeacon	STRUCT DEST	16640	A103-24	22/24
26560	Hanin Rock Light	LT EXT	16580	A035-23	10/23
26665	Woody Island Channel Buoy 6	MISSING		A142-24	30/24
26910	Aiaktalik Island Light 5	DAYMK DMGD	16580	A133-20	49/20

26960	Harvester Island Spit Light 2	DAYMK DMGD	16580	A159-23	37/23	
27000	Northeast Arm Light 1	STRUCT DEST	16580	A143-21	50/21	
27025	Dry Spruce Island Rock Light 7	LT EXT	16580	A008-22	06/22	
27155	Goloi Sandspit Light 3	LT EXT/STRUCT DMGD	16540	A177-23	41/23	
27250	Bechevin Bay Entrance Buoy BB	MISSING	16520	A130-21	43/21	
27410	Isanotski Strait Light 3	LT EXT	16520	A222-23	50/23	
27465	Rocky Point Shoal Lighted Buoy RP	LT EXT		A120-24	25/24	
27505	Bailey Ledge Light	LT EXT/STRUCT DMGD	16520	A122-20	43/20	
27542	Sweeper Cove Range Front Light	DAYMK DMGD		A223-23	50/23	
27827	St. George Harbor Entrance Light 1	STRUCT DEST		A118-22	42/22	
27872	Okwega Pass Light OP	STRUCT DEST	16240	A149-23	36/23	
27895	Point Romanof Light	STRUCT DEST	16240	A153-24	36/24	
27972	Nome Harbor Range Front Light	LT EXT	16200	A145-24	33/24	
REPANCIES	(FEDERAL AIDS) CORRECTED					
REPANCIES LLNR	(FEDERAL AIDS) CORRECTED Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM End
LLNR	Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM End
LLNR REPANCIES	Aid Name 5 (PRIVATE AIDS)					
LLNR REPANCIES LLNR	Aid Name (PRIVATE AIDS) Aid Name	Status	Chart No. Chart No.	BNM Ref.	LNM St	LNM End
LLNR EPANCIES LLNR 22201	Aid Name F (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light	Status STRUCT DEST		BNM Ref. J202-15	LNM St 47/15	
LLNR LLNR 22201 22202	Aid Name 6 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light	Status STRUCT DEST STRUCT DEST		BNM Ref. J202-15 J203-15	LNM St 47/15 47/15	
LLNR EEPANCIES LLNR 22201 22202 22203	Aid Name F (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light	Status STRUCT DEST STRUCT DEST STRUCT DEST		BNM Ref. J202-15 J203-15 J204-15	LNM St 47/15 47/15 47/15	
LLNR LLNR 22201 22202 22203 23908	Aid Name F (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2)	Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT		BNM Ref. J202-15 J203-15 J204-15 J175-14	LNM St 47/15 47/15 47/15 38/14	
LLNR EEPANCIES LLNR 22201 22202 22203	Aid Name F (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light	Status STRUCT DEST STRUCT DEST STRUCT DEST		BNM Ref. J202-15 J203-15 J204-15	LNM St 47/15 47/15 47/15	

DISCREPANCIES (PRIVATE AIDS	CORRECTED

Whittier Passenger Dock Lights (2)

4th of July Channel LT 1

Seward Marine Dock Light

LLNR	Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM End
LLIVIX	Ald Name	Status	Chart No.	DIVITINGI.	LINITIOL	LINI'I LIIU

LT EXT

LT EXT

STRUCT DEST

None

PLATFORM DISCREPANCIES

25893

26005

26010

Name Position BNM Ref. LNM St LNM End Status

None

PLATFORM DISCREPANCIES CORRECTED

Name Position BNM Ref. LNM St LNM End Status

None

SECTION III - TEMPORARY CHANGES and TEMPORARY CHANGES CORRECTED

This section contains temporary changes and corrections to Aids to Navigation for this edition. When charted aids are temporarily relocated for dredging, testing, evaluation, or marking an obstruction, a temporary correction shall be listed in Section IV giving the new position.

TEMPORARY CHANGES

LLNR	Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM End
22329	Moser Bay Coast Guard Lighted Mooring	DISCONTINUED	17420		14/24	
	Buoy					

20/10

23/23

20/22

A031-10

A097-23

	23355	Portage Pass Daybeaco	n 11	TRUB		17360	J093-18	30/18	
	23790	Horse Shoal Light 1		DISCONTI	NUED	17300	J102-19	51/19	
	23945	Favorite Reef Light 2		DISCONTI	NUED	17300	J152-23	24/23	
	24065	Tenakee Inlet Entrance	Light 1	DISCONTI	NUED	17300	J172-22	50/22	
	24957	Mitchell Rock Daybeaco	n	DISCONTI	NUED		J022-17	04/17	
	25025.5	Japonski Island Daybea	con 2	DISCONTI	NUED	17320	J196-16	49/16	
	25575	Orca Inlet Channel Ligh	t 12	TRLB		16700	A138-24	30/24	
	25647	NOAA Data Lighted Buo	y 46081	DISCONTI	NUED	16700	A126-19	46/19	
	25805	Port Valdez Coast Guard	d Mooring Buoy	DISCONTI	NUED		A095-18	33/18	
EMPOF	RARY CHANG	SES CORRECTED							
	LLNR	Aid Name		Status		Chart No.	BNM Ref.	LNM St	LNM End
ne									
_ATFOI	RM TEMPOR	ARY CHANGES							
Nar	ne		Status			Position	BNM Ref.	LNM St	LNM End
ne									
		ARY CHANGES CORREC							
Nar None	ne		Status			Position	BNM Ref.	LNM St	LNM End
		s	ECTION IV -	CHART (CORRECT	TIONS			
his secti	This section contains o	on contains corrections to fe	ederally and private	ely maintaine	d Aids to Nav	gation, as well as	NOS corrections	art only.	
is up to	on contains of the mariner to	on contains corrections to fe orrective actions affecting of decide which chart(s) are	ederally and private chart(s). Correction to be corrected. T	ely maintaine ons appear nu The following o	d Aids to Nav merically by c example expla	igation, as well as hart number, and ains individual eler	pertain to that cha	art only.	ition.
is up to hart	on contains c	on contains corrections to fe orrective actions affecting o	ederally and private chart(s). Correction to be corrected. Totice Horizon	ely maintaine ons appear nu The following o	d Aids to Nav	gation, as well as hart number, and	pertain to that change of a typical	art only.	tion.
is up to hart umber . 2327	on contains of the mariner to Chart Edition . 91st Ed.	on contains corrections to feorective actions affecting condition affecting condition chart(s) are Edition Last Local North Date to Mariners	ederally and private chart(s). Correction to be corrected. To lotice Horizon Datum F I 26/97 NAD 8	rely maintaine ons appear nu The following of tal Reference	d Aids to Nav merically by c example expla Source of	gation, as well as hart number, and ains individual eler Current Local	pertain to that change of a typical	art only.	ition.
is up to hart umber l 2327 hart Title Ma	on contains of the mariner to Chart Edition . 91st Ed. e: NY-NJ-NEVain Panel 224	on contains corrections to feorrective actions affecting conditions affecting to decide which chart(s) are Edition Last Local North Date to Mariners	ederally and private chart(s). Correction to be corrected. To lotice Horizon Datum F I 26/97 NAD 8	rely maintaine ons appear nu The following of tal Reference	d Aids to Nav merically by dexample explained Source of Correction	igation, as well as hart number, and ains individual eler Current Local Notice to Mari . I	pertain to that ch nents of a typical ners	art only.	tion.
chart lumber 2327 chart Title Ma Femp)	con contains of the mariner to the mariner to Chart Edition . 91st Ed. e: NY-NJ-NE\ ain Panel 224 ADD NA . Gree ective	on contains corrections to feorective actions affecting of decide which chart(s) are Edition Last Local N Date to Mariners . 19-APR-97 Last LNM: W YORK HARBOR - RARIO	ederally and private chart(s). Correction to be corrected. To lotice Horizon Datum F I 26/97 NAD 8	rely maintaine ons appear nu The following of tal Reference	d Aids to Nav merically by dexample explained Source of Correction	igation, as well as hart number, and ains individual eler Current Local Notice to Mari . 27/97	pertain to that ch nents of a typical ners	art only.	tion.
is up to Chart lumber 2327 Chart Titli Ma Temp) Corre Act	con contains of the mariner to the mariner to Edition	on contains corrections to feorective actions affecting to decide which chart(s) are Edition Last Local N Date to Mariners . 19-APR-97 Last LNM: W YORK HARBOR - RARIT 5 NEW YORK HARBOR TIONAL DOCK CHANNEL n can . Object of Corrective Action he chart correction action is	ederally and private chart(s). Correction to be corrected. To lotice Horizont Datum F	rely maintaine ons appear nu The following of tal Reference 	d Aids to Nav merically by dexample expla Source of Correction . . CGD01 at 40-41-09 . Position	gation, as well as hart number, and ains individual eler Current Local Notice to Mari . 27/97 0.001N 074-02-48 are given in degre	pertain to that chenents of a typical ners 3.001W	art only. chart correc	
chart lumber l	on contains of the mariner to the mariner to Chart Edition I . 91st Ed. e: NY-NJ-NE\ain Panel 224 ADD NA I . Gree ective ion dicates that to of light sectore	on contains corrections to feorective actions affecting to decide which chart(s) are Edition Last Local N Date to Mariners . 19-APR-97 Last LNM: W YORK HARBOR - RARIT 5 NEW YORK HARBOR TIONAL DOCK CHANNEL n can . Object of Corrective Action ne chart correction action is a re toward the light from	ederally and private chart(s). Correction to be corrected. To tice Horizon Datum F. I 26/97 NAD 8 FAN RIVER BUOY 3	rely maintaine ons appear nu The following of tal Reference 33	d Aids to Nav merically by c example expla Source of Correction . . CGD01 at 40-41-09 . Position and bearings f lights is expl	gation, as well as hart number, and ains individual eler Current Local Notice to Mari . 27/97 0.001N 074-02-48 are given in degre	pertain to that chenents of a typical ners 3.001W	art only. chart correc	noted.
chart lumber	con contains of the mariner to the mariner to Edition	on contains corrections to feorective actions affecting to decide which chart(s) are Edition Last Local N Date to Mariners . 19-APR-97 Last LNM: W YORK HARBOR - RARIT 5 NEW YORK HARBOR TIONAL DOCK CHANNEL n can . Object of Corrective Action he chart correction action is a re toward the light from	ederally and private chart(s). Correction to be corrected. To lotice Horizont Datum F	rely maintaine ons appear nu The following of tal Reference	d Aids to Nav merically by dexample expla Source of Correction . . CGD01 at 40-41-09 . Position	gation, as well as hart number, and ains individual eler Current Local Notice to Mari . 27/97 0.001N 074-02-48 are given in degre	pertain to that chenents of a typical ners 3.001W	art only. chart correc	
chart little was to be chart and the chart a	con contains of the mariner to the mariner to Chart Edition I . 91st Ed. e: NY-NJ-NE\ain Panel 224 ADD NA I . Gree ective ion dicates that to of light sector 9th the: North Pace	on contains corrections to feorective actions affecting to decide which chart(s) are Edition Last Local N Date to Mariners . 19-APR-97 Last LNM: W YORK HARBOR - RARIT 5 NEW YORK HARBOR TIONAL DOCK CHANNEL n can . Object of Corrective Action he chart correction action is are toward the light from Ed. 01-DEC-15	ederally and private chart(s). Correction to be corrected. To tice Horizont Datum F	rely maintaine ons appear nu The following of tal Reference	d Aids to Nav merically by dexample expla Source of Correction . . CGD01 at 40-41-09 . Position and bearings f lights is expl	gation, as well as hart number, and ains individual eler Current Local Notice to Mari . 27/97 0.001N 074-02-48 are given in degreessed in nautical	pertain to that chenents of a typical ners 3.001W	art only. chart correc	noted.
is up to thart illumber I 2327 hart Title Ma Corre Act Femp) in earings 0 Chart Title	con contains of the mariner to the mariner to Edition Chart Edition . 91st Ed. e: NY-NJ-NEVain Panel 224 ADD NA . Gree ective ion dicates that to flight sector 9th the: North Pac Main Panel 2	en contains corrections to feorrective actions affecting of decide which chart(s) are Edition Last Local N Date to Mariners . 19-APR-97 Last LNM: W YORK HARBOR - RARIT 5 NEW YORK HARBOR TIONAL DOCK CHANNEL n can . Object of Corrective Action The chart correction action is a are toward the light from Ed. 01-DEC-15 cific Ocean (eastern part) 400 NORTH PACIFIC OC N No new editions of chart Sep-24. Comparable or I coverage is available. Se Nautical Charts" in Section	ederally and private chart(s). Correction to be corrected. To tice Horizon Datum F	rely maintaine ons appear nu fe following of tal Reference	d Aids to Nav merically by c example expla Source of Correction . I . CGD01 at 40-41-0s I . Position and bearings f lights is expla (AD 83 (Side: A canceled on (onal Chart (EN and Raster st of all cance	igation, as well as hart number, and ains individual eler Current Local Notice to Mari . 27/97 0.001N 074-02-48 are given in degreessed in nautical in the second in	pertain to that chenents of a typical ners 3.001W	art only. chart correc	noted.
is up to chart flumber	con contains of the mariner to the marine to the mariner to the m	en contains corrections to feorrective actions affecting of decide which chart(s) are Edition Last Local N Date to Mariners . 19-APR-97 Last LNM: W YORK HARBOR - RARIT 5 NEW YORK HARBOR TIONAL DOCK CHANNEL n can . Object of Corrective Action The chart correction action is a retoward the light from Ed. 01-DEC-15 cific Ocean (eastern part) 400 NORTH PACIFIC OC N No new editions of chart Sep-24. Comparable or I coverage is available. Se Nautical Charts" in Section NOAA charts is at https:	ederally and private chart(s). Correction to be corrected. To tice Horizon Datum F	rely maintaine ons appear nurbe following of tal Reference	d Aids to Nav merically by c example expla Source of Correction . . CGD01 at 40-41-05 . Position and bearings f lights is explained AD 83 //Side: A canceled on (anal Chart (EN and Raster st of all cance ole.shtml.	igation, as well as hart number, and ains individual eler Current Local Notice to Mari . 27/97 0.001N 074-02-48 are given in degreessed in nautical in the second in	pertain to that chenents of a typical ners 3.001W	art only. chart correc	noted. 36/24
chart Title Act Temp) in Bearings Chart Title Act Temp) in Correct Co	con contains of the mariner to the mariner to the mariner to Chart Edition . 91st Ed. e: NY-NJ-NEI Edin Panel 224 ADD NA . Gree ective ion dicates that to flight secton 9th the: North Pace Main Panel 2 LAST EDITION 10th Edit Edit Edit Edit Edit Edit Edit Edit	en contains corrections to feorrective actions affecting of decide which chart(s) are Edition Last Local N Date to Mariners . 19-APR-97 Last LNM: W YORK HARBOR - RARIT 5 NEW YORK HARBOR TIONAL DOCK CHANNEL n can . Object of Corrective Action The chart correction action is a are toward the light from Ed. 01-DEC-15 cific Ocean (eastern part) 400 NORTH PACIFIC OC N No new editions of chart Sep-24. Comparable or I coverage is available. Se Nautical Charts" in Section	ederally and private chart(s). Correction to be corrected. To tice Horizon Datum F	rely maintaine ons appear nurhe following of tal Reference	d Aids to Nav merically by c example expla Source of Correction . . CGD01 at 40-41-05 . Position and bearings f lights is expla IAD 83 Side: A canceled on (and Chart (EN and Raster st of all cance ole.shtml.	igation, as well as hart number, and ains individual eler Current Local Notice to Mari . 27/97 0.001N 074-02-48 are given in degreessed in nautical in the company of	pertain to that chenents of a typical ners 3.001W	art only. chart correc	noted.

coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml.

	fic Ocean West Coast O	Last LNM: 31/22 f North America Mexicar FO DIXON ENTRANCE. F		rance	36/24
LAST EDITION	Sep-24. Comparable or I coverage is available. Se Nautical Charts" in Section	501 will be published. It varger scale Electronic Navier "Cancellation of NOAA Por I of this LNM for details//www.charts.noaa.gov/M	igational Chart (ENC) aper and Raster . A list of all canceled	NOS 	
513 10th ChartTitle: Bering Sea	Southern Part	Last LNM: 26/22 HERN PART Page/Si	NAD 83		36/24
Maii i aliei 24	OU DEMING OFF GOO!	TIERRY ART: Tage/or	ue	NOS	
LAST EDITION	Sep-24. Comparable or I coverage is available. Se Nautical Charts" in Section	: 513 will be published. It warger scale Electronic Navi ee "Cancellation of NOAA Poor I of this LNM for details //www.charts.noaa.gov/Mo	igational Chart (ENC) laper and Raster s. A list of all canceled		
514 9th E ChartTitle: Bering Sea	Northern Part	Last LNM: 01/18	NAD 83		36/24
Main Panel 24	04 BERING SEA NORTH	IERN PART Page/Sid	le: -	NOS	
LAST EDITION	Sep-24. Comparable or I coverage is available. Se Nautical Charts" in Section	: 514 will be published. It warger scale Electronic Navi e "Cancellation of NOAA Por I of this LNM for details //www.charts.noaa.gov/Mo	igational Chart (ENC) aper and Raster A list of all canceled	NOS	
	rica West Coast San Die	Last LNM: 34/22 ego to Aleutian Islands a UTIAN ISLANDS AND HA		nge/Side: A NOS	36/24
LAST EDITION	Sep-24. Comparable or I coverage is available. Se Nautical Charts" in Section	: 530 will be published. It warger scale Electronic Navi ee "Cancellation of NOAA Por I of this LNM for details //www.charts.noaa.gov/Mo	igational Chart (ENC) aper and Raster . A list of all canceled	NOS	
16003 19th ChartTitle: Arctic Coa	01110110	Last LNM: 48/18	NAD 83		36/24
	08 ARCTIC COAST	Page/Side: -			
LAST EDITION	04-Sep-24. Comparable (ENC) coverage is availa Nautical Charts" in Section	: 16003 will be published. I or larger scale Electronic N ble. See "Cancellation of N on I of this LNM for details //www.charts.noaa.gov/M	Navigational Chart IOAA Paper and Raster s. A list of all canceled	NOS 	
16004 13th ChartTitle: Point Barro	Ed. 01-MAY-15 ow to Herschel Island	Last LNM: 20/15	NAD 83		36/24
Main Panel 24	09 POINT BARROW TO	HERSCHEL ISLAND. Pa	ige/Side: A	NOC	
LAST EDITION	04-Sep-24. Comparable (ENC) coverage is availa Nautical Charts" in Section	: 16004 will be published. I or larger scale Electronic N ble. See "Cancellation of N on I of this LNM for details //www.charts.noaa.gov/M	Navigational Chart IOAA Paper and Raster s. A list of all canceled	NOS	
16005 12th		Last LNM: 51/19	NAD 83		36/24
•	ce of Wales to Pt. Barrow 10 CAPE PRINCE OF W	<i>ı</i> ALES TO POINT BARRO	W Page/Side: -		
	No new editions of chart 04-Sep-24. Comparable	: 16005 will be published. I or larger scale Electronic N ble. See "Cancellation of N	It will be canceled on Navigational Chart	NOS 	

Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml.

16006 38th Ed. 36/24 01-NOV-18 Last LNM: 19/22 **NAD 83** ChartTitle: Bering Sea-eastern part;St. Matthew Island, Bering Sea;Cape Etolin, Achorage, Nunivak Island Main Panel 2411 BERING SEA EASTERN PART - -. Page/Side: -NOS LAST EDITION No new editions of chart 16006 will be published. It will be canceled on 04-Sep-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml. 16011 39th Ed. 36/24 01-DEC-15 Last LNM: 19/22 **NAD 83** ChartTitle: Alaska Peninsula and Aleutian Islands to Seguam Pass Main Panel 2415 ALASKA PENINSULA & ALEUTIAN ISLANDS - SEGUAM PASS. Page/Side: A NOS LAST EDITION No new editions of chart 16011 will be published. It will be canceled on 04-Sep-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml. 16012 36/24 24th Ed. 01-DEC-15 Last LNM: 26/22 **NAD 83** ChartTitle: Aleutian Islands Amukta Island to Attu Island Main Panel 2416 AMUKTA ISLAND TO ATTU ISLAND. Page/Side: A NOS LAST EDITION No new editions of chart 16012 will be published. It will be canceled on 04-Sep-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml. 16013 36/24 31st Ed. 01-JUN-15 Last LNM: 34/22 **NAD 83** ChartTitle: Cape St. Elias to Shumagin Islands; Semidi Islands Main Panel 2417 CAPE ST. ELIAS TO SHUMAGIN ISLANDS. Page/Side: A NOS LAST EDITION No new editions of chart 16013 will be published. It will be canceled on 02-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml. 16016 22nd Ed. 01-AUG-12 36/24 **NAD 83** Last LNM: 22/22 ChartTitle: Dixon Entrance to Cape St. Elias Main Panel 2419 DIXON ENTRANCE TO CAPE ST. ELIAS. Page/Side: N/A NOS LAST EDITION No new editions of chart 16016 will be published. It will be canceled on 02-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml. 16200 16th Ed. 01-DEC-18 Last LNM: 51/19 **NAD 83** 36/24 ChartTitle: Norton Sound; Golovnin Bay Main Panel 2449 NORTON SOUND TO BERING STRAIT - -. Page/Side: -NOS LAST EDITION No new editions of chart 16200 will be published. It will be canceled on 30-Oct-24, Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml. 16220 7th Ed. 01-DEC-18 Last LNM: 51/18 **NAD 83** 36/24 ChartTitle: Bering Sea St. Lawrence Island to Bering Strait Main Panel 2571 BERING SEA ST. LAWRENCE ISLAND TO BERING STRAIT - -. Page/Side: -NOS LAST EDITION No new editions of chart 16220 will be published. It will be canceled on 30-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled

16240 11th Ed. 01-MAY-15 Last LNM: 38/21 NAD 83 ChartTitle: Cape Ramonzof to St. Michael; St. Michael Bay; Approaches to Cape Ramanzof Main Panel 2454 CAPE ROMANZOF TO ST. MICHAEL. Page/Side: A	NOS	36/24
LAST EDITION No new editions of chart 16240 will be published. It will be canceled on 30-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml.		
16300 10th Ed. 01-NOV-13 Last LNM: 38/21 NAD 83 ChartTitle: Kuskokwim Bay;Goodnews Bay Main Panel 2457 KUSKOKWIM BAY. Page/Side: N/A		36/24
LAST EDITION No new editions of chart 16300 will be published. It will be canceled on 30-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml.	NOS 	
16380 16th Ed. 01-FEB-15 Last LNM: 05/15 NAD 83 ChartTitle: Pribilof Islands		36/24
Main Panel 2465 PRIBILOF ISLANDS. Page/Side: A LAST EDITION No new editions of chart 16380 will be published. It will be canceled on 30-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml.	NOS	
16420 12th Ed. 01-DEC-15 Last LNM: 22/16 NAD 83 ChartTitle: Near Islands Buldir Island to Attu Island Main Panel 2468 NEAR ISLANDS BULDIR ISLAND TO ATTU ISLAND. Page/Side: A		36/24
LAST EDITION No new editions of chart 16420 will be published. It will be canceled on 30-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml.	NOS 	
16421 11th Ed. 01-MAY-15 Last LNM: 22/16 NAD 83 ChartTitle: Ingenstrem Rocks to Attu Island Main Panel 2469 NEAR ISLANDS INGENSTREM ROCKS TO ATTU I. Page/Side: A	No.	36/24
LAST EDITION No new editions of chart 16421 will be published. It will be canceled on 30-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml.	NOS 	
16440 16th Ed. 01-DEC-15 Last LNM: 26/22 NAD 83 ChartTitle: Rat Islands Semisopochnoi Island to Buldir I. Main Panel 2480 RAT ISLANDS. Page/Side: A		36/24
LAST EDITION No new editions of chart 16440 will be published. It will be canceled on 30-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml.	NOS 	
16460 17th Ed. 01-DEC-15 Last LNM: 49/15 NAD 83 ChartTitle: Igitkin Is. to Semisopochnoi Island Main Panel 2484 IGITKIN ISL AND TO SEMISOPOCHNOI ISL AND Page/Side: A		36/24
Main Panel 2484 IGITKIN ISLAND TO SEMISOPOCHNOI ISLAND. Page/Side: A	NOS	
LAST EDITION No new editions of chart 16460 will be published. It will be canceled on 30-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml.		

	Ed. 01-DEC-15 nd to Igitkin Island;Finch 99 AMUKTA ISLAND TO	-		ilia Island	36/24
	No new editions of chart 30-Oct-24. Comparable o (ENC) coverage is availab Nautical Charts" in Section	Ü	It will be canceled on lavigational Chart IOAA Paper and Raster s. A list of all canceled	NOS 	
16500 12th ChartTitle: Unalaska I. Main Panel 25		Last LNM: 49/15 JKTA I. Page/Side: A	NAD 83		36/24
LAST EDITION	(ENC) coverage is available Nautical Charts" in Section	16500 will be published. I or larger scale Electronic Nole. See "Cancellation of Non I of this LNM for details /www.charts.noaa.gov/Mo	lavigational Chart IOAA Paper and Raster s. A list of all canceled	NOS 	
	Ed. 01-DEC-15 d Akutan Passes and ap 18 UNIMAK AND AKUTA		NAD 83		36/24
	No new editions of chart 04-Dec-24. Comparable ((ENC) coverage is availal Nautical Charts" in Section	· ·	It will be canceled on Navigational Chart IOAA Paper and Raster S. A list of all canceled	NOS 	
•	Ed. 01-OCT-10 Islands to Sanak Islands 28 SHUMAGIN ISLANDS	•	NAD 83 Page/Side: N/A	NOS	36/24
LAST EDITION	(ENC) coverage is available Nautical Charts" in Section	16540 will be published. In larger scale Electronic Note: See "Cancellation of Nor I of this LNM for details/www.charts.noaa.gov/Mo	Navigational Chart IOAA Paper and Raster s. A list of all canceled		
•	Ed. 01-APR-15 o Cape Kumlik, Alaska P 44 WIDE BAY TO CAPE		NAD 83		36/24
LAST EDITION	(ENC) coverage is available Nautical Charts" in Section	16568 will be published. I or larger scale Electronic N ole. See "Cancellation of N on I of this LNM for details /www.charts.noaa.gov/M	Navigational Chart IOAA Paper and Raster s. A list of all canceled	NOS	
	Ed. 01-MAR-15 Ind;Southwest Anchorag 46 KODIAK ISLAND. Pa	•	NAD 83		36/24
LAST EDITION	(ENC) coverage is available Nautical Charts" in Section	16580 will be published. I or larger scale Electronic Nole. See "Cancellation of Non I of this LNM for details /www.charts.noaa.gov/Mo	Navigational Chart IOAA Paper and Raster s. A list of all canceled	NOS	
16640 25th ChartTitle: Cook Inlet- Main Panel 25		Last LNM: 07/20 IERN PART. Page/Side:	NAD 83 N/A		36/24
LAST EDITION	(ENC) coverage is available Nautical Charts" in Section	16640 will be published. I or larger scale Electronic N ole. See "Cancellation of N on I of this LNM for details /www.charts.noaa.gov/M	Navigational Chart IOAA Paper and Raster s. A list of all canceled	NOS 	
16660 31st ChartTitle: Cook Inlet-		Last LNM: 07/20	NAD 83		36/24

Main Panel 25	79 COOK INLET NORTH	IERN PART. Page/Side	: N/A	NOC	
LAST EDITION	No new editions of chart 04-Dec-24. Comparable of (ENC) coverage is availal Nautical Charts" in Section NOAA charts is at https:/	or larger scale Electronic ble. See "Cancellation of I on I of this LNM for detail	Navigational Chart NOAA Paper and Raster s. A list of all canceled	NOS 	
	Ed. 01-JUN-15 gton to East Chugach Isl 92 POINT ELRINGTON T		NAD 83 Page/Side: A		36/24
LAST EDITION	No new editions of chart 04-Dec-24. Comparable ((ENC) coverage is availal Nautical Charts" in Sectio NOAA charts is at https:/	or larger scale Electronic ble. See "Cancellation of I on I of this LNM for detail	Navigational Chart NOAA Paper and Raster s. A list of all canceled	NOS 	
16700 32nd ChartTitle: Prince Will	*	Last LNM: 32/20	NAD 83		36/24
	97 PRINCE WILLIAM SO	UND. Page/Side: N/A			
LAST EDITION	No new editions of chart 04-Dec-24. Comparable ((ENC) coverage is availal Nautical Charts" in Sectio NOAA charts is at https:/	or larger scale Electronic ble. See "Cancellation of I on I of this LNM for detail	Navigational Chart NOAA Paper and Raster s. A list of all canceled	NOS 	
16760 11th ChartTitle: Cross Sou	nd to Yakutat Bay	Last LNM: 34/20	NAD 83		36/24
Main Panel 26	13 CROSS SOUND TO Y	AKUTAT BAY. Page/Si	ide: A	NOS	
LAST EDITION	No new editions of chart 04-Dec-24. Comparable of (ENC) coverage is availal Nautical Charts" in Section NOAA charts is at https:/	or larger scale Electronic ble. See "Cancellation of I on I of this LNM for detail	Navigational Chart NOAA Paper and Raster s. A list of all canceled		
	Ed. 01-OCT-12 Passage to Cross Sound 17 STEPHENS PASSAG		NAD 83	ւL. Page/Side: N/A	36/24
LAST EDITION	No new editions of chart 04-Dec-24. Comparable of (ENC) coverage is availal Nautical Charts" in Sectio NOAA charts is at https:/	or larger scale Electronic ble. See "Cancellation of I on I of this LNM for detail	Navigational Chart NOAA Paper and Raster s. A list of all canceled	NOS	
17320 20th ChartTitle: Coronation	Ed. 01-FEB-17 I Island to Lisianski Strai	Last LNM: 09/22 t	NAD 83		36/24
	No new editions of chart 04-Dec-24. Comparable of (ENC) coverage is availal Nautical Charts" in Section NOAA charts is at https:/	17320 will be published. or larger scale Electronic ble. See "Cancellation of l on I of this LNM for detail	It will be canceled on Navigational Chart NOAA Paper and Raster is. A list of all canceled	NOS 	
	Ed. 01-JUN-15 nd to Midway Islands, inc 79 ETOLIN ISL TO MIDW	•	• •	Side: A	36/24
LAST EDITION	No new editions of chart 04-Dec-24. Comparable ((ENC) coverage is availal Nautical Charts" in Sectio NOAA charts is at https:/	or larger scale Electronic ble. See "Cancellation of I on I of this LNM for detail	Navigational Chart NOAA Paper and Raster s. A list of all canceled	NOS 	-
17400 19th	Ed. 01-JUL-20 ance to Chatham Strait	Last LNM: 28/20	NAD 83		36/24
	15 DIXON ENTRANCE T	O CHATHAM STRAIT	Page/Side: -	NOS	

NOS

LAST EDITION $\,$ No new editions of chart 17400 will be published. It will be canceled on

04-Dec-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml.

17420 29th Ed. 01-FEB-13 Last LNM: 34/18 NAD 83

36/24

ChartTitle: Hecate Strait to Etolin Island, including Behm and Portland Canals

NOS

Main Panel 2729 HECATE STRAIT TO ETOLIN ISLAND. Page/Side: N/A

LAST EDITION No new editions of chart 17420 will be published. It will be canceled on 04-Dec-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled

NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml.

OIL RIG MOVEMENT

Drill Rigs/Vessels Removed

<u>Latitude</u> <u>Longitude</u> <u>Block</u> <u>Rigs/Vessel</u> <u>Chart</u> <u>Type</u>

Drill Rigs/Vessels Established

Latitude Longitude Block Rigs/Vessel Chart Type Status

None

SECTION V - ADVANCE NOTICES

This section contains advance notice of approved projects, changes to aids to navigation, or upcoming temporary changes such as dredging, etc.

Mariners are advised to use caution while transiting these areas.

SUMMARY OF ADVANCED APPROVED PROJECTS

Approved Project(s)
None

Project Date
Ref. LNM

Advance Notice(s)

690 ALASKA – SOUTHEAST – SITKA

The Coast Guard intends to rename and upgrade Japonski Island Buoy 2 (LLNR 25025.51) to Japonski Island Lighted Buoy 2 (LLNR 25025.51) with a red flash every 4 seconds (R 4s). Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 38/20

Status

ALASKA - SOUTHEAST - STEPHENS PASSAGE

The Coast Guard is intends to publish on charts and in the Light List an obscured sector for Five Finger Light (LLNR 23280). The obscured sector is from 332° – 352° true. This obscured sector currently exists for the aid. Mariners with comments or concerns are requested to contact Todd Buck with the Coast Guard District 17 Waterways Management Office at 907-463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 24/24

SECTION VI - PROPOSED CHANGES

Periodically, the Coast Guard evaluates its system of aids to navigation to determine whether the conditions for which the aids to navigation were established have changed. When changes occur, the feasibility of improving, relocating, replacing, or discontinuing aids are considered. This section contains notice(s) of non-approved, proposed projects open for comment. SPECIAL NOTE: Mariners are requested to respond in writing to the District office unless otherwise noted (see banner page for address).

PROPOSED WATERWAY PROJECTS OPEN FOR PUBLIC COMMENT

Proposed Project(s) Closing Docket No. Ref. LNM

None

Proposed Change Notice(s)

ALASKA - WESTERN - NORTON SOUND - GOLOVIN BAY

The Coast Guard is proposing adding navigational aids within Golovin Bay. These aids may include Lights, Daybeacons, or buoys. Mariners are requested to provide recommendations on locations that would facilitate safe navigation within Golovin Bay. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

04 September 2024

LNM: 26/18

SECTION VII - GENERAL

This section contains information of general concern to the Mariners. Mariners are advised to use caution while transiting these areas.

59 ALASKA – SOUTHCENTRAL – COOK INLET – HOMER HARBOR

Alaska Marine Excavation, LLC. will be conducting dredging operations in the Homer Harbor Entrance and USCG Hickory berth starting April 15 2024 thru May 1st 2024 and resuming on September 1st 2024 thru October 11th, 2024. Dredging operations will continue 24 hours a day. The dredge COMMANDER is a 58' cutter head suction dredge, red and yellow in color, with a partially submerged pipeline. The pipeline will be marked where it exits the harbor on the beach and the pipeline's anchors will be marked by buoys. The dredge COMMANDER and tug Growler will be working on VHF/FM channel 79 and monitoring VHF/FM channels 13 and 16. Questions/concerns can also be directed to Brok Shafer with Alaska Marine Excavation, LLC at (907) 399-4549 or by email to brok@akmx.com.

LNM: 13/24

159 ALASKA - SOUTHEASTERN - LISIANSKI INLET

The Lisianski Inlet Daybeacon 4 was destroyed. A temporary Unlighted Buoy has been relocated to 58° 02-06.520N 136° 21-54.860W to best mark waterway. Unit will plan for permanaent correction weather and operations permitting. All mariners are reminded to exercise caution when transiting the area. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

Chart 17300 LNM: BNM J

273-23

SECTION VIII - LIGHT LIST CORRECTIONS

An Asterisk *, indicates the column in which a correction has been made to new information

(1) (2)(7)(8)(3)(4)(5) (6)Name and Location Position Characteristic Hèight Structure Remarks No. Range

None

PUBLICATION CORRECTIONS

None

ENCLOSURES

ALASKA

3624 Subsurface Buoys.pdf

Compilation of Subsurface and Surface oceanography moorings properly reported to U.S. Coast Guard District 17.

LNM: 36/24

ALASKA

3624 AMSEA.pdf AMSEA Maritime Training

LNM: 36/24

Daniel A. Davis
Waterways Management Branch
Seventeenth Coast Guard District
OPERATIONAL EXCELLENCE THROUGH LEADERSHIP, TEAMWORK, AND INNOVATION.

This is the current compilation of all subsurface and surface oceanographic moorings that have been reported to the U.S. Coast Guard District 17 Waterways Branch. The name, type, location, depth, water depth, and a Point of Contact for all data buoys, surface and subsurface, shall be reported as quickly as is practical if they are placed within the navigable waters (within 200 nm) of the United States. Data buoys placed in the Arctic region but outside of 200 nm of the United States may be reported and will be included in this compilation (for informational purposes only). This notification process is for inclusion in the Local Notice to Mariners to provide navigational information to mariners and does not supersede any permission or permitting requirements. Any notifications, corrections, additions, deletions, or comments for the Alaska region (Coast Guard District 17) or the Arctic region should be submitted via e-mail to smb-d17juneau-lnm@uscg.mil or to Todd Buck, USCG D17(dpw), at 907-463-2269 or by email to todd.r.buck@uscg.mil. This compilation is as current as the Local Notice to Mariners (LNM) included in as an enclosure. The referenced LNM may have additional information and indicates the last time an entry was updated.

ALASKA – ARCTIC – ARCTIC OCEAN

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
N/A	72°27.655'N, 157°23.774'W	780 feet	731 feet	39/10	Ethan Roth ehroth@ucsd.edu
N/A	72° 47.939'N, 158°23.941'W	1,066 feet	1,017 feet	39/10	Ethan Roth ehroth@ucsd.edu
N/A	72°07.275'N, 160"29.698'W	131 feet	115 feet	35/12	Thomas Weingartner 907-474-7993
N/A	72°09.747'N, 159°07.349'W	167 feet	85 feet	35/12	Thomas Weingartner 907-474-7993
N/A	72°10.875'N, 159°33.117'W	184 feet	95 feet	35/12	Thomas Weingartner 907-474-7993
N/A	72°41.745'N, 164°31.935'W	N/A	151 feet	35/12	N/A
N/A	72°31.517'N, 164°05.944'W	N/A	164 feet	35/12	N/A
N/A	72°16.850'N, 163°32.034'W	N/A	131 feet	35/12	N/A
AIM16-1	75°06.003'N, 168°00.004'W	535 feet	142 feet	44/16	Dr. Humfrey Melling 250-363-6552
AMOS-VLF-1	77°29.600'N, 140°10.800'W	12,264 feet	230 feet	35/22	Craig Lee, craiglee@uw/edu
AMOS-C	76°24.800'N, 142°28.200'W	12,326 feet	131 feet	35/22	Craig Lee, craiglee@uw/edu
AMOS-NW	76°08.800'N, 145°17.000'W	12,441 feet	328 feet	35/22	Craig Lee, craiglee@uw/edu
AMOS-NE	75°46.400'N, 141°30.800'W	12,251 feet	328 feet	35/22	Craig Lee, craiglee@uw/edu
AMOS-B	75°30.000'N, 144°08.400'W	12,379 feet	328 feet	35/22	Craig Lee, craiglee@uw/edu
AMOS-SE	74°52.500'N, 143°05.200'W	12,241 feet	328 feet	35/22	Craig Lee, craiglee@uw/edu
AMOS-SW	75°13.000'N, 146°40.600'W	12,464 feet	328 feet	35/22	Craig Lee, craiglee@uw/edu
AMOS-A	74°35.300'N, 145°32.700'W	12,339 feet	131 feet	35/22	Craig Lee, craiglee@uw/edu
NAP-23t	74°31.375'N, 161°56.536'W	5,528 feet	115 feet	36/24	Motoyo ITOH +81-46-867-9488

CANADA - ARCTIC - BEAUFORT SEA

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
ACW16-30	68°59.173'N, 105°53.030'W	242 feet	231 feet	44/16	Dr. Humfrey Melling 250-363-6552
CB12	70°33.770'N, 127°41.710'W	125 feet	116 feet	44/16	Dr. Humfrey Melling 250-363-6552
IBO16-1a	70°20.031'N, 133°44.369'W	180 feet	171 feet	44/16	Dr. Humfrey Melling 250-363-6552
IBO16-1b	70°20.035'N, 133°44.452'W	180 feet	171 feet	44/16	Dr. Humfrey Melling 250-363-6552
IBO16-2	70°59.359'N, 133°44.636'W	365 feet	146 feet	44/16	Dr. Humfrey Melling 250-363-6552
IBO16-9a	70°03.534'N, 133°42.918'W	116 feet	106 feet	44/16	Dr. Humfrey Melling 250-363-6552
IBO16-9b	70°03.501'N, 133°42.937'W	116 feet	106 feet	44/16	Dr. Humfrey Melling 250-363-6552
SIC16-11	69°46.483'N, 137°02.757'W	117 feet	107 feet	44/16	Dr. Humfrey Melling 250-363-6552
HI16	69°39.284'N, 138°55.279'W	134 feet	125 feet	44/16	Dr. Humfrey Melling 250-363-6552

ALASKA - ARTCIC - BEAUFORT SEA

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
N/A	71°35.980'N, 161°30.3221'W	151 feet	111 feet	48/14	David Leech 907-224-4319
AON-BS3	71°23.659'N, 152°03.046'W	482 feet	115 feet	49/14	Dr. Robert Pickart 508-289-2858
ODAS-1	70°24.889'N, 147°39.206'W	26 feet	24 feet	30/19	Carmen Lawrence 902-405-3336
ODAS-2	70°16.663'N, 147°35.493'W	19 feet	17 feet	30/19	Carmen Lawrence 902-405-3336
BCE-22	71°40.385'N, 154°59.988'W	384 feet	62 feet	36/24	Motoyo ITOH +81-46-867-9488
BCC-22	71°44.067'N, 155°09.840'W	951 feet	66 feet	36/24	Motoyo ITOH +81-46-867-9488
BCW-22	71°47.781'N, 155°20. 812'W	554 feet	115 feet	36/24	Motoyo ITOH +81-46-867-9488
AL24-AU-IC01	70°50.040'N, 163°07.560'W	148 feet	121 feet	36/24	Catherine Berchok 206-526-6331
AL24-AU-BF02	71°45.240'N, 154°28.500'W	344 feet	312 feet	36/24	Catherine Berchok 206-526-6331

ALASKA – ARCTIC – CHUKCHI SEA

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
CEM1-19	71°35.971'N, 161°30.419'W	154 feet	108 feet	35/19	Peter Shipton 907-224-4319
CEM2-19	71°35.979'N, 161°31.648'W	154 feet	108 feet	35/19	Peter Shipton 907-224-4319
AL23-AU-IC02	71°12.880'N, 164°14.910'W	141 feet	108 feet	40/23	Catherine Berchok 206-526-6331
23CKP-1A	50°50.230'N, 163°07.521'W	144 feet	115 feet	41/23	David Strausz 206-526-4510
23CKP-2A	71°12.934'N, 164°15.024'W	144 feet	118 feet	41/23	David Strausz 206-526-4510
23CKP-3A	71°49.656'N, 166°01.127'W	144 feet	121 feet	41/23	David Strausz 206-526-4510
23CKP-4A	71°02.700'N, 160°29.404'W	167 feet	135 feet	41/23	David Strausz 206-526-4510
23CKP-5A	71°12.500'N, 158°00.000'W	161 feet	141 feet	41/23	David Strausz 206-526-4510
23CKP-9A	72°28.201'N, 15634.203'W	3,018 feet	886 feet	41/23	David Strausz 206-526-4510
23CKP-12A	67°54.348'N, 168°10.853'W	190 feet	148 feet	41/23	David Strausz 206-526-4510
23CKV-12A	67°54.624'N, 168°10.875'W	190 feet	108 feet	41/23	David Strausz 206-526-4510

ALASKA – ARCTIC – CHUKCHI SEA (Continued)

ALASKA – ARCTIC – CHUKCHI SEA (Continued)						
TYPE/NAME: 23CKP-15A AL24-AU-IC03 AL24-AU-PB01	POSITION: 72°18.590'N, 167°16.250'W 71°49.860'N, 166°01.080'W 71°12.240'N, 157°59.940'W	WATER DEPTH: 157 feet 148 feet 157 feet	TOP FLOAT DEPTH: 128 feet 121 feet 131 feet	Ref. LNM: 41/23 36/24 36/24	POC: David Strausz 206-526-4510 Catherine Berchok 206-526-6331 Catherine Berchok 206-526-6331	
ALASKA – WEST	TERN – KOTZEBUE SOUND					
TYPE/NAME: OTZ-N OTZ-M OTZ-S OTZ-Ch	POSITION: 67°6.791'N, 163°46.328'W 67°5.148'N, 163°48.282'W 67°3.365'N, 163°48.699'W 66°14.346'N, 166°51.926'W	WATER DEPTH: 37 feet 58 feet 60 feet 51 feet	TOP FLOAT DEPTH: 27 feet 48 feet 50 feet 41 feet	Ref. LNM: 48/14 48/14 48/14 48/14	POC: Dr. Manuel Castellote 206-526-6866 Dr. Manuel Castellote 206-526-6866 Dr. Manuel Castellote 206-526-6866 Dr. Manuel Castellote 206-526-6866	
			mon Ev o . m n Engy	D 6 7 3 D 7	no c	
TYPE/NAME: AOOS-AXYS NB-17t BS-17t A2-23 A3-23 A4-23	POSITION: 65°00.700'N, 169°27.23'W 65°03.884'N, 169°38.045'W 66°16.075'N, 168°54.098'W 65°46.860'N, 168°34.060'W 66°19.600'N, 168°56.940'W 65°44.760'N, 168°15.760'W	WATER DEPTH: 171 feet 187 feet 184 feet 190 feet 161 feet	TOP FLOAT DEPTH: Surface 89 feet 105 feet 49 feet 23 feet 49 feet	Ref. LNM: 30/15 29/17 29/17 36/24 36/24 36/24	POC: Darcy Dugan 907-644-6718 Makoto Sampei +81-138-40-8844 Makoto Sampei +81-138-40-8844 Rebecca Woodgate 206-221-3268 Rebecca Woodgate 206-221-3268 Rebecca Woodgate 206-221-3268	
ALASKA – SOUT	HWESTERN – BERING SEA					
TYPE/NAME: PUF-18 PUF-19 AL23-AU-M08 23BS-2C 23BS-4A 23BSP-4A 23BSP-5A 23BSP-5A 23BSP-14A 23BSITAER-8A 23BSST-8A 23BSY-8A 23BSY-8A 23BSY-8A 24KUM-2A SPOT-32004C AL24-AU-NM01 AL24-AU-BS10 AL24-AU-BS11 AL24-AU-PC01 TYPE/NAME: AL24-AU-UN01	POSITION: 56°15.340'N, 168°17.361'W 58°24.700'N, 167°36.900'W 62°12.286'N, 174°40.585'W 56°51.630'N, 164°03.290'W 57°51.983'N, 168°52.432'W 57°52.230'N, 168°53.164'W 59°55.168'W, 171°42.149'W 64°00.251'N, 167°55.150'W 62°12.107'N, 174°39.660'W 62°12.002'N, 174°40.782'W 62°12.339'N, 174°40.782'W 62°12.339'N, 174°40.558'W 62°12.339'N, 174°39.890'W 56°52.066'N, 164°03.511'W 58°15.713'N, 163°33.441'W 60°31.139'N, 165°05.293'W 64°51.480'N, 168°26.880'W 56°09.600'N, 166°34.920'W 61°05.040'N, 170°15.840'W 56°07.762'N, 168°18.780'W HWESTERN – UNIMAK PASS	506 feet 167 feet 230 feet 243 feet 243 feet 243 feet 243 feet 236 feet 236 feet 138 feet 240 feet 240 feet 240 feet 240 feet 131 feet 140 feet 150 feet 161 feet 161 feet 161 feet	TOP FLOAT DEPTH:	43/21 43/21 40/23 41/23 41/23 41/23 41/23 41/23 41/23 41/23 41/23 41/23 41/23 41/23 41/23 41/23 41/23 41/24 41/25 41/26 41	POC: Thomas Vanpelt 907-242-7725 Thomas Vanpelt 907-242-7725 Catherine Berchok 206-526-6331 David Strausz 206-526-4510 Catherine Berchok 206-526-6331	
	HCENTRAL – GULF OF ALA			30/24	Catherine Berchok 200-320-0331	
TYPE/NAME: GA23-AU-SU01	POSITION: 56°35.990'N, 157°00.000'W		TOP FLOAT DEPTH: 400 feet	Ref. LNM: 41/23	POC: Catherine Berchok 206-526-6331	
ALASKA – SOUT	HCENTRAL – GULF OF ALA	SKA – STEVENSO	N ENTRANCE			
TYPE/NAME: GA23-AU-SE01	POSITION: 58°42.540'N, 152°12.530'W	WATER DEPTH: 430 feet	TOP FLOAT DEPTH: 404 feet	Ref. LNM: 41/23	POC: Catherine Berchok 206-526-6331	
ALASKA – SOUT	HCENTRAL - COOK INLET	- KAMISHAK BAY	?			
	POSITION: °16'34.5168"N, 154°07'03.6837' °15'24.7255"N, 154°02'45.7066'	W 16 feet	TOP FLOAT DEPTH: 13 feet 39 feet	Ref. LNM: 03/18 03/18	POC: Jason Crockett 907-315-6513 Jason Crockett 907-315-6513	
ALASKA – SOUT	HCENTRAL – GULF OF ALA	SKA				
TYPE/NAME: UAF GAK4M GEO1-2019 GEO2-2019 GEO3-2019	POSITION: 59°24.231'N, 149°00.731'W 59°00.850'N, 148°41.410'W 59°00.917'N, 148°41.604'W 59°00.988'N, 148°41.797'W	WATER DEPTH: 656 feet 722 feet 722 feet 722 feet	TOP FLOAT DEPTH: 328 feet Surface 72 feet Surface	Ref. LNM: 45/16 29/19 29/19 29/19	POC: Dr. Andrew McDonnell 907-474-7529 Seth Danielson 907-474-7834 Seth Danielson 907-474-7834 Seth Danielson 907-474-7834	

ALASKA - SOUTHCENTRAL - GULF OF ALASKA (Continued)

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
AOOS-204	59°35.850'N, 151°49.746'W	111 feet	Surface	32/21	James Behrens 858-534-3032
GA23-AU-BT01	57°01.760'N, 152°59.690'W	253 feet	230 feet	34/23	Catherine Berchok 206-526-6331
GA23-AU-SN01	53°58.360'N, 161°40.070'W	1,375 feet	243 feet	34/23	Catherine Berchok 206-526-6331
GA23-AU-CR01	55°34.340'N, 154°58.460'W	1,319 feet	233 feet	34/23	Catherine Berchok 206-526-6331
GA23-AU-SM01	53°07.960'N, 168°55.210'W	433 feet	400 feet	38/23	Catherine Berchok 206-526-6331
GA23-AU-PT01	54°38.200'N, 150°21.160'W	2,438 feet	233 feet	38/23	Catherine Berchok 206-526-6331
23CB-1A	57°43.456'N, 152°17.001'W	545 feet	472 feet	41/23	David Strausz 206-526-4510
23SH-1A	54°51.177'N, 158°59.481'W	256 feet	203 feet	41/23	David Strausz 206-526-4510
24UPP-3A	54°18.400'N, 164°45.100'W	243 feet	217 feet	24/24	David Strausz 206-526-4510
UWAPL24	50°02'30.000"N, 145°10'12.000"W	UNK	Surface	26/24	Joe Talbert 206-409-4627

ALASKA – SOUTHCENTRAL – GULF OF ALASKA – RESURRECTION BAY

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:

GAKOA 59°54'39.55"N, 149°20'57.47"W 171 feet Surface 13/19 Natalie Monacci 907-474-7956 GAK1 59°51'11.952"N, 149°30'03.96"W 869 feet 66 feet 13/19 Peter Shipton 907-224-4319

ALASKA - SOUTHCENTRAL - PRINCE WILLIAM SOUND

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
PWSSC-15	60°36.791'N, 147°11.996'W	722 feet 19	7 feet (Surfacing 2X per c	lay) 15/16	R. W. Campbell 907-424-5800 x241
H01	60°20.550'N, 146°43.824'W	98 feet	66 feet	09/17	Mary Anne Bishop 907-424-5800 x228
HA	60°20.274'N, 146°43.248'W	591 feet	532 feet	09/17	Mary Anne Bishop 907-424-5800 x228
H02	60°20.400'N, 146°44.520'W	879 feet	791 feet	09/17	Mary Anne Bishop 907-424-5800 x228
HB	60°20.094'N, 146°43.974'W	830 feet	747 feet	09/17	Mary Anne Bishop 907-424-5800 x228
H04	60°20.112'N, 146°45.966'W	886 feet	797 feet	09/17	Mary Anne Bishop 907-424-5800 x228
H05	60°19.968'N, 146°46.710'W	886 feet	797 feet	09/17	Mary Anne Bishop 907-424-5800 x228
H06	60°19.812'N, 146°47.418'W	896 feet	806 feet	09/17	Mary Anne Bishop 907-424-5800 x228
H07	60°19.668'N, 146°48.138'W	909 feet	818 feet	09/17	Mary Anne Bishop 907-424-5800 x228
H08	60°19.470'N, 146°48.954'W	935 feet	842 feet	09/17	Mary Anne Bishop 907-424-5800 x228
H09	60°19.320'N, 146°49.782'W	1007 feet	906 feet	09/17	Mary Anne Bishop 907-424-5800 x228
H10	60°19.188'N, 146°50.508'W	1060 feet	954 feet	09/17	Mary Anne Bishop 907-424-5800 x228
H13	60°18.738'N, 146°52.656'W	909 feet	818 feet	09/17	Mary Anne Bishop 907-424-5800 x228
H14	60°18.588'N, 146°53.340'W	522 feet	470 feet	09/17	Mary Anne Bishop 907-424-5800 x228
H15	60°18.468'N, 146°53.994'W	276 feet	244 feet	09/17	Mary Anne Bishop 907-424-5800 x228
HC	60°18.120'N, 146°53.568'W	449 feet	404 feet	09/17	Mary Anne Bishop 907-424-5800 x228
H11	60°19.008'N, 146°51.228'W	1135 feet	1022 feet	09/17	Mary Anne Bishop 907-424-5800 x228
H16	60°18.540'N, 146°54.552'W	85 feet	53 feet	09/17	Mary Anne Bishop 907-424-5800 x228
HD	60°17.982'N, 146°54.336'W	151 feet	119 feet	09/17	Mary Anne Bishop 907-424-5800 x228
M01	59°55.482'N, 147°48.630'W	295 feet	263 feet	09/17	Mary Anne Bishop 907-424-5800 x228
M02	59°55.848'N, 147°49.074'W	446 feet	401 feet	09/17	Mary Anne Bishop 907-424-5800 x228
M03	59°56.178'N, 147°49.518'W	509 feet	458 feet	09/17	Mary Anne Bishop 907-424-5800 x228
M04	59°56.556'N, 147°49.956'W	577 feet	519 feet	09/17	Mary Anne Bishop 907-424-5800 x228
M05	59°56.886'N, 147°50.382'W	640 feet	576 feet	09/17	Mary Anne Bishop 907-424-5800 x228
M07	59°57.546'N, 147°51.234'W	741 feet	667 feet	09/17	Mary Anne Bishop 907-424-5800 x228
MC	59°58.182'N, 147°52.872'W	745 feet	671 feet	09/17	Mary Anne Bishop 907-424-5800 x228
M11	59°58.842'N, 147°52.866'W	472 feet	425 feet	09/17	Mary Anne Bishop 907-424-5800 x228
MD	59°58.518'N, 147°53.352'W	614 feet	553 feet	09/17	Mary Anne Bishop 907-424-5800 x228
BP07	60°06.894'N, 148°14.118'W	171 feet	154 feet	36/24	Mary Anne Bishop 907-424-5800 x228
POWP05	60°02.784'N, 148°07.482'W	315 feet	299 feet	36/24	Mary Anne Bishop 907-424-5800 x228
POWP06	60°02.790'N, 148°07.789'W	154 feet	138 feet	36/24	Mary Anne Bishop 907-424-5800 x228
EP03	59°59.466'N, 148°05.778'W	207 feet	190 feet	36/24	Mary Anne Bishop 907-424-5800 x228
EP04	59°59.706'N, 148°06.060'W	276 feet	259 feet	36/24	Mary Anne Bishop 907-424-5800 x228
LP01	59°58.848'N, 148°01.914'W	112 feet	95 feet	36/24	Mary Anne Bishop 907-424-5800 x228
LP02	59°59.082'N, 148°02.219'W	144 feet	128 feet	36/24	Mary Anne Bishop 907-424-5800 x228
M06	59°57.222'N, 147°50.838'W	702 feet	686 feet	36/24	Mary Anne Bishop 907-424-5800 x228
M08	59°57.858'N, 147°51.630'W	758 feet	741 feet	36/24	Mary Anne Bishop 907-424-5800 x228
M09	59°58.146'N, 147°52.008'W	643 feet	617 feet	36/24	Mary Anne Bishop 907-424-5800 x228
M10	59°58.512'N, 147°52.434'W	784 feet	768 feet	36/24	Mary Anne Bishop 907-424-5800 x228
H03	60°20.256'N, 146°45.264'W	876 feet	860 feet	36/24	Mary Anne Bishop 907-424-5800 x228
H12	60°18.888'N, 146°51.918'W	1194 feet	1079 feet	36/24	Mary Anne Bishop 907-424-5800 x228

${\bf ALASKA-SOUTHEAST}$

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
Icy Strait	58° 14.6112'N, 136° 7.28972'W	614 feet	594 feet	35/09	Dave Carlile 907-465-4216
Icy Strait	58° 14.5037'N, 136° 7.27185'W	541 feet	521 feet	35/09	Dave Carlile 907-465-4216
Icy Strait	58° 14.3962'N, 136° 7.25398'W	522 feet	502 feet	35/09	Dave Carlile 907-465-4216
Icy Strait	58° 14.2887'N, 136° 7.23611'W	358 feet	338 feet	35/09	Dave Carlile 907-465-4216
Icy Strait	58° 14.1812'N, 136° 7.21824'W	266 feet	246 feet	35/09	Dave Carlile 907-465-4216
Chatham Strait	56° 9.6115'N, 134° 33.78278'W	1814 feet	1795 feet	35/09	Dave Carlile 907-465-4216
Chatham Strait	56° 9.6209'N, 134° 33.97584'W	1820 feet	1800 feet	35/09	Dave Carlile 907-465-4216
Chatham Strait	56° 9.6303'N, 134° 34.1689'W	1811 feet	1791 feet	35/09	Dave Carlile 907-465-4216
Chatham Strait	56° 9.6397'N, 134° 34.36195'W	1811 feet	1791 feet	35/09	Dave Carlile 907-465-4216
Chatham Strait	56° 9.6491'N, 134° 34.55501'W	1798 feet	1778 feet	35/09	Dave Carlile 907-465-4216

ALASKA - SOUTHEAST (Continued)

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
Chatham Strait	56° 8.6362'N, 134° 25.56783'W	1916 feet	417 feet	35/09	Dave Carlile 907-465-4216
Chatham Strait	56° 8.655'N, 134° 25.95379'W	1930 feet	1910 feet	35/09	Dave Carlile 907-465-4216
Chatham Strait	56° 8.6644'N, 134° 26.14676'W	1932 feet	1912 feet	35/09	Dave Carlile 907-465-4216
Chatham Strait	56° 8.6738'N, 134° 26.3397'W	1936 feet	1916 feet	35/09	Dave Carlile 907-465-4216
Chatham Strait	56° 8.6832'N, 134° 26.53272'W	1932 feet	1912 feet	35/09	Dave Carlile 907-465-4216
Chatham Strait	56° 8.6926'N, 134° 26.7257'W	1932 feet	1912 feet	35/09	Dave Carlile 907-465-4216
Frederick Sound	57° 3.34'N, 134° 15.64'W	1180 feet	928 feet	35/09	Dave Carlile 907-465-4216
Frederick Sound	57° 3.1874'N, 134° 15.35938'W	1155 feet	1135 feet	35/09	Dave Carlile 907-465-4216
Frederick Sound	57° 3.1111'N, 134° 15.21907'W	1155 feet	1135 feet	35/09	Dave Carlile 907-465-4216
Frederick Sound	57° 3.0348'N, 134° 15.07877'W	1155 feet	1135 feet	35/09	Dave Carlile 907-465-4216
Frederick Sound	57° 2.9584'N, 134° 14.93847'W	1158 feet	1138 feet	35/09	Dave Carlile 907-465-4216
Ommaney	56° 5.1769'N, 134° 46.8910'W	1191 feet	1171 feet	33/10	Dave Carlile 907-465-4216
Ommaney	56° 5.0755'N, 134° 46.8249'W	1200 feet	1180 feet	33/10	Dave Carlile 907-465-4216
Ommaney	56° 4.9741'N, 134° 46.7587' W	1200 feet	1180 feet	33/10	Dave Carlile 907-465-4216
Ommaney	55° 59.6327' N, 134°57.3717' W	1214 feet	1194 feet	33/10	Dave Carlile 907-465-4216
Ommaney	55° 59.5313'N, 134° 57.3057'W	1191 feet	1171 feet	33/10	Dave Carlile 907-465-4216
Ommaney	55° 59.4298'N, 134° 57.2397'W	1191 feet	1171 feet	33/10	Dave Carlile 907-465-4216
Ommaney	55° 59.3284'N, 134° 57.1737'W	1220 feet	1200 feet	33/10	Dave Carlile 907-465-4216
Frederick Sound	57° 2.8821'N, 134° 14.79818'W	1158 feet	1138 feet	35/09	Dave Carlile 907-465-4216
Ommaney	56° 5.4812' N, 134° 47.0895' W	1181 feet	912 feet	33/10	Dave Carlile 907-465-4216
Ommaney	56° 5.3798'N, 134° 47.0233'W	1191 feet	1171 feet	33/10	Dave Carlile 907-465-4216
Ommaney	56° 5.2783'N, 134° 46.9572'W	1191 feet	1171 feet	33/10	Dave Carlile 907-465-4216
Ommaney	55° 59.2270'N, 134° 57.1077'W	1220 feet	1200 feet	33/10	Dave Carlile 907-465-4216
Ommaney	55° 59.1256'N, 134° 57.0417' W	1220 feet	1200 feet	33/10	Dave Carlile 907-465-4216
20CSP-4A	58°07.363'N, 136°35.604'W	1,099 feet	1,060 feet	06/20	David Strausz 206-526-4510

ALASKA – NORTH PACIFIC OCEAN

TYPE/NAME:	POSITION:	WATER DEPTH:	TOP FLOAT DEPTH:	Ref. LNM:	POC:
MFM-A	49°58.60'N, 144°14.77'W	13,540 feet	49 feet	24/15	Gabriella Chavez 858-822-4938
MFM-B	50°19.82'N, 144°23.90'W	13,599 feet	49 feet	24/15	Gabriella Chavez 858-822-4938
GHPM-1	50°04.79'N, 144°48.18'W	13, 842 feet	483 feet	24/15	Gabriella Chavez 858-822-4938



Alaska Marine Safety Education Association

2924 Halibut Point Road, Sitka, Alaska 99835-9668 phone 907-747-3287 / fax 907-747-3259 / www.amsea.org

For Immediate Release

Date Issued: August 30, 2024 Kill Date: September 6, 2024

AMSEA Workshops of Interest to Mariners in District 17

The Alaska Marine Safety Education Association is offering a number of classes in U.S. Coast Guard District 17 that may be of interest to mariners. Many of these workshops are offered at a reduced cost to commercial fishermen, thanks to support from the U.S. Coast Guard, the National Institute for Occupational Safety and Health, the Alaska Department of Commerce, Community and Economic Development, and AMSEA members.

Register online at www.amsea.org or call (907) 747-328

Marine Safety Instructor Training

The MSIT is an intensive train-the-trainer course that prepares individuals to effectively teach cold-water survival procedures, use of marine safety equipment, and vessel safety drills. Upon completion of the course, participants will be prepared to teach AMSEA's U.S. Coast Guard accepted Fishing Vessel Drill Conductor training, pending authorization from the Coast Guard. Topics covered during the course include:

- Preparation for emergencies
- Cold-water near drowning
- Hypothermia
- Cold-water survival
- Survival equipment, procedures & onboard drills
- Risk Assessment
- Ergonomics
- Methods of instructions

Start Date	End Date	Location	State
09/30/2024	10/5/2024	Sitka	AK