

INTERNATIONAL MARITIME ORGANIZATION

4 ALBERT EMBANKMENT  
LONDON SE1 7SR

Telephone: 0171-735 7611  
Fax: 0171-587 3210  
Telex: 23588 IMOLDN G



IMO

**E**

FL

MS

Ref. T2/2.07

SN/Circ.198/Corr.1  
29 March 1999

### **ROUTEING MEASURES OTHER THAN TRAFFIC SEPARATION SCHEMES**

The following correction should be made to SN/Circ.198, annex 2 -  
Amended rules for navigation of laden tankers around the Southern coast of South Africa.

In paragraph 3.1 (first sentence, fourth line) the text should read as follows:

"position, Slangkop Point light 070°(T) x 20 nautical miles."