

Page 127-Paragraph 106, lines 2-3; read:
the E sandspit to a 1¼-fathom spot in 59°55'43"N.,
141°25'54"W. Depths to the N of the shoal are greater ...
(BP 183151; H-10985)

Page 127-Paragraph 107, lines 2-6; read:
side of Riou Bay. A bar, with a least depth of ¾-fathom, NW
of Moraine Island, extends from 59°55'57"N., 141°23'37"W.
to 59°56'01"N., 141°23'53"W. A shallow but navigable
channel exists between the ¾-fathom bar and a 1¼-fathom
spot about 0.5 mile to the E. A temporary ...
(BP 183151; H-10985)

Page 127-Paragraph 108, line 3; read:
NE end of the island is conspicuous. A shoal extends 1 ...
(BP 183151; H-10985)

Page 127-Paragraph 114, lines 5-8; read:
may yield in very high winds. In 2000, the controlling depth in
the NW part of the harbor was 4 fathoms with a 1¼-fathom
spot at the entrance in 59°56'00"N., 141°22'45"W. Do not
anchor between Moraine Island ...
(BP 183151; H-10985)

Page 233-Paragraph 1415, line 7; read:
Ship Creek side of the dock.

Port MacKenzie Dock: (61°16'05"N., 149°55'01"W.), on
the W shore of Knik Arm, 1.3 mile WNW of Cairn Point; 500-
foot face; 20 feet alongside; deck height, 36 feet; filter rock
ramp; 8,000 acres of open storage; water, electricity;
highway connections; receipt of bulk commodities,
containerized cargo, iron and steel materials, petroleum
products, vehicles and heavy equipment, and modular
buildings. Owned and operated by the Matanuska-Susitna
Borough.

(CL 795/04; BP 172712)

Page 473-Paragraph 618, lines 10-12; read:
above the mouth of the Snake River. A small boat harbor is
at the N end of the turning basin. In June 2002-August 2003,
the controlling depth was 7.1 feet to the basin, thence 6.6 to
8 feet in the basin with lesser ...

(CL 654/04; BP 181853; BP 181401)