Local Notice to Mariners for District 7 06/17/2025

Alafia River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Alafia River Light 7	23275	STRUCT MISSING/TRLB	FD
Alafia River Light 15	23315	STRUCT DEST/TRLB/HAZ NAV	FD

Altamaha Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Altamaha Sound Daybeacon 197	36887	STRUCT DEST/TRUB	FD
Altamaha Sound Light 201	36905	STRUCT DEST/TRLB	FD
Altamaha Sound Light 202	36910	STRUCT DEST/TRLB	FD
Altamaha Sound Light 209	36930	STRUCT DEST/TRLB	FD
Altamaha Sound Range Front Light C	36935	STRUCT DEST	FD

Amelia River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Amelia River Lighted Buoy 4	37940	ADRIFT	FD

Anclote Anchorage North Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anclote Anchorage North Entrance Light 7	26130	STRUCT DEST/HAZ NAV/TRLB/OFF STATION	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gulf Harbors South Channel Light 1	26410	LT EXT	PA
Upper Cross Bayou Daybeacon 1	26453	STRUCT DEST	PA
Gulf Harbors North Channel Daybeacon 10	26500	STRUCT DEST	PA
Sea Forest Cut Channel Daybeacon 9	26451.8	STRUCT DEST/HAZ NAV	PA
Gulf Harbors North Channel Light 2	26460	STRUCT DEST	PA

Anclote River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anclote River Light 9	26180	STRUCT DEST/TRLB	FD
Anclote River Daybeacon 11	26190	STRUCT DEST/TRLB/HAZ NAV	FD
Anclote River Daybeacon 12	26190.5	HAZ NAV/STRUCT DEST/TRLB	FD
Anclote River Turning Basin Shoal Daybeacon A	26360	STRUCT MISSING/TRUB	FD
Anclote River Turning Basin Shoal Daybeacon B	26365	STRUCT MISSING/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anclote Village Marina Daybeacon 7	26233.7	DAYMK MISSING	PA

Angelfish Creek

NAME	LLNR	STATUS	AID TYPE
Angelfish Creek Daybeacon 1	11185	STRUCT DEST/HAZ NAV/TRLB	FD
Angelfish Creek Daybeacon 4	11205	STRUCT DEST	FD
Angelfish Creek Light 6	11215	STRUCT DEST/TRLB	FD

Ashepoo-Coosaw Cut-Off

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ashepoo-Coosaw Cutoff Daybeacon 169	35160	STRUCT MISSING/TRUB	FD

Ashley River

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Charleston Harbor South Channel - Ashley River/General/Bridges/Construction	5	General/Bridges/Construction From: 2025-02-12 To: 2026-01-30 Location: 32.78257° N / 79.96052° W Bridge Name: Ashley River Pedestrian Bridge Construction of the Ashley River Crossing Pedestrian Bridge has begun on the Ashley River, in Charleston, SC. The new bridge will be constructed to the southeast (immediately adjacent) of the T. Allen Legare / US 17 Bridge. Construction barges will be partially obstructing the channel, approximately 65-70 feet of the channel will be available to navigation. Vessels requiring a full channel passage must contact Mr. Sean Lynch, 728-205-1580, at least 24 hours prior to the transit. Construction activities will be 24 hours a day, seven days a week. The SE section of the T. Allen Legare / US 17 Bridge fender will be temporarily removed. The remaining section will be properly lighted. One dolphin at the NE fender will be removed during the construction. Vessels should use caution and maintain safe speeds while transiting the area.	Lon: -079° 57'

Atlantic IWW

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sebastian Inlet North Jetty Light	655	LT EXT	PA
Sailfish Point Marina Channel Daybeacon 5	10025	STRUCT DEST/HAZ NAV	PA
Sailfish Point Marina Channel Daybeacon 2	10010	STRUCT DEST	PA
Sailfish Point Marina Channel Daybeacon 7	10035	STRUCT DEST	PA

Bahia De Boqueron

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bajo Enmedio South Lighted Buoy 1	32325	SINKING/TRLB	FD

Bahia De Guayanilla

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bahia De Guayanilla Entrance Range Rear Light	32075	LT EXT	FD

Bahia De Jobos

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Aguirre Power Plant Lighted Buoy 1	31890	OFF STA	PA
Aguirre Power Plant Lighted Buoy 2	31895	OFF STA	PA
Aguirre Power Plant Lighted Buoy 3	31900	OFF STA	PA
Aguirre Power Plant Lighted Buoy 4	31905	OFF STA	PA
Aguirre Power Plant Lighted Buoy 5	31910	OFF STA	PA
Aguirre Power Plant Lighted Buoy 6	31915	OFF STA	PA
Aguirre Power Plant Lighted Buoy 8	31920	OFF STA	PA

Bahia De Ponce

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Isla De Cardona Light	31950	STRUCT DEST	FD
Bahia De Ponce Range Rear Light	31965	REDUCED INT	FD

NAME	LLNR	STATUS	AID TYPE
Ponce Harbor Pier Obstruction Lights (4)	31985	STRUCT DMGD	PA

Bahia De Ponce And Approaches

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Isla Caja De Muertos Light	31925	LT EXT	FD
Private Discrepancies			

NAME	LLNR	STATUS	AID TYPE
Ponce Yacht & Fishing Club Special Purpose Buoy A	31927	MISSING	PA
Rio Bucana East Jetty Light	31940	STRUCT DEST	PA

Bahia De San Juan

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bahia De San Juan Lighted Buoy 2	30760	BUOY DMGD/OFF STATION	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bahia De San Juan FAD Lighted Buoy E	30736.4	MISSING	PA
Bahia De San Juan FAD Lighted Buoy F	30736.5	OFF STA	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Army Terminal Channel Lighted Buoy 7	30885	RELOCATED FOR DREDGING	FD
Army Terminal Channel Temporary Buoy 7A	null	ESTABLISHED	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Bahia De San Juan/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 18.43499° N / 66.10732° W Aid Name: Army Terminal Channel Lighted Buoy 7 LLNR: 30885 Action: RELOCATE Army Terminal Channel Lighted Buoy 7 (LLNR 30885) will be permanently relocated to position 18-26-10.272N/066-06-27.668W. Army Terminal Channel Lighted Buoy 7A (LLNR 30885 .5) will be permanently established in position 18-26-03.650N/066-06-25.656W.	Lat: 18° 26' 06" Lon: -066° 06' 26"
Bahia De San Juan/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 18.43435° N / 66.10713° W Aid Name: Army Terminal Channel Lighted Buoy 7A LLNR: 30885 .5 Action: ESTABLISH Army Terminal Channel Lighted Buoy 7 (LLNR 30885) will be permanently relocated to position 18-26-10.272N/066-06-27.668W. Army Terminal Channel Lighted Buoy 7A (LLNR 30885 .5) will be permanently established in position 18-26-03.650N/066-06-25.656W.	Lat: 18° 26' 04" Lon: -066° 06' 26"
Bahia De San Juan/General/Marine Events/Swim	Marine Events	General/Marine Events/Swim 20713 The U.S. Coast Guard will be enforcing a Special Local Regulation for the San Juan Harbor Swim described in Title 33 Code of Federal Regulations (CFR) 100.701 Table 1 on July 20, 2025, from 10 a.m. to 12 p.m. The regulated area encompasses all waters of San Juan Harbor encompassed within the following points: i. San Juan Harbor, San Juan, Puerto Rico; All waters encompassed within the following points: Point 1: La Puntilla Final, Coast Guard Base at position 18°27'33" N, 066°07'00" W, then south to point 2: Cataño Ferry Pier at position 18°26'36" N, 066°07'00" W, then northeast along the Cataño shoreline to point 3: Punta Cataño at position 18°26'40" N, 066°06'48" W, then northwest to point 4: Pier 1 San Juan at position 18°27'40" N, 066°06'49" W, then back along the shoreline to origin. The U.S. Coast Guard may be contacted via VHF-FM channel 16. For more information, contact Mr. Andres Santiago Febres at 787-594-3030 or via email at ollopez@catano.pr.gov	

Banana River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Banana River Daybeacon 7A	42490	STRUCT DEST/TRUB	FD
Banana River Daybeacon 15	42555	STRUCT DEST/TRUB	FD

NAME	LLNR	STATUS	AID TYPE
Tortoise Island Channel Daybeacon 1	42463	STRUCT DEST/HAZ NAV	PA
Hospital Cut Daybeacon 6	42611.5	DAYMK MISSING	PA
Tortoise Island Ctr Channel Daybeacon 2	42450	DAYMK IMCH	PA
Tortoise Island Center Channel Daybeacon 4	42460	DAYMK IMCH	PA
Tortoise Island Center Channel Daybeacon 5	42460.1	DAYMK IMCH	PA
Tortoise Island Center Channel Daybeacon 6	42460.20000000004	DAYMK MISSING	PA
Tortoise Island Center Channel Daybeacon 7	42460.3	DAYMK IMCH	PA
Tortoise Island Center Channel Daybeacon 8	42460.4	DAYMK IMCH	PA
Manatee Cove Marina Daybeacon 1	42490.1	STRUCT DEST/HAZ NAV	PA
Manatee Cove Marina Daybeacon 4	42490.4	STRUCT DMGD	PA
Pelican Creek Light 2	42615	STRUCT DEST	PA
Central Avenue Entrance Channel Light 2	42830	LT EXT	PA

6/17/25, 10:41 AM		Maritime Safety Information Products Navigation Center			
	Kelly Park Channel Daybeacon 3	43040	STRUCT DEST/HAZ NAV	PA	
	Kelly Park Channel Daybeacon 4	43045	STRUCT DEST	PA	

STRUCT DEST/HAZ NAV

PA

43050

Additional MSI Categories					
TITLE	SUBCATEGORY	DESCRIPTION	LOCATION		
Canaveral Barge Canal -	Marine	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 28.2669° N / 80.6097° W 28.17191° N /			
Banana	Construction	80.61245° W 28.25602° N / 80.6612° W 28.2669° N / 80.6097° W Gator Dredging will continue muck removal operations within the Grand Canal			
River/General/Marine	(Excluding	and adjacent canals within a subdivision, north of Samson Island Park and south of Patrick Air Force Base. Operations will begin on or about			
Construction (Excluding	Bridges)	March 15, 2022 until approximately November 30, 2025 - Monday through Saturday, 30 minutes after sunrise until 30 minutes before sunset. The			
Bridges)/Dredging		dredge DANI L will monitor VHF-FM channels 16 and 68. Mariners are urged to use extreme caution in the area, transit at their slowest safe speed	I		
		to minimize wake, and proceed with caution after passing arrangements have been made. Floating and submerged high density polyethylene			
		pipeline associated with the hydraulic dredging operations of the canals will be utilized. Pipeline, work vessels, dredge barge, booster pump			
		barges and buoys will be visibly lighted and will be in the area until all work is complete. The configuration will change daily and Vessels and/or			
		equipment will be in multiple locations at the same time. For further information, contact: Charlie Gertz (727) 902-6055.			

Banana River North

Federal Discrepancies

Kelly Park Channel Daybeacon 5

NAME	LLNR	STATUS	AID TYPE
Banana River North Daybeacon 34	41920	STRUCT DEST/TRUB	FD
Banana River North Light 35	41925	STRUCT DEST/TRLB	FD

Barnes Sound

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Manatee Bay Daybeacon 2	50310	STRUCT DEST	PA
Manatee Bay Daybeacon 3	50315	STRUCT DEST	PA
Manatee Creek Daybeacon 5	50255	STRUCT DEST	PA
Manatee Creek Daybeacon 6	50260	STRUCT DEST	PA
Manatee Creek Daybeacon 7	50265	STRUCT DEST	PA
Manatee Creek Daybeacon 8	50270	STRUCT DEST	PA
Manatee Creek Daybeacon 8A	50275	STRUCT DEST	PA
Manatee Creek Daybeacon 9	50280	STRUCT DEST	PA
Manatee Creek Daybeacon 10	50285	STRUCT DEST	PA

Barron River Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Barron River Channel Daybeacon 37	16180	STRUCT DEST/TRUB	FD

Beaufort River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Broad Creek Daybeacon 13	4490	STRUCT DEST	PA
Broad Creek Daybeacon 19	4510	DAYMK IMCH	PA
Broad Creek Daybeacon 21	4515	DAYMK IMCH	PA

TITLE	SUBCATEGORY	DESCRIPTION	LOCATIO
Port Royal Sound - Beaufort	Bridges	General/Bridges/Temp Deviation From: 2024-10-29 To: 2024-11-29 Location: 32.42753° N / 80.66921° W Bridge Name: Lady's Island Woods	Lat:
River/General/Bridges/Temp		Memorial Bridge The bridge need not open for navigation, including tugs with tows during the following: - July 4, 2025, from 7:45 a.m. to	32° 25' 39
Deviation		9:30 a.m. to facilitate the Help of Beaufort 5k October 4, 2025, from 6:30 a.m. to 9:45 a.m. to facilitate the SC Shrimp Festival 5k 2025	Lon:
		November 1, 2025, from 7:15 a.m. to 9:45 a.m. to facilitate the Holy Trinity Classic Christian School Swing Bridge Run 2025. Public Vessels, vessels in emergency situations, and vessels that may pass through the bridge without an opening should be passed at any time.	-080° 40' 09"
Port Royal Sound - Beaufort	Bridges	General/Bridges/Temp Deviation From: 2024-11-05 To: 2024-11-30 Location: 32.42753° N / 80.66921° W Bridge Name: Lady's Island Woods	Lat:
River/General/Bridges/Temp		Memorial Bridge This temporary deviation to the drawbridge operating schedule is effective from 6 a.m. on May 24, 2025, 2025, through	32° 25' 39
Deviation		11:59 p.m. on June 20, 2025. At which time it will become permanent per federal rulemaking under docket USCG-2024-0198,	Lon:
		https://www.federalregister.gov. Under this temporary deviation, the Lady's Island (Woods Memorial) Bridge shall open on signal; except	-080° 40'
		that the draw need not open from 6 a.m. to 9:29 a.m. and 3:31 p.m. to 7 p.m., Monday through Friday, except Federal holidays. Between	09"
		9:30 a.m. and 3:30 p.m., Monday through Friday, except Federal holidays, the draw need open only once an hour on the half hour. Public	
		vessels of the United States and tugs with tows, will be passed through anytime.	

Port Royal Sound - Beaufort

(Scheduled Or Emergency)

River/General/Bridges/Closure

Bridges

Maritime Safety Information Products | Navigation Center

General/Bridges/Closure (Scheduled Or Emergency) From: 2025-03-11 To: 2025-09-07 Location: 32.42753° N / 80.66921° W Bridge Name: Lady's Island Woods Memorial Bridge - AICW The southern channel is closed to navigation until further notice. All vessels are advised to transit through the swing bridge using the northern channel only. The northeastern section of the fender system is damaged and missing. There is no pier lighting identifying the northeastern fender. All mariners are advised to use extreme caution when transiting.

Lat: 32° 25' 39" Lon: -080° 40' 09"

Big Bend Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE			
Big Bend Channel Lighted Buoy 9	OFF STATION	FD				
Private Discrepancies						
· · · · · · · · · · · · · · · · · · ·						
NAME	LLNR	STATUS	AID TYPE			

Big Marco Pass Gordon Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Big Marco Pass-Gordon Pass Daybeacon 2	17095	STRUCT DEST/TRUB/OFF STATION	FD
Big Marco Pass-Gordon Pass Daybeacon 1A	17100	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 2A	17160	STRUCT MISSING/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 3	17165	STRUCT MISSING/TRUB/OFF STATION	FD
Big Marco Pass-Gordon Pass Daybeacon 17	17210	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 18A	17220	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 26	17255	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 28A	17275	STRUCT DEST/TRUB	FD
3 Big Marco Pass-Gordon Pass Daybeacon 33	17300	STRUCT DEST/TRUB	FD
3ig Marco Pass-Gordon Pass Daybeacon 36	17310	STRUCT DEST/TRUB	FD
3ig Marco Pass-Gordan Pass Daybeacon 40	17320	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 46	17335	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 53	17370	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 54	17375	STRUCT DMGD	FD
Big Marco Pass-Gordon Pass Daybeacon 56	17385	STRUCT MISSING/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 60	17400	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 65	17415	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 66	17420	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 67	17420.5	STRUCT MISSING/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Big Marco Pass Obstruction Daybeacon C	17087.2	STRUCT DEST	PA
Big Marco Pass Obstruction Daybeacon A	17087	STRUCT DEST	PA
Big Marco Pass Obstruction Daybeacon B	17087.1	STRUCT DEST	PA
Big Marco Pass Obstruction Light E	17087.4	STRUCT DEST	PA
Isles Of Capri Daybeacon 6	17125	STRUCT MISSING	PA

Biscayne Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Biscayne Bay Daybeacon 57	48490	STRUCT DEST/TRUB	FD

NAME	LLNR	STATUS	AID TYPE
Matheson Hammock South Channel Light 2	49455	LT EXT	PA
Bakers Haulover Smallboat Channel Daybeacon 2	47795	STRUCT DEST	PA
Miami Seaquarium Inlet Pipe Obstruction Light	48600	STRUCT DEST/HAZ NAV	PA
John A Brennan Channel Light 13	49040	LT EXT	PA
Coral Gables Waterway Light 1	49285	STRUCT DEST	PA
Coral Gables Waterway Daybeacon 3	49295	STRUCT DEST	PA
Coral Gables Waterway Daybeacon 4	49300	STRUCT DEST	PA
Coral Gables Waterway Daybeacon 6	49310	DAYMK IMCH	PA
Matheson Hammock South Channel Range Front Light	49445	DAYMK MISSING/STRUCT DMGD	PA

Maritime Safety Information Products | Navigation Center

Matheson Hammock South Channel Range Rear Light	49450	DAYMK MISSING	PA
Matheson Hammock South Channel Daybeacon 9	49485	DAYMK MISSING	PA
Black Point Channel Daybeacon 1	49735	STRUCT DEST	PA
Black Point Channel Daybeacon 6	49760	STRUCT DEST	PA
Black Point Channel Daybeacon 12	49790	STRUCT DEST	PA
Adams Key Light	50105	LT EXT/DAYMK MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Biscayne Bay/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-04-08 To: 2027-12-31 Location: 25.80607° N / 80.25855° W Bridge Name: South Florida Rail Corridor Railroad Bridge - Miami River The draw of the FDOT Railroad Bridge, mile 5.3 at Miami, Florida need not open to navigation. This temporary interim rule (TIR) is effective April 4, 2025, through 11:59 p.m. on December 31, 2027. We encourage you to submit comments through the Federal Decision Making Portal at https://www.regulations.gov. To do so, go to https://www.regulations.gov, type USCG-2025-0204 in the search box and click "Search." Next, look for this document in the Search Results column, and click on it. Then click on the Comment option. Comments and related material must reach the Coast Guard on or before July 3, 2025.	Lat: 25° 48' 22" Lon: -080° 15' 31"
Biscayne Bay/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-04-18 To: 2025-06-28 Location: 25.79503° N / 80.24545° W Bridge Name: Tamiami Bridge - Miami River (Tamiami (C-4) Canal The bridge shall open on the quarter and three-quarter hour. Public vessels of the United States, vessels declaring an emergency and tugs with tows shall be passed at any time. This temporary deviation is effective from 8 a.m. on April 18, 2025, until 11:59 p.m. on June 27, 2025. This action is necessary to allow for repairs to machinery components.	Lat: 25° 47' 42" Lon: -080° 14' 44"
Biscayne Bay/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-05-19 To: 2025-08-30 Location: 25.78882° N / 80.23137° W Bridge Name: Northwest 22nd Avenue Bridge - Miami River - From 8 a.m. on Wednesday, May 28, 2025, through 5 p.m. on Friday, August 29, 2025, the drawbridge will provide single-leaf openings with a 2-hour notice for a full opening The bridge will continue to operate on demand, except during the curfew hours from 7:35 a.m. to 8:59 a.m. and 4:45 p.m. to 5:59 p.m., Monday through Friday, except Federal holidays, the bridge need not open to navigation. (33 CFR 117.305(b)) - When the southern leaf is left in the down position, approximately 20 ft of horizontal clearance is available for navigation. The northern leaf, when in the down position, provides approximately 40 ft of horizontal clearance Mariners are advised to contact the bridge tender at least 2 hours prior to transiting the Miami River if a full channel passage is necessary.	Lat: 25° 47' 20" Lon: -080° 13' 53"
Biscayne Bay/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 25.6632° N / 80.24784° W Fincantieri Infrastructure Florida & GLF USA will be conducting pile driving, dredging and water sampling in the vicinity of Biscayne Bay Aquatic Preserve and Government Cut at furture MSC berths 8 and 9 (25-46-21.1332N/080-9-25.5348W to 25-46-9.1848N/080-8-57.0084W). The estimated completion date is December 15, 2025, hours of operation are 6:30 a.m. to 6:30 p.m., 7 days a week. GLF Construction Corporation will be mobilizing a Crane Barge (54 feet x 150 feet), Service Barge (30 feet X 150 feet), and a Push Boat (15 feet x 25 feet) to the project site on or around June 16, 2022. The equipment is being mobilized to install and maintain the turbidity control system required to perform both land and water-based dredging works. During the installation of the system the above equipment will be operating in the area south of the north navigation channel adjacent to Port Miami. If and when necessary, the equipment will be moved along the southern edge of the north navigation channel to perform any maintenance. Upon arrival at the site the GLF equipment will be positioned inside the Turbidity Control System south of the Navigation Channel and will not move out until completion of the work. GLF will continuously monitor VHF-FM channel 16 and use Channel 9 to maneuver barge and vessels. For further information contact:Alejandro Brito (786) 821-4587 or Alejandro.brito@fl.fcinfrastructure.com.	Lat: 25° 39' 48" Lon: -080° 14' 52"
Biscayne Bay/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 18821 Miami-Dade County Parks, Recreation, and Open Spaces Department will have a contractor within the Haulover Park Boat Ramps and marina replacing the boat ramps and docks. In-water work is expected to begin May 2025 and will continue through July 31, 2025. A barge will be staged within the marina to carry out the marine scope of work. All mariners are requested to use extreme caution and proceed at slow speed (No Wake) when transiting to and from the open portion of boat ramps. The channel to access the marina will remain open to mariners 24 hours a day 7 days a week. All in-water equipment is required to be lighted at night. For further information please contact U.S. Coast Guard Sector Miami.	

Biscayne Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Biscayne Channel Light 3	10820	STRUCT DEST/TRLB	FD
Biscayne Channel Daybeacon 4	10825	HAZ NAV/STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Springs Boat Club Shoal Buoy West	10886	MSLD SIG	PA
Miami Springs Boat Club Shoal Buoy North	10887	MISSING	PA
Miami Springs Boat Club Shoal Buoy South	10889	MISSING	PA

Blackwater Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Blackwater Sound Light 38	50365	LT EXT	FD

Bloody Point Range

NAME	LLNR	STATUS	AID TYPE
Bloody Point Range Front Light	4585	LT EXT	FD

Maritime Safety Information Products | Navigation Center

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Bloody Point Range Lighted Bell Buoy 8	4580	RELOCATED FOR DREDGING	FD
Bloody Point Range Lighted Buoy 13	4615	RELOCATED FOR DREDGING	FD

Blount Island

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Blount Island Turning Basin Lighted Buoy 45	7395	RELOCATED FOR DREDGING	FD
Blount Island Turning Basin Buoy A	7396	RELOCATED FOR DREDGING	FD
Blount Island Turning Basin Buoy B	7397	RELOCATED FOR DREDGING	FD
Blount Island Turning Basin Buoy C	7398	RELOCATED FOR DREDGING	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Fulton Cutoff - Blount	Advanced Notice of	Blount Island Turning Basin LB 45 (LLNR 7395) will be permanently relocated to 30-23-08.280N/081-32-35.920W. The flash	Lat:
Island/ATON/Advanced Notice of Change	Change	characteristic will remain a FL G 4s, but the nominal range will be reduced from 5NM to 4NM.	30° 23' 08"
			Lon:
			-081° 32' 36"

Boca Chita Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
East Featherbeds Obstruction Daybeacon A	49703	DAYMK MISSING	PA
East Featherbed North Obstruction Daybeacon	49703.1	DAYMK MISSING	PA
East Featherbed West Obstruction Daybeacon	49703.3	STRUCT DEST	PA
East Featherbed Northeast Obstruction Daybeacon	49703.5	STRUCT DEST	PA
East Featherbed Southeast Obstruction Daybeacon	49703.6	DAYMK IMCH	PA
East Featherbed NNE Obstruction Daybeacon	49703.70000000004	STRUCT DEST	PA
Middle Featherbeds North Obstruction Daybeacon	49704	DAYMK MISSING	PA
Middle Featherbed NNE Obstruction Daybeacon	49704.3	DAYMK MISSING	PA
Featherbed Bank Shoal Daybeacon X	49725	STRUCT DEST/HAZ NAV	PA

Boca Ciega Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Boca Ciega Bay Daybeacon 35	60915	STRUCT DEST	FD

Boca Ciega Bay To Anclote Anchorage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
The Narrows Daybeacon 14	61535	STRUCT MISSING/TRUB	FD
The Narrows Daybeacon 25	61580	TRUB/STRUCT MISSING	FD
The Narrows Light 27B	61600	STRUCT MISSING/TRLB	FD
The Narrows Daybeacon 38	61660	STRUCT DEST/TRUB	FD

Boca Ciega Key

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Boca Ciega Bay Daybeacon 39	61040	STRUCT DEST/TRUB	FD

Boca Grande Yacht Basin Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Boca Grande Yacht Basin Channel Light 7	21340	STRUCT DEST/TRLB	FD

TITLE SUBCATEGORY	DESCRIPTION	LOCATION
-------------------	-------------	----------

Gasparilla Sound Channel - Boca Grande Yacht Bridges Basin Channel/General/Bridges/Maintenance

Maritime Safety Information Products | Navigation Center

 General/Bridges/Maintenance From: 2025-01-07 To: 2025-11-03 Location: 26.75371° N / 82.2584° W Bridge Name: Boca Grande
 Lat:

 Bayou Temporary Bridge Temporary Construction Bridge (TCB) across the Boca Grande Bayou is authorized to remain in place
 26° 45' 13"

 through April 1, 2026, to allow for the completion of work at the Gasparilla Island Water Association Wastewater Treatment Plant.
 Lon:

 Remaining work includes final site work, demolition of existing structures and removal of the TCB. The center span shall be
 -082° 15'

 removed to allow for unrestricted boating traffic from January 1, 2025, through May 1, 2025, and again from January 1, 2026,
 30"

Bohicket Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bohicket Creek Daybeacon 5	3905	STRUCT MISSING	FD

Bowlegs Cut

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bay Harbour Light	12378	LT EXT	PA

Braden River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Braden River Daybeacon 9	22097.8	STRUCT DEST/HAZ NAV	PA
Braden River Daybeacon 11	22098	STRUCT DEST	PA

Brunswick River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Brunswick Point Cut Range Front Light 2	6230	REDUCED INT	FD
Brandy Point Jetty Daybeacon	6290	STRUCT DEST/HAZ NAV/TRUB	FD

Butchers Bend

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Butchers Bend Light 109	9200	STRUCT DEST/TRLB	FD

Buttermilk Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Buttermilk Sound Daybeacon 217	36967	STRUCT DEST/TRUB	FD
Buttermilk Sound Daybeacon 218	36975	DBD DEST	FD

Caesar Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Caesar Creek Daybeacon 14	11050	STRUCT DEST	FD
Caesar Creek Buoy 29	11125	MISSING	FD
Caesar Creek Buoy 30	11130	MISSING	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Elliott Key - Caesar	Advanced Notice	ATON/Advanced Notice of Change Location: 25.40402° N / 80.24117° W Aid Name: Caesar Creek Buoy 29 LLNR: 11125 Action: DISCONTINUE	Lat:
Creek/ATON/Advanced	of Change	The following changes have been approved to the aids to navigation system in Caesar Creek. Caesar Creek B 29 (LLNR 11125) and Caesar Creek	25° 24' 14"
Notice of Change		B 30 (LLNR 11130) will be permanently discontinued. The immediate area surrounding these buoys has significant shoaling which reduces the	Lon:
		effectiveness in desired navigational safety. Due to strong currents these buoys are constantly being drug off station. Due to the limitations of	-080° 14'
		CG assets that can service this area, buoy mooring configuration is limited. Mariners have been observed entering or departing the channel in	28"
		other areas due to the shoaling experienced.	

Maritime Safety Information Products | Navigation Center

Elliott Key - Caesar	Advanced Notice	ATON/Advanced Notice of Change Location: 25.40427° N / 80.24105° W Aid Name: Caesar Creek Buoy 30 LLNR: 11130 Action: DISCONTINUE	Lat:
Creek/ATON/Advanced	of Change	The following changes have been approved to the aids to navigation system in Caesar Creek. Caesar Creek B 29 (LLNR 11125) and Caesar Creek	25° 24' 15"
Notice of Change		B 30 (LLNR 11130) will be permanently discontinued. The immediate area surrounding these buoys has significant shoaling which reduces the	Lon:
		effectiveness in desired navigational safety. Due to strong currents these buoys are constantly being drug off station. Due to the limitations of	-080° 14'
		CG assets that can service this area, buoy mooring configuration is limited. Mariners have been observed entering or departing the channel in	28"
		other areas due to the shoaling experienced.	

Calibogue Sound

Additional MSI Categories						
TITLE	SUBCATEGORY	DESCRIPTION	LOCATION			
Calibogue Sound Entrance - Calibogue Sound/ATON/Advanced Notice of Change	of Change	ATON/Advanced Notice of Change Location: 32.1499° N / 80.83043° W Aid Name: Calibogue Sound Light 32 LLNR: 35800 Action: CHANGE Action Type Change Light Characteristic The following change has been approved to the Aid to Navigation system in the Intracoastal Waterway Calibogue Sound, part of the Intracoastal Waterway (ICW). The nominal range permanently reduced from 5NM to 4NM. The current nominal range of 5NM is not necessary. Based on the design of the Short-Range Aids System (SRA), mariners should be able to see two lighted aids to navigation forward of the aid from which they are alongside. Based on this data, a nominal range of 4NM is more than adequate.	Lat: 32° 08' 60" Lon: -080° 49' 50"			

Caloosahatchee River

Federal Discrepancies

•						
NAME	LLNR	STATUS	AID TYPE			
Caloosahatchee River Daybeacon 19	52210	STRUCT MISSING	FD			
Caloosahatchee River Light 70	53725	STRUCT DEST/TRLB	FD			
Caloosahatchee River Light 72	53790	STRUCT DEST/TRLB/HAZ NAV	FD			
Caloosahatchee River Daybeacon 94	54760	STRUCT MISSING/TRUB	FD			
Caloosahatchee River Daybeacon 99	54785	TRUB/STRUCT MISSING	FD			

NAME	LLNR	STATUS	AID TYPE
Caloosahatchee River Mooring Channel Daybeacon 4	52644	DAYMK MISSING	PA
Marinatown Daybeacon 12	52710	STRUCT DMGD	PA
Marinatown Daybeacon 23	52765	DAYMK MISSING	PA
Cape Coral Rim Channel Daybeacon 23	53070	HAZ NAV/DAYMK MISSING	PA
/an Riper Channel Daybeacon 2	54296	DAYMK MISSING	PA
/an Riper Channel Daybeacon 4	54296.5	DAYMK MISSING	PA
imini Entrance Channel Daybeacon 2	54305	STRUCT DMGD	PA
Redfish Cove Channel Daybeacon 18	54445	STRUCT DEST	PA
Redfish Cove Channel Daybeacon 20	54455	STRUCT DEST	PA
t Myers Yacht Basin Breakwater Light	52640	STRUCT DEST	PA
Caloosahatchee River Mooring Channel Daybeacon 1	52641	STRUCT DEST	PA
Caloosahatchee River Mooring Channel Daybeacon 2	52642	DAYMK MISSING	PA
Caloosahatchee River Mooring Channel Daybeacon 3	52643	DBD DEST	PA
Caloosahatchee River Mooring Channel Daybeacon 5	52644.1	DBD DEST	PA
Caloosahatchee River Mooring Channel Daybeacon 6	52644.20000000004	DAYMK MISSING	PA
t Myers Yacht Basin Breakwater West Light	52645	STRUCT DEST	PA
Aarinatown Daybeacon 1	52655	DBD DEST	PA
Aarinatown Daybeacon 3	52665	STRUCT DEST	PA
Aarinatown Daybeacon 4	52670	STRUCT DEST	PA
Aarinatown Daybeacon 5	52675	DBD DEST	PA
Aarinatown Daybeacon 7	52685	DAYMK MISSING	PA
Varinatown Daybeacon 8	52690	DBD DEST	PA
Aarinatown Daybeacon 13	52715	DBD DMGD	PA
Aarinatown Daybeacon 22	52760	STRUCT DEST	PA
Aarinatown Daybeacon 24	52770	DAYMK MISSING	PA
Narinatown Daybeacon 26	52780	STRUCT DEST	PA
Sulf Acres Channel Daybeacon 1	52825	STRUCT DEST	PA
Sulf Acres Channel Daybeacon 4	52840	STRUCT DEST	PA
Sulf Acres Channel Daybeacon 5	52845	STRUCT DEST	PA
Sulf Acres Channel Daybeacon 9	52870	STRUCT DEST	PA
Cape Coral Rim Channel Daybeacon 39	53110	STRUCT DEST	PA
/an Riper Channel Daybeacon 6	54297	DAYMK MISSING	PA
/an Riper Channel Daybeacon 8	54297.5	DAYMK MISSING	PA
/an Riper Channel Daybeacon 10	54298	DAYMK MISSING	PA
/an Riper Channel Daybeacon 12	54298.5	DAYMK MISSING	PA
Shell Point Obstruction Daybeacon A	54763	STRUCT DEST	PA

Canaveral Barge Canal

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sykes Creek Daybeacon 19	41620	STRUCT DEST	РА

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Canaveral Harbor - Canaveral Barge Canal/General/Bridges/Construction		General/Bridges/Construction From: 2024-11-12 To: 2025-10-31 Location: 28.40575° N / 80.69424° W Bridge Name: Sea Ray Drive Bridge SEMA Construction, on behalf of the bridge owner, Brevard County, has commenced the demolition, removal, and replacement of Sea Ray Drive Bridge over Sykes Creek on Merritt Island. The contractor will have a small boat on-site, which will be removed from the water at end-of-day. Temporary work platforms may be utilized at future stages of the project. There are no proposed channel restrictions for the early part of this project but can be expected starting approximately early April 2025. For waterways related questions, contact Coast Guard Sector Jacksonville Waterways Management Division at (904) 714-7631 or via email at D07-DG-SECJAX-WATERWAYS@uscg.mil.	Lat: 28° 24' 21" Lon: -080° 41' 39"
Canaveral Harbor - Canaveral Barge Canal/General/Bridges/Temp Deviation		General/Bridges/Temp Deviation From: 2025-03-12 To: 2025-09-29 Location: 28.40925° N / 80.63224° W Bridge Name: 401 State Route Bridges From 7 a.m. on April 2, 2025, through 7 p.m. on September 28, 2025, the drawbridges will provide single-leaf openings with a 4-hour notice for a full opening, per its specific requirements 33 CFR 117.273(b). During this time, the channel will be partially obstructed under the spans painting is occurring. A one-hour advanced notice is required for vessels needing more than 45 feet of horizontal clearance but can safely pass with the spans in the down (closed) position.	Lat: 28° 24' 33" Lon: -080° 37' 56"
Canaveral Harbor - Canaveral Barge Canal/General/Bridges/Repairs, Painting, Or Fender Replacement	5	General/Bridges/Repairs, Painting, Or Fender Replacement From: 2025-03-12 To: 2025-10-18 Location: 28.40925° N / 80.63224° W Bridge Name: 401 State Route Bridges A painting/repair project begins on April 1, 2025, and will be completed on or around October 18, 2025. During the time the bridges will be operating under a temporary deviation to drawbridges operations. The contractor will be on-site 24 hours a day. All in-water equipment should be lighted in accordance with Inland Navigation Rules. Mariners are advised to use caution when transiting through the bridges.	Lat: 28° 24' 33" Lon: -080° 37' 56"

Canaveral Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Canaveral Harbor Entrance Channel Light 14	9655	LT EXT	FD

Cape Haze Shoal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cape Haze Shoal Light 5	19990	HAZ NAV/STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pine Island West Channel Daybeacon 5	56510.1	STRUCT DEST/HAZ NAV	PA
Burnt Store Marina Light 2	20000	LT EXT	PA
Burnt Store Marina Daybeacon 5	20015	STRUCT DEST	PA
Alligator Creek Daybeacon 23	20305	STRUCT DMGD	PA
Alligator Creek Daybeacon 24	20310	STRUCT DEST	PA

Capri Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Capri Pass Light 3	16955	TRLB/STRUCT MISSING	FD
Capri Pass Light 4	16960	STRUCT MISSING/TRLB	FD
Capri Pass Light 4	16960	STRUCT MISSING/TRLB	FD
Capri Pass Daybeacon C	16980	TRLB	FD
Capri Pass Shoal Daybeacon B	17050	STRUCT DEST/TRUB	FD

NAME	LLNR	STATUS	AID TYPE
Addison Bay Daybeacon 4	16901.4	STRUCT DEST/HAZ NAV	PA
Addison Bay Daybeacon 1	16901.1	STRUCT DEST	PA
Addison Bay Daybeacon 2	16901.2	STRUCT DEST	PA
Addison Bay Daybeacon 5	16901.5	STRUCT DEST	PA
South Point North Obstruction Daybeacon	16961	STRUCT DEST/HAZ NAV	PA
South Point S. Obstruction Daybeacon	16962	STRUCT DEST/HAZ NAV	PA
Royal Marco Point North Obstruction Daybeacon	16986	STRUCT DEST	PA
Royal Marco Point S. Obst. Daybeacon	16987	STRUCT DEST	PA
Collier Bay Daybeacon 13	17021	DAYMK MISSING	PA

Maritime Safety Information Products | Navigation Center

Collier Bay Daybeacon 15	17023	DAYMK MISSING	PA
Factory Bay E Channel Daybeacon 2	17070	DBD DMGD	PA
Factory Bay E Channel Daybeacon 4	17075	DBD DEST	PA

Captiva Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Captiva Channel Daybeacon 5	55620	STRUCT DEST	PA

Caxambas Bay

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Blackwater River Daybeacon 24	16565	STRUCT DEST/HAZ NAV	PA
Moran's Marina Channel Daybeacon 1	16835	DAYMK MISSING	PA
Moran's Marina Channel Daybeacon 2	16840	DAYMK MISSING	PA
Blackwater River Daybeacon 10	16505	DAYMK MISSING	PA
Blackwater River Daybeacon 11	16510	STRUCT DEST/HAZ NAV	PA
Blackwater River Daybeacon 13	16520	STRUCT DEST	PA
Blackwater River Daybeacon 15	16530	STRUCT DEST	PA
Blackwater River Daybeacon 22	16555	STRUCT DEST	PA
Caxambas Bay South Approach Daybeacon 2	16675	STRUCT DEST	PA
Caxambas Bay Daybeacon 11	16715	DAYMK MISSING	PA
Horrs Island North Channel Daybeacon 8	16790	STRUCT DEST/HAZ NAV	PA
Snook Hole Channel Daybeacon 1	16790.01000000002	STRUCT DEST	PA
Snook Hole Channel Daybeacon 4	16790.04	STRUCT DEST/HAZ NAV	PA
Big Marco River Daybeacon 3	16800	STRUCT DEST	PA
Moran's Marina Channel Daybeacon 3	16845	DAYMK MISSING	PA
Big Marco River Daybeacon 16	16860	STRUCT DEST	PA
Big Marco River Daybeacon 21	16880	STRUCT DMGD	PA
Big Marco River Daybeacon 26	16900	STRUCT DEST/HAZ NAV	PA

Cedar Keys Main Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cedar Keys Main Channel Daybeacon 8	29770	STRUCT MISSING/TRUB	FD
Cedar Keys Main Channel Light 14	29790	STRUCT MISSING/TRLB	FD
Cedar Keys Main Channel Light 18	29800	STRUCT MISSING/TRLB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Cedar Keys Main	Hazards To	General/Hazards To Navigation/Hazards From: 2024-12-06 To: 2025-06-04 Location: 29.11403° N / 83.04028° W Cedar Key Main	Lat:
Channel/General/Hazards To	Navigation	Channel 19A has been temporarily established to guide vessel traffic channel ward and away from submerged wreckage between Cedar	29° 06' 51"
Navigation/Hazards		Keys Main Channel Daybeacon 19 (LLNR 29805) and Cedar Keys Main Channel Light 21 (LLNR 29810). All mariners are advised to transit	Lon:
		the area with caution.	-083° 02'
			25"

Cedar Keys Northwest Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cedar Keys Northwest Channel Daybeacon 14	29965	STRUCT MISSING/TRUB	FD
Cedar Keys Northwest Channel Daybeacon 17	29980	STRUCT MISSING/TRUB	FD
Cedar Keys Northwest Channel Light 19	29995	STRUCT DEST/HAZ NAV/TRLB	FD
Cedar Keys Northwest Channel Daybeacon 21	30005	TRLB/STRUCT DEST/HAZ NAV	FD
Cedar Key Northwest Channel Daybeacon 22	30010	TRLB/HAZ NAV/STRUCT DEST	FD

Cedar Keys South Bar Channel

NAME	LLNR	STATUS	AID TYPE
Cedar Keys South Bar Channel Daybeacon 4	29900	STRUCT MISSING/TRUB	FD

Charleston Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Charleston Entrance Lighted Buoy C	200	RAC INOP	FD
Charleston Harbor Channel Lighted Buoy 24	2470	OFF STATION	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - Charleston Harbor/ATON/Advanced Notice of Change	Advanced Notice of Change	Charleston Harbor Channel LB 18 (LLNR 2420) will have the bell permanently removed.	Lat: 32° 43' 27" Lon: -079° 48' 37"
Sector Charleston, Submerged Land Act (SLA) - Charleston Harbor/ATON/Advanced Notice of Change	Advanced Notice of Change	Charleston Harbor Channel LB 22 (LLNR 2440) will have the bell permanently removed.	Lat: 32° 44' 26" Lon: -079° 50' 41"
Sector Charleston, Submerged Land Act (SLA) - Charleston Harbor/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2025-02-25 To: 2026-11-13 Location: 32.75328° N / 79.87473° W 32.75232° N / 79.87355° W 32.75075° N / 79.87546° W 32.75198° N / 79.87705° W 32.75328° N / 79.87473° W Cape Romain Contractors will be replacing Fort Sumter and Fort Moultrie Docks and rehabilitate Liberty Square Pier. They will have a crane barge starting March 3, 2025, until May 31, 2026, at Fort Moultrie and crane barges at Fort Sumter and Liberty Square Pier as the project progresses. Estimated completion date of the entire project is 310ctober 31, 2026. All Vessels should use caution when transiting the work area. The crew at Fort Moultrie will monitor VHF-FM channels 13 and 16.	
Sector Charleston, Submerged Land Act (SLA) - Charleston Harbor/General/Miscellaneous	Miscellaneous	General/Miscellaneous Location: 32.69396° N / 79.78294° W 32.69304° N / 79.7677° W 32.69062° N / 79.7651° W 32.68091° N / 79.77577° W 32.68163° N / 79.8054° W 32.68778° N / 79.80401° W 32.69396° N / 79.78294° W Crowley Wind Services will be installing a temporary cable installation and marine construction. Operations are expected to begin in May with an estimated completion date of June 30, 2025, and be conducted 24 hours a day / seven days a week. Vessels being used will be Tug ISABELLE, CTV RELIANCE, diving vessel NORTHSTAR VOYAGER or equivalent. Marmac 306 Barge will be restricted in her ability to maneuver and will have up to 1500 meters of anchor mooring line out around the barge. Anchor/Lines will have buoys; barge will be illuminated during operation. Vessels will be monitoring VHF-FM channels 13 and 16. For further information contact Constantino Goulas, Manager of Marine Operations for Offshore Wind (904) 327-3748 or Tino.goulas@crowley.com	

Charleston Harbor North Channel

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Charleston Harbor - Charleston Harbor North Channel/ATON/Advanced Notice of Change	Advanced Notice of Change	Bennis Reach RFL (LLNR 2505.5) will be relocated to approximate position 32-47-15.433N/079-55-25.965W with an approximate focal height of 29'. The flash characteristics of the optic will remain a Q R. Two passing lights displaying a Fl W 2.5s will be mounted on opposite corners of the platform with both lights synchronized.	Lat: 32° 47' 18" Lon: -079° 55' 29"
Charleston Harbor - Charleston Harbor North Channel/ATON/Advanced Notice of Change	Advanced Notice of Change	Bennis Reach RRL (LLNR 2506) will be relocated to approximate position 32-47-22.658N/079-55-42.841W with an approximate focal height of 71 feet. The new position will keep the RRL on land, located on the top level of a parking garage in downtown Charleston. The flash characteristics of the optic will remain a R Iso 6s.	Lat: 32° 47' 24" Lon: -079° 55' 43"
Charleston Harbor - Charleston Harbor North Channel/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2025-02-25 To: 2026-11-13 Location: 32.78003° N / 79.92337° W 32.77867° N / 79.9233° W 32.77871° N / 79.92452° W 32.7797° N / 79.92455° W 32.78003° N / 79.92337° W Cape Romain Contractors will be replacing Fort Sumter and Fort Moultrie Docks and rehabilitate Liberty Square Pier. They will have a crane barge starting March 3, 2025, until May 31, 2026, at Fort Moultrie and crane barges at Fort Sumter and Liberty Square Pier as the project progresses. Estimated completion date of the entire project is 310ctober 31, 2026. All Vessels should use caution when transiting the work area. The crew at Fort Moultrie will monitor VHF-FM channels 13 and 16.	

Charleston Harbor Savannah River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ramshorn Creek Light 39	35825	STRUCT DEST/TRLB	FD
Private Discrepancies			

NAME	LLNR	STATUS	AID TYPE
Parris Island Fish Haven Buoy	35600	MISSING	PA
Braddock Cove Creek Jetty Light	35815.5	LT IMCH	PA

Charleston Harbor South Channel

NAME	LLNR	STATUS	AID TYPE	
Charleston Harbor South Channel Daybeacon 6	2685	STRUCT DEST/TRUB	FD	

Charlotte Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Charlotte Harbor Channel Lighted Buoy 5	19935	MISSING	FD

Chokoloskee Bay Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
National Park Service Boat Basin South Channel Daybeacon 1	16105	STRUCT DEST	PA
National Park Service Boat Basin South Channel Daybeacon 5	16125	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 1	16135	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 2	16140	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 5	16150	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 6	16155	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 7	16160	STRUCT DEST	PA

Christiansted Harbor Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Christiansted Schooner Channel Lighted Buoy 7	32965	BUOY DMGD	PA
Christiansted Schooner Channel Lighted Buoy 5	32950	OFF STA/LT EXT	PA
Christiansted Schooner Channel Lighted Buoy 6	32955	LT EXT	PA
Christiansted Schooner Channel Lighted Buoy 10	32980	LT EXT	PA
Christiansted Schooner Lighted Buoy 11	32985	LT EXT	PA

Clarks Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE	
Clarks Creek Lighted Buoy 6	2247	MISSING	FD	

Clearwater Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Clearwater Harbor Light 4	61725	STRUCT MISSING/TRLB	FD
Clearwater Wreck Light WR14A	61805	STRUCT MISSING/TRLB	FD
Clearwater Harbor Daybeacon 20	61847	STRUCT DEST/TRUB	FD

Clearwater Pass Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Clearwater Pass Channel Light 7	25700	STRUCT DMGD	FD

Clewiston Channel Route 1B

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Clewiston Channel (Rt 1B) Daybeacon 5	51275	STRUCT DEST/TRLB	FD
Clewiston Channel (Rt 1B) Daybeacon 9	51295	STRUCT DEST	FD
Clewiston Channel (Rt 1b) Light 12	51340	STRUCT DMGD	FD
Clewiston Channel (Rt 1B) Daybeacon 14	51350	STRUCT DEST/TRUB	FD

Cooper River

Maritime Safety Information Products | Navigation Center

NAME	LLNR		STATUS	AID	ТҮРЕ
Cooper River Daybeacon 114	3243	STRUCT DMGD		FD	
Private Discrepancies					
NAME		LLNR	STATUS	A	ID TYPE

NAME	LLINK	STATUS	AID I TPE
Upper Cooper River Daybeacon 22	3288.5	DAYMK DMGD	PA
Don Holt I-526 Bridge Racon	2905.5	RAC INOP	PA
Cooper River Ammunition Pier Light	3015	LT EXT	PA
South Carolina Gas & Elec North Pier Light	3260	LT EXT	PA
South Carolina Gas & Elec South Pier Light	3265	LT EXT	PA
Upper Cooper River Daybeacon 12	3287.8	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Charleston Harbor - Cooper River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2024-10-20 To: 2025-04-18 Location: 32.85289° N / 79.94381° W The USCG will be demolishing, rebuilding and dredging pier november in approximate position 32-51- 09.7N/079-56-48.8W. Operations are expected to commence January 15, 2024, with an estimated completion date of December 31, 2026. During the construction phase operations will be conducted Monday-Friday 7 a.m. to 7 p.m., during dredging operations may be continuous 24 hours a day/ 7 days a week. For further information contact: LCDR John Houk at John.R.Houk@uscg.mil.	Lat: 32° 51' 12" Lon: -079° 56' 45"
Charleston Harbor - Cooper River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 9392 Location: 32.8512° N / 79.94134° W Demolition is now in progress and there are cut piles that may be difficult to see at higher tide within the footprint of the old Pier Romeo. The Manson Construction Team has posted (1) "Danger" Buoy and an Amber Light for demarcation on the outermost submerged piles and obstructions. These markers are attached to a 36-inch diameter steel pile that stands about 20 feet above the water line and among the submerged objects. Beginning October 30, 2024, and ending October 30, 2026, Manson Construction will be performing demolition of the existing pier and construction of a new pier, bulkhead, and shoreline at the Romeo Pier NOAA Facility on the Cooper River. There will be a crane barge, material barges, and support vessels in the area assisting construction operations from 7a.m. to 7p.m., 7 days a week. These activities could pose a hazard to vessels traveling within 900 feet from the bulkhead to the center of the river. Mariners need to take caution when transiting the area. Please watch for dive flags, stay clear of the construction area, and away from any working equipment. Crews will be monitoring VHF-FM channel 61. For more information, please contact Doug Lowe at (904) 465-1762.	Lat: 32° 51' 04" Lon: -079° 56' 29"
Charleston Harbor - Cooper River/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 13304 SOUTHERN DREDGING CO. INC. DREDGE BRUNSWICK will be conducting berth maintenance dredging at the SCSPA North Charleston Terminal. The Dredge will operate on a 24 hour per day, 7 day per week basis until approximately June 27, 2025. To ensure safe passage in the vicinity of the operation, boaters should establish contact with the dredge on VHF marine channels 13 and 16 or by telephone at 843-729-1691.	
Charleston Harbor - Cooper River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 18251 Orion Marine Construction, Inc. will begin construction work at the Hugh K. Leatherman, Sr. Terminal located along the western shore of the Cooper River, North Charleston, SC at (32° 50' 28N/079° 55' 58W). Within the scope of the jobsite, there will be temporary steel structures that will be periodically move as the job progresses. The structures will display a FL 2.5 W, 2NM lights. Operations will consist of dredging, armor stone slope protection installation, pile driving, and new wharf construction. Operations at the project site will commence in May 2025 and will extend through December 2026. Tugboats will monitor VHF channel 13. Mariners are urged to use extreme caution when transiting the work area. For more information, contact the Project Superintendent, Dustyn Fields at dfields@orionmarinegroup.com, or Project Manager, Tyler Satterfield at tsatterfield@orionmarinegroup.com.	
Charleston Harbor - Cooper River/ATON/Proposed Notice of Change	Proposed Notice of Change	ATON/Proposed Notice of Change Location: 32.9403° N / 79.92368° W Aid Name: Cooper River Range D Rear Light LLNR: 3045 Action: RELOCATE The U.S. Coast Guard is proposing the following changes to the Aids to Navigation System in the Cooper River: Cooper River Range D Rear Light (LLNR 3045) will be permanently relocated to approximate position 32-56-27.083N / 079-55-21.194W. Cooper River Range D/F Front Light (LLNR 3040) will have the flash characteristic changed from a Q W to a FL W 2.5s. The light will continue to be an all-around light. Due to the current location of Cooper River Range D Rear Light (LLNR 30465) being inaccessible for a Coast Guard asset to effectively repair the structure, it was determined by relocating the rear range approximately 400 feet further from its current location will offer a much improved range quality and allow CG personnel to service at any tidal state. All comments should be emailed to: d07-smb- dpwpubliccomments@uscg.mil or andrew.m.engle@uscg.mil with Cooper River Range D/F as the subject line. Comments can also be mailed to Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Building, Miami, FL. 33131-3050 to be received by July 31, 2025.	
Charleston Harbor - Cooper River/ATON/Proposed Notice of Change	Proposed Notice of Change	ATON/Proposed Notice of Change Location: 32.93982° N / 79.92463° W Aid Name: Cooper River Range D/F Front Light LLNR: 3040 Action: CHANGE Action Type Change Light Signals The U.S. Coast Guard is proposing the following changes to the Aids to Navigation System in the Cooper River: Cooper River Range D Rear Light (LLNR 3045) will be permanently relocated to approximate position 32-56-27.083N / 079-55- 21.194W. Cooper River Range D/F Front Light (LLNR 3040) will have the flash characteristic changed from a Q W to a FL W 2.5s. The light will continue to be an all-around light. Due to the current location of Cooper River Range D Rear Light (LLNR 30465) being inaccessible for a Coast Guard asset to effectively repair the structure, it was determined by relocating the rear range approximately 400 feet further from its current location will offer a much improved range quality and allow CG personnel to service at any tidal state. All comments should be emailed to: d07- smb-dpwpubliccomments@uscg.mil or andrew.m.engle@uscg.mil with Cooper River Range D/F as the subject line. Comments can also be mailed to Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Building, Miami, FL. 33131-3050 to be received by July 31, 2025.	

Coosaw River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Parrot Creek Daybeacon 3	35235	STRUCT DEST	PA

<u>Cowpens</u>

NAME	LLNR	STATUS	AID TYPE

(Cowpens Daybeacon 73A	50605	STRUCT DEST/HAZ NAV/TRLB	FD

Cranes Bayou

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE	
Dock On The Bay Daybeacon 7	59015	DAYMK MISSING	PA	

Cross Florida Greenway

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cross Florida Greenway Daybeacon 27	29265	STRUCT DEST/TRUB	FD
Cross Florida Greenway Daybeacon 33	29295	STRUCT MISSING	FD
Cross Florida Greenway Daybeacon 36	29310	STRUCT DEST	FD

Cruz Bay

Federal Discrepancies

NAME LLNR			STATUS	AID TYPE		
Cruz Bay Light 32775		DAYMK MISSING		FD		
Private Discrepancies						
NAME		LLNR	STATUS	AID TYPE		
Cruz Bay Buoy 2	32	2785	OFF STA	PA		

Crystal River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Crystal River Entrance Daybeacon 12	28845	DAYMK MISSING	FD
Crystal River Entrance Daybeacon 14	28855	STRUCT MISSING/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Crystal River Daybeacon 25	28952.60000000002	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Crystal River/General/Bridges/Rehabilitation	Bridges	General/Bridges/Rehabilitation From: 2025-03-11 To: 2025-07-01 Location: 28.91606° N / 82.62775° W Bridge Name: North Museum Point Road Bridge The bridge is under repairs and a rehabilitation. The project is expected to be completed by June 30, 2025. The	Lat: 28° 54' 58"
		waterway may be obstructed to navigation; however, the contractor will move to allow for the passage of vessel traffic. All in-water equipment will be lighted. Mariners are advised to use caution when transiting the waterway.	Lon: -082° 37' 40"

Cumberland River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cumberland River Light 33	37390	STRUCT DEST/TRLB	FD
Cumberland River Light 35	37405	STRUCT MISSING/TRLB	FD
Cumberland River Light 46	37540	STRUCT MISSING/TRLB	FD
Cumberland River Daybeacon 51	37560	STRUCT DEST/TRUB	FD
Cumberland River Daybeacon 58A	37603	STRUCT DEST/HAZ NAV/TRLB	FD
Cumberland River Daybeacon 59A	37607	STRUCT DEST/TRUB	FD
Cumberland River Light 60	37610	STRUCT DEST/TRLB	FD
Cumberland River Daybeacon 63	37623	STRUCT DEST/TRUB	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Andrew Sound - Cumberland	Advanced Notice	Cumberland River LT 35 (LLNR 37405) will be relocated due to the water depth at current location being too deep for CG assets to effect	Lat:
River/ATON/Advanced Notice of	of Change	repairs. The aid will be relocated approximately 453 yards south of its current location in a depth of 15 feet. This change will ensure safe	30° 57' 15"
Change		navigation and keep the same alignment with the surrounding aids in the Cumberland River. Cumberland River LT 35 (LLNR 37405) will	Lon:
		be relocated to approximate position 30-57-14.700N/081-25-44.460W.	-081° 25'
			44"

Cumberland Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cumberland Sound Upper Range A Rear Light	6695	STRUCT DEST	FD
Cumberland Sound Shoal Light A	6773	STRUCT DEST	FD
Cumberland Sound Shoal Light B	6837	STRUCT DEST	FD
Cumberland Sound Shoal Light D	6867	STRUCT DEST	FD
Cumberland Sound Shoal Light G	6892	STRUCT DEST	FD
Cumberland Sound Shoal Light H	6894	STRUCT DEST/TRLB/MISSING	FD
Cumberland Sound Shoal Light I	6927	STRUCT DEST	FD
Cumberland Sound Range F Front Light	37645	LT EXT	FD
Cumberland Sound Daybeacon 71	37665	DBD DEST	FD

Cut A Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Skyway Pier Southeast Light	22425	LT EXT	PA
Tampa Bay Skyway Pier Northeast Light	22430	LT EXT	PA

Cut G Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Smacks Bayou Daybeacon 13	25025.9	STRUCT DEST	PA
Smacks Bayou Daybeacon 14	25026	HAZ NAV/DAYMK MISSING	PA
Smacks Bayou Daybeacon 1	25025	STRUCT DEST	PA
Smacks Bayou Daybeacon 3	25025.2	STRUCT DEST	PA
Smacks Bayou Daybeacon 5	25025.4	STRUCT DEST	PA
Smacks Bayou Daybeacon 6	25025.5	DAYMK MISSING	PA
Smacks Bayou Daybeacon 8	25025.60000000002	STRUCT DEST	PA
Smacks Bayou Daybeacon 10	25025.7	STRUCT DEST/HAZ NAV	PA
Smacks Bayou Daybeacon 15	25026.10000000002	DAYMK MISSING	PA
Smacks Bayou Daybeacon 16	25026.2	DAYMK MISSING	PA

Cut K Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE	
Tampa Bay Cut K Channel Lighted Buoy 10K	23930	BUOY DMGD	FD	

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Westshore Yacht Club Light 2	23814.10000000002	STRUCT DEST	PA
Old Tampa Bay Pipeline West Light	23950.5	STRUCT DEST/HAZ NAV	PA
Bay Crest Daybeacon 5	24275	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 9	25065	STRUCT DEST	PA
Bayou Grande Channel Daybeacon 30	25150	STRUCT DEST	PA
Mobel Americana Channel Daybeacon 3	25260.2	DAYMK MISSING	PA
Tanglewood Channel Daybeacon 1	25265	STRUCT DEST	PA
Rattlesnake Channel Daybeacon A	23814	DAYMK IMCH	PA
Westshore Yacht Club Daybeacon 4	23814.2	STRUCT DEST	PA
Culbreath Bayou North Daybeacon 3	24070	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 2	25040	STRUCT DEST	PA
Bayou Grande Channel Daybeacon 3	25045	DAYMK DMGD	PA
Bayou Grande Channel Daybeacon 21	25105	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 31	25155	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 41	25200	STRUCT DEST	PA

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
-------	-------------	-------------	----------

Maritime Safety Information Products | Navigation Center

Tampa Bay Cut J Channel - Cut K	Bridges	General/Bridges/Construction From: 2024-11-19 To: 2025-09-30 Location: 27.92889° N / 82.58725° W Bridge Name: Howard Frankland	Lat:
Channel/General/Bridges/Construction		I-275 Bridges Construction of the new I-275 Howard Frankland Bridge crossing Old Tampa Bay is ongoing. Bridge work will be	27° 55' 44"
		performed 24 hours per day, Monday through Saturday. 5/22/2025 THROUGH 7/31/2025 CCHANNEL TRAFFIC WILL BE OBSTRUCTED	Lon:
		NORTH OF THE EXISTING FENDER FOR INSTALLATION OF THE FENDER SYSTEM ON THE NEW HOWARD FRANKLAND BRIDGE. WE	-082° 35'
		WILL HAVE TUGBOATS ACTIVELY WORKING EVERY SHIFT WHILE THE CHANNEL IS OBSTRUCTED AND BARGES CAN BE MOVED OUT	14"
		OF THE CHANNEL WITHIN 30 MINUTES TO AN HOUR. DURING CONSTRUCTION THE CHANNEL WILL BE IMPEDED BY ~5'-0" ON	
		BOTH SIDES OF THE CHANNEL FOR INSTALLATION OF A PILE TEMPLATE. THIS IMPEDENCE IS ON THE EAST AND WEST SIDE OF THE	
		FENDER SYSTEM. TEMPLATES MAY BE INSTALLED UP TO 24 HOURS A DAY UNTIL CONSTRUCTION IS COMPLETE. VHF RADIO	
		CHANNELS MONITORED: 13, 22A, AND 16	

Darien River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Darien River Daybeacon 17	36826.70000000004	STRUCT DEST/TRUB	FD

Derrick Key Gap Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Derrick Key Gap Channel Daybeacon 2	30055	STRUCT DEST	FD
Derrick Key Gap Channel Daybeacon 3	30060	TRLB/STRUCT MISSING	FD

District 7, Oceanic boundary to EEZ

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Nicolas Point Channel Light 4	33400	STRUCT DEST/HAZ NAV/TRLB	FD
St Nicolas Point Channel Light 7	33415	STRUCT DEST/TRLB	FD
Radio Point Light 1	33490	LT EXT	FD
Evans Point Light 8	33530	DBD DEST	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
St Nicolas Point Channel Lighted Buoy 6	33410	RELOCATED FOR DREDGING	FD

Doboy Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Doboy Sound Buoy 2	5920	OFF STA	FD
Doboy Sound Buoy 3	5925	MISSING	FD
Doboy Sound Buoy 4	5930	OFF STA	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sapelo Island LT	5946	LT EXT	PA

Drummond Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Drummond Creek Cut Lighted Buoy 59	7500	OFF STATION	FD
Drummond Creek Range Front Light	7515	STRUCT DEST/TRLB	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Drummond Creek Lighted Buoy 58	7505	RELOCATED FOR DREDGING	FD
Drummond Creek Lighted Buoy 61	7525	RELOCATED FOR DREDGING	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Johns River - Drummond Creek/ATON/Advanced Notice of Change	Advanced Notice of Change	Drummond Creek RFL (LLNR 7515) will be permanently relocated to approximate position 30-24-45.104N / 081-35-35.319W. The RFL will remain a nighttime optic only and flash characteristic will remain as a Q R. The RFL will continue to display daymarks for the day-time signal. Both Drummond Creek RFL and RRL will be upgraded with LED light signals to provide a much more reliable signal when using this channel. An additional light will be established and mounted on top of the Drummond Creek RFL optic and synchronized with the RFL to display a Q R flash characteristics during nighttime hours only, with a nominal range of 3NM.	Lon:

Duplin River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Doboy Sound Light 178	36795	STRUCT MISSING/TRLB	FD

East Cape

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
East Cape Daybeacon 1A	15655	STRUCT DEST/HAZ NAV/TRUB	FD

Elba Island Cut

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Lower Flats Range - Elba	Advanced Notice	ATON/Advanced Notice of Change Location: 32.06387° N / 80.99495° W Aid Name: Elba Island Cut Light 10 LLNR: 35900 Action: CHANGE	Lat:
Island Cut/ATON/Advanced	of Change	Action Type Change Light Characteristic The following change has been approved to the Aid to Navigation system in the Intracoastal Waterway	32° 03' 50"
Notice of Change		Elba Island Cut Channel, part of the Intracoastal Waterway (ICW). The nominal range permanently reduced from 5NM to 4NM. The current	Lon:
		nominal range of 5NM is not necessary. Based on the design of the Short-Range Aids System (SRA), mariners should be able to see two lighted	-080° 59'
		aids to navigation forward of the aid from which they are alongside. Based on this data, a nominal range of 4NM is more than adequate.	42"

<u>Elliott Key</u>

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Elliott Key Daybeacon 15	10935	STRUCT DEST	FD
Elliott Key Light 16	10940	DAYMK MISSING/STRUCT DMGD/TRLB	FD
Elliott Key Daybeacon 17	10945	STRUCT DEST	FD
Elliott Key Daybeacon 19	10955	STRUCT DEST/HAZ NAV/TRLB	FD
Pacific Reef Daybeacon 3	10965	STRUCT DEST	FD

Entrada Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Entrada Channel Daybeacon 1	49240	STRUCT DEST/HAZ NAV	PA
Entrada Channel Daybeacon 3	49245	STRUCT DEST/HAZ NAV	PA
Entrada Channel Daybeacon 5	49250	DAYMK MISSING	PA
Entrada Channel Daybeacon 7	49255	DAYMK MISSING	PA
Entrada Channel Daybeacon 9	49260	DAYMK MISSING	PA
Entrada Channel Daybeacon 11	49265	DAYMK MISSING	PA
Entrada Channel Daybeacon 13	49270	DAYMK MISSING	PA

Fields Cut

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Lower Flats Range - Fields Cut/ATON/ATON Changes	ATON Changes	ATON/ATON Changes 21049 Location: 32.08681° N / 80.93346° W Aid Name: Fields Cut Lighted Buoy 48A LLNR: 35865.5 Action: RELOCATE New position: 32-05-10.910N / 080-55-59.591W QR	Lat: 32° 05' 13" Lon: -080° 56' 00"
Lower Flats Range - Fields Cut/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported 21052 Location: 32.08666° N / 80.9333° W Shoaling reported 3 FT at MLW	Lat: 32° 05' 12" Lon: -080° 55' 60"

Fishermans Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fishermans Channel Light 11	10685	STRUCT DEST/TRLB	FD

NAME	LLNR	STATUS	AID TYPE
Dodge Island Mooring Obstruction Light	10692	STRUCT DEST	PA

<u>Florida Bay</u>

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Long Key Light 44	13495	STRUCT DEST/HAZ NAV/TRLB	FD
East Turtle Shoal Light 45	13610	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Flamingo Channel Light 9	15680	DAYMK MISSING	PA
Flamingo Channel Light 15	15710	STRUCT DEST	PA
Flamingo Channel Daybeacon 16	15715	DAYMK MISSING	PA
Coot Bay Daybeacon 2	15730	STRUCT DEST	PA
Coot Bay Daybeacon 8	15755	DAYMK MISSING	PA

Florida Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Florida Passage Daybeacon 102	36385	STRUCT MISSING/TRUB	FD

Floyd Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Floyd Creek Daybeacon A27	37496	STRUCT DEST/TRUB	FD

Fort Gates

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fort Gates Light 67	8525	STRUCT DEST/TRLB	FD

Fort Jackson

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fort Jackson Inbound Range Front Light	4955	STRUCT MISSING	FD

Fort Pierce Inlet Inner Harbor

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Fort Pierce Inlet Inner Harbor Lighted Buoy 9	9840	WATCHING PROPERLY	FD	2025-06-10

Frederica River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fredericka Yacht Club Obstruction Light	6170	LT EXT	PA

Fulton Cutoff

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE	
Fulton Cutoff Light 36	7360	STRUCT DEST/TRLB	FD	

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Fulton Cutoff Lighted Buoy 37	7365	RELOCATED FOR DREDGING	FD
Blount Island Turning Basin Lighted Buoy 43	7385	RELOCATED FOR DREDGING	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION	

Maritime Safety Information Products | Navigation Center

St Johns River - Fulton Cutoff/ATON/Advanced Notice of Change	Advanced Notice of Change	Fulton Cutoff LB 35 (LLNR 7345) will be permanently relocated to 30-23-24.090N/081-30-22.230W. This change calls to relocate (6) lighted buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe navigation for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this change. All positions listed are approximate. Permanent positions will be advertised when the work is completed.	Lat: 30° 23' 24" Lon: -081° 30' 22"
St Johns River - Fulton Cutoff/ATON/Advanced Notice of Change		Blount Island Turning Basin LB 43 (LLNR 7385) will be permanently relocated to 30-23-13.450N/081-32-05.380W. The flash characteristic will remain a Fl G 6s, but the nominal range will be reduced from 5NM to 4NM.	Lat: 30° 23' 13" Lon: -081° 32' 05"

Gables Estates

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gables Estates Daybeacon 2A	49345	STRUCT DEST/HAZ NAV	PA
Gables Estates Light 2	49340	LT EXT	PA

Gadsden Point Cross Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gadsden Point Cross Channel Daybeacon 10	22965	STRUCT MISSING/TRUB	FD

Gadsden Point Cut

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE	
Gadsden Point Cut Range Rear Light Passing Lights	22855.5	RELIGHTED	FD	2025-06-10	

Garden Cove

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Garden Cove Daybeacon 3	11550	DAYMK MISSING	PA
Garden Cove Daybeacon 4	11555	DBD DEST	PA
Garden Cove Daybeacon 4	11555	DAYMK IMCH/STRUCT DMGD	PA
Garden Cove Daybeacon 6	11565	STRUCT DEST/HAZ NAV	PA
Garden Cove Daybeacon 8	11575	DAYMK IMCH	PA
Garden Cove Daybeacon 9	11580	DAYMK MISSING	PA
Garden Cove Daybeacon 11	11590	RBN IMCH	PA

Gasparilla Sound Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gasparilla Sound Channel Daybeacon 21	56650	STRUCT MISSING/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gasparilla Island South Obstruction Light	1305.2	LT EXT	PA
Gaparilla Island West Obstruction Light	1305.4	LT EXT	PA
Gasparilla Island North Obstruction Light	1305.600000000001	LT EXT	PA
Gasparilla Marina Channel Daybeacon 6	56715	STRUCT DEST	PA

Gordon Pass Channel

NAME	LLNR	STATUS	AID TYPE
Gordon Pass Channel Buoy 1	17453	MISSING	FD
Gordon Pass Channel Light 3	17460	STRUCT MISSING/TRLB	FD
Gordon Pass Channel Light 4	17465	DBD DEST	FD

Great Pocket

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Great Pocket Daybeacon 10	45970	STRUCT DEST/TRUB	FD

Grouper Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Grouper Creek Daybeacon 52A	50425	STRUCT DEST/HAZ NAV/TRLB	FD

Halifax River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Halifax River Daybeacon 40	40180	STRUCT DMGD	FD
Halifax River Daybeacon 48	40215	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 53	40235	STRUCT MISSING/TRUB	FD
Halifax River Daybeacon 56	40245	STRUCT MISSING/TRUB	FD
Halifax River Daybeacon 57	40335	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 60	40435	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 72	40490	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Adventure Yacht Harbor Daybeacon 6	40375	STRUCT DEST	PA
Halifax Harbor Daybeacon 1	40055	DAYMK MISSING	PA
Halifax Harbor Daybeacon 4	40070	DAYMK MISSING	PA
Halifax Harbor Daybeacon 6	40080	DAYMK MISSING	PA
Halifax Harbor Daybeacon 8	40090	STRUCT DEST	PA
Halifax Harbor Daybeacon 9	40095	STRUCT DEST	PA
Adventure Yacht Harbor Daybeacon 4	40365	DAYMK MISSING	PA
Adventure Yacht Harbor Daybeacon 7	40380	STRUCT DEST	PA
Adventure Yacht Harbor Daybeacon 8	40385	DAYMK MISSING	PA
Adventure Yacht Harbor Daybeacon 9	40390	DAYMK MISSING	PA
Adventure Yacht Harbor Junction Daybeacon	40410	DAYMK IMCH	PA

Hampton River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hampton River Daybeacon 12	5975	STRUCT DEST/TRUB	FD

Hillsboro Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsboro Inlet Entrance Light 2	10293	DBD DEST	FD

Hillsboro River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsboro River Light 73	47225	DBD DMGD	FD
Pompano Beach Light 76	47235	HAZ NAV/STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Moran Dock North Light	47175	LT IMCH	PA
Moran Dock Center Light	47180	LT IMCH	PA
Moran Dock South Light	47185	LT EXT	РА

Maritime Safety Information Products | Navigation Center

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Hillsboro Inlet - Hillsboro River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-05-28 To: 2025-07-05 Location: 26.25026° N / 80.09003° W Bridge Name: Northeast 14th Street Bridge - AICW The bridge need not open to navigation including tugs with tows, from 9 p.m. to 11 p.m. on Friday, July 4, 2025, to facilitate the City of Pompano Beach July 4th Fireworks Spectacular Event. Public vessels of the United States and vessels in distress shall be passed at any time.	Lat: 26° 15' 01" Lon: -080° 05' 24"
Hillsboro Inlet - Hillsboro River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-05-28 To: 2025-07-05 Location: 26.23187° N / 80.09382° W Bridge Name: East Atlantic Boulevard Bridge - AICW The bridge need not open to navigation including tugs with tows, from 9 p.m. to 11 p.m. on Friday, July 4, 2025, to facilitate the City of Pompano Beach July 4th Fireworks Spectacular Event. Public vessels of the United States and vessels in distress shall be passed at any time.	Lat: 26° 13' 55" Lon: -080° 05' 38"
Hillsboro Inlet - Hillsboro River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-06-02 To: 2025-07-05 Location: 26.18988° N / 80.10284° W Bridge Name: Commercial Boulevard Bridge - AICW The bridge need not open to navigation including tugs with tows, from 9 p.m. to 11 p.m. on Friday, July 4, 2025, to facilitate the Town of Lauderdale-by-the-Sea July 4th Fireworks Event. Public vessels of the United States and vessels in distress shall be passed at any time.	Lat: 26° 11' 24" Lon: -080° 06' 10"

Hillsborough Cut C Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsborough Cut C Channel Inbound Range Front Light	23435	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Yacht & Country Club Daybeacon 4	23454	STRUCT DEST	PA
Hookers Point North Warning Daybeacon	23515	STRUCT DEST/HAZ NAV	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Big Bend Channel - Hillsborough Cut C Channel/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 27.90797° N / 82.43823° W Aid Name: Hillsborough Cut C Channel Inbound Range Front Light LLNR: 23435 Action: CHANGE Action Type Change Light Characteristic Hillsborough Cut C Channel Inbound Range Front Light (LLNR 23435) characteristic will change to Iso W 2s (NIGHT) and Iso W 2s (Day).	Lat: 27° 54' 29" Lon: -082° 26' 18"
Big Bend Channel - Hillsborough Cut C Channel/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 27.92022° N / 82.43696° W Aid Name: Hillsborough Cut C Channel Inbound Range Rear Light LLNR: 23440 Action: CHANGE Action Type Change Light Characteristic Hillsborough Cut C Channel Inbound Range Rear Light (LLNR 23440) characteristic will change to Iso W 6s (NIGHT) and Iso W 6s (Day).	Lat: 27° 55' 13" Lon: -082° 26' 13"
Big Bend Channel - Hillsborough Cut C Channel/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes Orion Marine Group is currently contracted by the Tampa Bay Port Authority, operating as Port Tampa Bay, to construct the new berth (Berth 218 Wharf) at the Titan America facility. Orion respectfully requests that a revised Notice to Mariners be issued concerning our construction operations at 4231 Maritime Boulevard, Tampa, FL, specifically for Berth 218 Wharf. The construction activities will be conducted using the ORION IS-1505 Barge, a rental material barge from McDonough Marine Services (unnamed), as well as the ORION BRAVE. Floating equipment will be positioned within the designated Jobsite Working Limits, as delineated in the attached drawing of the Berth 218 project site. Orion will deploy spuds on the ORION IS-1505 Barge, which will be equipped with illuminating lights to enhance visibility. All floating equipment will be staged east of the channel inlet and equipped with marine lights. The ORION BRAVE will operate under the "WDM4416" call sign and actively monitor channels 13, 16, and 74 for communications. Construction is scheduled from October 21, 2024, to November 15, 2025. During this timeframe, operations will occur from 6 a.m. to 6 p.m., six days per week (Monday through Saturday). The floating equipment will remain onsite for the duration of the project. Orion respectfully advises all mariners to exercise heightened caution when navigating the construction area. We kindly request that vessels reduce speed while transiting through the Port Tampa Bay channel at Berth 218.	

Hillsborough Cut D Channel

Federal Discrepancies

NAME		LLNR	STATUS	AID TYPE
Hillsborough Cut D Channel Outbound Range Rear Light 2			LT EXT	FD
Private Discrepancies				
NAME	LLNR	ST	ATUS	AID TYPE
Bulk Liquid Cargo Dolphin 4 Obstruction Light	23530	STRUCT DEST		PA

Hollywood Beach

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION	

Maritime Safety Information Products | Navigation Center

Port Everglades - Hollywood Beach/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 26.07538° N / 80.11411° W Continental Heavy Civil Corp. will be conducting marine construction, dredging, barge operations and pile driving in the ICW from 1,300 feet south of the Dania Beach Cutoff Channel to Sheridan Street west of the ICW. From 26-03-37.17N/080-06-53.74W to 26-03-37.17N/080-06-53.74W. Operations are expected to commence July 3, 2023 with an estimated completion date of July 3, 2025. Operations will be conducted Monday through Saturday 6 a.m. to 7 p.m. Navigation will not be impeded. Mariners are urged to proceed with caution while operating in the vicinity of the vessels. There will be multiple vessels onscene and they will be monitoring VHF-FM channel 69. For further information contact: Jose Galicia, project manager jgalicia@chcivil.com	Lat: 26° 04' 31" Lon: -080° 06' 51"
Port Everglades - Hollywood Beach/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2024-10-20 To: 2025- 04-18 Location: 26.05735° N / 80.11538° W Continental Heavy Civil Corp. will be Installing wood piles and rip-rap stone to protect mangroves and the shoreline from erosion. Land clearing and removal of invasive trees of the islands. Work is scheduled to commence February 5, 2024, Monday to Friday from 6 a.m. to 6 p.m. with an estimated completion date of July 1, 2025. Work will be done approximately 1,300 feet South of Dania Boulevard Bridge on the West side of the ICWW limits, adjacent to the West Lake Park Islands. Northern point of work: 26-03-08.73N/80-06-56.33W Southern point of work: 26-02-55.31N/80-06-57.51W For further information contact the project manager: Jose Galicia at Jgalicia@chcivil.com.	-080° 06'
Port Everglades - Hollywood Beach/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 26.03806° N / 80.11733° W Continental Heavy Civil Corp. will be conducting dredging in the vicinity of West Lake Park Segment 4 along the FL ICW, approximately 1,600 feet South of Dania Boulevard Bridge. Dredging is anticipated to begin September 15, 2023, to July 15, 2025. There will be a 30 foot by 90 foot barge spud down and a 100 foot by 30 foot wide material barge moored on each side anchor lights will be marking the 4 corners. Four Buoys with Danger Keep out labels to be installed outlining the four corners of the mooring area. Buoy 1: 26-02-54.44N/080-07-02.33W Buoy 2: 26-02-55.15N/080-06-58.49W Buoy 3: 26-02-56.78N/080-06-59.21W Buoy 4: 26-02-56.31N/080-07-02.62W For further information contact: Jose Galicia, project manager jgalicia@chcivil.com.	Lon:

Homosassa River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Homosassa River Daybeacon 2	28715	STRUCT DEST/HAZ NAV	PA

Horseshoe Beach

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Horseshoe Beach Approach Daybeacon 4	30365	STRUCT MISSING/TRUB	FD
Horseshoe Beach Approach Light 7	30375	STRUCT MISSING/TRLB	FD
Horseshoe Beach Approach Light 9	30380	STRUCT MISSING/TRLB	FD
Horseshoe Beach Channel Light 10	30385	TRLB/STRUCT DEST/HAZ NAV	FD
Horseshoe Beach Channel Daybeacon 12	30395	STRUCT MISSING	FD
Horseshoe Beach Channel Daybeacon 13	30400	STRUCT MISSING	FD
Horseshoe Beach Channel Daybeacon 14	30410	HAZ NAV/STRUCT DEST/TRUB	FD
Horseshoe Beach Channel Daybeacon 15	30420	STRUCT MISSING/TRLB	FD
Horseshoe Beach Channel Light 16A	30425	STRUCT MISSING	FD
Horseshoe Beach Channel Daybeacon 21	30445	STRUCT MISSING	FD
Horseshoe Beach Channel Daybeacon 23	30450	STRUCT MISSING	FD

Indian Key Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Indian Key Pass Light 4	15980	STRUCT DEST	FD
Indian Key Pass Daybeacon 13	16020	STRUCT DEST/TRUB	FD

Indian River North Section

NAME	LLNR	STATUS	AID TYPE
Indian River (North Section) Light 1	41100	STRUCT DEST/TRLB	FD
Indian River (North Section) Light 7	41130	STRUCT MISSING/TRUB	FD
Indian River (North Section) Daybeacon 34	41315	STRUCT MISSING/TRUB	FD
Indian River (North Section) Daybeacon 44	41415	STRUCT DEST/TRUB	FD
Indian River (North Section) Daybeacon 49	41430	DAYMK MISSING	FD
Indian River (North Section) Daybeacon 71	42090	STRUCT DEST/TRUB	FD
Indian River (North Section) Daybeacon 79	42175	STRUCT DMGD	FD
Indian River (North Section) Daybeacon 81	42185	STRUCT DEST/TRUB	FD
Indian River (North Section) Light 83	42190	LT EXT	FD
Indian River (North Section) Daybeacon 91	42270	STRUCT DEST/TRUB	FD
Indian River (North Section) Daybeacon 94	42280	STRUCT DEST/TRUB	FD
Indian River (North Section) Daybeacon 99	42335	STRUCT DMGD	FD

Maritime Safety Information Products | Navigation Center

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
POW-MIA Channel Danger Daybeacon A	42254	DAYMK MISSING	PA
POW-MIA Channel Danger Daybeacon D	42254.3	DAYMK MISSING	PA
POW-MIA Channel Danger Daybeacon E	42254.4	DAYMK MISSING	PA
Grills Riverside Marina Daybeacon 1	42286	DAYMK DMGD	PA
Grills Riverside Marina Daybeacon 3	42286.20000000004	DAYMK MISSING	PA
Grills Riverside Marina Daybeacon 4	42286.3	DAYMK MISSING	PA
Grills Riverside Marina Daybeacon 5	42286.4	HAZ NAV/DAYMK MISSING	PA
Jones Point Channel Buoy 1	41495	MISSING	PA
Jones Point Channel Buoy 2	41500	MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Banana River - Indian River North	Bridges	General/Bridges/Construction From: 2024-11-12 To: 2026-04-30 Location: 28.527349° N / 80.765526° W Bridge Name: NASA	Lat:
Section/General/Bridges/Construction		Causeway Bridges - AICW Construction continues on the new high-level bridges which is expected to be completed April 2026. The	28° 31' 38"
		navigational clearances provide a fixed vertical clearance of 66 feet at mean high water and 125 feet between the new fender	Lon:
		system. Construction vessels on the project will monitor channels 13, 16 and Working Channel 1. Mariners are urged to use extreme	-080° 45'
		caution in the area, transit at their slowest safe speed to minimize wake.	56"

Indian River South Section

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Indian River (South Section) Daybeacon 10	43265	STRUCT DEST/TRUB	FD
Indian River (South Section) Light 14	43275	DAYMK MISSING	FD
Indian River (South Section) Daybeacon 17	43290	DAYMK MISSING	FD
Indian River (South Section) Daybeacon 32	43415	STRUCT DEST/TRUB	FD
Indian River (South Section) Light 53	43520	HAZ NAV/STRUCT DEST/TRLB	FD
Indian River (South Section) Light 96	43860	DBD DEST	FD
Indian River (South Section) Light 112	43920	DAYMK DMGD	FD
Indian River (South Section) Daybeacon 132	44150	STRUCT DEST	FD
Indian River (South Section) Daybeacon 143	44380	STRUCT DEST	FD
Indian River (South Section) Daybeacon 144	44385	STRUCT DEST/TRUB	FD
Indian River (South Section) Daybeacon 160	44595	DBD DEST	FD
Indian River (South Section) Daybeacon 170	44830	STRUCT DMGD	FD
Indian River (South Section) Daybeacon 170	44830	STRUCT DEST/TRUB	FD
Indian River (South Section) Light 187	45115	STRUCT DEST/HAZ NAV/TRLB	FD
Indian River (South Section) Daybeacon 188	45195	STRUCT MISSING/TRUB	FD
Indian River (South Section) Light 192	45270	LT EXT/DAYMK MISSING/STRUCT DMGD/TRLB	FD
Indian River (South Section) Daybeacon 212	45390	STRUCT MISSING/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Turkey Creek Daybeacon 22	43272.20000000004	STRUCT DEST	PA
River Run Daybeacon 5	43720	DAYMK MISSING	PA
Tidewater Island Club Channel Daybeacon 3	44390.3	STRUCT MISSING	PA
Queens Cove Daybeacon 10	44945	STRUCT DEST/HAZ NAV	PA
Rigels Cove Channel Daybeacon 7	45615	DAYMK IMCH	PA
Outrigger Harbour Daybeacon 1	45710	STRUCT DEST	PA
Ind River Plantation Marina Channel Daybeacon 2	45825	STRUCT DMGD	PA
Breakwater Danger Daybeacon A	45863	DAYMK MISSING	PA
Breakwater Danger Daybeacon B	45863.1	DAYMK MISSING	PA

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Fort Pierce Inlet Inner Harbor - Indian River South Section/General/Bridges/Repairs, Painting, Or Fender Replacement		bridge repairs on the 17th street (SR 656) Bridge over the AICW (Indian River) mile marker 952.9 at Vero Beach, FL beginning November 13, 2023, with an estimated completion during January 2028. The project will remove and replace 400 feet of the eastern	Lat: 27° 37' 56" Lon: -080° 22' 16"

Maritime Safety Information Products | Navigation Center

Fort Pierce Inlet Inner Harbor - Indian	Bridges	General/Bridges/Conversion From: 2024-10-29 To: 2025-04-27 Location: 27.47199° N / 80.32452° W Bridge Name: A1A State Route	Lat:
River South		Bridge Vecellio & Grogan, Inc. ("V&G"), on behalf of the bridge owner, FDOT, are conducting construction operations for the	27° 28' 19"
Section/General/Bridges/Conversion		replacement of the A1A North Causeway Drawbridge across the AICW, mile 964.8, at Ft. Pierce, FL. A temporary work trestle (platform)	Lon:
		has been installed on the northeast side of the existing A1A North Causeway Bridge. In water work continues directly adjacent to and	-080° 19'
		across the navigable waterway with barge(s) in order to perform other associated construction activities. In April 2025, new bridge	28"
		beams will be installed over the channel which will permanently limit the vertical clearance to 85 ft. at mean high water. The existing	
		drawbridge will remain in use until sometime in late 2026. During bridge beam setting operations in April and May 2025, there will be	
		intermittent closures of the channel for 3-4 hours at a time for safety. Vessels needing a full channel passage are required to provide the bridge tender with a 2-hour advance notice to allow for the barges to clear the channel. During the evening/overnight hours the	
		channel will be unobstructed. All in-water equipment will be properly lighted. All mariners are requested to use caution and transit the area at a slow speed. For waterways questions or drawbridge operating issues, please contact USCG Sector Miami Waterways Division	
		at (305) 535-4317, email SectorMiamiWaterways@uscg.mil	

Intracoastal Waterway Florida Seventh District

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Okeechobee (Rt 2) Daybeacon 13	51445	STRUCT MISSING	FD

Isla De Vieques

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Isla De	Hazards To	The U.S. NAVY is advising all mariners to refrain from entering the following areas in Vieques, Puerto Rico: Northeast from Puerto Diablo to	
Vieques/General/Hazards To Navigation/Hazards	5	Punta Este and on the Southeast on Bahia Salinas Del Sur. Mariners are advised to stay away from this danger zone until further notice, as it contains (UXO) Unexploded Ordnance. The U.S. Coast Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041. For more information, contact Mrs. Maria Danois at: (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.	

Isla Magueyes

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Isla De Mona Light	32295	LT EXT/STRUCT DMGD	FD

Jekyll Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jekyll Creek Jetty Warning Daybeacon 8	37305	DAYMK MISSING	FD
Jekyll Creek Light 20A	37346	STRUCT DEST/TRLB	FD
Jekyll Creek Light 29	37370	STRUCT DEST/TRLB	FD

Johns Pass Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Johns Pass Channel Daybeacon 1	25580	STRUCT DEST/TRUB	FD
Johns Pass Channel Light 4	25600	LT EXT	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Johns Pass Channel Light 4	25600	RELIGHTED	FD	2025-06-09

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Treasure Island North Terminal Groin Obstruction Light	25600.01000000002	STRUCT DEST	PA

Jug Creek Shoal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jug Creek Shoal Daybeacon 9	56375	STRUCT MISSING	FD

Jupiter Inlet

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION	

Maritime Safety Information Products | Navigation Center

Sector Miami, Submerged Land Act (SLA) - Jupiter	Bridges	General/Bridges/Construction From: 2024-11-15 To: 2025-09-30 Location: 26.94755° N / 80.08495° W Bridge Name: Jupiter Federal Northbound Bridge CDR Maguire Engineering, on behalf of Florida Department of Transportation (FDOT) has been contracted to	Lat: 26° 56' 51"
Inlet/General/Bridges/Construction		replace the US1 Jupiter Federal Bridge across the Atlantic Intracoastal Waterway mile 1004.8, Jupiter. The old bascule bridge has been removed from the waterway and the new northbound bascule bridge has been constructed along the same alignment. The new navigational clearances will be 42ft of vertical clearance at the center and 125ft of horizontal clearance between the fenders when the project is complete. In-water equipment will continue to be present in the vicinity of construction of the new bridge through the end of 2024. All vessels are advised to transit the area with caution. For waterways questions or issues, call or e-mail Coast Guard Sector Miami, FL, Waterways Management Division, telephone 305-535-4317, email SectorMiamiWaterways@uscg.mil.	-080° 05'
Sector Miami, Submerged Land Act (SLA) - Jupiter Inlet/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported From: 2025-02-19 To: 2025-08-18 Location: 26.94754° N / 80.07894° W 26.94603° N / 80.078914° W 26.94603° N / 80.07814° W 26.94603° N / 80.07991° W 26.94752° N / 80.08029° W 26.94754° N / 80.07894° W The U.S. Coast Guard received a report of shoaling within the Intracoastal Waterway near Jupiter Lighthouse Park extending from the southeast corner toward Jupiter Inlet Buoy 2 (LLNR 46240) and extending south-southeast towards Jupiter Inlet Light 1 (LLNR 46235). Depth of water has been reported as low as 4 feet throughout the channel. The deepest water is located on the south side of the channel near Jupiter Inlet Light 1. Mariners are advised to reduce speed to bare steerageway and transit the area with extreme caution.	

Jupiter Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jupiter Sound Daybeacon 48	46180	STRUCT MISSING/TRUB	FD
Jupiter Sound Light 53	46200	STRUCT DMGD	FD

Keaton Beach

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Keaton Beach Daybeacon 2	30600	STRUCT DEST/TRUB	FD
Keaton Beach Light 5	30620	STRUCT MISSING/TRLB	FD
Keaton Beach Daybeacon 10	30635	STRUCT MISSING/TRUB	FD
Keaton Beach Light 11	30640	STRUCT DEST/TRLB	FD
Keaton Beach Daybeacon 13	30650	STRUCT MISSING/TRUB	FD
Keaton Beach Daybeacon 18	30675	STRUCT DEST/TRUB	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Keaton Beach Daybeacon 6	30625	WATCHING PROPERLY	FD	2025-06-11

Key Biscayne Yacht Club

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Key Biscayne Yacht Club Light 4	49085	DAYMK MISSING	PA

<u>Kings Bay</u>

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kings Bay Light 48	7000	STRUCT DEST/TRLB	FD
Kings Bay Light 50	7005	STRUCT DEST	FD
Kings Bay Light 52	7010	STRUCT DEST	FD
Kings Bay Light 53	7015	STRUCT DMGD	FD
Kings Bay Light 54	7020	STRUCT DEST	FD
Kings Bay Light 56	7025	STRUCT DEST	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Kings Bay/General/Marine	Marine	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2025-03-06 To: 2026-	
Construction (Excluding	Construction	04-10 Location: 30.7818° N / 81.49075° W 30.77592° N / 81.49028° W 30.77585° N / 81.49391° W 30.78155° N / 81.4947° W 30.7818°	
Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	(Excluding Bridges)	N / 81.49075° W UMX Crew will be starting dredging and underwater diving repairs work at MSF Facility (East River), Kings Bay Base, GA (30-46-45.5N / 81-29-29.5W). The crew will have a 120' x 45' Crane barge and 60' x 70' ton crane barge on-site. No wake is allowed near the job location. The project is scheduled to start on March 17, 2025, and is estimated to finish on March 17, 2026.	
Kings Bay/General/Marine	Marine	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 20717 From June 16 to June	
Construction (Excluding	Construction	20, 2025, there will be work conducted landside on Kings Bay Naval Base. Between the hours of 5 p.m. and 5 a.m. there may be	
Bridges)/Facilities, Barriers, Manmade	(Excluding Bridges)	possible power outages and there may be different light configurations than normal during those periods. Mariners are urged to use	
Reefs, Riprap, Jetties/Dikes		caution while transiting the area.	

Kings Island Turning Basin

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kings Island Turning Basin Light 16	5065	STRUCT MISSING/TRLB	FD

Kingsley Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kingsley Creek Daybeacon 13	38010	STRUCT DEST/TRUB	FD

Kissimmee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kissimmee River Light 1	51930	LT EXT	FD

Lake Boca Raton

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsboro Mile Daybeacon 1	47151	STRUCT DEST	PA
Hillsboro Mile Daybeacon 3	47152	STRUCT DEST	PA
Hillsboro Mile Daybeacon 7	47153	STRUCT DEST	PA

Lake Dexter

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Johns River - Lake	Miscellaneous	General/Miscellaneous From: 2025-02-11 To: 2025-08-10 Location: 32.27263° N / 80.53829° W 30.4907° N / 80.25264° W 24.57149° N / 78.80245°	
Dexter/General/Miscellaneous		W 23.97058° N / 83.32882° W 29.25227° N / 84.25167° W 32.24011° N / 81.43367° W 32.27263° N / 80.53829° W PUBLICATION-National Oceanic	
		and Atmospheric Administration (NOAA) - U.S. Coast Pilot 5, Gulf Coast, Puerto Rico, and Virgin Islands, 53rd Edition, 2025, has been issued and is	
		ready for free download and weekly updates at nauticalcharts.noaa.gov/publications/coast-pilot/index.html. Only Print-on-Demand (POD) bound copies are available for purchase; visit nauticalcharts.noaa.gov/publications/print-agents.html#coast-pilot. The 2025 Edition cancels the preceding 2024 Edition, and incorporates all previous corrections.	
it Johns River - Lake	Miscellaneous	General/Miscellaneous 20018 HURRICANE INFORMATION: The hurricane season extends from June 1st through November 30th. Hurricanes can	
Dexter/General/Miscellaneous	Wilseenaneous	cause excessive damage to vessels and loss of life. To minimize these dangers, the following precautions should be taken by all mariners before	
exteri deneral, miscenariedas		getting underway during the hurricane season: (a) Instruction of crew and passengers in location of emergency equipment and emergency	
		procedures; (b) Pre-sailing check of vessel, machinery, and equipment for seaworthiness; (c) Installation of strong ground tackle; (d) Review of	
		storm center evasion procedures; (e) Knowledge of nearest hurricane shelter or port; and (f) Constant radio watches on channel 16 VHF-FM and	
		frequent monitoring of weather broadcasts. The civilian hurricane warning service for the North Atlantic is provided by the National Hurricane	
		Center, Miami, Florida. The center collates ship, aircraft, radar, and satellite data to produce and issue tropical cyclone warnings and forecasts for	
		the North Atlantic Ocean, including the Caribbean Sea and the Gulf of Mexico. A Tropical Cyclone Public Advisory (TCP) is issued every six hours,	
		with intermediate bulletins provided as needed. For tropical storms and hurricanes threatening to cross the coast of the U.S., coastal warnings are	
		issued to the public so that precautionary actions, including evacuation, can be initiated to minimize damage and loss of life. Four alerts are	
		issued: (a) TROPICAL STORM WATCH – An announcement that sustained winds of 34 to 63 knots (39 to 73 mph or 63 to 118 km/hr) are possible	
		within the specified area within 48 hours in association with a tropical, subtropical, or post-tropical cyclone. (b) TROPICAL STORM WARNING – An	
		announcement that sustained winds of 34 to 63 knots (39 to 73 mph or 63 to 118 km/hr) are expected somewhere within the specified area within	
		36 hours in association with a tropical, subtropical, or post-tropical cyclone. (c) HURRICANE WATCH – An announcement that sustained winds of	
		64 knots (74 mph or 119 km/hr) or higher are possible within the specified area in association with a tropical, subtropical, or post-tropical cyclone.	
		Because hurricane preparedness activities become difficult once winds reach tropical storm force, the hurricane watch is issued 48 hours in advance of the anticipated onset of tropical storm force winds. (d) HURRICANE WARNING – An announcement that sustained winds of 64 knots	
		(74 mph or 119 km/hr) or higher are expected somewhere within the specified area in association with a tropical, subtropical, or post-tropical	
		cyclone. Because hurricane preparedness activities become difficult once winds reach tropical storm force, the warning is issued 36 hours in	
		advance of the anticipated onset of tropical-storm-force winds. The warning can remain in effect when dangerously high water or a combination	
		of dangerously high water and waves continue, even though winds may be less than hurricane force.	

Maritime Safety Information Products | Navigation Center

St Johns River - Lake	Miscellaneous	General/Miscellaneous 20019 HURRICANE INFORMATION CONT: Additional information of interest to mariners is included in the Tropical Cyclone
Dexter/General/Miscellaneous		Forecast/Advisory (TCM) and the Tropical Cyclone Surface Wind Speed Probabilities (PWS) products. The TCM provides current and forecast storm
		positions, intensities, and wind fields out to 120 hours. The PWS provides probabilities of sustained wind speeds equal to or exceeding 34-, 50-,
		and 64-kt wind speed thresholds for select coastal and offshore locations Mariners are reminded that aids to navigation, particularly lighted and
		unlighted buoys, may be moved from charted position, damaged, destroyed, extinguished, or otherwise deemed discrepant as a result of
		hurricanes and storms. Mariners should not rely solely upon the position or operation of an aid to navigation, but also employ such other methods
		of determining position as may be available. Port Hurricane Conditions are set up by the COTP and will change as the threat of severe weather
		increases, or as a storm approaches a specific COTP Area of Responsibility. For COTP-specific Port Hurricane Conditions, you should review
		information provided under the Port Directory tab of http://homeport.uscg.mil Condition 4 - Hurricane Seasonal Alert. 01 June-30 November; port
		status: open. Condition Whiskey - Sustained Gale Force winds associated with Tropical Cyclone activity are predicted within 72 hours; port status:
		open. Condition X-Ray – Sustained Gale Force winds associated with Tropical Cyclone activity are predicted within 48 hours; port status: open.
		Condition Yankee – Sustained Gale Force winds associated with Tropical Cyclone activity are predicted within 24 hours; port status: restricted;
		vessel/facility control measures in effect. Condition Zulu - Sustained Gale Force winds associated with Tropical Cyclone activity are predicted within
		12 hours; port status: closed to all vessel traffic and waterside activities except for activities approved by the COTP. Drawbridges along the coast
		may deviate from normal operating procedures. Drawbridges are authorized to remain closed upon approach of Gale Force winds of 34 knots or
		greater. Extended closure periods may be authorized up to 8 hours prior to arrival of Gale Force winds to facilitate evacuation of land traffic. Due
		to the uncertainty of hurricane movements and bridge closures, mariners are urged to seek passage through drawbridges well in advance of the
		arrival of Gale Force winds. http://www.nws.noaa.gov/com/weatherreadynation/hurricane_preparedness.html

Lake George

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Silver Glen Springs Run Buoy 1	8595	MISSING	PA
Silver Glen Springs Run Buoy 24	8695	MISSING	PA
Silver Glen Springs Run Buoy 25	8700	OFF STA	PA
Silver Glen Springs Run Buoy 2A	8715	SINKING/BUOY DMGD	PA
Silver Glen Springs Run Buoy 9A	8740	MISSING	PA
Silver Glen Springs Run Pref Buoy A	8750	MISSING	PA

Lake Monroe

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Monroe Bar Light 1	9240	STRUCT DEST/HAZ NAV/TRLB	FD

Lake Okeechobee Route 1

Federal Discrepancies NAME LLNR STATUS AID TYPE Lake Okeechobee (Rt 1) Daybeacon 3 51195 DBD DEST FD

Lake Worth Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Worth Creek Daybeacon 7	46375	STRUCT DEST/TRUB	FD

Additional MSI Categories

Jupiter Inlet - Lake Worth Bridges General/Bridges/Temp Deviation From: 2024-11-05 To: 2025-09-01 Location: 26.93383° N / 80.08399° W Bridge Name: Indiantown Road Creek/General/Bridges/Temp Eastbound and Westbound Bridges The TIR is identified by docket number USCG-2023-0652 at https://www.regulations.gov. Additional Deviation information is provided in the online document, please read. The U.S. Coast Guard has issued a TIR which amends drawbridge operation	TITLE	DESCRIPTION	SUBCATEGORY	LOCATION
regulation, 33 CFR 117.261(p) which will govern Indiantown Road Bridge, mile 1006.2, at Jupiter, Florida. The TIR is effective from 12:01 a.m. October 25, 2024, through 11:59 p.m. on August 31, 2025. You may submit comments identified by docket number USCG-2023-0652 using Federal Decision Making Portal at https://www.regulations.gov. The comment period ends November 25, 2024. If you have questions on this rulemaking, call or e-mail Ms. Jennifer Zercher, Bridge Management Specialist, Seventh Coast Guard District, telephone (305) 415-6740, emai	eek/General/Bridges/Temp	and Westbound Bridges The TIR is identified by docket number USCG-2023-0652 at https://www.regulations.gov. Additional is provided in the online document, please read. The U.S. Coast Guard has issued a TIR which amends drawbridge operation 33 CFR 117.261(p) which will govern Indiantown Road Bridge, mile 1006.2, at Jupiter, Florida. The TIR is effective from 12:01 a.m. on 2024, through 11:59 p.m. on August 31, 2025. You may submit comments identified by docket number USCG-2023-0652 using ision Making Portal at https://www.regulations.gov. The comment period ends November 25, 2024. If you have questions on this	5	Lat: 26° 56' 02" Lon: -080° 05' 02"

Lake Worth Inlet

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Lake Worth Inlet Lighted Buoy 4	10200	RESET ON STATION	FD	2025-06-08

Lake Worth North

NAME	LLNR	STATUS	AID TYPE

Maritime Safety Information Products | Navigation Center

Lake Worth North Light 36	46600	STRUCT DEST	FD
Additional MSI Categories			

j.			
TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Lake Worth	Bridges	General/Bridges/Construction From: 2025-01-14 To: 2027-01-31 Location: 26.808528° N / 80.056123° W Bridge Name: US Hwy 1/SR 5	Lat:
North/General/Bridges/Construction			26° 48' 31"
		replacement of the US Hwy 1/SR 5 Bridge. Mariners are advised to utilize the northern canal to access the Atlantic Intracoastal Waterway.	
		The Lighthouse Drive Bridge across the northern canal provides a vertical clearance of 14.5 feet and a horizontal clearance of 22.5 feet. For	
		waterways questions, please contact USCG Sector Miami Waterways Division at (305) 535-4317, email SectorMiamiWaterways@uscg.mil	22"

Lake Worth South

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Worth South Daybeacon 3	46730	STRUCT DEST	FD
Lake Worth South Daybeacon 4	46740	STRUCT DEST/HAZ NAV/TRLB	FD
Lake Worth South Daybeacon 34	46965	STRUCT DEST/HAZ NAV/TRLB	FD
Lake Worth South Light 35	46970	DAYMK MISSING	FD
Lake Worth South Daybeacon 40	46985	TRUB/STRUCT MISSING	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Lake Worth Inlet - Lake Worth	Bridges	General/Bridges/Temp Deviation From: 2025-06-10 To: 2025-07-05 Location: 26.61539° N / 80.04368° W Bridge Name: Lake Avenue	Lat:
South/General/Bridges/Temp Deviation		Bridge - AICW The bridge need not open to navigation, including tugs with tows, from 8:30 p.m. to 10 p.m. on Friday, July 4, 2025, to	26° 36' 55"
		facilitate City of Lake Worth Annual 4th of July Celebration. Public vessels of the United States and vessels in distress shall be passed at	Lon:
		any time.	-080° 02'
			37"

Largo Sound Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Newport Bay Daybeacon 7	11851.6	HAZ NAV/STRUCT DMGD	PA

Lemon Bay Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lemon Bay Channel Daybeacon 16	57275.5	STRUCT MISSING/TRUB	FD
Lemon Bay Channel Daybeacon 20A	57340	STRUCT DEST	FD
Lemon Bay Channel Light 24	57360	STRUCT MISSING/TRLB	FD
Lemon Bay Channel Daybeacon 26	57420	STRUCT MISSING/TRUB	FD
Lemon Bay Channel Daybeacon 40	57625	STRUCT MISSING/TRUB	FD
Lemon Bay Channel Light 47	57655	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Forked Creek West Obstruction Daybeacon	57618.9	STRUCT DEST	PA
Forked Creek North Obstruction Daybeacon	57619	STRUCT DEST	PA
Forked Creek East Obstruction Daybeacon	57619.3	STRUCT DEST	PA
Gottfried Creek Daybeacon 5	57357.4	DAYMK DMGD	PA
Forked Creek Daybeacon 1	57617	STRUCT DEST/HAZ NAV	PA

Little Lake George

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Lake George Light 53	8435	LT EXT	FD
Little Lake George Daybeacon 54	8450	STRUCT DEST/TRLB	FD

Little Manatee River

NAME	LLNR	STATUS	AID TYPE
Little Manatee River Approach Light LM	24481	STRUCT MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Shell Point Daybeacon 3	22698.2	STRUCT DEST	PA
Shell Point Daybeacon 7	22698.60000000002	STRUCT DEST	PA

Little Mud River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Mud River Daybeacon 189	36855	STRUCT DEST/TRUB	FD
Little Mud River Light 190	36865	STRUCT DEST/TRLB	FD
Little Mud River Light 195	36875	STRUCT MISSING/TRLB	FD
Little Mud River Light 196	36880	STRUCT DEST/TRLB	FD

Little River Winyah Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little River-Winyah Bay Obstruction Daybeacon B	33647	STRUCT MISSING/TRUB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Winyah Bay Channel - Little River Winyah Bay/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 33.76374° N / 78.81957° W Aid Name: Little River-Winyah Bay Daybeacon 21B LLNR: 33705.5 Action: RENAME Little River-Winyah Bay DBN 21B (LLNR 33705.5) will be renamed Little River-Winyah Bay DBN 21C (LLNR 33705.5). Establish Little River-Winyah Bay LT 21B (LLNR 33705.3) in approximate position 33-46-56.075N, 078-47-21.582W. The light will display a flash characteristic of Q G, with a nominal range of 4 nautical miles.	Lat: 33° 45' 49" Lon: -078° 49' 10"
Winyah Bay Channel - Little River Winyah Bay/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change 19407 Location: 33.82754° N / 78.70574° W Aid Name: Little River-Winyah Bay Buoy 15B The U.S. Coast Guard has approved the following change in the Little River-Winyah Bay Channel, Intracoastal Waterway, to improve navigational safety and reliability. Little River-Winyah Bay Buoy 15B (LLNR 33660.1) will be permanently established in approximate position 33-49-39.137N, 078- 42-20.648W.	Lat: 33° 49' 39" Lon: -078° 42' 21"
Winyah Bay Channel - Little River Winyah Bay/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-04-10 To: 2025-11-01 Location: 33.851704° N / 78.656302° W Bridge Name: Little River Bridge - AICW Effective from 12:01 a.m. on May 5, 2025, through 11:59 p.m. on October 31, 2025, the Little River Bridge shall open on signal except that from 7 a.m. to 9 a.m. and 4 p.m. to 6 p.m., Monday through Friday, except Federal holidays, the draw will open on the hour and half hour. Public vessels of the United States and tugs with tows, upon proper signal, will be passed through anytime. A notice of temporary deviation from regulations, request for comments will be published in the Federal Register. Comments are due on or before June 27, 2025. Comments may be submitted under docket number USCG-2025-0152 using Federal Decision-Making Portal at https://www.regulations.gov.	23"
Winyah Bay Channel - Little River Winyah Bay/General/Hazards To Navigation/Hazards	Hazards To Navigation	General/Hazards To Navigation/Hazards From: 2025-01-29 To: 2025-07-28 Location: 33.7849° N / 78.7861° W 33.78451° N / 78.78545° W 33.77003° N / 78.80923° W 33.77049° N / 78.80979° W 33.7849° N / 78.7861° W Obstacle was reported about 1.5 miles north of mile 357 on the west bank of the waterway. There are 2 large trees that were knocked over from the bank and the trees are in the channel.	

Little Shark River Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Shark River Entrance Daybeacon 3	15955	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cormorant Pass Daybeacon 48	15870	DAYMK IMCH	PA
Oyster Bay Daybeacon 53	15885	DAYMK MISSING	PA
Oyster Bay Daybeacon 63	15915	DAYMK MISSING	PA
Little Shark River Daybeacon 69	15940	DAYMK IMCH	PA

Long Branch

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Long Branch Lighted Buoy 69	7575	RELOCATED FOR DREDGING	FD
Long Branch Lighted Buoy 71	7590	RELOCATED FOR DREDGING	FD

Long Key

NAME	LLNR	STATUS	AID TYPE
Long Key Daybeacon 1X	12385	STRUCT DEST/TRUB	FD

Long Key Cape Sable

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sprigger Bank Light 5	15605	HAZ NAV/STRUCT DEST/TRLB	FD

Lower Flats Range

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Elba Island Light 39	4850	STRUCT DEST	FD

Loxahatchee River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Loxahatchee River Daybeacon 7	46280	DAYMK IMCH	PA
Loxahatchee River Daybeacon 15	46320	DAYMK IMCH	PA
Loxahatchee River South Channel Daybeacon 7	46373.5	STRUCT DMGD	PA

Mackay River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mackay River Cutoff Light 229	37090	STRUCT DEST/TRLB	FD
Mackay River Cutoff Light 231	37095	STRUCT DEST/TRLB	FD
Mackay River Light 239	37160	STRUCT DEST/HAZ NAV/TRLB	FD
Mackay River Light 241	37170	STRUCT DEST/TRLB	FD
Mackay River Light 244	37190	STRUCT DEST/TRLB	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Mackay River Light 245	37195	RELIGHTED	FD	2025-06-11

Manatee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Manatee River Daybeacon 21	22050	STRUCT MISSING	FD
Manatee River Daybeacon 28	22095	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tidewater Preserve Marina Daybeacon 2	22105.2	STRUCT DEST	PA
Colony Cove Daybeacon 2	22110	STRUCT DEST/TRUB	PA

Matanzas Pass Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Matanzas Pass Channel Daybeacon 24	18290	STRUCT MISSING/TRUB	FD
Matanzas Pass Channel Daybeacon 26	18295	HAZ NAV/STRUCT MISSING/TRUB	FD

NAME	LLNR	STATUS	AID TYPE
Hurricane Bay Marina West Channel Daybeacon 7	18160	STRUCT DEST/HAZ NAV	PA
Siesta Isles Daybeacon 4	18215	STRUCT DEST	PA
Matanzas Harbor Channel Daybeacon 3	18296.10000000002	STRUCT DEST/HAZ NAV	PA
North Estero Bay Daybeacon 63	18725	STRUCT DEST/TRUB	PA
Mullock Creek Daybeacon 13	18835	STRUCT DEST/HAZ NAV	PA
Matanzas Harbor Channel Daybeacon 5	18296.3	STRUCT DEST	PA
North Estero Bay Daybeacon 4	18315	STRUCT DEST	PA
North Estero Bay Daybeacon 5	18316	STRUCT MISSING	PA
Bayside Estates Channel Daybeacon 2	18405	STRUCT DEST	PA

Maritime Safety Information Products | Navigation Center

Bayside Estates Channel Daybeacon 4	18415	HAZ NAV/STRUCT DEST	PA
Bayside Estates Channel Daybeacon 14	18450	STRUCT DEST	PA
North Estero Bay Daybeacon 19	18565	STRUCT DMGD	PA
North Estero Bay Daybeacon 35	18605	STRUCT DEST	PA
Mullock Creek Daybeacon 2A	18760	STRUCT DEST	PA
Mullock Creek Daybeacon 45	18920	STRUCT DEST	PA

Matanzas River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Matanzas River Light 1	39035	STRUCT DEST/TRLB	FD
Matanzas River Buoy 2	39040	OFF STA	FD
Matanzas River Daybeacon 5	39055	STRUCT MISSING	FD
Matanzas River Daybeacon 6A	39060.1	STRUCT DEST/TRUB	FD
Matanzas River Light 43	39330	STRUCT MISSING/TRLB	FD
Matanzas River Daybeacon 60	39455	STRUCT DEST/TRUB	FD
Matanzas River Light 72	39495	DAYMK MISSING	FD
Matanzas River Light 79	39520	STRUCT MISSING/TRLB	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Matanzas River Daybeacon 62	39460	WATCHING PROPERLY	FD	2025-06-04

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Salt Run Daybeacon 1	38915	STRUCT DEST	PA
Salt Run Daybeacon 4	38930	STRUCT DEST	PA
Salt Run Daybeacon 7	38945	STRUCT DMGD	PA
Salt Run Daybeacon 3	38925	STRUCT DEST	PA
Salt Run Daybeacon 6	38940	STRUCT MISSING	PA
Salt Run Daybeacon 11	38965	STRUCT DEST/HAZ NAV	PA
Fish Island Marina Daybeacon 1	39080	DAYMK MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Augustine Inlet - Matanzas River/ATON/Advanced Notice of Change		ATON/Advanced Notice of Change Location: 29.90535° N / 81.29553° W Aid Name: Matanzas River Light 1 LLNR: 39035 Action: CHANGE Action Type Change Aid Subtype The following change has been approved to the Aid to Navigation system in the Matanzas River. Matanzas River Light 1 (LLNR 39035) will permanently be changed to Matanzas River Lighted Buoy 1 (LLNR 39035). Matanzas River Light 1 has been destroyed on a few occasions over the last 10 years and it is currently being advertised as destroyed since 2020. In addition, the water depth at its assigned position is 21 feet making it more difficult for a CG asset to spud and maintain position to rebuild the aid safely. Converting the light to a floating aid will allow for a timelier response and consistent maintenance in the event the aid becomes discrepant. Therefore, this change will provide mariners a more reliable signal while approaching the Matanzas River Channel entrance from the St. Augustine Inlet and while exiting the channel.	Lat: 29° 54' 19" Lon: -081° 17' 44"
St Augustine Inlet - Matanzas River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-05-27 To: 2025-07-05 Location: 29.892918° N / 81.307398° W Bridge Name: Bridge of Lions Bridge The bridge need not open to navigation, including tugs with tows, as follows: - From 8:30 p.m. to 11 p.m. on Friday, July 4, 2025, to facilitate Fireworks over the Matanzas From 7:30 a.m. to 9 a.m. on Saturday, July 12, 2025, to facilitate Bridge of Lions 5k Walk/Run Public vessels of the United States and vessels in distress shall be passed at any time.	Lat: 29° 53' 35' Lon: -081° 18' 27"

Matheny Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Venice Inlet-Siesta Key Daybeacon 14	57900	STRUCT DEST/TRUB	FD
Venice Inlet-Siesta Key Light 34	58105	STRUCT DEST/TRLB	FD
Venice Inlet-Siesta Key Daybeacon 49	58225	STRUCT DEST/TRUB	FD

NAME	LLNR	STATUS	AID TYPE
Phillippi Creek Daybeacon 13	58366	STRUCT DEST	PA
Snake Island Daybeacon A	57834	STRUCT DEST	PA
Snake Island Daybeacon B	57834.1	STRUCT DEST	PA
Snake Island Daybeacon C	57834.20000000004	STRUCT DEST	PA
Midnight Pass Lagoon Daybeacon 4	58185	STRUCT DEST	PA
Midnight Pass Lagoon Daybeacon 5	58190	STRUCT DEST	PA
Midnight Pass Lagoon Daybeacon 7	58200	STRUCT DEST	PA

Maritime Safety Information Products | Navigation Center

Midnight Pass Daybeacon 13	58205.3	STRUCT DMGD	PA
Midnight Pass Daybeacon 17	58205.5	STRUCT DEST	PA
Matheny Creek Daybeacon 1	58292	STRUCT DMGD	PA
Phillippi Creek Daybeacon 2	58365.20000000004	DAYMK MISSING	PA
Phillippi Creek Daybeacon 7	58365.6	DAYMK MISSING	PA
Phillippi Creek Daybeacon 11	58365.9	STRUCT DEST/HAZ NAV	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Venice Inlet - Matheny Creek/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-03-19 To: 2025-07-05 Location: 27.30273° N / 82.54467° W Bridge Name: Siesta Key Bridge - GICW The bridge need not open to navigation including tugs with tows, from 9:00 p.m. to 11:59 p.m. on Friday, July 4, 2025, to facilitate the Siesta Key 4th of July Community Fireworks.	Lat: 27° 18' 10" Lon: -082° 32' 41"
Venice Inlet - Matheny Creek/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-03-19 To: 2025-07-05 Location: 27.25448° N / 82.53152° W Bridge Name: Stickney Point Bridge - GICW The bridge need not open to navigation including tugs with tows, from 9:00 p.m. to 11:59 p.m. on Friday, July 4, 2025, to facilitate the Siesta Key 4th of July Community Fireworks.	Lat: 27° 15' 16" Lon: -082° 31' 53"
Venice Inlet - Matheny Creek/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 17465 Continental Heavy Civil Corp. will conduct shoreline reconstruction and coastal armoring. Work will be performed between 22 North Casey Key Road to 400 N Casey Key Road, and 526 to 840 N Casey Key Road. Staging and loading area will be the entire footprint of the Nokomis Beach "spillover" parking lot, located at 101 S Casey Key Road. Heavy equipment such as lattice-boom crawler cranes and heavy excavators will load onto barges from Albee Road and will route down to intercoastal to the Venice inlet, proceed to the Gulf and then up the coast to the jobsite and back. Continental Heavy Civil expects to work a regular schedule from 6am to 6pm Monday through Saturday, with some necessary Sundays. Estimated completion time for the entire project May 1st, 2027. All Vessels should use caution when transiting the work area. The crew at Casey Road will monitor VHF-FM channels 13 and 16.	

Mayport Basin

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE	
Mayport Basin Range Front Light	7155	55 NIGHT LT BURNING DAY FI		
Temporary Changes				
icinpolary changes				
NAME	LLNR	STATUS	AID TYPE	

Miami Beach Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Beach Channel Light 11	48015	STRUCT DEST/TRLB	FD

Miami Main Channel

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Government Cut Range Front Light	10505	RELIGHTED	FD	2025-06-07
Miami Main Channel Lighted Buoy 10	10525	WATCHING PROPERLY	FD	2025-06-06
Miami Main Channel Lighted Buoy 12	10535	WATCHING PROPERLY	FD	2025-06-06

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Beach Marina Breakwater North Light	10570	LT EXT	PA

Miami Turning Basin

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Turning Basin Articulated Light E	10770	STRUCT DEST/TRLB/HAZ NAV	FD

Mile Point

NAME	LLNR	STATUS	AID TYPE
Mile Point Lower Range Front Light	7260	REDUCED INT	FD

Maritime Safety Information Products | Navigation Center

Mile Point Lighted Buoy 24	7280	OFF STATION	FD
Mile Point Light A	7281	DAYMK MISSING	FD
Mile Point Light C	7283	STRUCT DEST	FD
Mile Point Upper Range Front Light	7287	REDUCED INT	FD
Mile Point Upper Range Rear Light	7290	LT EXT	FD

Additional MSI Categories TITLE SUBCATEGORY DESCRIPTION LOCATION St Johns River - Mile Advanced Notice of Mile Point Lower RFL (LLNR 7260) will be relocated to approximate position: 30-22-44.551N/081-27-11.480W to align with the Lat Point/ATON/Advanced Notice of newly dredged channel. In addition, both Mile Point Lower RFL and Mile Point Lower RRL will be changed to a 24-hour optic. All day 30° 22' 44" Change Change marks will be permanently discontinued. Lon: -081° 27' 11" St Johns River - Mile Advanced Notice of Mile Point Lower RRL (LLNR 7265) will be relocated to approximate position: 30-22-43.316N/081-27-14.558W to align with the Lat: Point/ATON/Advanced Notice of newly dredged channel. In addition, both Mile Point Lower RFL and Mile Point Lower RRL will be changed to a 24-hour optic. All day 30° 22' 42" Change Change marks will be permanently discontinued. Lon: -081° 27' 14" St Johns River - Mile Advanced Notice of Mile Point Upper RFL (LLNR 7287) will be relocated to approximate position: 30-22-44.266N/081-27-12.139W to align with the Lat: Point/ATON/Advanced Notice of Change newly dredged channel. In addition, both Mile Point Upper RFL and Mile Point Upper RRL will be changed to a 24-hour optic. All 30° 22' 44" Change day marks will be permanently discontinued. Lon: -081° 27' 11' St Johns River - Mile Advanced Notice of Mile Point Upper RRL (LLNR 7290) will be relocated to approximate position: 30-22-34.772N/081-26-58.725W to align with the Lat: Point/ATON/Advanced Notice of Change newly dredged channel. In addition, both Mile Point Upper RFL and Mile Point Upper RRL will be changed to a 24-hour optic. All 30° 22' 35" Change day marks will be permanently discontinued. Lon: -081° 26' 58"

Mosquito Lagoon

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mosquito Lagoon Daybeacon 8	40925	STRUCT DEST/TRUB	FD

Mount Pleasant Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mount Pleasant Channel Daybeacon 3	3520	STRUCT MISSING/TRUB	FD

Murphy Island

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Murphy Island Light 26	8305	DAYMK MISSING	FD

Myakka River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Gulf Cove Entrance Daybeacon 5	20175	DAYMK MISSING	PA
Upper Myakka River Daybeacon 12	20395	HAZ NAV/STRUCT DEST	PA

Naples Bay Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Naples Bay Channel Daybeacon 22	17550	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Naples Yacht Club Daybeacon 5	17667	DAYMK MISSING	PA

Nassau Cutoff

NAME	LLNR	STATUS	AID TYPE
Nassau Cutoff Light 47	38175	STRUCT MISSING/TRLB	FD

New Channel Range

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Long Island Crossing - New Channel	Advanced Notice of	After completion of dredging and channel re-alignment, the water depth at the current assigned position for New Channel RFL	Lat:
Range/ATON/Advanced Notice of	Change	(LLNR 4770), makes it impossible for the Coast Guard to rebuild this range in its advertised position. Therefore, New Channel RFL	32° 02' 22"
Change		(LLNR 4770) will be permanently relocated to a new assigned position at approximately 32-02-21.801N/080-55-39.437W.	Lon:
			-080° 55'
			39"

New Pass

Federal Discrepancies

NAME	LLNR	STATUS		AID TYPE	
New Pass Channel Light 13	21705	STRUCT MIS	SING/TRLB		FD
Private Discrepancies					
NAME			LLNR	STATUS	AID TYPE
Anglers Club Reef Daybeacon AC			21701	STRUCT DEST	PA
City Island Breakwater Light			21710	STRUCT DEST	PA
Sarasota Basin Obstruction Light A			21752	STRUCT DEST	PA
Sarasota Basin Obstruction Daybeacon B			21754	STRUCT DEST	PA

New River Sound

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Stranahan River - New River	Bridges	General/Bridges/Repairs, Painting, Or Fender Replacement From: 2024-11-19 To: 2025-05-31 Location: 26.08395° N / 80.1844° W Bridge	Lat:
Sound/General/Bridges/Repairs,		Name: Interstate 595 Bridge - South New River Canal Construction for widening the I-595 Bridge continues. Impacts to navigation are	26° 05' 02"
Painting, Or Fender Replacement		expected. This will be to install bridge maintenance platforms on the pier caps facing the channel. During this time the Contractor will be	Lon:
		partially obstructing the channel with work barges and will request a 1-hour advance notice of arrival. Boaters should contact Leo	-080° 11'
		Villegas (561)334-9239 to request passage. Construction of this project is ongoing and is expected to continue until July 31st, 2025. For	04"
		waterways questions, call or e-mail Coast Guard Sector Miami, FL, Waterways Management Division, telephone 305-535-4317, email SectorMiamiWaterways@uscg.mil.	
Stranahan River - New River	Bridges	General/Bridges/Temp Deviation From: 2025-05-16 To: 2025-07-05 Location: 26.11977° N / 80.10904° W Bridge Name: East Las Olas	Lat:
Sound/General/Bridges/Temp Deviation		Boulevard Bridge - AICW The bridge need not open to navigation including tugs with tows, from 9 p.m. to 10 p.m. on Friday, July 4,	26° 07' 11"
		2025, to facilitate the City of Fort Lauderdale July 4th Spectacular Event. Public vessels of the United States and vessels in distress shall	Lon:
		be passed at any time.	-080° 06'
			33"

New Smyrna Beach

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
New Smyrna Beach Daybeacon 28	40645	STRUCT DEST/TRUB	FD
New Smyrna Beach Daybeacon 51	40805	STRUCT DEST/TRUB	FD
New Smyrna Beach Daybeacon 62	40845	STRUCT DEST/TRUB	FD

North Edisto River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
North Edisto River Entrance Lighted Buoy 6		LT EXT	FD
North Edisto River Inner Buoy 7 3		MISSING	FD

North Newport River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Timmons Reef E Obstruction Daybeacon	36500	STRUCT DEST	PA

Ogeechee River

NAME	LLNR	STATUS	AID TYPE
Hell Gate Light 91	36285	STRUCT MISSING/TRLB	FD

6/17/25, 10:41 AM Maritime Safety Information Products | Navigation Center Hell Gate Light 92 36290 STRUCT MISSING/TRLB FD **Private Discrepancies** NAME LLNR STATUS AID TYPE LT EXT Fort Mcallister Fishing Pier Light 36360 PA **Oglethorpe Range Federal Discrepancies** NAME LLNR STATUS AID TYPE Fig Island Jetty Light 56 5005 STRUCT MISSING/TRLB FD **Additional MSI Categories** TITLE SUBCATEGORY DESCRIPTION LOCATION Fort Jackson - Oglethorpe Marine Construction General/Marine Construction (Excluding Bridges)/Dredging 18245 Marinex Construction, Inc. will begin mobilizing equipment and Range/General/Marine Construction pipeline to commence work at Ocean Terminal. All pipeline for this work will be appropriately lighted and laid outside the channel on (Excluding Bridges) (Excluding Bridges)/Dredging the South Carolina side of the river from the Talmadge Bridge to Back River. The Dredge WADMALAW will operate in this area through approximately August 31, 2025. Operations will be conducted 24 hours a day / seven days a week and monitor VHF-FM

Okeechobee Waterway

channels 13 and 16.

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Taylor Creek Daybeacon 6	51915	STRUCT DEST/TRUB	FD

NAME LLNR STATUS AID TYPE Dyess Canal Safewater Light DC 51980 STRUCT DEST PA

Old Rhodes Key

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Old Rhodes Key Light 22	11165	DBD DEST	FD
Old Rhodes Key Daybeacon 24	11175	STRUCT DEST/TRLB	FD

Ossabaw Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ossabaw Sound Preferred Channel Buoy N	5740	MISSING	FD
Ossabaw Sound North Channel Daybeacon 10	5760	STRUCT DEST/TRUB	FD
Ossabaw Sound North Channel Buoy 11	5765	OFF STATION	FD
Ossabaw Sound North Channel Daybeacon 12	5770	STRUCT DEST/TRUB	FD
Ossabaw Sound South Channel Daybeacon 5	5780	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Delegal Creek Channel Light 1	36229	STRUCT DEST	PA
Delegal Creek Channel Buoy 2	36230	MISSING	PA
Delegal Creek Channel Buoy 4	36233	OFF STA	PA
Delegal Creek Channel Light 8	36241.1	LT EXT	PA

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - Ossabaw Sound/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 31.86196° N / 81.03488° W Aid Name: Ossabaw Sound North Channel Daybeacon 10 LLNR: 5760 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the following change to the Aids to Navigation System in Ossabaw Sound. Ossabaw Sound North Channel DBN 10 (LLNR 5760) will be changed to Ossabaw Sound North Channel Buoy 10, using the same LLNR. Ossabaw Sound North Channel DBN 12 (LLNR 5770) will be changed to Ossabaw Sound North Channel Buoy 12, using the same LLNR. Ossabaw Sound South Channel DBN 5 (LLNR 5780) will be changed to Ossabaw Sound South	Lat: 31° 51' 43" Lon: -081° 02' 06"
Sector Charleston, Submerged Land Act (SLA) - Ossabaw Sound/ATON/Advanced Notice of Change	Advanced Notice of Change	Channel Buoy 5, using the same LLNR. ATON/Advanced Notice of Change Location: 31.8645° N / 81.05731° W Aid Name: Ossabaw Sound North Channel Daybeacon 12 LLNR: 5770 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the following change to the Aids to Navigation System in Ossabaw Sound. Ossabaw Sound North Channel DBN 10 (LLNR 5760) will be changed to Ossabaw Sound North Channel Buoy 10, using the same LLNR. Ossabaw Sound North Channel DBN 12 (LLNR 5770) will be changed to Ossabaw Sound North Channel Buoy 12, using the same LLNR. Ossabaw Sound South Channel DBN 5 (LLNR 5780) will be changed to Ossabaw Sound South Channel Buoy 5, using the same LLNR.	Lat: 31° 51' 52" Lon: -081° 03' 26"

 Sector Charleston, Submerged Land
 Advanced Notice
 ATON/Advanced Notice of Change From: 2025-03-12 To: 2026-09-08 Location: 31.82121° N / 81.03359° W Aid Name: Ossabaw Sound
 Lat:

 Act (SLA) - Ossabaw
 of Change
 South Channel Daybeacon 5 LLNR: 5780 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the
 31° 4

 Sound/ATON/Advanced Notice of
 following change to the Aids to Navigation System in Ossabaw Sound. Ossabaw Sound North Channel DBN 10 (LLNR 5760) will be
 Lon:

 Change
 changed to Ossabaw Sound North Channel Buoy 10, using the same LLNR. Ossabaw Sound North Channel DBN 12 (LLNR 5770) will be
 -081

 Off
 changed to Ossabaw Sound South Channel Buoy 12, using the same LLNR. Ossabaw Sound South Channel DBN 5 (LLNR 5780) will be
 -081

Lat: 31° 49' 16" Lon: -081° 02' 01"

Pablo Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pablo Creek Buoy 4	38355	MISSING	FD
Pablo Creek Light 5	38360	STRUCT DEST	FD
Pablo Creek Light 6	38365	STRUCT DEST	FD
Pablo Creek Light 17	38440	STRUCT MISSING/TRLB	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Pablo Creek Temporary Light 9	38380.20000000004	ESTABLISHED	FD

Palma Sola Bay

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Palma Sola Park Channel Daybeacon 1	59890	HAZ NAV/DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 4	59905	DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 5	59910	HAZ NAV/DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 6	59915	DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 7	59920	DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 8	59925	DAYMK IMCH	PA

Paradise Bay Estates Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Siesta Key-Tampa Bay Daybeacon 7	58480	STRUCT MISSING	FD
Sarasota Municipal Pier Channel Daybeacon 2	58495	STRUCT MISSING/TRUB	FD
Siesta Key-Tampa Bay Light 10	58535	STRUCT MISSING	FD
Siesta Key-Tampa Bay Daybeacon 16	58675	DAYMK MISSING	FD
Siesta Key-Tampa Bay Light 21	58830	STRUCT DEST	FD
Siesta Key-Tampa Bay Daybeacon 36	59325	HAZ NAV/STRUCT DEST/TRLB	FD
Siesta Key-Tampa Bay Daybeacon 40	59350	STRUCT MISSING/TRUB	FD

NAME	LLNR	STATUS	AID TYPE
Holiday Inn Marina Daybeacon 3	22047.3	STRUCT DEST	PA
Holiday Inn Marina Daybeacon 6	22047.7	STRUCT DEST	PA
Evans Artificial Reef Daybeacon	58480.5	STRUCT DEST/HAZ NAV	PA
Coral Shores Channel Daybeacon 3	59375	STRUCT DEST	PA
Coral Shores Channel Daybeacon 12	59420	DAYMK MISSING	PA
Coral Shores Channel Daybeacon 30	59510	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 2	59636	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 3	59640	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 3A	59641	STRUCT DEST/HAZ NAV	PA
Palma Sola Bay Channel Daybeacon 5	59645	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 6	59646	STRUCT DEST/HAZ NAV	PA
Palma Sola Bay Channel Junction A	59647	STRUCT DEST	PA
Cove Sound Moorings Channel Daybeacon 3	59657	DAYMK MISSING	PA
Perico Bayou Channel Daybeacon 9	59720	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 10	59820	STRUCT DMGD	PA
Palma Sola Bay Channel Daybeacon 12	59830	DAYMK MISSING	PA
Bradenton Beach City Channel Daybeacon 1	59935	DAYMK MISSING	PA
Bradenton Beach City Channel Daybeacon 2	59940	STRUCT DEST	PA
Bradenton Beach City Channel Daybeacon 3	59945	DAYMK MISSING	PA
Bradenton Beach City Channel Daybeacon 5	59955	STRUCT DEST	PA

Maritime Safety Information Products | Navigation Center

Bradenton Beach City Channel Junction Daybeacon A	59980	STRUCT DEST	PA
Anna Maria Channel Daybeacon 1	60190	STRUCT DMGD	PA
Anna Maria Channel Daybeacon 9	60230	STRUCT DEST/HAZ NAV	PA
Bay Isles Perimeter Channel Daybeacon 2	58667	DAYMK MISSING	PA
Bay Isles Perimeter Channel Daybeacon 9	58667.25	DAYMK MISSING	PA
Bay Isles Perimeter Channel Daybeacon 15	58667.45000000004	STRUCT DEST	PA
Bay Isles Perimeter Channel Daybeacon 24	58667.75	DAYMK MISSING	PA
Mt Vernon & Coral Shores Daybeacon 1N	59535	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 4	59642	STRUCT DEST	PA
Cove Sound Moorings Daybeacon 1	59650	OFF STA/HAZ NAV/DAYMK MISSING	PA
Cove Sound Moorings Daybeacon 2	59655	OFF STA/HAZ NAV/DAYMK MISSING	PA
San Remo Shore Channel Daybeacon 2	59760	DAYMK MISSING	PA
San Remo Shore Channel Daybeacon 8	59785	STRUCT DEST	PA
San Remo Shore Channel Daybeacon 13	59800	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 9	59815	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 11	59825	STRUCT DEST/HAZ NAV	PA
Palma Sola Bay Channel Daybeacon 15	59845	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 18	59860	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 19	59865	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 21	59870.5	DAYMK MISSING/STRUCT DMGD	PA
Anna Maria Channel Daybeacon 2	60195	DAYMK MISSING	PA
Anna Maria Channel Daybeacon 11	60240	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Southwest Channel - Paradise Bay Estates	Bridges	General/Bridges/Repairs, Painting, Or Fender Replacement From: 2025-06-13 To: 2025-07-21 Location: 27.46882° N /	Lat:
Channel/General/Bridges/Repairs, Painting, Or Fender Replacement		82.69324° W Bridge Name: Cortez Bridge - GICW Fender maintenance will occur from July 1 through July 18, 2025. The work consists of adding treated timber to the existing fenders. A small work boat will be utilized, and marine traffic will not be	27 28 08 Lon:
		impeded. All mariners are advised to use caution when transiting the area.	-082° 41'
			36"

Pass-A-Grille

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pass-A-Grille Channel Daybeacon 1	25460	STRUCT MISSING/TRLB/HAZ NAV	FD
Pass-A-Grille Channel Daybeacon 2	25465	STRUCT DEST/HAZ NAV/TRLB	FD
Pass-A-Grille Channel Daybeacon 12	25565	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dent's Channel Daybeacon 5	25520	STRUCT DEST	PA

Private Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Dent's Channel Daybeacon 2	25510.10000000002	REBUILT/RECOVERED	PA	2025-06-09
Dent's Channel Daybeacon 5	25520	REBUILT/RECOVERED	PA	2025-06-09

Peace River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Peace River Daybeacon 3	20480	DAYMK MISSING	FD
Peace River Light 4	20675	STRUCT MISSING/TRLB	FD

NAME	LLNR	STATUS	AID TYPE
Countryman Waterway Channel Daybeacon 6	20997	STRUCT DEST	PA
Spring Lake Waterway Daybeacon 21	21056.8	STRUCT DEST/HAZ NAV	PA
Ponce De Leon Park Channel Daybeacon 4	20455	STRUCT DEST	PA
Ponce De Leon Park Channel Light 9	20470	LT EXT	PA
Ponce de Leon Park Channel Daybeacon 18	20474.5	STRUCT DEST	PA
Elkcam Waterway Light 1	20905	LT EXT	PA
Manchester Waterway Daybeacon 14	20981.5	STRUCT DEST	PA
Manchester Waterway Daybeacon 17	20981.9	STRUCT DEST	PA
Manchester Waterway Daybeacon 24	20982.8	STRUCT DEST	PA

Maritime Safety Information Products | Navigation Center

Countryman Waterway Channel Daybeacon 3	20990	DAYMK MISSING	PA
Countryman Waterway Channel Daybeacon 8	21003	STRUCT MISSING	PA
Sunrise Waterway Daybeacon 2	21020	STRUCT DEST/HAZ NAV	PA
Spring Lake Waterway Daybeacon 23	21056.9	STRUCT DMGD	PA
Spring Lake Waterway Daybeacon 27	21057.2	STRUCT DEST	PA
Peace River (North Section) Daybeacon 7	21210	OFF STA	PA
Peace River (North Section) Daybeacon 9	21215	OFF STA	PA
Peace River (North Section) Daybeacon 10	21220	STRUCT DEST	PA
Peace River (North Section) Daybeacon 11	21225	OFF STA	PA
Peace River (North Section) Daybeacon 14	21235	STRUCT DEST	PA

Pine Island Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pine Island Sound Daybeacon 5	54825	STRUCT MISSING/TRUB	FD
Pine Island Sound Light 20	55425	STRUCT DEST/HAZ NAV/TRLB	FD
Pine Island Sound Daybeacon 28	55565	STRUCT MISSING	FD
Pine Island Sound Daybeacon 34	55590	STRUCT MISSING	FD
Pine Island Sound Light 45A	55900	DAYMK MISSING	FD
Pine Island Sound Daybeacon 50	55985	STRUCT MISSING	FD
Pine Island Sound Daybeacon 53	56000	STRUCT MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Safety Harbor Channel Daybeacon 3	55923	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 11	55940	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 17	55960	DAYMK MISSING	PA
Matlacha Pass Daybeacon 34	55050	STRUCT DEST/HAZ NAV	PA
Matlacha Pass Daybeacon 53	55130	STRUCT DEST	PA
Matlacha Pass Daybeacon 79	55225	DAYMK MISSING	PA
Matlacha Pass Daybeacon 81	55230	DAYMK MISSING	PA
Matlacha Pass Daybeacon 83	55235	DAYMK MISSING	PA
Matlacha Pass Daybeacon 85	55240	DAYMK MISSING	PA
Matlacha Pass Daybeacon 87	55245	DAYMK MISSING	PA
Matlacha Pass Daybeacon 89	55250	DAYMK MISSING	PA
Matlacha Pass Daybeacon 91	55255	DAYMK MISSING	PA
Matlacha Pass Daybeacon 92	55260	DAYMK MISSING	PA
Matlacha Pass Daybeacon 93	55265	DAYMK MISSING	PA
Paradise Canal Daybeacon 1	55310	DAYMK MISSING	PA
Paradise Canal Daybeacon 2	55315	DAYMK MISSING	PA
Paradise Canal Daybeacon 3	55320	STRUCT DEST	PA
Paradise Canal Daybeacon 5	55330	STRUCT DEST	PA
Long Cutoff Daybeacon 2	55370	STRUCT DEST/HAZ NAV	PA
Safety Harbor Channel Daybeacon 1	55915	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 5	55925	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 4	55930	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 7	55933	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 9	55935	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 12	55950	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 19	55965	DAYMK MISSING	PA

Pithlachascotee River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pithlachascottee River Daybeacon 43	26765	STRUCT DEST	PA
Pithlachascottee River Daybeacon 48	26780	STRUCT DEST/HAZ NAV	PA
Pithlachascottee River Daybeacon 51	26790	STRUCT DEST	PA
Pithlachascottee River Daybeacon 56	26805	STRUCT DEST	PA

Plantation Creek

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE	
Plantation Creek Daybeacon 3	6260	WATCHING PROPERLY	FD	2025-06-11	

Point Pinellas Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Point Pinellas Channel Light 9	24735.10000000002	STRUCT MISSING	FD
Point Pinellas Channel Light 10	24735.2	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Bayou Approachroach Daybeacon 3	24765	DAYMK MISSING	PA
Little Bayou Approachroach Daybeacon 7	24775	STRUCT MISSING	PA
Little Bayou Approachroach Daybeacon 9	24780	STRUCT DEST	PA
Coquina Key Cut Daybeacon 3	24835	STRUCT DEST/HAZ NAV	PA

Ponce De Leon Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce De Leon Cut Daybeacon 18	40610	STRUCT DEST/TRUB	FD

Ponce De Leon Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce De Leon Inlet North Jetty Light	9520	STRUCT DEST	FD
Ponce De Leon Inlet Buoy 7B	9544	OFF STATION	FD
Ponce De Leon Inlet Buoy 8A	9546	MISSING	FD
Ponce De Leon Inlet Light 12	9570	STRUCT DEST/TRLB	FD

Port Everglades

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE	
Port Everglades South Regulatory Light	10349	STRUCT DMGD	FD	

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Miami, Submerged Land Act (SLA) -	Marine	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2024-10-20 To:	Lat:
Port Everglades/General/Marine	Construction	2025-04-18 Location: 26.0961° N / 80.12005° W Orion Marine Construction, Inc. will be starting construction of the above	26° 05' 46"
Construction (Excluding Bridges)/Facilities,	(Excluding	referenced project from the water side using two crane loaded deck barges (999 crane on KS6019 barge and 1250 crane on	Lon:
Barriers, Manmade Reefs, Riprap,	Bridges)	KS6012 barge) along with four material barges (TBD1 through TBD4); all being serviced by a full-time push boat (TBD5). Orion will	-080° 07'
Jetties/Dikes		be on-site on July 15, 2024, and will start working on all activities related to the replacement of approximately 2300 feet of	12"
		bulkhead. Hours of operation will be from 7 a.m. to 7 p.m. The estimated completion date is July 1, 2026. All the barges are	
		intended to be spudded around the Port Everglades Berths 1-3 and 1A-1D area (26-05-53.68N / 080-07-12.11W) while working on	
		replacing the bulkhead in those locations. Vessels will be monitoring VHF-FM channel 11.	

Port Manatee Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Manatee Channel Outbound Range Rear Light	22558	STRUCT DEST/TRLB	FD
Port Manatee Channel Outbound Range Rear Passing Light	22559	STRUCT DEST	FD

Port Royal Sound

Federal Discrepancies NAME LLNR STATUS AID TYPE Port Royal Sound Channel Lighted Buoy 5 4095 MISSING FD

NAME	LLNR	STATUS	AID TYPE
Mackay Creek Light 1	4170	LT IMCH/STRUCT DMGD	PA

Port Sutton Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Sutton Channel Range Rear Light	23580	LT IMCH	FD

<u>Ppg Industries</u>

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ppg Industries Lighted Buoy 1	32150	MISSING	PA
Ppg Industries Lighted Buoy 2	32155	MISSING	PA
PPG Industries Lighted Buoy 3	32160	OFF STA	PA

Puerto Del Rey Marina

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bajos Chinchorro Del Sur Light	31380	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Puerto Del Rey	Hazards To	The U.S. NAVY is advising all mariners to refrain from entering the following area in Ceiba, Puerto Rico: the waters surrounding Isla Piñeros.	
Marina/General/Hazards To	Navigation	Mariners are advised to stay away from this danger zone until further notice, as it contains (UXO) Unexploded Ordnance. The U.S. Coast	
Navigation/Hazards		Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041. For more information, contact Mrs. Maria Danois at (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.	

Puerto Nuevo Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Isla Grande Pier 16 Southeast Light	30920	LT EXT	PA

Punta Gorda

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Punta Gorda East Jetty Light	31180	STRUCT DEST	PA
Punta Gorda West Jetty Light	31185	STRUCT DEST	PA
Punta Gorda East Seawall Light	31190	STRUCT DEST	PA
Punta Gorda West Seawall Light	31195	STRUCT DEST	PA

Radas Roosevelt Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE	
Radas Roosevelt Passage Lighted Buoy 3	31565	SINKING/TRLB	FD	

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATIO
Radas Roosevelt	Hazards To	General/Hazards To Navigation/Hazards From: 2025-01-29 To: 2027-07-28 Location: 18.17261° N / 65.39295° W 18.15467° N / 65.30472° W	
Passage/General/Hazards To	Navigation	18.15924° N / 65.28892° W 18.13738° N / 65.25219° W 18.13445° N / 65.26798° W 18.14815° N / 65.28824° W 18.14162° N / 65.30128° W	
Navigation/Hazards		18.16218° N / 65.39432° W 18.15533° N / 65.44273° W 18.16283° N / 65.44548° W 18.17261° N / 65.39295° W The U.S. NAVY is advising all	
		mariners to refrain from entering the following areas in Vieques, Puerto Rico: Northeast from Puerto Diablo to Punta Este and on the Southeast	
		on Bahia Salinas Del Sur. Mariners are advised to stay away from this danger zone until further notice, as it contains (UXO) Unexploded Ordnance.	
		The U.S. Coast Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041. For more information, contact Mrs. Maria	
		Danois at: (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.	

Redfish Pass

NAME	LLNR	STATUS	AID TYPE
Redfish Pass Lighted Buoy 1	1255	BUOY DMGD	PA
Redfish Pass Buoy 2	1257	BUOY DMGD	PA
Redfish Pass Buoy 4	1260	BUOY DMGD	PA

Redhook Bay

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Redhook Bay Buoy 2	32425	OFF STA	PA

Riverside

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Riverside Daybeacon 43	8980	STRUCT DEST/TRUB	FD

Roberts Bay Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Roberts Bay Channel Light 13	57760	DAYMK MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dona Bay Channel Daybeacon 10	21456	STRUCT DEST/HAZ NAV	PA
Dona Bay Channel Daybeacon 6	21455.60000000002	STRUCT DEST	PA
Dona Bay Channel Daybeacon 9	21455.9	STRUCT DEST	PA
Higel Park North Channel Buoy 1	57776	MISSING	PA
Higel Park North Channel Buoy 3	57777	MISSING	PA

Rockdedundy River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rockdedundy River Daybeacon 188	36850	TRUB/STRUCT MISSING	FD

Rocky Reef

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rocky Reef Daybeacon 12	51235	STRUCT DEST	FD

San Carlos Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
San Carlos Bay Light SC	17990	DAYMK MISSING	FD
Punta Rassa Light 3	18020	STRUCT MISSING/TRLB	FD
San Carlos Bay Channel Light 10	18035	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Punta Rassa Boat Ramp Channel Daybeacon 3	18050	STRUCT DEST	PA
Port Sanibel Marina Daybeacon 12	18068.10000000002	HAZ NAV/DAYMK MISSING	PA
Port Sanibel Marina Daybeacon 26	18069.3	DAYMK MISSING	PA
Port Sanibel Marina Daybeacon 30	18069.5	DAYMK DMGD	PA
Port Sanibel Marina Daybeacon 33	18069.7	DAYMK MISSING	PA
Port Sanibel Marina Daybeacon 42	18069.98	DAYMK MISSING	PA

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
San Carlos Bay/General/Bridges/Construction	5	General/Bridges/Construction From: 2024-11-12 To: 2026-12-31 Location: 26.40435° N / 81.88092° W Bridge Name: Big Carlos Pass Bridge - Big Carlos Pass Superior Construction, on behalf of the bridge owner Lee County, will be replacing the Big Carlos (SR 865) Bridge over the Big Carlos Pass. The existing bascule bridge will be replaced with a higher-level fixed bridge. In-water work is expected to begin October 2023 and will continue through December 2026. A temporary work trestle will be installed oceanward of the bridge and will span the waterway except across the main navigational channel. The work trestle will provide only 5 feet of vertical clearance throughout the structure. The drawbridge will remain fully operational at this time. All mariners are requested to use extreme caution and proceed at slow speed when transiting Big Carlos Pass and remain in the main channel when proceeding through the bridge. All in-water equipment is required to be lighted at night. For further information please contact U.S. Coast Guard Sector St. Petersburg at 727-824-7506 or via email at D07-SMB- Tampa-WWM@uscq.mil.	Lat: 26° 24' 16" Lon: -081° 52' 51"

San Sebastian River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
San Sebastian River Daybeacon 20	39170	STRUCT DEST	FD

Sand Key

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sand Key Daybeacon 25	61465	STRUCT DEST/DBD DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bay Pines Channel Daybeacon 1	61225	STRUCT DEST	PA
Bay Pines Channel Daybeacon 7	61240	STRUCT DEST	PA
Bay Pines Channel Daybeacon 16	61265	STRUCT DEST	PA
Bay Pines Channel Daybeacon 19	61275	STRUCT DMGD	PA
Bay Pines Channel Daybeacon 25	61295	STRUCT DEST	PA
Bay Pines Channel Daybeacon 31	61310	STRUCT DEST	PA

Sapelo River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sapelo River Daybeacon 2	5875	STRUCT MISSING	FD

Sapelo Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sapelo Sound Buoy 2	5840	MISSING	FD
Sapelo Sound Buoy 5	5850	OFF STATION	FD
Sapelo Sound Light 138	36630.1	STRUCT DEST/TRLB	FD

Sawpit Creek

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Sawpit Creek Daybeacon 49A	38193	DISCONTINUED	FD
Sawpit Creek Daybeacon 50	38195	RELOCATED FOR DREDGING	FD
Sawpit Creek Temporary Daybeacon 50A	38195.1	ESTABLISHED	FD

Sector Charleston, Exclusive Economic Zone (EEZ)

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tybee Creek Fishing Pier Light	370	LT EXT	PA

Sector Charleston, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little River Inlet Daybeacon 19	1750.5	STRUCT MISSING/TRUB	FD
Murrells Inlet Light 10	1800	TRLB/STRUCT MISSING	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
St Andrew Sound Wreck Temporary Lighted Buoy	37386	ESTABLISHED	FD

TITLE SUBCATEGORY DESCRIPTION LOCATION	TITLE	SUBCATEGORY	DESCRIPTION	LOCATION	
--	-------	-------------	-------------	----------	--

 Sector Charleston, Territorial Sea - Sector Charleston,
 Marine Construction
 General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 1976)
 Lat

 Submerged Land Act (SLA)/General/Marine Construction
 (Excluding Bridges)/Facilities, Barriers, Manmade Reefs,
 Riprap, Jetties/Dikes
 South Carolina Public Service Authority will be removing a land mass on
 33° 26' 56"

 Riprap, Jetties/Dikes
 Hours of operation are Monday – Friday 6 a.m. to 6 p.m. Vessels will be monitoring VHF-FM channel 16.
 -080° 09'

Sector Charleston, Territorial Sea

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St. Simons Light	520	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Capers Island Lighted Buoy D	169	OFF STATION	PA
Charleston Sixty Foot Reef Buoy	230	OFF STA	PA
Folly Beach Fishing Pier Obstruction Light	235	LT EXT	PA
North Edisto Reef Lighted Buoy	260	MISSING	PA
Edisto Sixty Foot Reef Buoy	270	OFF STA	PA
Fripp Island Lighted Buoy E	297	OFF STATION	PA
General Gordon Wreck Fish Haven Buoy	305	OFF STA	PA
Whitewater Reef Buoy	335	OFF STA	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Charleston Light	195	Reduced Intensity	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Exclusive	Advanced Notice	ATON/Advanced Notice of Change Location: 31.04263° N / 81.25632° W Aid Name: Brunswick Spoil Area Lighted Buoy C LLNR: 518 Action:	Lat:
Economic Zone (EEZ) - Sector	of Change	RENAME Brunswick Spoil Area Lighted Buoy C (LLNR 518) will be changed to Brunswick Spoil Area Lighted Buoy D (LLNR 518). The name	31° 02' 33"
Charleston, Territorial		change is to alleviate confusion when the Brunswick Pilots instruct commercial vessels to rendezvous with the pilot boat at the "Sea Buoy" (St	Lon:
Sea/ATON/Advanced Notice of		Simons Sound Lighted Buoy STS). The similarity in names between the two aids has caused confusion amongst mariners. With the Brunswick	-081° 15'
Change		Spoil Area Lighted Buoy C marking a shoal, this confusion could lead to a potential grounding.	23"
Sector Charleston, Exclusive	Proposed Notice	ATON/Proposed Notice of Change 14575 Location: 32.75793° N / 79.84324° W Aid Name: Charleston Light LLNR: 195 Action: CHANGE Action	Lat:
Economic Zone (EEZ) - Sector	of Change	Type Change Light Signals The U.S. Coast Guard is proposing the following changes to the Aids to Navigation System in the Charleston Harbor:	32° 45' 29"
Charleston, Territorial		Charleston Light (LLNR 195) will permanently have the nominal range reduced from 20NM to 17NM due to the installation of an LED optic. This	Lon:
Sea/ATON/Proposed Notice of		optic will ensure the light is more reliable as parts and essential components become harder to source for the existing optic. Any part or	-079° 50'
Change		component failure with the current equipment could potentially lead to an extended period where the light would be extinguished. The flash	36"
		characteristic and color will remain the same. All comments should be emailed to: d07-smb-dpwpubliccomments@uscg.mil or	
		andrew.m.engle@uscg.mil with Charleston Light as the subject line. Comments can also be mailed to Commander (dpw), Seventh Coast Guard	
		District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Building, Miami, FL 33131-3050 to be received by May 25, 2024.	

Sector Jacksonville, Submerged Land Act (SLA)

Federal Discrepancies					
NAME	LLNR	STATUS	AID TYPE		
St. Johns Light	575	LT IMCH	FD		

TITLE	SUBCATEGORY	DESCRIPTION	LOCATIO
Sector Jacksonville, Territorial Sea -	Marine	General/Marine Construction (Excluding Bridges)/Dredging 6783 Great Lakes Dredge and Dock Company, LLC will be conducting	
Sector Jacksonville, Submerged Land	Construction	dredging on or about December 25, 2024, with an estimated completion date of July 30, 2025. DREDGE ILLINOIS will be dredging	
Act (SLA)/General/Marine Construction	(Excluding	approximately 1.5 million cubic yards of beach compatible sand from the Sand Bypass Dredging Area (SBDA) and transporting the	
(Excluding Bridges)/Dredging	Bridges)	excavated material to the beach placement area, approx. 0.5 to 9.5 miles south of the Cape Canaveral south jetty. The SBDA is located approximately 0.1 to 1.6 miles north of the Port Canaveral North Jetty and within Cape Canaveral Space Force Station (CCSFS). There are approximately 50 buoys marking different locations. Mariners are requested to transit the area with caution. Other vessels being used are Derrick GL 64, anchor Barge GL 117, crew Boat MUSKEGON RIVER, survey Boat PEARL RIVER, tug BAYOU BRAVE, tug LISTO, tug SMITH HUNTER, tug SYLVIE FAYE, multi cat CAPE CANAVERAL. Vessels will be monitoring VHF-FM channels 5, 13 and 16.	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-12-30 To: 2025-06-28 Location: 30.70112° N / 81.42749° W 30.70053° N / 81.40072° W 30.61015° N / 81.35402° W 30.61074° N / 81.43779° W 30.70112° N / 81.42749° W Manson Construction Co. will be conducting hopper dredging (NEWPORT and GLENN EDWARDS) with beach disposal (Fort Clinch and North Beach) and nearshore/offshore disposal (south of Saint Marys Entrance) of dredged material. Operations are expected to commence on or about January 2, 2025, with an estimated completion date of March 15, 2025. Dredging operations to be conducted 7 days per week, 24 hours per day. Vessels will be monitoring VHF-FM channels 13, 16 and 66. Manson respectfully requests that all vessels transiting the dredging, disposal, and pipe assembly/disassembly areas reduce speed.	

Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 9374 From: 2025-01-21 To: 2025-11-07 Gator Dredging will be dredging Ponce Inlet and connecting ICW, disposing onto Ponce Inlet Beach. Operations are expected to commence on or about March 3, 2025, with an estimated completion date of November 7, 2025. Mariners are urged to use extreme caution in the area, transit at their slowest safe speed to minimize wake, and proceed with caution after passing arrangements have been made. Floating and submerged high density polyethylene (HDPE) and steel pipeline associated with the hydraulic dredging operations of the channel will be utilized. Pipeline, work vessels, dredge barge, booster pump barge(s) and buoys will be visibly lighted and marked according to coast guard regulations and will be in the area until all work is complete and can change configuration daily. Vessels BRITTYN B and DREDGE CLEARWATER and/or equipment will be in multiple locations at the same time and monitor VHF-FM channel 16.	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging Marinex Construction, Inc. will perform dredging work for the Nassau County Shore Protection Project, Beach Renourishment. The Dredge Savannah shall begin work as early as May 5, 2025, from the borrow site located 1 ½ Miles SE of the St. Mary's River Entrance (jetties). Dredge pipe and equipment will be staged and mobilized in the Amelia River near Tiger Island across from the Dee Dee Bartels County Boat Ramp. Installation of submerged pipeline will begin as early as April 25, 2025. The Dredge Savannah will operate 24-7 and monitor VHF-FM channels 13 and 16, from approximately May 5, 2025, through August 15, 2025, with demobilization of plant and equipment through September 1, 2025.	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 18002 On or about May 14, 2025, Cashman Dredging and Marine Contracting Company, LLC will begin dredging operations on U.S. Naval Station Mayport Maintenance Dredging, Duval County, Florida. The work will be done in the entrance channel and turning basin. This work will be done by the Mechanical Dredge "DALE PYATT" and the Trailing Suction Hopper Dredge "NEWPORT". Support tugs will be the "BRINN CORTNEY", "STASINOS BOYS", and "AMY HEBERT". We will be using the following dump scows: "JOE VERROCHI", M.E.R.C. SHEVLIN", and "KURT SHULTE". The dredge(s) will be supported by the survey/crew vessel "Survey 7", drag barge "Dana", tug "Miss IIa", and various other support vessels. All vessels will monitor VHF- FM channels 16,13,12 and use 74 as the working channel. Both Dredges will be using the ODMDS for open ocean disposal. Mariners are urged to transit at their slowest safe speed to minimize wake and proceed with caution after passing arrangements have been made. Dredges will operate 7 days a week, 24 hours a day. The work is scheduled to be completed on or before October 1, 2025.	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	General/Miscellaneous 20295 The U.S. Space Force may choose to enforce a restricted area as specified in 33 CFR 329.525 and 33 CFR 329.595. Primarily beginning 2 hours prior to the scheduled launch window of any rocket launches. The restricted area would remain in effect until suspended by Space Launch Delta 45.	

Sector Key West, Exclusive Economic Zone (EEZ)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dry Tortugas Southeast Channel Light 1	15440	HAZ NAV/LT EXT/DAYMK MISSING	FD
Dry Tortugas Southeast Channel Light 3	15450	STRUCT DEST/HAZ NAV/TRLB	FD
Fort Jefferson West Channel Daybeacon 10	15560	STRUCT DEST	FD

Sector Key West, Submerged Land Act (SLA)

NAME	LLNR	STATUS	AID TYP
Davis Reef Light 14	970	LT EXT	FD
Cosgrove Shoal Light	1070	LT EXT	FD
Halfmoon Shoal Light WR2	1085	STRUCT DEST	FD
New Ground Rocks Light	1190	HAZ NAV/LT EXT/STRUCT DMGD/TRLB	FD
Smith Shoal Light	1200	LT EXT	FD
Broad Creek Light 6	1215	DAYMK MISSING	FD
Turtle Harbor West Shoal Preferred Channel Light	11455	STRUCT DEST	FD
Key Largo Light 25	11485	STRUCT DEST	FD
Key Largo Light 25	11485	DBD DMGD	FD
Basin Hills Light 31BH	11500	STRUCT DEST	FD
Key Largo Daybeacon 32A	11675	STRUCT DEST/TRLB	FD
Mosquito Bank Light 2	11895	STRUCT DEST/HAZ NAV/TRLB	FD
Channel Key Daybeacon 7	12430	STRUCT MISSING/TRLB	FD
Porpoise Key Daybeacon 2	12685	HAZ NAV/DAYMK MISSING/TRLB	FD
Moser Channel South Daybeacon 5	13865	STRUCT DEST/TRLB/HAZ NAV	FD
Bahia Honda Key Light 49A	13875	DAYMK MISSING	FD
Niles Channel Daybeacon 6	13955	STRUCT DEST/HAZ NAV/TRLB	FD
Loggerhead Key Light 50A	13980	HAZ NAV/STRUCT DEST/TRLB	FD
oggerhead Key Light 50A	13980	STRUCT DEST/TRLB	FD
Pirates Cove Daybeacon 10	14175	STRUCT DEST/HAZ NAV/TRLB	FD
3oca Chica Channel Light 1	14505	HAZ NAV/TRLB/STRUCT DEST	FD
Key West Main Channel Range Front Light	14815	STRUCT DEST/TRLT	FD
Sand Key Channel Daybeacon 2	15090	DBD DEST	FD
Middle Ground Daybeacon 3	15095	DAYMK MISSING	FD
Key West Northwest Channel Light 6	15165	STRUCT DEST/TRLB	FD
Key West Northwest Channel Daybeacon 8	15200	STRUCT DEST/TRLB	FD
Key West Northwest Channel Daybeacon 15	15230	STRUCT DEST/TRUB	FD
Calda Channel Light 1	15330	STRUCT DEST/HAZ NAV/TRLB	FD
Calda Channel Daybeacon 5	15340	HAZ NAV/STRUCT DEST/TRLB	FD

Maritime Safety Information Products | Navigation Center

Calda Channel Daybeacon 6	15345	STRUCT DEST/HAZ NAV/TRLB	FD
Calda Channel Daybeacon 18	15400	STRUCT DEST/HAZ NAV/TRLB	FD
Calda Channel Daybeacon 22	15415	STRUCT DEST/HAZ NAV/TRLB	FD
Fort Jefferson East Channel Daybeacon 3	15470	STRUCT DEST/HAZ NAV/TRLB	FD
Fort Jefferson East Channel Daybeacon 5	15475	HAZ NAV/DAYMK MISSING/TRLB	FD
Fort Jefferson East Channel Daybeacon 6	15480	STRUCT DEST/HAZ NAV/TRLB	FD
Fort Jefferson East Channel Daybeacon 7	15485	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Broad Creek Daybeacon 13	11177.6	STRUCT DEST	PA
Kemp Channel Daybeacon 2	13990	STRUCT DEST/HAZ NAV	PA
Key West Oceanside Marina Daybeacon 2	14670	DAYMK MISSING	PA
Newfound Harbor Key Buoy C	1003.4	MISSING	PA
Newfound Harbor Key Buoy D	1003.6	MISSING	PA
Vestern Sambo Buoy B	1024.2	MISSING	PA
and Key Buoy B	1054.2	MISSING	PA
ewis Cut Shoal West Buoy	10907.5	MISSING	PA
Broad Creek Daybeacon 2	11177.1	STRUCT DEST	PA
Dispatch Creek Channel Daybeacon 20	11435	DAYMK IMCH	PA
larbor Course Creek Daybeacon 1	11440	DAYMK IMCH	PA
larbor Course Creek Daybeacon 2	11445	DAYMK IMCH	PA
Garden Cove Daybeacon 22	11645	STRUCT DEST	PA
ort Largo Channel Light 7	11765.30000000001	STRUCT DEST	PA
lue Water Trailer Vill Daybeacon 2	12015	STRUCT DEST	PA
Red Bay Shoal Daybeacon A	12511	STRUCT DEST	PA
a Siesta Resort Daybeacon 2	12810	STRUCT DEST/HAZ NAV	PA
Jpper Matecumbe West Channel Daybeacon 1	12825	STRUCT DEST/HAZ NAV	PA
aloosa Cove Channel Daybeacon 11	13385	STRUCT DMGD	PA
Duck Key Inlet Channel Light 1	13500	STRUCT DEST	PA
Duck Key Inlet Channel Daybeacon 2	13505	STRUCT DEST	PA
Duck Key Inlet Channel Daybeacon 7	13525.5	STRUCT DEST	PA
Coco Plum Channel Daybeacon 2	13625	STRUCT DEST	PA
oco Plum Channel Daybeacon 3	13630	STRUCT DEST	PA
Coco Plum Channel Daybeacon 4	13635	STRUCT DEST	PA
onefish Bay Channel Daybeacon 2	13670	STRUCT DEST	PA
onefish Bay Channel Daybeacon 4	13673	STRUCT DEST	PA
onefish Bay Channel Daybeacon 5	13675	STRUCT DEST	PA
onefish Bay Channel Daybeacon 7	13676	STRUCT DEST	PA
Bonefish Bay Channel Daybeacon 8	13676.30000000001	STRUCT DEST	PA
onefish Bay Shoal Daybeacon	13676.5	STRUCT DEST	PA
Bonefish Bay Channel Daybeacon 10	13676.7	STRUCT DEST	PA
onefish Bay Channel Daybeacon 11	13676.9	STRUCT DEST	PA
Bonefish Bay Channel Daybeacon 13	13677	STRUCT DEST	PA
oat House Channel Buoy 3	13680.2	MISSING	PA
Dolphin Marina Channel Daybeacon 2	13936.2	STRUCT DEST	PA
Cemp Channel Daybeacon 19	14073	STRUCT DEST	PA
emp Channel Daybeacon 24	14095	STRUCT DEST/HAZ NAV	PA
amarac Park Channel Obstruction E Daybeacon	14450	STRUCT DEST	PA
Cow Key Channel Daybeacon 11	14740	STRUCT DMGD	PA
ow Key Channel Daybeacon 13	14745	STRUCT DMGD	PA
ow Key Channel Daybeacon 36	14767.9	STRUCT DMGD	PA
asa Marina Daybeacon 4	14795	STRUCT DEST	PA
ort Taylor West Obstruction Light	14887	LT EXT	PA
Key West Mooring Field Light A	14980.1	LT EXT	PA
Key West Mooring Field Light B	14980.2	LT EXT	PA
Key West Mooring Field Light C	14980.30000000001	STRUCT DEST/HAZ NAV	PA
Key West Mooring Field Light D	14980.4	LT EXT	PA
Key West Mooring Field Light E	14980.5	LT EXT	PA

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
-------	-------------	-------------	----------

/17/25, 10:41 AM		Maritime Safety Information Products Navigation Center	
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	Key West Main Channel Range Front Light (LLNR 14815) will be relocated to approximate position 24-32-17.396N/081-48-22.958W. The RFL will be changed to a day/night optic, continuing to display a Q G flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued.	Lat: 24° 32' 17' Lon: -081° 48' 23"
Sector Key West, Territorial Sea – Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	Key West Main Channel Range Rear Light (LLNR 14820) will be changed to a day/night optic, continuing to display an ISO G 6s flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued.	Lat: 24° 32' 56' Lon: -081° 48' 26"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.56043° N / 81.8144° W Aid Name: Key West Main Channel Cut B Range Front Light LLNR: 14870 Action: CHANGE Action Type Change Structure The U.S. Coast Guard has approved the following change to the Aids to Navigation System in the Key West Main Channel: Key West Main Channel Cut B Range Front Light (LLNR 14870) will be rebuilt at a new focal height of 40 feet. All other characteristics will remain the same. Key West Main Channel Cut B Range Rear Light (LLNR 14875) will be rebuilt at a new focal height of 65 feet. All other characteristics will remain the same.	Lat: 24° 33' 38' Lon: -081° 48' 52"
Sector Key West, Territorial Sea – Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.5629° N / 81.81427° W Aid Name: Key West Main Channel Cut B Range Rear Light LLNR: 14875 Action: CHANGE Action Type Change Structure The U.S. Coast Guard has approved the following change to the Aids to Navigation System in the Key West Main Channel: Key West Main Channel Cut B Range Front Light (LLNR 14870) will be rebuilt at a new focal height of 40 feet. All other characteristics will remain the same. Key West Main Channel Cut B Range Rear Light (LLNR 14875) will be rebuilt at a new focal height of 65 feet. All other characteristics will remain the same.	Lat: 24° 33' 46' Lon: -081° 48' 51"
Sector Key West, Territorial Sea – Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change		Lat: 24° 35' 57' Lon: -081° 48' 35"
Sector Key West, Territorial Sea – Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.60718° N / 81.80627° W Aid Name: Calda Channel Daybeacon 18 LLNR: 15400 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guardhas approved the following changes to the Aids to Navigation System in Calda Channel: Discontinue Calda Channel Daybeacon 6 (LLNR 15345) and establish Calda Channel Buoy 6 (LLNR 15345) in approximate position 24-37-29.832N/081-48-54.830W. Discontinue Calda Channel Daybeacon 18 (LLNR 15400) and establish Calda Channel Buoy 18 (LLNR 15000) in approximate position 24-36-25.834N/081-48-22.586W. Discontinue Calda Channel Daybeacon 22 (LLNR 15415) and establish Calda Channel Buoy 22 (LLNR 15415) in approximate position 24-35-57.055N/081-48-34.971W.	Lat: 24° 36' 26' Lon: -081° 48' 23"
Sector Key West, Territorial Sea – Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.62495° N / 81.81523° W Aid Name: Calda Channel Daybeacon 6 LLNR: 15345 Action:	Lat: 24° 37' 30' Lon: -081° 48' 55"
Sector Key West, Territorial Sea – Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.57937° N / 81.79983° W Aid Name: Key West Harbor Range Front Light LLNR: 14900 Action: CHANGE Action Type Change Light Signals The U.S. Coast Guard has approved the following change to the Aids to Navigation System in the Key West Main Channel: Key West Harbor Range Front Light (LLNR 14900) will be changed to a day/night optic, continuing to display Q W flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued. Key West Harbor Range Rear Light (LLNR 14905) will be rebuilt to a focal height of 46 feet and changed to a day/night optic, continuing to display ISO W 6s flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued.	Lat: 24° 34' 46' Lon: -081° 47' 59"
Sector Key West, Territorial Sea – Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.58519° N / 81.79695° W Aid Name: Key West Harbor Range Rear Light LLNR: 14905 Action: CHANGE Action Type Change Light Signals The U.S. Coast Guard has approved the following change to the Aids to Navigation System in the Key West Main Channel: Key West Harbor Range Front Light (LLNR 14900) will be changed to a day/night optic, continuing to display Q W flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued. Key West Harbor Range Rear Light (LLNR 14905) will be rebuilt to a focal height of 46 feet and changed to a day/night optic, continuing to display ISO W 6s flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued.	Lat: 24° 35' 07' Lon: -081° 47' 49"
Sector Key West, Territorial Sea – Sector Key West, Submerged Land Act (SLA)/General/Bridges/Closure (Scheduled Or Emergency)	Bridges	General/Bridges/Closure (Scheduled Or Emergency) From: 2024-10-29 To: 2025-11-01 Location: 24.60464° N / 81.64066° W Bridge Name: Shark Key Pedestrian Bridge The Shark Channel pedestrian bridge is damaged with debris falling into the water. Mariners are advised to use caution in the area and avoid transiting under the bridge. For more information, contact Florida Keys Overseas Heritage Trail Assistant Park Manager, Jimmy Chandler at (305) 360-7958.	Lat: 24° 36' 17' Lon: -081° 38' 26"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/General/Bridges/Rehabilitation	Bridges	General/Bridges/Rehabilitation From: 2024-11-12 To: 2025-09-01 Location: 24.60459° N / 81.64045° W Bridge Name: Florida Keys Overseas Historical Trial Pedestrian Bridge - Shark Channel The pedestrian bridge is undergoing a rehabilitation project. The contractor will have barges and associated in-water equipment in and around the bridge at all times. All in-water equipment should be lighted in accordance with Inland Navigation rules. Navigation through the structure will be limited during construction; at any time, four (4) arches will be obstructed and closed to navigation. Mariners are advised to proceed at a safe speed and use caution when transiting through the area. The rehabilitation project will begin on or around 3/13/2025 and be completed by 9/1/2025. For waterways related questions, contact, Coast Guard Sector Key West Waterways, 305-292-8768 or email: SKWWaterways@uscg.mil.	Lat: 24° 36' 17' Lon: -081° 38' 26"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	General/Miscellaneous 18012 Mote Marine Laboratory and Aquarium will be launching an autonomous surface vessel for a gulf water quality survey and harmful algal bloom monitoring, traversing from Sarasota, FL to Key West, FL Operations are expected to being May 6, 2025, with an estimated completion date of May 21, 2025. Vessel is equipped with AIS transmit and receiving capabilities.	

Sector Key West, Territorial Sea - Sector	Naval Activity	General/Naval Activity/Military Operations 18248 The US Navy will be conducting exercises in Key West Florida in the coming weeks of
Key West, Submerged Land Act		August 4 – 15, August 25 - September 5, September 15 – 26. All support vessels will be monitoring VHF-FM channels 16 and 81A. On
(SLA)/General/Naval Activity/Military		Monday, August 11, 2025, September 1, 2025, and September 22, 2025, they will be conducting a dive down the Boca Chica Chanel to
(SLA)/General/Naval Activity/Military Operations		the harbor between 6 p.m. and 10 p.m. Divers will stay to the Eastern side of the channel, and they will have four boats plus two jet skis to deconflict with mariners and provide diver support and protection. On Tuesday August 12, 2025, September 2, 2025, and September 23, 2025, they will be conducting a day dive from 4 p.m. to 6:30 p.m. in Fleming Key Cut. They will have four boats and two jet skis on station to deconflict with other mariners and provide diver support and protection. Divers will be confined to transiting through the cut on only one side, leaving the other side open. Also, on Tuesday August 12, 2025, September 2, 2025, and September 23, 2025, they will be conducting a night dive from 7:30 p.m. to 10 p.m. along the western edge of Key West from the mouth of Key West Bight to Truman Waterfront Park. Divers will be no farther from shore than 50 meters and should pose a minimal obstruction to routine navigational operations. Depending on the weather and sea state, they may flex to doing an offset dive. They would splash the divers at either Key West Main Channel Daybeacon 21 (LLNR 4925) diving east into the Basin, or Key West Main Channel Lighted Buoy 15 (LLNR 14895)
		diving east into the Basin. They will have four boats and two jet skis on station to deconflict with other mariners and provide diver support and protection. On Wednesday, August 13, 2025, September 3, 2025, and September 24, 2025, they will be conducting a day into night dive from 7p.m. until 9:30 p.m. around Fleming Key Cut. They will have four boats and two jet skis on station to deconflict with other mariners and provide diver support and protection. Divers will be confined to 50 meters off the shore of the Military side of the base in the water and will not deviate further out into the channel.

Sector Key West, Territorial Sea

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pacific Reef Light	935	LT EXT/TRLT	FD
Elbow Reef Light 6	950	STRUCT DEST/LT IMCH/REDUCED INT/DAYMK MISSING/TRLT	FD
Molasses Reef Light 10	960	LT EXT/STRUCT DMGD	FD
Tennessee Reef Light	990	LT EXT/STRUCT DMGD	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Carysfort Reef Buoy C	947.4	MISSING	PA
The Elbow Buoy B	948.2	MISSING	PA
The Elbow Buoy C	948.4	MISSING	PA
The Elbow Buoy D	948.6	MISSING	PA
Dry Rocks Buoy A	953	MISSING	PA
Grecian Rocks Buoy D	954.6	MISSING	PA
Sombrero Key Buoy B	1002.2	MSLD SIG	PA
Looe Key Buoy C	1007.4	MISSING	PA
Looe Key Telemetering Lighted Buoy LR	1007.800000000001	MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Key West, Exclusive Economic Zone (EEZ) - Sector Key West, Territorial Sea/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2024-11-26 To: 2024-11-27 Location: 24.88752° N / 81.7° W 24.88333° N / 81.7° W 24.88333° N / 81.70458° W 24.88752° N / 81.70458° W 24.88750° W 24.88750° N	
Sector Key West, Exclusive Economic Zone (EEZ) - Sector Key West, Territorial Sea/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes Location: 24.88752° N / 81.7° W 24.88333° N / 81.70458° W 24.88752° N / 81.70458° W 24.88752° N / 81.7° W Monroe County has continued adding to a new artificial reef site off Monroe County with a 10-year permit. The Gulfside Ten Mile Reef site is a 0.25 nautical mile square, encompassing 53 acres of sand bottom of which less than one acre of artificial reef material footprint will be deployed during the lifetime of the permit. The site is located in the Gulf of America within federal waters and lies outside of the boundaries for the Florida Keys National Marine Sanctuary. The center of the site is located approximately 16.7 nautical miles at a bearing of 23° north of Key West at an average depth of 45 feet MLLW. All deployed material will retain at least a 25-ft navigational clearance.	

Sector Miami, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
NSWC Lighted Buoy E	811	HAZ NAV/BUOY DMGD/LT EXT	FD

· · · · · · · · · · · · ·					
NAME	LLNR	STATUS	AID TYPE		
Jupiter Inlet Jetty Light 2	735	LT EXT	PA		
Key Biscayne FAD Northwest Buoy	900	MISSING	PA		
Key Biscayne FAD Northeast Buoy	905	MISSING	PA		
Key Biscayne FAD Southwest Buoy	910	MISSING	PA		
Key Biscayne FAD Southeast Buoy	915	MISSING	PA		
Neptune Memorial Reef Buoy AA	915.1	STRUCT DEST	PA		
Neptune Memorial Reef Buoy BB	915.2	STRUCT DEST	PA		

6/17/25, 10:41 AM		Maritime Safety Information Products Navigation Center			
	Neptune Memorial Reef Buoy CC	915.300000000001	STRUCT DEST	PA	
	Neptune Memorial Reef Buoy DD	915.4	STRUCT DEST	PA	

Sector San Juan, Territorial Sea

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Aguadilla Jetty Light 1	32405	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Devcon International Channel Buoy 2	33000	OFF STA	PA
Devcon International Channel Buoy 3	33005	OFF STA	PA
CariCOOS Wave Buoy D	32401	ADRIFT	PA
Devcon International Channel Buoy 5	33015	OFF STA	PA
Lime Tree Bay Port Basin Light 15	33200	STRUCT DEST	PA
Krause Lagoon Channel Entrance Lighted Buoy 1	33210	TRLB	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector San Juan, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-20 To: 2025-04-18 Location: 18.093° N / 65.62092° W The United States Navy has installed subsurface coral restoration structures offshore of Ilsa de Vieques within the boundaries of the former Navy training range (UXO-16), for a Navy environmental restoration project. The structures include 2 geodesic spheres that are 8 feet diameter, and will be moored to the seafloor such that the tops of the structures will sit at 24 feet below the surface. These structures will not be sitting directly on the seafloor - they will be in the mid-water, moored to the seafloor (which is approximately 55 feet deep at this location) with a 3-anchor system, without surface marker buoys. The structures are expected to remain in place until at least June 30, 2026 in the approximate coordinates: 18-06-01.49N/065-36-17.97W 18-05- 59.94N/065-36-17.17W For further information contact: Jessica Carilli, US Navy (760) 815-2629.	Lat: 18° 05' 35" Lon: -065° 37' 15"
Sector San Juan, Territorial Sea/General/Hazards To Navigation/Hazards	Hazards To Navigation	General/Hazards To Navigation/Hazards From: 2025-01-29 To: 2027-07-28 Location: 18.26572° N / 65.57337° W 18.23996° N / 65.57028° W 18.23931° N / 65.60289° W 18.26474° N / 65.60444° W 18.26572° N / 65.57337° W The U.S. NAVY is advising all mariners to refrain from entering the following area in Ceiba, Puerto Rico: the waters surrounding Isla Piñeros. Mariners are advised to stay away from this danger zone until further notice as it contains (UXO) Unexploded Ordnance. The U.S. Coast Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041. For more information, contact Mrs. Maria Danois at (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.	
Sector San Juan, Territorial Sea/General/Marine Events/Regatta (Race)	Marine Events	General/Marine Events/Regatta (Race) The U.S. Coast Guard will be enforcing a Special Local Regulation for the St. Thomas Carnival Boat Race 2025 described in Title 33 Code of Federal Regulations (CFR) 100.701 Table 1 on April 28, 2025, from 10 a.m. to 5 p.m. The regulated area encompasses all waters of St. Thomas Harbor encompassed within the following points: i. Race Area. All waters of the St. Thomas Harbor located around Hassel Island St. Thomas, U.S. Virgin Island encompassed within the following points: Starting at Point 1 in position 18°20.2' N, 64°56.1' W; thence southeast to Point 2 in position 18°19.7' N, 64°55.7' W; thence south to Point 3 in position 18°19.4' N, 64°55.7' W; thence southwest to point 4 in position 18°19.3' N, 64°56.0' W; thence northwest to point 5 in position 18°19.9' N, 64°56.5' W; thence northeast to point 6 in position 18°20.2' N, 064°56.3' W; thence east back to origin. ii. Jet Ski Race Area. All waters encompassed the following points: Starting at Point 1 in position 18°20.1' N, 64°55.9' W; thence west to Point 2 in position 18°20.1' N, 64°55.1' W; thence north to Point 3 in position 18°20.3' N, 64°55.1' W; thence east to Point 4 in position 18°20.3' N, 64°55.9' W; thence south back to origin. iii. Buffer Zone. All waters of the St. Thomas Harbor located around Hassel Island, encompassed within the following points: Starting at Point 1 in position 18°20.1' N, 64°55.7' W; thence south to Point 3 in position 18°20.3' N, 64°55.1' W; thence south are on the set to Point 4 in position 18°20.3' N, 64°55.9' W; thence south back to origin. iii. Buffer Zone. All waters of the St. Thomas Harbor located around Hassel Island, encompassed within the following points: Starting at Point 1 in position 18°19.7' N, 64°55.7' W; thence southeast to Point 3 in position 18°19.3' N, 64°55.7' W; thence southeast to Point 2 in position 18°19.3' N, 64°55.7' W; thence southeast to Point 3 in position 18°19.3' N, 64°55.7' W; thence around Hassel Island, encompassed within the following points: Starting at	

Sector St. Peterburg, Exclusive Economic Zone (EEZ)

Private Discrepancies

(EEZ)/General/Marine

Construction (Excluding Bridges)/Survey Operations

NAME			LLNR	STATUS	AID TYPE	
Scripps Wave Lighted Buoy A		1367	MISSING	PA		
Additional MSI Categories						
TITLE	SUBCATEGORY		DESCRIPTION			LOCATION
District 7, Oceanic boundary to	Marine	General/Marine Construction (Excluding Bridges)/Survey	Operations Location: 2	8.735° N / 84.39833° W 28.735° N /	84.16° W 28.69333° N /	
EEZ - Sector St. Peterburg, Construction 84.07333° W 28.255° N / 83.79° W 28.27167° N / 83.99667° W 28.16667° N / 83.96° W 28.16333° N / 84.13667° W 28.28667° N / 84.44333° W						
Exclusive Economic Zone	(Excluding	28.735° N / 84.39833° W SAILDRONE, INC. will be conducting research with up to two Uncrewed Surface Vehicles (USVs), called SAILDRONE				

construction	04.07555 W 20.255 N 04.15007 W 20.2107 N 05.5507 W 20.10057 N 04.15007 W 20.2007 N 04.14555 W
(Excluding	28.735° N / 84.39833° W SAILDRONE, INC. will be conducting research with up to two Uncrewed Surface Vehicles (USVs), called SAILDRONE
Bridges)	VOYAGERs, approximately 90 nautical miles northwest of St. Petersburg, FL. The vehicles are supporting the Florida Seafloor Mapping Initiative
	in partnership with the Florida Department of Environmental Protection to conduct a survey off the West Florida Shelf known as The Florida
	Middle Grounds. The vehicles are deployed from St. Petersburg, FL and are expected to make stops from the survey area to St. Petersburg
	throughout this period. These vehicles will conduct 24 hr operations for the aforementioned duration. Vehicles are monitored remotely 24/7
	by the SAILDRONE Mission Control Team. SAILDRONE VOYAGERs are primarily wind-propelled Uncrewed Surface Vehicles (USVs) equipped
	with an electric thruster used for survey operations. Mariners are requested to remain clear from the research equipment. Questions regarding
	this notice can be directed to Saildrone Mission Control at missioncontrol@saildrone.com or via phone at +1-510-722-6070.

District 7, Oceanic boundary to	Marine
EEZ - Sector St. Peterburg,	Construction
Exclusive Economic Zone	(Excluding
(EEZ)/General/Marine	Bridges)
Construction (Excluding	
Bridges)/Survey Operations	

Maritime Safety Information Products | Navigation Center

General/Marine Construction (Excluding Bridges)/Survey Operations 19366 Fugro USA Marine inc, will be conducting hydrographic surveys 24 hours a day, 7 days a week. M/V Renegade and M/V Anna M will be monitoring VHF-FM channel 16 and operating inside the following area with an estimated completion date of July 11, 2025. NW: 28-16-43.38N / 84-00-49.08W SW: 26-16-39.00N / 83-11-52.78W NE: 28-15-10.77N / 83-19-57.83W SE: 26-20-42.34N / 82-34-36.12W

Sector St. Petersburg, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anclote Anchorage South Entrance Light 1	1535	HAZ NAV/STRUCT DEST/TRLB	FD
Seahorse Reef Light	1615	STRUCT DEST/HAZ NAV	FD

NAME	LLNR	STATUS	AID TYP
ort of Islands Marina Daybeacon 3	16235	STRUCT DEST	PA
octors Pass Light DP	17700	LT EXT	PA
ater Turkey Bay Daybeacon 13	17877	DAYMK DMGD	PA
outh Estero Bay Daybeacon 12	19150	STRUCT DEST/HAZ NAV	PA
outh Estero Bay Daybeacon 37	19550	STRUCT DEST	PA
gnal Cove Daybeacon 4	26955	STRUCT DEST	PA
udson Creek Light 2	27015	LT EXT	PA
udson Creek Daybeacon 7	27040	STRUCT DEST/HAZ NAV/TRUB	PA
udson Beach Park Daybeacon 1	27110	STRUCT DEST	PA
ea Pines Channel Daybeacon 3	27150	STRUCT DEST/HAZ NAV	PA
ipeka Daybeacon 7	27310	STRUCT DEST/HAZ NAV	PA
ernando Beach Channel Daybeacon 27	27630.5	STRUCT DEST/HAZ NAV	PA
ng Key North Breakwater Obstruction Daybeacon	1410	STRUCT DEST	PA
ort of Islands Marina Daybeacon 4	16240	STRUCT DEST	PA
ort of Islands Marina Daybeacon 5	16245	STRUCT DMGD	PA
ort of Islands Marina Daybeacon 6	16250	STRUCT DEST/HAZ NAV	PA
ort of Islands Marina Daybeacon 11	16265	DAYMK MISSING	PA
ort of Islands Marina Daybeacon 15	16280	STRUCT DEST	PA
ort of Islands Marina Daybeacon 26	16310	STRUCT DEST	PA
ort of Islands Marina Daybeacon 27	16315	STRUCT DEST	PA
ort of Islands Marina Daybeacon 42	16380	STRUCT DEST/HAZ NAV	PA
ort of Islands Marina Daybeacon 44	16390	STRUCT DEST	PA
pe Romano Channel Daybeacon 2	16792	STRUCT DEST	PA
pe Romano Channel Daybeacon 4	16792.1	STRUCT DEST	PA
ape Romano Channel Daybeacon 17	16793	DAYMK MISSING	PA
axambas Breakwater North Obstruction Daybeacon	16917	STRUCT DEST	PA
axambas Breakwater South Obstruction Light	16918	LT EXT	PA
xambas Breakwater South Obstruction Daybeacon	16918.5	DAYMK MISSING	PA
octors Pass Daybeacon 16	17770	STRUCT DEST	PA
arefoot Boat Club Daybeacon 10	17915	STRUCT DEST	PA
arefoot Boat Club Daybeacon 12	17920	STRUCT DEST	PA
g Carlos Pass Lighted Buoy 1	17975	MISSING	PA
g Carlos Pass Buoy 2	17976	MISSING	PA
g Carlos Pass Buoy 3	17977	MISSING	PA
g Carlos Pass Buoy 4	17980	MISSING	PA
g Carlos Pass Buoy 5	17985	MISSING	PA
itero Pointe Channel Daybeacon 29	18996.07	STRUCT DEST/HAZ NAV	PA
aywinds Channel Daybeacon 3	19347.3	STRUCT DEST	PA
oring Creek Daybeacon 17	19400	STRUCT DEST	PA
buth Estero Bay Daybeacon 45	19585	STRUCT DEST	PA
poonut Jacks Daybeacon 5	19786.2	STRUCT DEST	PA
ripps Wave Data Lighted Buoy CDIP STA 214	22247	OFF STA	PA
gnal Cove Light 2	26945	LT EXT	PA
gnal Cove Daybeacon 5	26960	STRUCT DEST	PA
udson Creek Daybeacon 5	27030	STRUCT DEST/TRDBN	PA
idson Creek Daybeacon 20	27030	STRUCT DEST/TRUB	PA
udson Creek Daybeacon 20 udson Creek Daybeacon 23	27085		PA
	27095	STRUCT DEST	PA
ea Pines Channel Daybeacon 23	27265	STRUCT DEST	PA

Maritime Safety Information Products | Navigation Center

17/20, 10. 4 1 AW	Manume Galety mormation		
Hernando Beach Channel Daybeacon 6	27530	STRUCT DEST	PA
Hernando Beach Channel Daybeacon 7	27535	STRUCT DEST	PA
Hernando Beach Channel Daybeacon 10	27550	STRUCT DEST	PA
Hernando Beach Channel Daybeacon 22	27610	STRUCT DEST	PA
Hernando Beach Channel Daybeacon 23	27615	STRUCT MISSING	PA
Hernando Beach Channel Daybeacon 40	27685	STRUCT DEST/HAZ NAV	PA
Hernando Beach Channel Daybeacon 44	27705	STRUCT DEST	PA
Hernando Beach Channel Light 53	27737	STRUCT DEST/HAZ NAV	PA
Iohnson Rock Obstruction Daybeacon	27930	STRUCT MISSING	PA
Chassahowitzka Daybeacon 17	28305	STRUCT DEST	PA
lorida Power Corporation Channel Light 3	28960	LT IMCH/DAYMK MISSING	PA
Iorida Power Corporation Channel Light 4	28965	LT IMCH/DAYMK MISSING	PA
lorida Power Corporation Channel Light 6	28975	LT EXT	PA
Iorida Power Corporation Channel Light 8	28985	LT EXT	PA
Iorida Power Corporation Channel Light 13	29005	STRUCT DEST	PA
Iorida Power Corporation Channel Light 14	29010	LT EXT	PA
lorida Power Corporation Channel Light 16	29015	LT EXT	PA
lorida Power Corporation Channel Light 17	29020	LT IMCH	PA
lorida Power Corporation Channel Light 21	29035	LT EXT	PA
lorida Power Corporation Channel Light 32	29075	STRUCT DEST/HAZ NAV	PA
lorida Power Corporation Channel Light 47	29150	LT IMCH	PA
lorida Power Corporation Channel Light 48	29155	LT IMCH	PA
Vaccasassa Bay And River Daybeacon 5	29665	STRUCT DEST	PA
Vaccasassa Bay And River Daybeacon 9	29675	STRUCT DEST	PA
Vaccasassa Bay And River Daybeacon 11	29680	STRUCT DMGD	PA
Vaccasassa Bay And River Daybeacon 13	29685	STRUCT DEST	PA
Vaccasassa Bay And River Daybeacon 15	29690	STRUCT DEST	PA
Vaccasassa Bay And River Daybeacon 17	29695	STRUCT DMGD	PA
Vaccasassa Bay And River Daybeacon 21	29705	STRUCT DEST	PA
Vaccasassa Bay And River Daybeacon 23	29710	DAYMK DMGD	PA
Vaccasassa Bay And River Daybeacon 25	29720	STRUCT DEST	PA
Vaccasassa Bay And River Daybeacon 27	29725	DAYMK MISSING/STRUCT DMGD	PA
Vaccasassa Bay And River Daybeacon 30	29735	STRUCT DEST/HAZ NAV	PA
Vaccasassa Bay And River Daybeacon 32	29740	STRUCT DMGD	PA
Suwannee River Alligator Pass Light 2	30085	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 4	30090	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 5	30095	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 7	30100	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 9	30110	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 1	30115	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 13	30120	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 19	30120	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 19	30140	STRUCT DEST/HAZ NAV	PA
	30165		PA
uwannee River Alligator Pass Daybeacon 29 uwannee River McGriff Pass Daybeacon 1	30170	STRUCT DEST STRUCT DEST	PA
· · ·			
Suwannee River Mcgriff Pass Daybeacon 3	30180	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 5	30185 30200	STRUCT DEST	PA PA
Suwannee River Mcgriff Pass Daybeacon 7		STRUCT DEST	
Suwannee River Mcgriff Pass Daybeacon 8	30205	STRUCT DEST	PA
iuwannee River Mcgriff Pass Daybeacon 9	30210	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 20	30233	STRUCT DEST	PA
alt Creek Daybeacon 15	30305	STRUCT DEST	PA
Salt Creek Daybeacon 16	30310	STRUCT DEST	PA
Salt Creek Daybeacon 17	30315	STRUCT DEST	PA

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector St. Petersburg, Territorial Sea - Sector St. Petersburg, Submerged Land Act (SLA)/General/Hazards To Navigation/Shoaling Reported	Navigation	mariners are advised that shoaling and shallow water has developed at the entrance of New Pass in Lee County, Florida in vicinity of New Pass Lighted Buoy 1 (LLNR 17964). All mariners are advised to use caution while transiting new pass due to the potentially hazardous conditions. For further information please contact U.S. Coast Guard Sector St. Petersburg at (727) 824-	Lat: 26° 22' 28" Lon: -081° 52' 34"

Sheephead Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sheephead Cut Daybeacon 7	40705	STRUCT DEST/TRUB	FD

Shell Key

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Race Channel Daybeacon 11B	13085	STRUCT DMGD	PA
Little Basin East Daybeacon 1	50540	DAYMK MISSING	PA
Little Basin East Daybeacon 2	50545	STRUCT DEST/HAZ NAV	PA
Little Basin East Daybeacon 4	50555	DAYMK MISSING	PA

Sherman Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sherman Cut Range Rear Light	7240	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION		
St Johns River - Sherman Cut/ATON/Advanced Notice of Change	Advanced Notice of Change	Sherman Cut RFL (LLNR 7235) will be relocated to approximate position: 30-22-44.220N/081-26-46.188W to align with the newly dredged channel. In addition, Sherman Cut RFL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 44" Lon: -081° 26' 45"		
St Johns River - Sherman Cut/ATON/Advanced Notice of Change	Advanced Notice of Change	Sherman Cut RRL (LLNR 7240) will be relocated to approximate position: 30-22-26.194N/081-27-03.893W to align with the newly dredged channel. In addition Sherman Cut RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 35" Lon: -081° 26' 55'		

Sim-Par Marina Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Marina Bay Channel Daybeacon 4	39715	STRUCT DEST	PA

Singer Island Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Singer Island Channel Daybeacon 6	10212.30000000001	STRUCT DEST/HAZ NAV/TRLB	FD

Sisters Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sisters Creek Light 74	38300	STRUCT DEST/TRLB	FD
Sisters Creek Daybeacon 80	38320	STRUCT DEST/TRUB	FD
Sisters Creek Light 82	38325	STRUCT DEST/TRLB/HAZ NAV	FD
Sisters Creek Light 83	38330	STRUCT DEST/HAZ NAV/TRLB	FD

Skidaway Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Skidaway Narrows Daybeacon 60	36140	STRUCT DEST/TRUB	FD

Snake Creek

NAME	LLNR	STATUS	AID TYPE
Snake Creek Daybeacon 4	12215	STRUCT DEST/TRUB	FD
Snake Creek Daybeacon 5	12225	STRUCT DEST/TRLB	FD

6/17/25,	10.11	
0/11/20,	10.41	AIVI

FD

Snake Creek Daybeacon 7	12240	STRUCT DEST/TRUB
-------------------------	-------	------------------

Snapper Creek Marina

Federal Discrepancies					
NAME	LLNR		STATUS	AID TYPE	
Safety Valve Bank Light 1A	49530	STRUCT DEST/TRLB		FD	
Private Discrepancies					
NAME		LLNR	STATUS	AID TYPE	
Snapper Creek Marina Daybeacon 2		49515	DAYMK MISSING	PA	

Sonde De Vieques

Federal Discrepancies

NAME	LLNR		STATUS		AID TYPE
Cayo Lobito Light	31525 STRUCT DEST			FD	
Private Discrepancies					
NAME			LLNR	STATUS	AID TYPE
North St Thomas Lighted Buoy H			31683	OFF STA	PA

South Altamaha River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Altamaha River Daybeacon 4	36995	STRUCT MISSING/TRUB	FD

South Amelia River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Amelia River Daybeacon 21	38050	STRUCT MISSING/TRUB	FD
South Amelia River Light 24	38060	DAYMK MISSING	FD

South Jupiter Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Jupiter Narrows Daybeacon 25	46085	STRUCT MISSING/TRUB/MISSING	FD

South Newport River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Newport River Light 135	36620	STRUCT MISSING/TRLB	FD

Southwest Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Southwest Channel Light 2 (Tampa Bay)	21840	STRUCT MISSING	FD

St Andrew Sound

NAME	LLNR	STATUS	AID TYPE
St Andrew Sound Buoy 29A	37375	MISSING	FD
St Andrew Sound Lighted Buoy 30	37380	OFF STA	FD
St Andrew Sound Lighted Buoy 31	37383	LT EXT	FD
St Andrew Sound Lighted Buoy 32	37385	OFF STA	FD

St Augustine Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Augustine Inlet Lighted Buoy 5	9495	MISSING	FD
St Augustine Inlet Buoy 10	9510	OFF STA	FD

St Catherines Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Catherines Sound Lighted Buoy 2	5795	MISSING	FD
St Catherines Sound Buoy 1	5800	MISSING	FD
St Catherines Sound Buoy 3	5805	MISSING	FD

St Helena Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Helena Sound Entrance Buoy 4	3965	MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hunting Island Pier Light	4070	STRUCT DEST/LT EXT	PA

St Johns River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pilot Town Cut Range Front Light	7200	LT EXT	FD
St Johns Bluff Light S	7335	STRUCT DEST/TRLB	FD
Quarantine Island Upper Range Front Light	7450	NIGHT LT BURNING DAY	FD
Winter Point Daybeacon	7670	STRUCT DEST/TRUB	FD
Winter Point Light 1	7675	STRUCT DEST/TRLB	FD
Winter Point Light 2	7680	STRUCT DEST/TRLB	FD
Ortega River Shoal Daybeacon	7685	STRUCT DEST/TRUB	FD
Christopher Point Light 5	7725	DAYMK MISSING	FD
Red Bay Point Light 22	7895	STRUCT DEST/TRLB	FD
Tocoi Cut Entrance Light 33	7935	HAZ NAV/STRUCT DMGD/TRLB	FD
Upper Palatka Light 1	8195	LT EXT	FD
Upper Palatka Light 2	8200	LT EXT	FD
Upper Palatka Daybeacon 3	8205	STRUCT MISSING/TRUB	FD
Rivercrest Light 10	8235	LT EXT	FD
Nashua Daybeacon 42A	8390	STRUCT DEST/TRUB	FD
Stephens Point Daybeacon 46	8415	STRUCT DEST/TRUB	FD
Adams Lake Daybeacon 23	8910	STRUCT DEST/HAZ NAV/TRLB	FD
Wekiva Cutoff Daybeacon 95	9155	STRUCT DEST	FD
Wekiva Bend Cutoff Light 96	9160	STRUCT DEST/HAZ NAV/TRLB	FD
Mothers Arms Daybeacon 4	9425	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Goodbys Creek Channel Buoy 4	7765.3	OFF STA	PA
Ortega River Lighted Buoy 2	7696	MISSING	PA
Ortega River Lighted Buoy 13	7697	MISSING	PA
Goodbys Creek Channel Buoy 5	7765.40000000001	OFF STA	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Dunn Creek Cut Lighted Buoy 55	7490	RELOCATED FOR DREDGING	FD
Mile Point Temporary Lower Range Front Light	7260.2	ESTABLISHED	FD
Mile Point Temporary Lower Range Rear Light	7265.2	ESTABLISHED	FD
Training Wall Temporary Range Front Light	7295.2	ESTABLISHED	FD
Drummond Creek Temporary Range Front Light	7515.2	ESTABLISHED	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Advanced Notice of Change	Advanced Notice of Change	St. Johns Bluff LB 30 (LLNR 7329) will be permanently relocated to 30-23-32.020N/081-29-29.730W. This change calls to relocate (6) lighted buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe navigation for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this change. All positions listed are approximate. Permanent positions will be advertised when the work is completed.	Lat: 30° 23' 32" Lon: -081° 29' 30"
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Advanced Notice of Change	Advanced Notice of Change	Training Wall RFL (LLNR 7295) will be relocated to approximate position: 30-23-48.120N/081-28-41.707W to align with the newly dredged channel. In addition, both Training Wall RFL and Training Wall RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 23' 47" Lon: -081° 28' 39"
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Advanced Notice of Change	Advanced Notice of Change	Training Wall RRL (LLNR 7300) will be relocated to approximate position: 30-23-57.479N/081-28-54.848W to align with the newly dredged channel. In addition, both Training Wall RFL and Training Wall RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 23' 58" Lon: -081° 28' 55"
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 28.88295° N / 81.36595° W Aid Name: Wekiva Cutoff Daybeacon 95 LLNR: 9155 Action: DISCONTINUE Wekiva Cutoff DBN 95 (LLNR 9155) will be permanently discontinued. The current location of this structure is located very close to the shoreline, this presents a misleading signal due to more space and plenty of safe water presented on the opposite side of the aid.	Lat: 28° 52' 59" Lon: -081° 21' 57"
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/General/Bridges/Construction	Bridges	General/Bridges/Construction From: 2025-05-06 To: 2026-06-01 Location: No coordinates available Bridge Name: Shands Bridge Construction has begun on a new high-level fixed bridge and will continue until an estimated completion date of September 1, 2030. The new bridge will consist of a vertical clearance of 65 feet and a 150-Ft. horizontal clearance at the navigation channel. Construction will require the use of material storage barges and barge-mounted cranes; all in-water equipment is required to be lighted at night. Work activities on the new bridge will include pier construction, girder erection, fender system installation, and overhead deck operations that could present a hazard to marine traffic. This phase will require periodic channel restrictions or short-term closures and is tentatively scheduled to take place in 2029. Work barges and associated in-water equipment will be in the vicinity of the bridge. All mariners are advised to transit the area with caution.	-081° 37' 08"

St Joseph Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Joseph Sound Daybeacon 1	61850	STRUCT MISSING	FD
St Joseph Sound Daybeacon 9	61885	STRUCT DEST/TRUB	FD
St Joseph Sound Daybeacon 15	61970	STRUCT DEST/TRUB	FD
St Joseph Sound Daybeacon 21	62035	STRUCT DEST/TRUB	FD
St Joseph Sound Daybeacon 38	62275	STRUCT DEST/HAZ NAV/TRLB	FD
St Joseph Sound Light 39	62280	STRUCT DEST/TRLB/HAZ NAV	FD
St Joseph Sound Daybeacon 40	62285	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Safety Harbor Marina Light 2	24375	DAYMK MISSING	PA
Safety Harbor Marina Daybeacon 3	24380	DAYMK DMGD	PA
Safety Harbor Marina Daybeacon 4	24385	DAYMK MISSING	PA
Hurricane Pass Daybeacon 1	25975	DBD DEST	PA
Hurricane Pass Daybeacon 2	25980	STRUCT DEST	PA
Hurricane Pass Daybeacon 4	25990	DBD DEST	PA
Hurricane Pass Daybeacon 5A	25997	STRUCT DEST	PA
Hurricane Pass Daybeacon 7	26005	DBD DEST/STRUCT DMGD	PA
Hurricane Pass Daybeacon 7A	26007	STRUCT DMGD	PA
Caladesi Island Channel Daybeacon 7	61935	DAYMK DMGD	PA
Caladesi Island Channel Daybeacon 7	61935	DAYMK MISSING	PA
Caladesi Island Channel Daybeacon 8	61940	DAYMK DMGD	PA

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph	Bridges	General/Bridges/Temp Deviation From: 2025-04-25 To: 2025-07-05 Location: 28.05115° N / 82.79542° W Bridge Name: Dunedin	Lat:
Sound/General/Bridges/Temp Deviation		Causeway Bridge - GICW The bridge need not open to navigation, including tugs with tows, from 11 p.m. on Thursday, July 3, 2025,	28° 03' 04"
		until 1:30 a.m. on Friday, July 4, 2025, to facilitate the 46th Annual Kiwanis Midnight Run. Public vessels of the United States and	Lon:
		vessels in distress shall be passed at any time.	-082° 47'
			44"

Maritime Safety Information Products | Navigation Center

Clearwater Harbor - St Joseph	Hazards To	General/Hazards To Navigation/Shoaling Reported 20402 All mariners are advised that extreme shoaling and shallow water has	
Sound/General/Hazards To	Navigation	developed throughout Hurricane Pass Channel in between Caladesi and Honeymoon Islands in Pinellas County, FL, specifically in the	
Navigation/Shoaling Reported		vicinity when transiting between Hurricane Pass Channel Daybeacons 8 through 11. All mariners are advised to use extreme caution	
		while transiting Hurricane Pass Channel to the potentially hazardous conditions. For further information please contact U.S. Coast	
		Guard Sector St. Petersburg at (727) 824-7506.	

St Lucie Canal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie Canal Daybeacon 40A	51140	STRUCT DEST/TRUB	FD

St Lucie Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie Inlet Light 3	10000	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Southern Port Salerno Daybeacon 2	10177	STRUCT DEST	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
St Lucie Inlet Buoy 5	10125	RELOCATED FOR DREDGING	FD
St Lucie Inlet Buoy 6	10130	RELOCATED FOR DREDGING	FD

St Lucie River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie River Daybeacon 5	50675	STRUCT DEST/TRUB	FD
St Lucie River Daybeacon 12A	50725.5	STRUCT DEST	FD
St Lucie River Light 13	50730	STRUCT DMGD/TRLB	FD
St Lucie River Light 17	50750	DBD DMGD	FD
St Lucie River Daybeacon 22A	50780	STRUCT DEST/TRUB	FD
St Lucie River Light 23A	50835	STRUCT DEST/HAZ NAV/TRLB	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
St Lucie River Buoy 3	50640	RESET ON STATION	FD	2025-06-11

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Manatee Pocket Channel Daybeacon 2	50677.1	STRUCT DEST	PA
Manatee Pocket Channel North Extension Daybeacon 5	50678.20000000004	STRUCT DEST	PA
Rocky Point Access Channel Daybeacon 1	50641	STRUCT DEST	PA
Manatee Pocket Channel Daybeacon 10	50677.5	STRUCT DEST	PA
St. Lucie River Stuart Ext Daybeacon 1	50838	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Lucie Inlet - St Lucie River/ATON/Advanced Notice of Change		Woods Point Daybeacon 1 (LLNR 50760) will be changed to Woods Point Buoy 1 (LLNR 50760). This change will give mariners a more reliable signal when transiting this channel.	Lat: 27° 12' 18" Lon: -080° 12' 47"
St Lucie Inlet - St Lucie River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2024-12-31 To: 2025-06-01 Location: 27.20368° N / 80.26011° W Bridge Name: Florida East Coast Railroad Bridge The Temporary Interim Rule (TIR) has been extended through September 30, 2025. The railroad bridge will operate in accordance with 33 CFR 117.317(k).	Lat: 27° 12' 13" Lon: -080° 15' 36"

St Lucie River North Fork

NAME	LLNR	STATUS	AID TYPE

Maritime Safety Information Products | Navigation Center

STRUCT DEST

PA

St Lucie River (North Fork) Daybeacon 7	508	85 STRUCT DEST	FD
Private Discrepancies			
NAME	LLNR	STATUS	AID TYPE
Seagate Harbor Daybeacon 1	50861	STRUCT DEST/HAZ NAV	PA

50905

St. Lucie River (North Fork) Daybeacon 11 Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Lucie River - St Lucie River North Fork/General/Bridges/Rehabilitation	Bridges	General/Bridges/Rehabilitation From: 2024-11-22 To: 2025-11-30 Location: 27.27175° N / 80.32449° W Bridge Name: Port St Lucie Boulevard Bridge - Long Creek Seacoast Inc. will be conducting repairs on the bridges across Long Creek. The improvements under this contract consist of structures, riprap, bedding stone, earthwork (excavation), clearing and grubbing, MOT, environmental protections, and monitor existing structures along State Road 716 at Long Creek. In-water equipment will be present, the waterway will not be fully obstructed at any time.	Lat: 27° 16' 18" Lon: -080° 19' 28"
St Lucie River - St Lucie River North Fork/General/Bridges/Rehabilitation	Bridges	General/Bridges/Rehabilitation From: 2024-11-22 To: 2025-11-30 Location: 27.27173° N / 80.32221° W Bridge Name: Port St Lucie Boulevard Bridge - North Fork St Lucie River Seacoast Inc. will be conducting repairs on the bridges across North Fork St Lucie River. The improvements under this contract consist of structures, riprap, bedding stone, earthwork (excavation), clearing and grubbing, MOT, environmental protections, and monitor existing structures along State Road 716 at North Fork St Lucie River. In-water equipment will be present, the waterway will not be fully obstructed at any time.	Lat: 27° 16' 18" Lon: -080° 19' 20"
St Lucie River - St Lucie River North Fork/ATON/Proposed Notice of Change		ATON/Proposed Notice of Change 7619 Location: 27.20914° N / 80.26947° W Aid Name: St Lucie River (North Fork) Daybeacon 5 LLNR: 50855 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard is proposing to make the following change in the St. Lucie River. St. Lucie River N. Fork DBN 5 (LLNR 50855) will be changed to St. Lucie River N. Fork LT 5, using the same LLNR. This aid is currently located near a bend on the St Lucie River (North Fork) and unlighted. Given the turn for the channel it is best to install a light on the aid to provide a better signal during nighttime hours. There are currently no lighted aids in the immediate area. Lighting this aid would keep the maritime community safer and assist with navigation while transiting the river. All comments should be emailed to: D07-SMB-DPWPublicComments@uscg.mil or Andrew.m.engle@uscg.mil with St. Lucie River N. Fork LT 5 as the subject line. Comments can also be mailed to: Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Bldg, Miami, FL. 33131-3050 to be received by June 11, 2025.	Lat: 27° 12' 33" Lon: -080° 16' 10"

St Lucie River South Fork

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie River (South Fork) Daybeacon 24	51000	STRUCT DEST/TRUB	FD
St Lucie River (South Fork) Daybeacon 25A	51010	STRUCT DEST	FD

St Marys Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Marys Entrance Range Rear Light	6530	LT EXT	FD
St Marys South Jetty Buoy B	6615	MISSING	FD
St Marys North Jetty Buoy C	6620	MISSING	FD
St Marys South Jetty Buoy D	6625	OFF STATION	FD
St Marys Daybeacon N	6680	STRUCT DEST/HAZ NAV	FD

St Marys River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Marys River Daybeacon 8	6810	STRUCT DEST	FD

St Petersburg Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Snell Isle Daybeacon 4	25020.2	STRUCT DEST/HAZ NAV	PA
Snell Isle Daybeacon 5	25020.3	STRUCT DEST	PA
Coffee Pot Bayou Daybeacon 1	25021	STRUCT DEST	PA

St Petersburg Yacht Basin

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Petersburg Yacht Basin Light 1	25015	STRUCT DMGD/TRLB	FD
St Petersburg Yacht Basin Light 2	25020	TRLB/STRUCT DEST	FD

NAME	LLNR	STATUS	AID TYPE
St. Petersburg Mooring Field Buoy B	25009.10000000002	MISSING	PA
St. Petersburg Mooring Field Buoy C	25009.2	MISSING	PA

St Simons Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Simons Sound Entrance Lighted Buoy 6	6060	SINKING/TRLB	FD
Plantation Creek Range Rear Light	6135	STRUCT DEST	FD
Cedar Hammock Outbound Range Front Light	6205	STRUCT DMGD/TRLT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
	of Change	Cedar Hammock RFL (LLNR 6195) will be permanently relocated to approximate position 32-06-02.513N/081-27-57.935W. The RFL will be changed to a day/night optic and continuing to display a Q G flash characteristic for a 24hr continuous cycle. The daymarks will be permanently discontinued. Cedar Hammock RFL Passing LT (LLNR 6195.1) will be permanently established to display a FI W 2.5s flash characteristic during nighttime hours only, with a nominal range of 4NM.	Lat: 31° 06' 01" Lon: -081° 28' 05"
Sector Charleston, Submerged Land Act (SLA) - St Simons Sound/ATON/Advanced Notice of Change	of Change	Cedar Hammock RRL (LLNR 6200) will be permanently relocated to approximate position 31-05-58.956N/081-28-13.677W. The RRL will be changed to a day/night optic and continuing to display an Iso G 6s flash characteristic for a 24hr continuous cycle. The daymarks will be permanently discontinued. Cedar Hammock RRL Passing Light (LLNR 6200.1) will be permanently established by mounting (2) optics located on the NW and SE corners of the platform for Cedar Hammock RRL (LLNR 6200.) The (2) optics will be synchronized and display a FI W 2.5s flash characteristic during nighttime hours only, with a nominal range of 4NM. Due to the current location of Cedar Hammock RRL (LLNR 6200) being inaccessible for a CG asset to effectively repair the structure, it was determined by relocating both range structures it will not only offer an excellent range quality index for all mariners but be accessible to all CG assets to provide consistent maintenance to both structures.	Lat: 31° 05' 50" Lon: -081° 28' 52"

Steinhatchee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Steinhatchee River Light 9	30480	DBD DEST/STRUCT DEST/TRLB/HAZ NAV	FD
Steinhatchee River Daybeacon 14	30490.5	HAZ NAV/STRUCT DEST/TRLB	FD
Steinhatchee River Daybeacon 34	30570	STRUCT MISSING/HAZ NAV/TRLB	FD
Steinhatchee River Daybeacon 48	30580.9	STRUCT DEST/TRUB	FD

Stono River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Stono River Daybeacon 20	34640	STRUCT DEST/HAZ NAV/TRLB	FD

Stranahan River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Stranahan River Daybeacon 25	47410	STRUCT DMGD	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Port Everglades - Stranahan River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-05-22 To: 2025-11-29 Location: 26.10057° N / 80.11856° W Bridge Name: Southeast 17th Street Bridge - AICW The Coast Guard has issued a temporary deviation to test a proposed change to the drawbridge operating schedule. This temporary deviation is effective from 6 a.m. on June 2, 2025, through 11:59 p.m. on November 28, 2025. Under the temporary deviation, the bridge shall open on the hour and half-hour; except that from 6:50 a.m. to 9:10 a.m. and from 3:50 p.m. to 6:10 p.m., Monday through Friday, except Federal holidays, the drawbridge shall open once an hour at the top of the hour.	Lat: 26° 06' 02" Lon: -080° 07' 07"
Port Everglades - Stranahan River/General/Hazards To Navigation/Hazards	Hazards To Navigation	General/Hazards To Navigation/Hazards 20853 Location: 26.11168° N / 80.11807° W Large concrete block just below the waterline at low tide.	Lat: 26° 06' 42" Lon: -080° 07' 05"

Sunset Harbour Channel

NAME	LLNR	STATUS	AID TYPE
Flagler Monument Daybeacon 2	48145	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sunset Harbour Channel Light 8	48110	LT EXT	PA

Sunshine Skyway Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sunshine Skyway Channel Daybeacon 2	60320	STRUCT MISSING	FD
Sunshine Skyway Channel Daybeacon 22	60415	STRUCT DEST/TRUB	FD
Sunshine Skyway Channel Daybeacon 23	60420	STRUCT DEST/TRUB	FD

Suwannee Sound South Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Suwannee Sound South Entrance Daybeacon 2	30015	STRUCT MISSING	FD
Suwannee Sound South Entrance Daybeacon 7	30030	STRUCT MISSING	FD
Suwannee Sound South Entrance Daybeacon 11	30040	STRUCT MISSING	FD
Suwannee Sound South Entrance Daybeacon 15	30050	STRUCT MISSING	FD

Tamp Bay Cut C Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut C Channel Outbound Range Front Light	22580	TRLT	FD
Tampa Bay Cut C Channel Outbound Range Rear Light	22585	TRLT	FD

Tampa Bay

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Harbor Marina Daybeacon 3	24570	STRUCT DEST	PA
Simmons Park Channel Daybeacon 4	24606.3	STRUCT DEST/HAZ NAV	PA
Simmons Park Channel Daybeacon 13	24607.2	STRUCT DEST	PA
Apollo Beach Daybeacon 4	24625	DAYMK DMGD	PA
Apollo Beach Daybeacon 9	24643	STRUCT DEST	PA
Cockroach Bay Channel Daybeacon 2	22635	HAZ NAV/DAYMK MISSING	PA
Cockroach Bay Channel Daybeacon 8	22665	DAYMK MISSING	PA
Cockroach Bay Channel Daybeacon 11	22680	DAYMK MISSING	PA
Cockroach Bay Channel Daybeacon 15	22696	STRUCT DEST	PA
Little Harbor Channel Daybeacon 4	24505	STRUCT DEST	PA
Little Harbor Channel Daybeacon 7	24515	STRUCT DEST	PA
Little Harbor Marina Daybeacon 6	24585	HAZ NAV/DAYMK MISSING	PA
Simmons Park Channel Daybeacon 3	24606.2	HAZ NAV/DAYMK MISSING	PA
Harbor Channel Daybeacon 3	24663.2	STRUCT DEST	PA

Tampa Bay Cut D Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut D Channel Outbound Range Rear Light	22715	LT EXT	FD
Tampa Bay Cut D Channel Outbound Range Rear Passing Light	22715.10000000002	STRUCT DEST	FD

Tampa Bay Cut E Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut E Channel Inbound Range Rear Light	22765	STRUCT DEST/HAZ NAV/TRLB	FD
Tampa Bay Cut E Channel Inbound Range Rear Light Passing Light	22765.5	STRUCT DEST	FD

NAME	LLNR	STATUS	AID TYPE
------	------	--------	----------

North Yacht Basin Daybeacon 2

22786 STRUCT DEST

PA

Tampa Bay Cut F Channel

Federal Discrepancies			
NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut F Inbound Range Rear Passing Light	22815.2	LT EXT	FD
Federal Discrenancies Corrected			

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Tampa Bay Cut F Channel Outbound Range Rear Passing Light	22803	WATCHING PROPERLY	FD	2025-06-10

Taylor Creek Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Taylor Creek Channel Daybeacon 3	45100	STRUCT DEST	FD

Terminal Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jacksonville Shipyards Pier 6 Light	7655	LT EXT	PA

The Bight Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE	
The Bight Channel Light 44	4920	STRUCT MISSING/TRLB	FD	

Titusville Yacht Basin

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Titusville Yacht Basin Daybeacon 1	41210	STRUCT DEST/TRUB	FD
Titusville Yacht Basin Daybeacon 3	41220	STRUCT DEST/TRUB	FD

Tolomato River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tolomato River Light 9	38645	STRUCT DEST/HAZ NAV/TRLB	FD
Tolomato River Light 44	38790	STRUCT MISSING/TRLB	FD
Tolomato River Light 45	38800	STRUCT DEST/TRLB	FD
Tolomato River Light 57A	38885	STRUCT DEST	FD
Tolomato River Lighted Buoy 59	38905.5	MISSING	FD

Treasure Island

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Treasure Island Light 3	61050	HAZ NAV/STRUCT DEST/TRLB	FD
Treasure Island Light 9	61070	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jungle Beach Daybeacon 2	61170	STRUCT DEST/HAZ NAV/DAYMK MISSING	PA
Jungle Beach Daybeacon 4	61180	DAYMK DMGD	PA
Jungle Beach Daybeacon 11	61215	STRUCT DEST	PA

Trout River

NAME	LLNR	STATUS	AID TYPE

Maritime Safety Information Products | Navigation Center

Trout River Daybeacon 2	7550	STRUCT DEST/TRUB	FD

		•
Private	Discren	ancies
1 III acc	Disticp	aneres

NAME	LLNR	STATUS	AID TYPE
Maxwell Boat Ramp Channel Daybeacon 5	7557.90000000001	STRUCT DEST	PA
Ribault River Channel Lighted Buoy 1	7559	MISSING/HAZ NAV	PA
Ribault River Channel Lighted Buoy 3	7559.15000000001	ADRIFT	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Trout River Cut Lighted Buoy 63	7540	RELOCATED FOR DREDGING	FD

Turtle River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Turtle River Lighted Buoy 2A	6322	LT EXT	FD
Turtle River Light 4	6325	STRUCT DEST/TRLB	FD
Turtle River Daybeacon 10	6385	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hermitage Island Plant Outfall Obstruction Light	6395	STRUCT DEST	PA

Umbrella Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Umbrella Creek Daybeacon A9	37440	DAYMK MISSING	FD

<u>Unknown</u>

NAME	LLNR	STATUS	AID TYPE
Haig Point Light	4370	LT IMCH	PA
Sebastian Inlet Channel Daybeacon 1A	9730	STRUCT DEST	PA
Sebastian Inlet Channel Daybeacon 5	9750	STRUCT DEST	PA
Sebastian Inlet Channel Daybeacon 28	9812.2	STRUCT DEST/HAZ NAV	PA
Stump Pass Marina Daybeacon 2	21390	STRUCT DEST/HAZ NAV	PA
Stump Pass Marina Daybeacon 3	21395	STRUCT DEST/HAZ NAV	PA
Big Sarasota Pass Buoy 7	21500.7	MISSING	PA
Plymouth Harbor East Obstruction Daybeacon	21547	STRUCT DEST/HAZ NAV	PA
Plymouth Harbor West Obstruction Daybeacon	21547.10000000002	STRUCT DEST/HAZ NAV	PA
South Lido North Obstruction Daybeacon	21555.10000000002	STRUCT DEST/HAZ NAV	PA
South Lido South Obstruction Daybeacon	21555.2	STRUCT DEST/HAZ NAV	PA
North Siesta Key Daybeacon 1	21570.10000000002	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 18	21577	STRUCT DEST/HAZ NAV	PA
Country Club Shores Daybeacon 4	21665	DAYMK DMGD	PA
Point Pinellas Daybeacon 3	24745	STRUCT DEST/HAZ NAV	PA
as Mareas Light 4	31835	LT EXT	PA
as Mareas Articulated Light 5	31840	LT EXT	PA
as Mareas Light 6	31845	LT EXT	PA
as Mareas Pier Light (3)	31850	LT EXT	PA
Boat Works Channel Daybeacon 3	40140	DAYMK MISSING	PA
Boat Works Channel Daybeacon 4	40145	DAYMK MISSING	PA
Boat Works Channel Daybeacon 7	40160	DAYMK DMGD	PA
3oat Works Channel Daybeacon 9	40170	STRUCT DEST	PA
Matthews Marina Daybeacon 2	40255	STRUCT DEST	PA
ndian Cove Marina Daybeacon 3	42140	DAYMK DMGD	PA
ndian Cove Marina Daybeacon 5	42150	DAYMK DMGD	PA
ndian Cove Marina Daybeacon 7	42160	DAYMK DMGD	PA
Jays Harbor Lights Marina Daybeacon 1	42205	HAZ NAV/DAYMK MISSING	PA
lays Harbor Lights Marina Daybeacon 2	42210	HAZ NAV/DAYMK DMGD/STRUCT DMGD	PA
Jays Harbor Lights Marina Daybeacon 3	42215	DAYMK MISSING	PA

jay hots Dapheners'ADDADD ADDADD ADDADD ADDData Martin Daylacon 1ADDADD ADDADDADDData Martin Daylacon 2ADDADDSTRLCT DETADDData Martin Daylacon 2ADDSTRLCT DETADDData Martin Daylacon 3ADDSTRLCT DETADDData Martin Daylacon 3ADDSTRLCT DETADDData Martin Daylacon 4ADDSTRLCT DETADDData Martin Daylacon 3ADDADDADDADDData Martin Daylacon 4ADDADDADDADDData Martin Daylacon 4ADDADDADDADDData Martin Daylacon 5ADDADDADDADDData Martin Daylacon 4ADDADDADDADDData Martin Daylacon 4ADDADDADDADDData Martin Daylacon 4ADDADDADDADDData Martin Dawlacon 4ADDADDADDADDData	·	-		
sis de Mars Suystenni 444935170000 10000000000000000000000000000000	Jays Harbor Lights Marina Daybeacon 4	42220	HAZ NAV/DAYMK MISSING/STRUCT DMGD	PA
National Subjector IMethoSUCC DEFIMethoSati Marka Subjector IMethoMethodMethodMethodSati Marka Subjector IMethodMethodMethodMethodSati Marka Subjector IMethodM	Sea Isle Marina Daybeacon 1	48400	STRUCT DEST	PA
Sol is Marka Dypapori-4441STRUC DERYMeSol is Marka Dypapori-4443STRUC DERYMeSol is Marka Dypapori-4443STRUC DERYMeDering Chard Dypapori-4613STRUC DERYMeDering Chard Dypapori-4613MeX MUNIAM MUNIAMeDering Chard Dypapori-4603MeX DUP/MUNIAM MUNIAMeDering Chard Dypapori-4603MeX DUP/MUNIAMeDering Chard Dypapori-4604MeX DUP/MUNIAMeDering Chard Dypapori-4604MeMeDering Chard Dypapori-46	Sea Isle Marina Daybeacon 2	48405	STRUCT DEST	PA
Solit Murr Dyyson 1MediaSTUC 1971MediaSolit Murr Dyyson 7M93STUC 1971MediaSolit Murr Dyyson 7M93STUC 1971MediaSolit Murr Dyyson 7M93STUC 1971MediaDering Charm Dybson 7M93MediaMediaDering Charm Dybson 7MediaMediaMediaDering Charm Dybson 7MediaMediaMediaLing Anc Charm Mury 7MediaMediaMediaLing	Sea Isle Marina Daybeacon 3	48410	STRUCT DEST	PA
Solit Murr Dyyson 1MediaSTUC 1971MediaSolit Murr Dyyson 7M93STUC 1971MediaSolit Murr Dyyson 7M93STUC 1971MediaSolit Murr Dyyson 7M93STUC 1971MediaDering Charm Dybson 7M93MediaMediaDering Charm Dybson 7MediaMediaMediaDering Charm Dybson 7MediaMediaMediaLing Anc Charm Mury 7MediaMediaMediaLing	Sea Isle Marina Daybeacon 4	48415	STRUCT DEST	PA
sick idention 3.pybeam 6444351000 CDGT41000Denking Charlon 2.pybeam 64813472 AVX/MARM MISBING481Denking Charlon 2.pybeam 64853472 AVX/MARM MISBING481Denking Charlon 2.pybeam 64853472 AVX/MARM MISBING481Denking Charlon 2.pybeam 64853472 AVX/MARM MISBING481Denking Scheren Deplacen 4489351000 CDGT/1212/WARL481Denking Scheren Deplacen 4489351000 CDGT/1212/WARL481Denking Scheren Deplacen 4489351000 CDGT/1212/WARL481Denking Scheren Deplacen 448936151 CDGT/1212/WARL481Denking Scheren Deplacen 448936151 CDGT/1212/WARL481Denking Scheren Deplacen 448934931481Denking Scheren Deplacen 44893493149314931Denking Scheren Deplacen 44930493149314931Denking Scheren Deplacen 449304931493149314931Deplace Devlacen Berger 4493649314931493149314931Deplace Devlacen 349304931 <t< td=""><td></td><td></td><td></td><td></td></t<>				
set is Name appeasen?4480510C 10G741Dering Channel Depinson? 54650422 NAVXAPANE NASSAG40Dering Channel Depinson? 54650422 NAVXAPANE NASSAG40Conders Park Varias Channel Light 14860510C 10G7 NAZ NAVTRUE40Lindt Channel Depinson? 54850510C 10G7 NAZ NAVTRUE40Conders Park Varias Channel Light 14850510C 10G7 NAZ NAVTRUE40Conders Park Varias Channel Light 24850615 SUL 2005 NAV NAVTRUE40Conders Park Varias Channel Light 24850615 SUL 2005 NAV NAVTRUE40Conders Park Varias Channel Light 24850615 SUL 2005 NAVTRUE40Conders Park Varias Channel Light 250004550G61Conders Park Varias Channel Light 25000500061Conders Park Varias Channel Light 25000500060Conders Park Varias Channel Lig	-			
pering forme 'bybosen's 16895472 NVDVMN MISBINGMDering forme 'bybosen's 16895472 NVDVMN MISBINGMDering forme 'bybosen's 16895472 NVDVMN MISBINGMDering forme 'bybosen's 168951812C DST/M2 NVDRMDiard Fork Mister's Depisent 469851812C DST/M2 NVDRMDiard Fork Mister's Depisent 469851812C DST/M2 NVDRMDiard Fork Mister's Depisent 4698508511812C DST/M2 NVDRMDiard Park Mister's Depisent 469850851MMDiard Park Mister's Depisent 469850851MMDiard Park Mister's Depisent 469850851MMMDiard Park Charler Diard 209960851MMM<	-			
Dening Gauna Dipolescon 5MADDening Gauna Dipolescon 56850MAT MAD/AMMA MUSSINGMADCandar Jork Varna Charall Lipit 146864TILAC DIST/NAZ NAU/TELMMADDening Gauna Dipolescon 46805TILAC DIST/NAZ NAU/TELMMADDening Gauna Dipolescon 46805TILAC DIST/NAZ NAU/TELMMADDening Gauna Dipolescon 46805TILAT DIST/NAZ NAU/TELMMADTakey Rath Channel Roly 76905MISSINGMADTakey Rath Channel Roly 76905MISSINGMISSINGMADTakey Rath Channel Roly 76905MISSINGMISSINGMISSINGTakey Rath Channel Roly 76905MISSINGMISSINGMISSINGLipk y Hank Daphasen 164156116MISSINGMISSINGLipk y Hank Daphasen 16416GITLAC DIST/NAZ NAU/MISSINGMISSINGLipk y Channel Daphasen 161166116MISSINGMISSINGBayne Channel Daphasen 761166116MISSINGMISSINGBayne Channel Daphasen 761166116MISSINGMISSINGBayne Channel Daphasen 761166116MISSINGMISSINGBayne Channel Daphasen 761166116MISSINGMISSINGBayne Channel Daphasen 7 <td>-</td> <td></td> <td>STRUCT DEST</td> <td></td>	-		STRUCT DEST	
Dering Charle bybeson 6MediaMediaMediaMediaStruct Distrike Name Upin 18951STUCT Distrike Name Upin 1RelStruct Distrike Name Upin 18951STUCT Distrike Name Upin 1RelStruct Distrike Name Upin 18951STUCT Distrike Name Upin 1RelCharge Fact Annuel Bay 18951MisSing Garan 1RelLinky Fact Charan Bay 18951MisSing Garan 1RelBay 1Sing Garan 1Sing Garan 1RelRelBay	5 5	48615	HAZ NAV/DAYMK MISSING	PA
Canada Akaina Charmil. 1991 148486STRUCT DEST/NAZ NAVITALIOMDening Bay Charmid Dagbeston 149585STRUCT DEST NAZ NAVIMDening Bay Charmid Dagbeston 149585STRUCT DEST/NAZ NAVIMDening Bay Charmid Dagbeston 149596MESNAGMALinkey Nint Charmid Linky 1694960F STAMLinkey Nint Charmid Linky 210000MESNAGMALinkey Nint Charmid Linky 240007MESNAGMALinkey Nint Charmid Linky 240007MESNAGMALinkey Nint Charmid Linky 240007MESNAGMALinkey Nint Dagbeston 139595STRUCT DEST/NAZ NAVMABaylee Charmid Digheston 139595STRUCT DEST/NAZ NAVMABaylee Charmid Digheston 137395STRUCT DESTMABaylee Charmid Digheston 137395STRUCT DESTMABaylee Charmid Digheston 137416DAMAK MISSINGMABaylee Charmid Digheston 137418DAMAK MISSINGMABaylee Charmid Digheston 137418DAMAK MISSINGMABaylee Charmid Digheston 147418DAMAK MISSINGMABaylee Charmid Digheston 136419STRUCT DESTMABaylee Charmid Digheston 146410MAMABaylee Charmid Digheston 146410MA<	Deering Channel Daybeacon 5	48630	HAZ NAV/DAYMK MISSING	PA
sharth Clanver bybeson fPMDerrik py Charton Dybeson fPMS1TRUCT DST/NAVPMConver, Mult Lyht 2PMS1UT DTPMCharty Abla Charnel Boy 3PMS1UT DTPMLinkey Nat. Charnel Boy 3PMS1PMS1PMS1Linkey Nat. Charnel Boy 3PMS1PMS1PMS1Linkey Nat. Charnel Boy 3S009PMS1PMS1Linkey Nat. Charnel Boy 3S1000PMS1PMS1Digites Charnel Dybbeson 3S1000S1000PMS1Bigete Charnel Dybbeson 4S1345S1000PMS1Bigete Charnel Dybbeson 5S1000S1000PMS1Bigete Charnel Dybbeson 6S1340S1000PMS1Bigete Charnel Dybbeson 7S1000S1000PMS1Bigete Charnel Dybbeson 7S1000S1000PMS1Bigete Charnel Dybeson 7S1000S1000PMS1Bigete Charnel Dybeson 7S1000S1000PM<1	Deering Channel Daybeacon 6	48635	HAZ NAV/DAYMK MISSING	PA
beeny pick hand topkeon4496%Stract (1857)A2 NAVATokey Nati Channel Buoy 34980157749104910Tokey Nati Channel Buoy 3492807530757810Tokey Nati Channel Buoy 3600007530810810Tokey Nati Channel Buoy 35000MISING810Tokey Nati Channel Buoy 3500051000810Tokey Nati Channel Buoy 35100051000810Bapiero Channel Depkeon 1530051000810Bapiero Channel Depkeon 1530051000810Bapiero Channel Depkeon 1541851000810Bapiero Channel Depkeon 15100051000810Bapiero Channel Depkeon 15100051000810Bapie	Crandon Park Marina Channel Light 14	48845	STRUCT DEST/HAZ NAV/TRLB	PA
pennja plannel Dajekaon I9589700 TB71/N2 NWMTodoy Plannel Dajekaon I96001057MTodoy Planc Labaro I laoy 39600MSINGMTodoy Planc Labaro I laoy 396000451AMTodoy Planc Labaro I laoy 39600MSINGMTuloy Nucl Channel Isoy 39000MSINGMTuloy Nucl Channel Boy 329000MSINGMTuloy Nucl Channel Boy 329000MSINGMBoyies Channel Dopkens 190009000MSINGMBoyies Channel Dopkens 1900090009000MBoyies Channel Dopkens 1900090009000MBoyies Channel Dopkens 19000900090009000Boyies Channel Dopkens 19000 <td< td=""><td>Island E Channel Daybeacon 2</td><td>49055.1</td><td>STRUCT DEST</td><td>PA</td></td<>	Island E Channel Daybeacon 2	49055.1	STRUCT DEST	PA
Convergencia4900Irbit14714Turkey Piert Channel Bays69MSSB4064Turkey Piert Channel Bays646464Turkey Piert Channel Bays50MSSB4064Turkey Piert Channel Bays5000MSSB4670Turkey Piert Channel Bays5000MSSB4670Paradier Wahr5000MSSB4670Paradier Wahr5000MSSB4670Paradier Wahr5000MSSB4670Paradier Wahr5000MSSB4670Paradier Wahr5000MSSB4670Paradier Wahr5000MSSB4670Paradier Wahr57400MUCH DET70Paradier Wahr57400MUCH MUCH DET70Paradier Wahr57400MUCH MUCH DET70Paradier Wahr574	-	49585	STRUCT DEST/HAZ NAV	PA
Totaky Point Channel Bioy 39990MISNN0ATurky Point Channel Bioy 3699500°F 51ANATurky Point Channel Bioy 35000MISNN0NATurky Point Channel Bioy 35000MISNN0NABioyeen Channel Diplexen 15000STRUCT DISTNABioyeen Channel Diplexen 35100STRUCT DISTNABioyeen Channel Diplexen 65105STRUCT DISTNABioyeen Channel Diplexen 75100DAMK MISSNGNABioyeen Channel Diplexen 75110DAMK MISSNGNABioyeen Channel Diplexen 15141DAMK MISSNGNABioyeen Channel Diplexen 75160MISSNGNABioyeen Channel Diplexen 75160MISSNGNABioyee				
Tutkp Nit Channel Juty 669856955 (A)8Tutkp Nit Channel Juty 75080MISDIG80Tutkp Nit Channel Juty 2.35070MISDIG80Pandle Wart Channel Juty 2.35070MISDIG80Juty 2.4Statt Channel Juty 2.48080Juty 2.45780STULCT DIST80Baylew Channel Juty 2.45781STULCT DIST80Baylew Channel Juty 2.45741DAVMK MISDIG80Baylew Ch				
Tuky Port Channel Buy 769900F STA9ATuky Port Channel Buy 215006MSSNGMATuky Port Channel Buy 235007MSSNGMATuky Port Channel Buy 2450075MSSNGPADarlate Mort Channel Buy 235075MAZANATAMK MSSNGPATuky Port Channel Buy 245075MAZANATAMK MSSNGPADarlate bort Channel Buyescon 135485STRUCT DEST/MAZANATAPABayles Channel Dybescon 135786STRUCT DEST/MAZANATAPABayles Channel Dybescon 45786STRUCT DESTPABayles Channel Dybescon 65786STRUCT DESTPABayles Channel Dybescon 65786STRUCT DESTPABayles Channel Dybescon 1057416DMMK MSSNGPABayles Damel Dybescon 1057416DMMK MSSNGPABayles Dybescon 1057418DMMK MSSNGPABayles Dybescon 1257418DMMK MSSNGPABayles Dybescon 25910DMMK MSSNGPABackarn Anic Channel Bybescon 25910DMMK MSSNGPABackarn Anic Channel Bybescon 25920MSSNGPASaranta Si Squad Re Buy 9S930MSSNGPASaranta Si Squad Re Buy 9S930MSSNGPA <td></td> <td></td> <td></td> <td></td>				
Turky Pint Channel Bury 21S000MSSNGMATurky Pint Channel Bury 23S007MSSNGMSSNGMAPanalur Kulf Club Daybacon 12S0275MSSNGMSMAUndre Harry Mint Channel Daybacon 13S1385STUCT DEST YIAZ XAVMABayloc Channel Daybacon 3S7380DVMC MOD ODMABayloc Channel Daybacon 4S7380STUCT DEST YIAZ XAVMABayloc Channel Daybacon 4S7380STUCT DEST YIAZ XAVMABayloc Channel Daybacon 4S7380STUCT DESTMABayloc Channel Daybacon 4S7380STUCT DESTMABayloc Channel Daybacon 5S1415STUCT DESTMABayloc Channel Daybacon 9S1415STUCT DESTMABayloc Channel Daybacon 1S1418DAYAK MISSNGMABayloc Channel Daybacon 1S1418DAYAK MISSNGMABiyloc Channel Daybacon 1S1418DAYAK MISSNGMABiyloc Channel Daybacon 1S1418DAYAK MISSNGMABiyloc Darnel Daybacon 1S1418M	-			
Turkey Point Channel Buy 249000MSSINGMATurkey Point Channel Buy 2450075MSSINGMATurkey Point Channel Buy 2450075MSSINGMAJurke March Buy 2450075MSSINGMAUnice Henry Y. Marina Dybescon 135885STRUCT DEST/IAE AWAMABayleon Channel Dybescon 1357805STRUCT DESTPABayleon Channel Dybescon 457805STRUCT DESTPABayleon Channel Dybescon 657805STRUCT DESTPABayleon Channel Dybescon 757815STRUCT DESTPABayleon Channel Dybescon 857405STRUCT DESTPABayleon Channel Dybescon 1057415STRUCT DESTPABayleon Channel Dybescon 1057418DVMK MSSINGPABayleon Damel Dybescon 1057418DVMK MSSINGPABayleon Damel Dybescon 105118DVMK MSSINGPABayleon Damel Dybescon 12STRUCT DESTPABayleon Damel Dybescon 13STRUCT DESTPABayleon Damel Dybescon 14STRUCT DESTPABayleon Damel Dybescon 15STRUCT DESTPABayleon Damel Dybescon 16STRUCT DESTPABayleon Damel Dybescon 17STRUCT DESTPAStruct Stat Stat Stat Stat Stat Stat Stat St	Turkey Point Channel Buoy 7	49990	OFF STA	PA
Trates Path Channel Bacy ASMONMASSNGPAPandase back Club Daybascon 12S2855MAZ NAV/DMNK MISSNGMAUnder harty Markan Sphascon 13S6380STRUCT DEST/MAZ NAVMAEnglewand Channel Daybascon 3S7380STRUCT DESTMABaybasc Channel Daybascon 4S7380STRUCT DESTMABaybasc Channel Daybascon 4S7380STRUCT DESTMABaybasc Channel Daybascon 4S7380STRUCT DESTMABaybasc Channel Daybascon 4S7480STRUCT DESTMABaybasc Channel Daybascon 4S7481STRUCT DESTMABaybasc Darnel Daybascon 1S74181DAYAMK MISSNGMABaybasc Darnel Daybascon 1S74181DAYAMK MISSNGMABaybasc Darnel Daybascon 1S1418DAYAMK MISSNGMABaybasc Darnel Daybascon 1S1418DAYAMK MISSNGMABaybasc Darnel Daybascon 2S1418.DAYAMK MISSNGMABaybasc Darnel Daybascon 1S1418DAYAMK MISSNGMABaybasc Darnel Daybascon 2S1418.DAYAMK MISSNGMABaybasc Darnel Daybascon 2S1418.DAYAMK MISSNGMABaybasc Darnel Daybascon 2S1418.DAYAMK MISSNGMABaybasc Darnel Daybascon 2S1418.DAYAMK MISSNGMABaybasc Darnel Daybascon 3S1418.DAYAMK MISSNGMASarasca Si Supad Ke Busy AS1500MISSNGMASarasca Si Supad Ke Busy AS650MISSNGMASarasca Si Supad Ke Busy F<	Turkey Point Channel Buoy 21	50060	MISSING	PA
predict Sub1 Sub1 Subplexen 12SPSVA NWYGMK ISSINGPAUnde Henry Manna Dybexen 13SFBSSTRUCT DEST NAWPABigwice Vinamel Dybexen 3STBSDSTRUCT DEST NAWPABigwice Vinamel Dybexen 4STBSDSTRUCT DESTPABigwice Vinamel Dybexen 6STBSDSTRUCT DESTPABigwice Vinamel Dybexen 6STBSDSTRUCT DESTPABigwice Vinamel Dybexen 6STBSDSTRUCT DESTPABigwice Vinamel Dybexen 7STBSDSTRUCT DESTPABigwice Vinamel Dybexen 10STBSDSTRUCT DESTPABigwice Diamel Dybexen 11STB1DAYMK MISSINGPABigwice Diamel Dybexen 11STB1DAYMK MISSINGPABigwice Diamel Dybexen 12STB1DAYMK MISSINGPABigwice Diamel Dybexen 13STB1DAYMK MISSINGPABigwice Diamel Dybexen 14STB1DAYMK MISSINGPABigwice Diamel Dybexen 15STB1DAYMK MISSINGPABigwice Diamel Dybexen 14STB1DAYMK MISSINGPABigwice Diamel Dybexen 14STB1DAYMK MISSINGPABigwice Diamel Dybexen 15STB1DAYMK MISSINGPABigwice Diamel Dybexen 14STB1DAYMK MISSINGPABigwice Diamel Dybexen 15STB1DAYMK MISSINGPABigwice Diamel Dybexen 15STB1DAYMK MISSINGPABigwice Diamel Dybexen 15STB1DAYMK MISSINGPASareart Si Siguad 15 Huoy 14SB2SB35M	Turkey Point Channel Buoy 23	50070	MISSING	PA
predict Sub1 Sub1 Subplexen 12SPSVA NWYGMK ISSINGPAUnde Henry Manna Dybexen 13SFBSSTRUCT DEST NAWPABigwice Vinamel Dybexen 3STBSDSTRUCT DEST NAWPABigwice Vinamel Dybexen 4STBSDSTRUCT DESTPABigwice Vinamel Dybexen 6STBSDSTRUCT DESTPABigwice Vinamel Dybexen 6STBSDSTRUCT DESTPABigwice Vinamel Dybexen 6STBSDSTRUCT DESTPABigwice Vinamel Dybexen 7STBSDSTRUCT DESTPABigwice Vinamel Dybexen 10STBSDSTRUCT DESTPABigwice Diamel Dybexen 11STB1DAYMK MISSINGPABigwice Diamel Dybexen 11STB1DAYMK MISSINGPABigwice Diamel Dybexen 12STB1DAYMK MISSINGPABigwice Diamel Dybexen 13STB1DAYMK MISSINGPABigwice Diamel Dybexen 14STB1DAYMK MISSINGPABigwice Diamel Dybexen 15STB1DAYMK MISSINGPABigwice Diamel Dybexen 14STB1DAYMK MISSINGPABigwice Diamel Dybexen 14STB1DAYMK MISSINGPABigwice Diamel Dybexen 15STB1DAYMK MISSINGPABigwice Diamel Dybexen 14STB1DAYMK MISSINGPABigwice Diamel Dybexen 15STB1DAYMK MISSINGPABigwice Diamel Dybexen 15STB1DAYMK MISSINGPABigwice Diamel Dybexen 15STB1DAYMK MISSINGPASareart Si Siguad 15 Huoy 14SB2SB35M	Turkey Point Channel Buoy 24	50075	MISSING	PA
under hypothesion 139858STRUCT DEXTAVE NAVPAEngleword Channel Daybescon 857380STRUCT DEXTPABayword Channel Daybescon 457380STRUCT DESTPABayword Channel Daybescon 657380STRUCT DESTPABayword Channel Daybescon 757400STRUCT DESTPABayword Channel Daybescon 757410DAMMK MSSINGPABayword Channel Daybescon 757410DAMMK MSSINGPABayword Channel Daybescon 757418DAMMK MSSINGPABayword Channel Daybescon 757418DAMMK MSSINGPABayword Channel Daybescon 757418DAMMK MSSINGPABaykord Channel Daybescon 757418DAMMK MSSINGPABaykord Starib Starib Starib5550DAMMK MSSINGPABackburn Paint Channel Daybescon 25550MSSINGPABackburn Paint Channel Daybescon 25550MSSINGPASanzota Sial Saudi R. Buoy 85550MSSINGPASanzota Sial Saudi R. Buoy 95650MSSINGPASanzota Sial Saudi R. Buoy 15600MSSINGPASanzota Sial Saudi R. Buoy 15600MSSINGPA <tr< td=""><td></td><td></td><td></td><td></td></tr<>				
snglenood Channel Daybescon 897359.5STRUCT DESTPABaylew Channel Daybescon 457380DAYMK (DMCQ)PABaylew Channel Daybescon 657385STRUCT DESTPABaylew Channel Daybescon 657395STRUCT DESTPABaylew Channel Daybescon 757406STRUCT DESTPABaylew Channel Daybescon 1057410DAYMK MISINGPABaylew Channel Daybescon 1057413DAYMK MISINGPABaylew Channel Daybescon 1057418DAYMK MISINGPABaylew Channel Daybescon 151418DAYMK MISINGPABaylew Channel Daybescon 251418DAYMK MISINGPABaylew Channel Daybescon 251010DAYMK MISINGPABackdum Port Channel Daybescon 25102DAYMK MISINGPABackdum Port Channel Daybescon 25555MISINGPASanzota Sil Squad R Enury 65555MISINGPASanzota Sil Squad R Enury 15650MISINGPASanzota Sil Squad R Enury 15650MISINGPASanzota Sil Squad R Enury 15660MISINGPASanzota Sil	-			
Bayver (channel Daybascon 3STAUCSTAUCDeV/DPABayvier (channel Daybascon 4S7285STAUCT DESTPABayvier (channel Daybascon 8S7405STAUCT DESTPABayvier (channel Daybascon 9S7410OAVMK MISSINGPABayvier (channel Daybascon 10S7415STRUCT DESTPABay Heights Daybascon 10S7418OAVMK MISSINGPABay Heights Daybascon 1S7418OAVMK MISSINGPABay Heights Daybascon 1S7418OAVMK MISSINGPABackbarne Point Channel Daybascon 1S7418OAVMK MISSINGPABackbarne Point Channel Daybascon 2S101DAVMK MISSINGPABackbarne Point Channel Daybascon 2S101DAVMK MISSINGPASarasota Si Sapad R: Buoy AS6850MISSINGPASarasota Si Sapad R: Buoy AS6850MISSINGPASarasota Si Sapad R: Buoy PS6850MISSINGPASarasota Si Sapad R: Buoy FS6800MISSINGPASarasota Si Sapad R: Buoy FS6800MISSIN				
by/vec/chamel Daybeacen 457385STRUCT DESTPABayvec/chamel Daybeacen 657395STRUCT DESTPABayvec/chamel Daybeacen 957410DAVMK MISSINGPABayvec/chamel Daybeacen 1057415STRUCT DESTPABayvec/chamel Daybeacen 1057418DAVMK MISSINGPABayvec/chamel Daybeacen 157418DAVMK MISSINGPABay Height Daybeacen 257418.1DAVMK MISSINGPABay Height Daybeacen 25810DAVMK MISSINGPABackbarn Point Chamel Daybeacen 258102DAVMK MISSINGPABackbarn Point Chamel Daybeacen 25810DAVMK MISSINGPASarastot Sil Squad R Buoy CS880MISSINGPASarastot Sil Squad R Buoy CS880MISSINGPASarastot Sil Squad R Buoy FS860MISSINGPASarastot Sil Squad R Buoy IS861MISSINGPASarastot Sil Squad R Buoy IS862MISSINGPASarastot Sil Squad R Buoy IS865MISSINGPASarastot Sil Squad R Buoy IS865MISSINGPASarastot Sil Squad R Buoy IS866MISSINGPASarastot Sil Squad R Buoy IS866MISSINGPASarastot Sil Squad				
Baylew Channel Dapbeacon 6S7896STRUCT DESTPABaylew Channel Dapbeacon 8S7405STRUCT DESTPABaylew Channel Dapbeacon 10S7410DAYMK MISSINGPABy Heights Dapbeacon 11S7410DAYMK MISSINGPABy Heights Dapbeacon 2S7418DAYMK MISSINGPABickburn Point Channel Daybeacon 2S8101DAYMK MISSINGPABickburn Point Channel Daybeacon 2S8102DAYMK MISSINGPASaraots Sail Squad R Buoy AS880MISSINGPASaraots Sail Squad R Buoy CS880MISSINGPASaraots Sail Squad R Buoy FS880MISSINGPASaraots Sail Squad R Buoy CS880MISSINGPASaraots Sail Squad R Buoy FS860MISSINGPASaraots Sail Squad R Buoy F			DAYMK DMGD	
Baylew Channel Daybeacon 85405STRUCT DESTPABaylew Channel Daybeacon 95710DAYMA MISINGPABaylew Channel Daybeacon 1057416DAYMA MISINGPABay Heights Daybeacon 157418DAYMAK MISSINGPABay Heights Daybeacon 157418DAYMAK MISSINGPABakchurn Point Channel Daybeacon 15610DAYMAK MISSINGPABlackburn Point Channel Daybeacon 258102DAYMAK MISSINGPASaraota Si Sayada Re Buay A5850MISSINGPASaraota Si Sayada Re Buay B5855MISSINGPASaraota Si Sayada Re Buay P5860MISSINGPASaraota Si Sayada Re Buay F5860MISSINGPASaraota Si Sayada Re Buay F5860MISSINGPASaraota Si Sayada Re Buay F5860MISSINGPASaraota Si Sayada Re Buay I5860MISSINGPASaraota Sai Sayada	Bayview Channel Daybeacon 4	57385	STRUCT DEST	PA
Baylew Channel Daybeacon 95/410DAYMK MISSINGPABaylew Channel Daybeacon 105/415STRUCT DESTPABy Heights Daybeacon 125/418 1DAYMK MISSINGPABy Heights Daybeacon 25/610DAYMK MISSINGPABackburn Poirt Channel Daybeacon 25/610DAYMK MISSINGPASarasota Sil Squad Re Buoy A5/850MISSINGPASarasota Sil Squad Re Buoy A5/850MISSINGPASarasota Sil Squad Re Buoy C5/850MISSINGPASarasota Sil Squad Re Buoy F5/860MISSINGPASarasota Sil Squad Re Buoy I5/861MISSINGPASarasota Sil Squad Re Buoy I5/861MISSINGPASarasot	Bayview Channel Daybeacon 6	57395	STRUCT DEST	PA
Baykew Channal Daybeacon 1057415STRUCT DESTPABay Heights Daybeacon 157416DAYMK MISSINGPABackburn Point Channel Daybeacon 158101DAYMK MISSINGPABlackburn Point Channel Daybeacon 258102DAYMK MISSINGPAStarsotta Sail Squad Re Buoy A5850MISSINGPASarsotta Sail Squad Re Buoy B5855MISSINGPASarsotta Sail Squad Re Buoy C5859MISSINGPASarsotta Sail Squad Re Buoy P5850MISSINGPASarsotta Sail Squad Re Buoy F5860MISSINGPASarsotta Sail Squad Re Buoy F5860MISSINGPASarsotta Sail Squad Re Buoy F5860MISSINGPASarsotta Sail Squad Re Buoy I5860MISSINGPASarsotta Sail Squad Re Buoy I5860MISSINGPAButomoud Harbor Channel Joubeacon 105860MISSINGPAButomoud Harbor Channel Joubeacon 25915DAVMK MISSINGPACatlana Channel Daybeacon 35945MISCUT DEST-MIZ AUNPACatlana Channel Daybeacon 35960STRUCT D	Bayview Channel Daybeacon 8	57405	STRUCT DEST	PA
Bay Heights Daybeacon 1S7418DAYMK MISSINGPABay Heights Daybeacon 2S7418.1DAYMK MISSINGPABickburn Poirt Channel Daybeacon 2S8101DAYMK MISSINGPABickburn Poirt Channel Daybeacon 2S8102DAYMK MISSINGPASarastot Sal Squad Re Buoy AS850MISSINGPASarastot Sal Squad Re Buoy CS850MISSINGPASarastot Sal Squad Re Buoy CS850MISSINGPASarastot Sal Squad Re Buoy CS850MISSINGPASarastot Sal Squad Re Buoy FS860MISSINGPASarastot Sal Squad Re Buoy FS860MISSINGPASarastot Sal Squad Re Buoy FS860MISSINGPASarastot Sal Squad Re Buoy IS861MISSINGPASarastot Sal Squad Re Buoy IS862MISSINGPASarastot Sal Squad Re Buoy IS862MISSINGPASarastot Sal Squad Re Buoy IS863MISSINGPASarastot Sal Squad Re Buoy IS865MISSINGPASarastot Sal Squad R	Bayview Channel Daybeacon 9	57410	DAYMK MISSING	PA
Bay Heights Daybeacon 1S7418DAYMK MISSINGPABay Heights Daybeacon 2S7418.1DAYMK MISSINGPABickburn Poirt Channel Daybeacon 2S8101DAYMK MISSINGPABickburn Poirt Channel Daybeacon 2S8102DAYMK MISSINGPASarastot Sal Squad Re Buoy AS850MISSINGPASarastot Sal Squad Re Buoy CS850MISSINGPASarastot Sal Squad Re Buoy CS850MISSINGPASarastot Sal Squad Re Buoy CS850MISSINGPASarastot Sal Squad Re Buoy FS860MISSINGPASarastot Sal Squad Re Buoy FS860MISSINGPASarastot Sal Squad Re Buoy FS860MISSINGPASarastot Sal Squad Re Buoy IS861MISSINGPASarastot Sal Squad Re Buoy IS862MISSINGPASarastot Sal Squad Re Buoy IS862MISSINGPASarastot Sal Squad Re Buoy IS863MISSINGPASarastot Sal Squad Re Buoy IS865MISSINGPASarastot Sal Squad R		57415	STRUCT DEST	PA
Bay Heights Daybeacon 25718.1DAYMK MISSINGPAIBlackhum Piot Channel Daybeacon 158101DAYMK MISSINGPAISarasota Sail Squad Rc Buoy A5850MISSINGPAISarasota Sail Squad Rc Buoy B58580MISSINGPAISarasota Sail Squad Rc Buoy C58590MISSINGPAISarasota Sail Squad Rc Buoy C58590MISSINGPAISarasota Sail Squad Rc Buoy C58590MISSINGPAISarasota Sail Squad Rc Buoy F58605MISSINGPAISarasota Sail Squad Rc Buoy F58605MISSINGPAISarasota Sail Squad Rc Buoy F58605MISSINGPAISarasota Sail Squad Rc Buoy I58605MISSINGPAISarasota Sail Squad Rc Buoy I58603MISSINGPAISarasota Sail Squad Rc Buoy I58603MISSINGPAIBay Isbe South Channel Daybeacon 1058663MISSINGPAIBay Isbe South Channel Daybeacon 235945DAYMK MISSINGPAIBattomwood Habor Channel Daybeacon 235945MIXCIT DESTPAICatalina Channel Daybeacon 359625STRUCT DESTPAICatalina Channel Daybeacon 35965STRUCT DESTPAICatalina Channel Daybeacon 36963STRUCT DESTPAISebastain Infel Channel Day				
Blackburn Point Channel Daybeacon 1S8101DAYMK MISSINGPAIBlackburn Point Channel Daybeacon 2S50102MMK MISSINGPAISarasota Sal Squad Rc Buoy AS5850MISSINGPAISarasota Sal Squad Rc Buoy CS5850MISSINGPAISarasota Sal Squad Rc Buoy CS5850MISSINGPAISarasota Sal Squad Rc Buoy CS5850MISSINGPAISarasota Sal Squad Rc Buoy CS6850MISSINGPAISarasota Sal Squad Rc Buoy FS6800MISSINGPAISarasota Sal Squad Rc Buoy FS6801MISSINGPAISarasota Sal Squad Rc Buoy IS6802MISSINGPAISarasota Sal Squad Rc Buoy IS6803MISSINGPAISarasota Sal Squad Rc Buoy IS6803MISSINGPAISarasota Sal Squad Rc Buoy IS6803S1RUCT DEST/HA2 NAVPAILongboat Harbor North Marina Daybeacon BS905DAYMK MISSINGPAIButtomood Harbor Channel Daybeacon 23S945ATAW/DAYMK MISSINGPAICatalian Channel Daybeacon 1S920STRUCT DESTPAICatalian Channel Daybeacon 1S9603STRUCT DESTPAICatalian Channel Daybeacon 1S9604STRUCT DESTPAIBradenton Beach City South Channel Daybeacon 1S9605STRUCT DESTPAI<				
Blackburn Point Channel Daybeacon 2SB102DAYMK MISSINGPASarasota Sali Squad R. Buoy ASB500MISSINGPASarasota Sali Squad R. Buoy BSB500MISSINGPASarasota Sali Squad R. Buoy CSB500MISSINGPASarasota Sali Squad R. Buoy DSB500MISSINGPASarasota Sali Squad R. Buoy DSB600MISSINGPASarasota Sali Squad R. Buoy FSB600MISSINGPASarasota Sali Squad R. Buoy ISB605MISSINGPASarasota Sali Squad R. Buoy ISB605SB605SB606PASarasota Sali Squad R. Buoy ISB605SB606SB606PASarasota Sali Squad R. Buoy ISB605SB607PAPASarasota Sali Squad R. Buoy ISB605SB607SB607PASarasota Sali Squad R. Buoy I <td< td=""><td></td><td></td><td></td><td></td></td<>				
Sarasota Sail Squad Rc Buoy AS880MISSINGPAISarasota Sail Squad Rc Buoy BS8950MISSINGPAISarasota Sail Squad Rc Buoy CS8950MISSINGPAISarasota Sail Squad Rc Buoy DS8950MISSINGPAISarasota Sail Squad Rc Buoy FS8000MISSINGPAISarasota Sail Squad Rc Buoy HS8020MISSINGPAISarasota Sail Squad Rc Buoy IS8020MISSINGPAISarasota Sail Squad Rc Buoy KS8030MISSINGPAISarasota Sail Squad Rc Buoy KS8030MISSINGPAISarasota Sail Squad Rc Buoy KS8030MISSINGPAILongboat Key Moorings Light 1S8030SRUCT DEST/HAZ NAVPAILongboat Key Moorings Light 1S8030SRUCT DEST/HAZ NAVPAILongboat Harbor North Marina Daybeacon 2S9450AIZA NAV/DAYMIK MISSINGPAILongboat Harbor North Marina Daybeacon 1S9620SRUCT DESTPAICatalina Channel Daybeacon 1S9620SRUCT DESTPAICatalina Channel Daybeacon 1S9620SRUCT DESTPAIBradenton Beach City South Channel Daybeacon 1S9620SRUCT DESTPAIBradenton Beach City South Channel Daybeacon 1S9620SRUCT DESTPAIBradenton Beach City South Channel Daybeacon 1	Blackburn Point Channel Daybeacon 1	58101	DAYMK MISSING	PA
Sarasota Sail Squad Rc Buoy BSeasonMissingPASarasota Sail Squad Rc Buoy CS890Missing CPASarasota Sail Squad Rc Buoy DS890Missing CPASarasota Sail Squad Rc Buoy ES8600Missing CPASarasota Sail Squad Rc Buoy FS6605Missing CPASarasota Sail Squad Rc Buoy HS6605Missing CPASarasota Sail Squad Rc Buoy HS6605Missing CPASarasota Sail Squad Rc Buoy HS6605Missing CPASarasota Sail Squad Rc Buoy JS6805Missing CPASarasota Sail Squad Rc Buoy JS6805DAVMK Missing CPASarasota Sail Squad Rc Buoy LS6805DAVMK Missing CPASarasota Sail Squad Rc Buoy LS6805S7RUCT DESTPACatalina Channel Daybeacon 2S9805S7RUCT DESTPACatalina Channel Daybeacon 3S9605STRUCT DESTPASebastan Intel Channel Daybeacon 13G1020HAZ NAV/DAVMK Missing CPA<	Blackburn Point Channel Daybeacon 2	58102	DAYMK MISSING	PA
Sarasta Sail Squad Rc Bury C58590MISSINGPASarasta Sail Squad Rc Bury D58690MISSINGPASarasta Sail Squad Rc Bury E58600MISSINGPASarasta Sail Squad Rc Bury F58605MISSINGPASarasta Sail Squad Rc Bury I58615MISSINGPASarasta Sail Squad Rc Bury I58620MISSINGPASarasta Sail Squad Rc Bury I58620MISSINGPASarasta Sail Squad Rc Bury I58620MISSINGPASarasta Sail Squad Rc Bury I58630MISSINGPASarasta Sail Squad Rc Bury K58630MISSINGPABay Isles South Channel Daybeacon 105865HAZ NAV/DAYMK MISSINGPAButtonwood Harbor Channel Junction Daybeacon 85895DAYMK MISSINGPAButtonwood Harbor Channel Daybeacon 25915DAYMK MISSINGPACatalina Channel Daybeacon 35925STRUCT DEST/HAZ NAVPACatalina Channel Daybeacon 159630STRUCT DESTPACatalina Channel Daybeacon 159630STRUCT DESTPABradenton Beach City South Channel Daybeacon 159630STRUCT DESTPA<	Sarasota Sail Squad Rc Buoy A	58580	MISSING	PA
Sarasota Sail Squad Rc Buoy DS899MISSINGPASarasota Sail Squad Rc Buoy FS600MISSINGPASarasota Sail Squad Rc Buoy FS600MISSINGPASarasota Sail Squad Rc Buoy HS601MISSINGPASarasota Sail Squad Rc Buoy HS602MISSINGPASarasota Sail Squad Rc Buoy IS602MISSINGPASarasota Sail Squad Rc Buoy IS603MISSINGPASarasota Sail Squad Rc Buoy IS603MISSINGPASarasota Sail Squad Rc Buoy IS665HZ NAV/DX/MK MISSINGPACatalian Channel Daybeacon 10S665DA/MK MISSINGPALongboat Key Moorings Light 1S680STRUCT DEST/HAZ NAVPAButtonwood Harbor Channel Daybeacon 2S943DA/MK MISSINGPACatalian Channel Daybeacon 2S945MIXCI DESTPACatalian Channel Daybeacon 3S962STRUCT DESTPACatalian Channel Daybeacon 13S963STRUCT DESTPASarasota Sail Squad Cov Cerek Daybeacon 13S963STRUCT DESTPASebastian Intel Channel Daybeacon 13S963STRUCT DESTPASebastian Intel Channel Daybeacon 13S963STRUCT DESTPASebastian Intel Channel	Sarasota Sail Squad Rc Buoy B	58585	MISSING	PA
Sarasota Sail Squad Rc Buoy DS899MISSINGPASarasota Sail Squad Rc Buoy FS600MISSINGPASarasota Sail Squad Rc Buoy FS600MISSINGPASarasota Sail Squad Rc Buoy HS601MISSINGPASarasota Sail Squad Rc Buoy HS602MISSINGPASarasota Sail Squad Rc Buoy IS602MISSINGPASarasota Sail Squad Rc Buoy IS603MISSINGPASarasota Sail Squad Rc Buoy IS603MISSINGPASarasota Sail Squad Rc Buoy IS665HZ NAV/DX/MK MISSINGPACatalian Channel Daybeacon 10S665DA/MK MISSINGPALongboat Key Moorings Light 1S680STRUCT DEST/HAZ NAVPAButtonwood Harbor Channel Daybeacon 2S943DA/MK MISSINGPACatalian Channel Daybeacon 2S945MIXCI DESTPACatalian Channel Daybeacon 3S962STRUCT DESTPACatalian Channel Daybeacon 13S963STRUCT DESTPASarasota Sail Squad Cov Cerek Daybeacon 13S963STRUCT DESTPASebastian Intel Channel Daybeacon 13S963STRUCT DESTPASebastian Intel Channel Daybeacon 13S963STRUCT DESTPASebastian Intel Channel	Sarasota Sail Squad Rc Buoy C	58590	MISSING	PA
Sarasota Sail Squad Rc Buoy E58600MISSINGPASarasota Sail Squad Rc Buoy F58005MISSINGPASarasota Sail Squad Rc Buoy H58051MISSINGPASarasota Sail Squad Rc Buoy I58051MISSINGPASarasota Sail Squad Rc Buoy I58020MISSINGPASarasota Sail Squad Rc Buoy I58020MISSINGPASarasota Sail Squad Rc Buoy I58030MISSINGPASarasota Sail Squad Rc Buoy I58060SIRUCT DEST/HAZ NAVPABay Isles South Channel Daybeacon 1058060SIRUCT DEST/HAZ NAVPAButtonwood Harbor Channel Junction Daybeacon B59050DAYMK MISSINGPAButtonwood Harbor Channel Daybeacon 25935DAYMK MISSINGPACatalina Channel Daybeacon 359450SIRUCT DESTPACatalina Channel Daybeacon 459620SIRUCT DESTPACatalina Channel Daybeacon 559630SIRUCT DESTPACatalina Channel Daybeacon 1359650SIRUCT DESTPACatalina Channel Daybeacon 1360120HAZ NAV/DAYMK MISSINGPABaynard Cove Creek Daybeacon 1360120HAZ NAV/DAYMK MISSINGPASebastian Intel Channel Daybeacon 179109DAYMK MISSINGPASebastian Intel Channel Daybeacon 179109DAYMK MISSINGPASebastian Intel Channel Daybeacon 179109DAYMK MISSINGPASebastian Intel Channel Daybeacon 179100DAYMK MISSINGPASebastian Intel Channel		58595	MISSING	PA
Sarasota Sail Squad Rc Buoy F56005MISSINGPASarasota Sail Squad Rc Buoy H56010MISSINGPASarasota Sail Squad Rc Buoy I56020MISSINGPASarasota Sail Squad Rc Buoy J56020MISSINGPASarasota Sail Squad Rc Buoy J56020MISSINGPASarasota Sail Squad Rc Buoy J56620MISSINGPABay Isles South Channel Daybeacon 105665HAZ NAV/DAYMK MISSINGPAButtomood Harbor Channel Junction Daybeacon B58030DAYMK MISSINGPAButtomood Harbor Channel Daybeacon 25985DAYMK MISSINGPACatalina Channel Daybeacon 25985DAYMK MISSINGPACatalina Channel Daybeacon 359820STRUCT DEST/HAZ NAVPACatalina Channel Daybeacon 459600STRUCT DESTPACatalina Channel Daybeacon 159600STRUCT DESTPACatalina Channel Daybeacon 159960STRUCT DESTPABardenton Beach City South Channel Daybeacon 359965STRUCT DESTPABardenton Beach City South Channel Daybeacon 161020HAZ NAV/DAYMK MISSINGPABaynard Cove Creek Daybeacon 136102HAZ NAV/DAYMK MISSINGPASebastian Inter Channel Daybeacon 179410DAYIBAPASebastian Inter Channel Daybeacon 259810DOLT DESTPASebastian Inter Channel Daybeacon 259810DAYMK MISSINGPASebastian Inter Channel Daybeacon 259810DAYMK MISSINGPA				
Sarasota Sail Squad Rc Buoy HS6615MISSINGPASarasota Sail Squad Rc Buoy IS6620MISSINGPASarasota Sail Squad Rc Buoy JS6620MISSINGPASarasota Sail Squad Rc Buoy JS6630MISSINGPASarasota Sail Squad Rc Buoy KS6630MISSINGPASarasota Sail Squad Rc Buoy KS6665HAZ NAV/DAYMK MISSINGPABay Isles South Channel Daybeacon 10S6665HAZ NAV/DAYMK MISSINGPAButtonwood Harbor Channel Junction Daybeacon 8S905DAYMK MISSINGPAButtonwood Harbor Channel Junction Daybeacon 23S9045HAZ NAV/DAYMK MISSINGPACatalina Channel Daybeacon 13S9620STRUCT DESTPACatalina Channel Daybeacon 3S9620STRUCT DESTPACatalina Channel Daybeacon 1S9620STRUCT DESTPACatalina Channel Daybeacon 1S9620STRUCT DESTPACatalina Channel Daybeacon 1S9620STRUCT DESTPACatalina Channel Daybeacon 1S9630STRUCT DESTPACatalina Channel Daybeacon 1S9630STRUCT DESTPABradenton Beach City South Channel Daybeacon 1S9950STRUCT DESTPABradenton Beach City South Channel Daybeacon 3S9950STRUCT DESTPASebastian Inlet Channel Daybeacon 13S6120HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 17S810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 17S810DAYMK MISSINGPA </td <td>· · · ·</td> <td></td> <td></td> <td></td>	· · · ·			
Sarasota Sail Squad Rc Buoy I58620MISSINGPASarasota Sail Squad Rc Buoy J58625MISSINGPASarasota Sail Squad Rc Buoy K56630MISSINGPABay Isles South Channel Daybeacon 1058663HZX NAV/DAYMK MISSINGPABay Isles South Channel Daybeacon 1058660STRUCT DEST/HAZ NAVPAButtonwood Harbor Channel Daybeacon 2358945HAZ NAV/DAYMK MISSINGPACatalina Channel Daybeacon 259135DAYMK MISSINGPACatalina Channel Daybeacon 359620STRUCT DESTPACatalina Channel Daybeacon 459620STRUCT DESTPACatalina Channel Daybeacon 559630STRUCT DESTPACatalina Channel Daybeacon 159600STRUCT DESTPACatalina Channel Daybeacon 359625STRUCT DESTPACatalina Channel Daybeacon 459960STRUCT DESTPABradenton Beach City South Channel Daybeacon 159960STRUCT DESTPABradenton Beach City South Channel Daybeacon 359965STRUCT DESTPABradenton Beach City South Channel Daybeacon 359965STRUCT DESTPASebastian Inlet Channel Daybeacon 109775HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 175810DAYMK M				
Sarasota Sail Squad Rc Buoy ISee25MISSINGPASarasota Sail Squad Rc Buoy KSe630MISSINGPABay Isles South Channel Daybeacon 10Se665HAZ NAV/DAYMK MISSINGPALongboat Key Moorings Light 1Se680STRUCT DEST/HAZ NAVPAButtonwood Harbor Channel Daybeacon 2Se895DAYMK MISSINGPACatalina Channel Daybeacon 2.3S9895HAZ NAV/DAYMK MISSINGPACatalina Channel Daybeacon 2.3S9620STRUCT DESTPACatalina Channel Daybeacon 3S9620STRUCT DESTPACatalina Channel Daybeacon 5S9630STRUCT DESTPABradenton Beach City South Channel Daybeacon 1S9630STRUCT DESTPABradenton Beach City South Channel Daybeacon 3S9965STRUCT DESTPABradenton Beach City South Channel Daybeacon 10S0120HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 10S975HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 17S9605DAYMK MISSINGPASebastian Inlet Channel Daybeacon 17S9605DAYMK MISSINGPASebastian Inlet Channel Daybeacon 17S9605DAYMK MISSINGPA </td <td>Sarasota Sail Squad Rc Buoy H</td> <td></td> <td></td> <td></td>	Sarasota Sail Squad Rc Buoy H			
Sarasota Sail Squad Rc Buy K58630MISSINGPABay Isles South Channel Daybeacon 1058665HAZ NAV/DAYMK MISSINGPALongboat Key Moorings Light 158680STRUCT DEST/HAZ NAVPAButtonwood Harbor Channel Junction Daybeacon B58905DAYMK MISSINGPAButtonwood Harbor Channel Daybeacon 2358945HAZ NAV/DAYMK MISSINGPALongboat Harbor North Marina Daybeacon 259135DAYMK MISSINGPACatalina Channel Daybeacon 359620STRUCT DESTPACatalina Channel Daybeacon 559630STRUCT DESTPACatalina Channel Daybeacon 559630STRUCT DESTPABradenton Beach City South Channel Daybeacon 159960STRUCT DESTPABradenton Beach City South Channel Daybeacon 359965STRUCT DESTPABradenton Beach City South Channel Daybeacon 360120HAZ NAV/DAYMK MISSINGPABeynard Cove Creek Daybeacon 1360120HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 129810.9DED DESTPASebastian Inlet Channel Daybeacon 259810.9DED DESTPASebastian Inlet Channel Daybeacon 179810.9DAYMK MISSINGPASebastian Inlet Channel Daybeacon 1216050DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DED DESTPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPA<	Sarasota Sail Squad Rc Buoy I	58620	MISSING	PA
Bay Isles South Channel Daybeacon 1058665HAZ NAV/DAYMK MISSINGPALongboat Key Moorings Light 158680STRUCT DEST/HAZ NAVPAButtonwood Harbor Channel Junction Daybeacon 858905DAYMK MISSINGPAButtonwood Harbor Channel Daybeacon 2358945HAZ NAV/DAYMK MISSINGPALongboat Harbor North Marina Daybeacon 259152DAYMK MISSINGPACatalina Channel Daybeacon 159620STRUCT DESTPACatalina Channel Daybeacon 559620STRUCT DESTPACatalina Channel Daybeacon 559630STRUCT DESTPABradenton Beach City South Channel Daybeacon 159660STRUCT DESTPABradenton Beach City South Channel Daybeacon 359965STRUCT DESTPABradenton Beach City South Channel Daybeacon 360120HAZ NAV/DAYMK MISSINGPABradenton Beach City South Channel Daybeacon 1360120HAZ NAV/DAYMK MISSINGPABaynard Cove Creek Daybeacon 24355STRUCT DESTPASebastian Inlet Channel Daybeacon 109775HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810.9DAYMK MISSINGPASebastian Inlet Channel Daybeacon 29810.9DAYMK MISSINGPASebastian Inlet Channel Daybeacon 110605DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810.9DAYMK MISSINGPASebastian Inlet Channel Daybeacon 1310605DAYMK MISSINGPASebastian Inlet Channel Daybeacon 1410605 <td< td=""><td>Sarasota Sail Squad Rc Buoy J</td><td>58625</td><td>MISSING</td><td>PA</td></td<>	Sarasota Sail Squad Rc Buoy J	58625	MISSING	PA
Longboat Key Moorings Light 158680STRUCT DEST/HAZ NAVPAButtonwood Harbor Channel Junction Daybeacon B58905DAYMK MISSINGPAButtonwood Harbor Channel Daybeacon 2358945HAZ NAV/DAYMK MISSINGPALongboat Harbor North Marina Daybeacon 259135DAYMK MISSINGPACatalina Channel Daybeacon 159620STRUCT DESTPACatalina Channel Daybeacon 359625STRUCT DESTPACatalina Channel Daybeacon 559630STRUCT DESTPABradenton Beach City South Channel Daybeacon 159960STRUCT DESTPABradenton Beach City South Channel Daybeacon 359965STRUCT DESTPABradenton Beach City South Channel Daybeacon 359965STRUCT DESTPABradenton Beach City South Channel Daybeacon 36120HAZ NAV/DAYMK MISSINGPABaynard Cove Creek Daybeacon 109775HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DBD DESTPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA	Sarasota Sail Squad Rc Buoy K	58630	MISSING	PA
Buttonwood Harbor Channel Junction Daybeacon B58905DAYMK MISSINGPAButtonwood Harbor Channel Daybeacon 2358945HAZ NAV/DAYMK MISSINGPALongboat Harbor North Marina Daybeacon 259135DAYMK MISSINGPACatalina Channel Daybeacon 159620STRUCT DESTPACatalina Channel Daybeacon 359625STRUCT DESTPACatalina Channel Daybeacon 559630STRUCT DESTPABradenton Beach City South Channel Daybeacon 159960STRUCT DESTPABradenton Beach City South Channel Daybeacon 359965STRUCT DESTPABradenton Beach City South Channel Daybeacon 360120HAZ NAV/DAYMK MISSINGPABradenton Beach City South Channel Daybeacon 359965STRUCT DESTPABradenton Beach City South Channel Daybeacon 360120HAZ NAV/DAYMK MISSINGPABaynard Cove Creek Daybeacon 109775HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DBD DESTPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMisc Boundary Shoal Daybeacon 412595STRUCT DEST/HAZ NAVPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA	Bay Isles South Channel Daybeacon 10	58665	HAZ NAV/DAYMK MISSING	PA
Buttonwood Harbor Channel Junction Daybeacon B58905DAYMK MISSINGPAButtonwood Harbor Channel Daybeacon 2358945HAZ NAV/DAYMK MISSINGPALongboat Harbor North Marina Daybeacon 259135DAYMK MISSINGPACatalina Channel Daybeacon 159620STRUCT DESTPACatalina Channel Daybeacon 359625STRUCT DESTPACatalina Channel Daybeacon 559630STRUCT DESTPABradenton Beach City South Channel Daybeacon 159960STRUCT DESTPABradenton Beach City South Channel Daybeacon 359965STRUCT DESTPABradenton Beach City South Channel Daybeacon 361020HAZ NAV/DAYMK MISSINGPABradenton Beach City South Channel Daybeacon 369965STRUCT DESTPABradenton Beach City South Channel Daybeacon 361020HAZ NAV/DAYMK MISSINGPABaynard Cove Creek Daybeacon 1361020HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DBD DESTPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMisc Boundary Shoal Daybeacon 410735DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA	Longboat Key Moorings Light 1	58680	STRUCT DEST/HAZ NAV	PA
Buttonwood Harbor Channel Daybeacon 258945HAZ NAV/DAYMK MISSINGPALongboat Harbor North Marina Daybeacon 259135DAYMK MISSINGPACatalina Channel Daybeacon 159620STRUCT DESTPACatalina Channel Daybeacon 359630STRUCT DESTPACatalina Channel Daybeacon 559630STRUCT DESTPABradenton Beach City South Channel Daybeacon 159960STRUCT DESTPABradenton Beach City South Channel Daybeacon 359965STRUCT DESTPABradenton Beach City South Channel Daybeacon 360120HAZ NAV/DAYMK MISSINGPABradenton Beach City South Channel Daybeacon 360120HAZ NAV/DAYMK MISSINGPABradenton Beach City South Channel Daybeacon 360120HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 109775HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DBD DESTPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMsrc Boundary Shoal Daybeacon 412555TRUCT DEST/HAZ NAVPAOhio Key Channel Daybeacon 412595TRUCT DEST/HAZ NAVPA				
Longboat Harbor North Marina Daybeacon 259135DAYMK MISSINGPACatalina Channel Daybeacon 159620STRUCT DESTPACatalina Channel Daybeacon 359625STRUCT DESTPACatalina Channel Daybeacon 559630STRUCT DESTPABradenton Beach City South Channel Daybeacon 159960STRUCT DESTPABradenton Beach City South Channel Daybeacon 369120STRUCT DESTPABradenton Beach City South Channel Daybeacon 360120HAZ NAV/DAYMK MISSINGPABradenton Beach City South Channel Daybeacon 360120HAZ NAV/DAYMK MISSINGPABradenton Beach City South Channel Daybeacon 360120HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 109775HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DAYMK MISSINGPASebastian Inlet Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMarc Boundary Shoal Daybeacon 410735DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA	-			
Catalina Channel Daybeacon 1SP620STRUCT DESTPACatalina Channel Daybeacon 3SP625STRUCT DESTPACatalina Channel Daybeacon 5S9630STRUCT DESTPABradenton Beach City South Channel Daybeacon 1S9960STRUCT DESTPABradenton Beach City South Channel Daybeacon 3S9965STRUCT DESTPAPerico Harbor Marina Daybeacon 1360120HAZ NAV/DAYMK MISSINGPABaynard Cove Creek Daybeacon 109775KHZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810.DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DBD DESTPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMisc Boundary Shoal Daybeacon 410735DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DESTPA				
Catalina Channel Daybeacon 359625STRUCT DESTPACatalina Channel Daybeacon 559630STRUCT DESTPABradenton Beach City South Channel Daybeacon 159960STRUCT DESTPABradenton Beach City South Channel Daybeacon 359963STRUCT DESTPAPerico Harbor Marina Daybeacon 1360120HAZ NAV/DAYMK MISSINGPABaynard Cove Creek Daybeacon 24355STRUCT DESTPASebastian Inlet Channel Daybeacon 109775HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DESTPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMorce Boundary Shool Daybeacon10735DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA	Longboat Harbor North Marina Daybeacon 2			
Catalina Channel Daybeacon 5SP630STRUCT DESTPABradenton Beach City South Channel Daybeacon 1S9960STRUCT DESTPABradenton Beach City South Channel Daybeacon 3S9965STRUCT DESTPAPerico Harbor Marina Daybeacon 1360120HAZ NAV/DAYMK MISSINGPABaynard Cove Creek Daybeacon 24355STRUCT DESTPASebastian Inlet Channel Daybeacon 109775HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DAYMK MISSINGPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMsrc Boundary Shoal Daybeacon 412595STRUCT DESTPAOhio Key Channel Daybeacon 412595STRUCT DESTPA	Catalina Channel Daybeacon 1	59620	STRUCT DEST	PA
Bradenton Beach City South Channel Daybeacon 159960STRUCT DESTPABradenton Beach City South Channel Daybeacon 359965STRUCT DESTPAPerico Harbor Marina Daybeacon 1360120HAZ NAV/DAYMK MISSINGPABaynard Cove Creek Daybeacon 24355STRUCT DESTPASebastian Inlet Channel Daybeacon 109775HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DBD DESTPAFisher Island Marina Channel North Obstruction Daybeacon10650DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10735DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA	Catalina Channel Daybeacon 3	59625	STRUCT DEST	PA
Bradenton Beach City South Channel Daybeacon 359965STRUCT DESTPAPerico Harbor Marina Daybeacon 1360120HAZ NAV/DAYMK MISSINGPABaynard Cove Creek Daybeacon 24355STRUCT DESTPASebastian Inlet Channel Daybeacon 109775HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DBD DESTPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10735DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA	Catalina Channel Daybeacon 5	59630	STRUCT DEST	PA
Bradenton Beach City South Channel Daybeacon 359965STRUCT DESTPAPerico Harbor Marina Daybeacon 1360120HAZ NAV/DAYMK MISSINGPABaynard Cove Creek Daybeacon 24355STRUCT DESTPASebastian Inlet Channel Daybeacon 109775HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DBD DESTPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10735DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA	Bradenton Beach City South Channel Daybeacon 1	59960	STRUCT DEST	PA
Perico Harbor Marina Daybeacon 1360120HAZ NAV/DAYMK MISSINGPABaynard Cove Creek Daybeacon 24355STRUCT DESTPASebastian Inlet Channel Daybeacon 10975HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DBD DESTPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10735DAYMK MISSINGPAOho Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA	· · · · ·			
Baynard Cove Creek Daybeacon 2435STRUCT DESTPASebastian Inlet Channel Daybeacon 109775HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DBD DESTPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMsrc Boundary Shoal Daybeacon 410735DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA				
Sebastian Inlet Channel Daybeacon 109775HAZ NAV/DAYMK MISSINGPASebastian Inlet Channel Daybeacon 179810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DBD DESTPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMsrc Boundary Shoal Daybeacon 410735DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA	-			
Sebastian Inlet Channel Daybeacon 179810DAYMK MISSINGPASebastian Inlet Channel Daybeacon 259810.9DBD DESTPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMsrc Boundary Shoal Daybeacon 410735DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA				
Sebastian Inlet Channel Daybeacon 259810.9DBD DESTPAFisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMsrc Boundary Shoal Daybeacon10735DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA	-		HAZ NAV/DAYMK MISSING	
Fisher Island Marina Channel North Obstruction Daybeacon10605DAYMK MISSINGPAFisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMsrc Boundary Shoal Daybeacon10735DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA	Sebastian Inlet Channel Daybeacon 17	9810	DAYMK MISSING	PA
Fisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMsrc Boundary Shoal Daybeacon10735DAYMK MISSINGPAOhio Key Channel Daybeacon 412595STRUCT DEST/HAZ NAVPA	Sebastian Inlet Channel Daybeacon 25	9810.9	DBD DEST	PA
Fisher Island Breakwater East Obstruction Daybeacon10650DAYMK MISSINGPAMsrc Boundary Shoal Daybeacon10735DAYMK MISSINGPAOhio Key Channel Daybeacon 42595STRUCT DEST/HAZ NAVPA	Fisher Island Marina Channel North Obstruction Daybeacon	10605	DAYMK MISSING	PA
Msrc Boundary Shoal Daybeacon 10735 DAYMK MISSING PA Ohio Key Channel Daybeacon 4 12595 STRUCT DEST/HAZ NAV PA	-	10650	DAYMK MISSING	PA
Ohio Key Channel Daybeacon 4 12595 STRUCT DEST/HAZ NAV PA				
Istump Pass Marina Daybeacon 4 21400 STRUCT DEST PA				
	Stump Pass Marina Daybeacon 4	21400	STRUCT DEST	PA

<i>x</i> 11/20, 10.117 M	manano caloty momane	in reduce prangation conten	
Big Sarasota Pass Daybeacon 8	21500.8	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 11	21510	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 11A	21510.5	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 13	21515	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 15	21525	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 16	21570	STRUCT DEST	PA
North Siesta Key Daybeacon 9	21570.5	STRUCT DEST	PA
North Siesta Key Daybeacon 11	21570.60000000002	STRUCT MISSING	PA
Country Club Shores Daybeacon 2	21660	DAYMK MISSING	PA
MacDill Marina Channel Daybeacon 2	22975	STRUCT DEST	PA
Point Pinellas Daybeacon 1	24740		PA
		HAZ NAV/STRUCT DMGD	
Isleta Marina Pier A Light	31240	LT EXT	PA
Isleta Marina Pier B Light	31245		PA
Isleta Marina Pier C Light	31250	LT EXT	PA
Puerto Yabucoa Channel Range Front Light	31745	LT EXT/STRUCT DMGD	PA
Puerto Yabucoa Channel Range Rear Light	31750	LT EXT/STRUCT DMGD	PA
Las Mareas Range Front Light	31810	LT EXT	PA
Las Mareas Range Rear Light	31815	LT EXT	PA
Las Mareas Lighted Buoy 1	31820	OFF STA/LT EXT	PA
Las Mareas Lighted Buoy 2	31825	MISSING	PA
Water Island Channel Lighted Buoy 3	32626.2	LT EXT	PA
Marsh Harbor Marina Daybeacon 3	35420	DAYMK MISSING	PA
Marsh Harbor Marina Daybeacon 5	35430	DAYMK MISSING	PA
Fdot Villano Bridge South Breasting Light	38834	LT EXT	PA
Boat Works Channel Daybeacon 2	40135	DAYMK MISSING	PA
Boat Works Channel Daybeacon 5	40150	DAYMK MISSING	PA
Matthews Marina Daybeacon 3	40260	DAYMK IMCH	PA
Matthews Marina Daybeacon 5	40270	DAYMK MISSING	PA
Seven Seas Marina Daybeacon 11	40330	DAYMK MISSING	PA
Harbor Towne Marina Daybeacon 2	41245	STRUCT DEST	PA
	41250	STRUCT DEST	PA
Harbor Towne Marina Daybeacon 4	41250	DAYMK MISSING	PA
Harbor Towne Marina Daybeacon 9			
Riverdeck Channel Daybeacon 1	41295	STRUCT DEST	PA
Riverdeck Channel Daybeacon 2	41300	STRUCT DEST	PA
Riverdeck Channel Daybeacon 3	41305	STRUCT DEST	PA
Riverdeck Channel Daybeacon 4	41310	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 1	41345	DAYMK MISSING	PA
Kennedy Yacht Club Channel Daybeacon 2	41350	DAYMK MISSING	PA
Kennedy Yacht Club Channel Daybeacon 3	41355	DAYMK IMCH	PA
Kennedy Yacht Club Channel Daybeacon 4	41360	DAYMK IMCH	PA
Kennedy Yacht Club Channel Daybeacon 5	41365	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 7	41375	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 8	41380	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 9	41385	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 10	41390	STRUCT DEST	PA
Orlando Utilities Comission Channel Buoy 2	41445	MISSING	PA
Orlando Utilities Comission Channel Buoy 4	41450	MISSING	PA
Orlando Utilities Comission Channel Buoy 5	41455	MISSING	PA
Orlando Utilities Comission Channel Buoy 6	41460	MISSING	PA
Orlando Utilities Comission Channel Buoy 7	41465	MISSING	PA
Orlando Utilities Comission Channel Buoy 8	41405	MISSING	PA
	41470		
Diamond 99 Marina Daybeacon 1			PA
Diamond 99 Marina Daybeacon 2	42295		PA
Diamond 99 Marina Daybeacon 3	42300		PA
Diamond 99 Marina Daybeacon 4	42305		PA
Diamond 99 Marina Daybeacon 5	42310	STRUCT DEST	PA
Diamond 99 Marina Daybeacon 6	42315	DAYMK MISSING	PA
Diamond 99 Marina Daybeacon 7	42320	DAYMK MISSING	PA
Diamond 99 Marina Light 8	42325	STRUCT DEST	PA
Inlet Marina Daybeacon 1	43615	DAYMK MISSING	PA
Inlet Marina Daybeacon 2	43620	DAYMK MISSING	PA
Inlet Marina Daybeacon 4	43630	DAYMK MISSING	PA
Sembler Daybeacon 5	43655	DAYMK MISSING	PA
Channel 68 Marina Daybeacon 1 (Abandoned)	43685.1	STRUCT DEST/HAZ NAV	PA
Sembler Daybeacon 5	43655	DAYMK MISSING	PA

	,		
Channel 68 Marina Daybeacon 2 (Abandoned)	43685.20000000004	STRUCT DEST	PA
Channel 68 Marina Daybeacon 6 (Abandoned)	43685.6	STRUCT DEST	PA
Loggerhead Marina Daybeacon 10	44015	DAYMK MISSING	PA
Village Marina Daybeacon 2	44985	STRUCT DEST	PA
Riverside Marina (Ft. Pierce) Daybeacon 1	45035	STRUCT DEST	PA
Riverside Marina(Ft. Pierce) Daybeacon 3	45045	STRUCT DEST	PA
Riverside Marina(Ft. Pierce) Daybeacon 4	45050	DAYMK IMCH	PA
Riverside Marina(Ft. Pierce) Daybeacon 5	45055	STRUCT DEST	PA
Riverside Marina(Ft. Pierce) Daybeacon 7	45065	DAYMK MISSING	PA
Riverside Marina(Ft. Pierce) Daybeacon 8	45070	DAYMK MISSING	PA
Faber Cove Daybeacon 3	45135	STRUCT DEST/HAZ NAV	PA
Faber Cove Daybeacon 14	45185	STRUCT DEST	PA
Jensen Beach Channel Daybeacon 4	45495	STRUCT MISSING	PA
Jensen Beach Channel Daybeacon 5	45500	STRUCT MISSING	PA
Jensen Beach Channel Daybeacon 6	45505	STRUCT MISSING	PA
Miles Grant Daybeacon 2	45980	DAYMK IMCH	PA
Miles Grant Daybeacon 4	45990	DAYMK IMCH	PA
-			
Miles Grant Daybeacon 6	45995	DAYMK IMCH	PA
New Port Cove Marine Ctr Daybeacon 2	46620	STRUCT DEST	PA
Old Slip Marina Daybeacon 4	46680	STRUCT DEST/HAZ NAV	PA
Rybovich Spencer Ctr Channel Daybeacon 1	46780	STRUCT DEST	PA
Rybovich Spencer Ctr Channel Daybeacon 3	46790	STRUCT DEST	PA
Rybovich Spencer South Channel Daybeacon 1	46800	STRUCT DEST	PA
Rybovich Spencer South Channel Daybeacon 3	46810	STRUCT DEST	PA
Manalapan Channel Buoy 1	47007	STRUCT DEST	PA
Manalapan Channel Daybeacon 2	47007.5	STRUCT DEST	PA
Manalapan Channel Buoy 2	47008	STRUCT DEST	PA
Manalapan Channel Daybeacon 3	47008.5	STRUCT DEST	PA
Ocean Inlet Park Daybeacon 3	47050	MISSING	PA
Ocean Inlet Park Daybeacon 4	47055	STRUCT DEST	PA
Ocean Inlet Park Daybeacon 5	47060	STRUCT DEST	PA
Ocean Inlet Park Daybeacon 6	47065	STRUCT DEST	PA
Ocean Inlet Park Daybeacon 7	47070	STRUCT DEST	PA
Ocean Inlet Park Daybeacon 8	47075	STRUCT DEST	PA
Williams Island Daybeacon 1	47645	STRUCT DEST	PA
Williams Island Daybeacon 3	47650	DAYMK MISSING/STRUCT DMGD	PA
Williams Island Daybeacon 4	47655	DAYMK IMCH/STRUCT DMGD	PA
Williams Island Daybeacon 5	47660	STRUCT DEST	PA
	47665		PA
Williams Island Daybeacon 6		STRUCT DEST	
Williams Island Light 1	47685	STRUCT DEST	PA
Williams Island Light 2	47690	STRUCT DEST	PA
Intracoastal Yacht Club Channel Daybeacon 7	47737.1	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 8	47737.20000000004	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 9	47737.3	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 10	47737.4	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 11	47737.5	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 12	47737.6	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 13	47737.70000000004	DAYMK MISSING	PA
Mariners Bay Daybeacon 1	47890	DAYMK DMGD/STRUCT DMGD	PA
Mariners Bay Daybeacon 3	47895	STRUCT DEST	PA
Mariners Bay Daybeacon 5	47900	DAYMK MISSING	PA
Jockey Club Marina Daybeacon 10	47953	DAYMK MISSING	PA
Jockey Club Marina Daybeacon 15	47960	STRUCT DEST	PA
Jockey Club Marina Daybeacon 17	47965	STRUCT DEST	PA
Mike Gordon Restaurant Daybeacon 1	48220	STRUCT DEST	PA
Mike Gordon Restaurant Daybeacon 2	48225	STRUCT DEST/HAZ NAV	PA
Mike Gordon Restaurant Daybeacon 3	48225	DAYMK MISSING	PA
	48230		PA
Palm Bay Club Channel Daybeacon 2			
Palm Bay Club Channel Daybeacon 4	48300	DAYMK MISSING	PA
Palm Bay Club Channel Daybeacon 5	48305	DAYMK IMCH	PA
Palm Bay Club Channel Daybeacon 6	48310	DAYMK DMGD	PA
Palm Bay Club Channel Daybeacon 7	48315	DAYMK MISSING	PA
Palm Bay Club Channel Daybeacon 8	48320	DAYMK MISSING	PA
Deering Channel Daybeacon 1	48610	STRUCT DEST	PA

48620	DAYMK MISSING	PA
48625	DAYMK MISSING	PA
48640	DAYMK MISSING	PA
48645	DAYMK MISSING	PA
48650	HAZ NAV/DAYMK MISSING	PA
48665	STRUCT DEST	PA
48670	STRUCT DEST	PA
48705	LT EXT	PA
48710	LT EXT	PA
		PA
49095	DAYMK MISSING	PA
49100	STRUCT DMGD	PA
49100	DAYMK MISSING	PA
49105	MISSING	PA
49110	DBD DMGD	PA
49115	DAYMK MISSING	PA
49120	STRUCT DMGD	PA
49150	DAYMK MISSING	PA
49155	DAYMK MISSING	PA
49215	DAYMK IMCH	PA
49220	DAYMK MISSING	PA
49595	STRUCT MISSING	PA
		PA
52930	DAYMK MISSING	PA
52950	DAYMK IMCH/STRUCT DMGD	PA
52960	DAYMK MISSING	PA
53370	HAZ NAV/STRUCT DEST	PA
53475	DAYMK MISSING	PA
53511	STRUCT DEST	PA
53515	STRUCT DEST	PA
53520	STRUCT DEST	PA
53685	DAYMK MISSING	PA
53755	DAYMK MISSING	PA
56060	HAZ NAV/STRUCT DEST	PA
56665	STRUCT DEST/HAZ NAV	PA
56665	STRUCT DEST/HAZ NAV	PA
56665 56785	STRUCT DEST	PA PA
56665 56785 56790	STRUCT DEST DAYMK MISSING	РА РА РА
56665 56785 56790 56800	STRUCT DEST DAYMK MISSING STRUCT DEST/HAZ NAV	РА РА РА РА
56665 56785 56790 56800 56805	STRUCT DEST DAYMK MISSING STRUCT DEST/HAZ NAV STRUCT DEST	РА РА РА РА РА
56665 56785 56790 56800 56805 56825	STRUCT DEST DAYMK MISSING STRUCT DEST/HAZ NAV STRUCT DEST DAYMK MISSING	PA PA PA PA PA PA PA
56665 56785 56790 56800 56805	STRUCT DEST DAYMK MISSING STRUCT DEST/HAZ NAV STRUCT DEST	РА РА РА РА РА
	486454865048650486654870548710487454875548765487654876548765487654876549051.200000000449051.200000000449051.349051.449051.200000000449051.34905149051.349051.449051.349051.349051.349051.449051.349051.349051.349051.349051.349051.349051.349051.349051.349051.349051.349051.349051.349051.349051.34910049	48640DAYMK MISSING48650HAZ NAV/DAYMK MISSING48650STRUCT DEST486670STRUCT DEST48705LT EXT48710LT EXT487450DAYMK MISSING48755DAYMK MISSING48756DAYMK MISSING48756DAYMK MISSING48985STRUCT DEST49051STRUCT DEST49051MISSING49051STRUCT DEST49051STRUCT DEST49050STRUCT DEST49051STRUCT DEST49050STRUCT DEST49051STRUCT DEST49050STRUCT DEST49051STRUCT DEST49050STRUCT DEST49050STRUCT DEST49050STRUCT DEST49050STRUCT DEST49100DED DMGD49100STRUCT DEST49100STRUCT DEST49100STRUCT DEST49100STRUCT DEST49150STRUCT DEST49150STRUCT DEST49150STRUCT DEST49150STRUCT DEST49150STRUCT DEST49150STRUCT DEST49150STRUCT DEST5280

Maritime Safety Information Products | Navigation Center

11/20, 10.41 AM	Mananic Galety Information	In roducis Navigation Ochici	
Uncle Henry's Marina Daybeacon 24	56890	STRUCT DEST	PA
Uncle Henry's Marina Daybeacon 27	56905	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 30	56920	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 31	56925	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 35	56945	STRUCT DMGD	PA
Uncle Henry'S Marina Daybeacon 36	56950	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 37	56955	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 40	56970	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 40	56975	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 42	56980	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 43	56985	STRUCT DEST	PA
Uncle Henry's Marina Daybeacon 47	57005	STRUCT DEST	PA
Englewood Channel Daybeacon 22	57359.13000000005	STRUCT DEST	PA
Englewood Channel Daybeacon 10	57359.6	STRUCT DEST	PA
Venice Yacht Club Obstruction Light A	57779	STRUCT DEST	PA
San Remo Daybeacon 1	58446	STRUCT DEST	PA
San Remo Daybeacon 2	58447	STRUCT DEST	PA
San Remo Daybeacon 2	58447	DAYMK IMCH	PA
San Remo Daybeacon 3	58448	STRUCT DEST	PA
San Remo Daybeacon 5	58449	STRUCT DEST	PA
San Remo Daybeacon 5	58449	STRUCT DEST	PA
San Remo North Obstruction Daybeacon	58449.1	STRUCT DEST/HAZ NAV	PA
San Remo South Obstruction Daybeacon	58449.20000000004	STRUCT DEST/HAZ NAV	PA
Hudson Bayou Daybeacon 1	58485.1	DAYMK IMCH	PA
Hudson Bayou Daybeacon 3	58485.3	STRUCT MISSING	PA
Bird Key Channel Daybeacon 2	58510	DAYMK MISSING	PA
Bird Key Channel Daybeacon 3	58515	DAYMK MISSING	PA
Bird Key Channel Daybeacon 7	58525	DAYMK MISSING	PA
Bay Isles South Channel Daybeacon 1	58640	STRUCT DMGD	PA
Bay Isles South Channel Daybeacon 4	58650	DAYMK DMGD	PA
Bay Isles South Channel Daybeacon 6	58655 58910		PA PA
Buttonwood Harbor Channel Daybeacon 13			
Buttonwood Harbor Channel Daybeacon 20	58935	DAYMK MISSING	PA
Buttonwood Harbor Channel Daybeacon 24	58950	DAYMK MISSING	PA
Buttonwood Harbor Channel Daybeacon 26	58955	DAYMK MISSING	PA
Longboat Harbor Channel Daybeacon 13A	59050	DAYMK MISSING	PA
Longboat Harbor Channel Daybeacon 17	59070	DAYMK MISSING	PA
Longboat Harbor North Marina Daybeacon 4	59140	STRUCT DEST	PA
Longboat Harbor North Marina Daybeacon 6	59145	STRUCT DEST	PA
Longboat Harbor North Marina Daybeacon 8	59150	STRUCT DEST	PA
Buccaneer Inn Daybeacon 14	59265	DAYMK IMCH	PA
Buccaneer Inn Daybeacon 16	59270	DAYMK IMCH	PA
Buccaneer Inn Daybeacon 20	59285	STRUCT DEST	PA
Buccaneer Inn Daybeacon 24	59300	DAYMK IMCH	PA
Bayway Isles Channel Daybeacon 3	60635	STRUCT DEST	PA
Bayway Isles Channel Daybeacon 10	60660	DAYMK MISSING	PA
Gulfport Yacht Basin Channel Range Front Light	60700	LT EXT	PA
Gulfport Yacht Basin Channel Range Rear Light	60705	LT EXT	PA
Gulfport Yacht Club Channel Daybeacon 4	60745	STRUCT DEST	PA
Pasadena Yacht Club Channel Daybeacon 6	60770	STRUCT DEST/HAZ NAV	PA
Pasadena Yacht Club Channel Daybeacon 9	60780	STRUCT DEST	PA
Jungle Estates Daybeacon 4	61140	STRUCT DEST	PA
Jungle Estates Daybeacon 6	61150	STRUCT DEST	PA
Tarpon Cove Daybeacon 9	62165	STRUCT DEST	PA
Tarpon Cove Daybeacon 16	62195	STRUCT DEST	PA
Tarpon Cove Daybeacon 17	62200	STRUCT DEST	PA
Tarpon Cove Daybeacon 18	62205	STRUCT DEST/HAZ NAV	PA
Tarpon Cove Daybeacon 20	62215	STRUCT DEST	PA
Tarpon Cove Daybeacon 23	62225	STRUCT DEST	PA
Tarpon Cove Daybeacon 28	62246	STRUCT MISSING/HAZ NAV	PA
Tarpon Cove Daybeacon 28	62246	STRUCT DMGD	PA

Private Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE

Faber Cove Daybeacon 10		45160	REBUILT/RECOVERED	PA	2025-06-04	
Additional MSI Categori	es					
TITLE	SUBCATEGORY			DESCRIPTION		LOCATION
Unknown/General/Bridges/Construction	Bridges	SAN JOSE CREEK-GO	OLETA SLOUGH: STATE ROUTE 217 H	IGHWAY BRIDGE- Caltrans has	resumed in-water construction for the bridge	Lat:
		replacement project	t, scheduled to be completed by 31	October, 2025. Nets will be insta	alled in the slough to prevent fish from the area.	34° 25' 15"
		An open navigable p	n open navigable passage in the middle of the slough under the bridge will be available for mariners. Demolition of old bridge will			
		take place May 2025	5. Mariners are requested to transit	the area with caution. For more	information, contact the Coast Guard Bridge	-119° 49'

Upper Savannah River

Office at 571-607-2206 or by e-mail at D11Bridges@uscg.mil.

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Southern Nuclear Operating Co Obstruction Daybeacon A	5295	STRUCT DEST	PA
Southern Nuclear Operating Co Obstruction Daybeacon B	5295.1	STRUCT DEST	PA

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Port Wentworth Channel - Upper Savannah River/ATON/ATON Changes	5	ATON/ATON Changes 20876 Location: 33.4685° N / 81.93479° W Aid Name: Upper Savannah River Obstruction Buoy A LLNR: 5565 Action: ESTABLISH Position: 33-28-06.613N, 081-56-05.246W Delete: Upper Savannah River Buoy 100	Lat: 33° 28' 07" Lon: -081° 56' 05'
Port Wentworth Channel - Upper Savannah River/ATON/ATON Changes	ATON Changes	ATON/ATON Changes 20878 Location: 33.47005° N / 81.94157° W Aid Name: Upper Savannah River Obstruction Buoy B LLNR: 5570 Action: ESTABLISH Position: 33-28-12.178N, 081-56-29.649W Delete: Upper Savannah River Buoy 102	Lat: 33° 28' 12" Lon: -081° 56' 30'
Port Wentworth Channel - Upper Savannah River/ATON/ATON Changes	5	ATON/ATON Changes 20879 Location: 33.47248° N / 81.94911° W Aid Name: Upper Savannah River Obstruction Buoy C LLNR: 5575 Action: ESTABLISH Position: 33-28-20.935N, 081-56-56.786W Delete: Upper Savannah River Buoy 104	Lat: 33° 28' 21" Lon: -081° 56' 57'
Port Wentworth Channel - Upper Savannah River/ATON/ATON Changes	ATON Changes	ATON/ATON Changes 20880 Location: 33.47584° N / 81.95639° W Aid Name: Upper Savannah River Obstruction Buoy D LLNR: 5576 Action: ESTABLISH Position: 33-28-33.022N, 081-57-23.019W	Lat: 33° 28' 33" Lon: -081° 57' 23'
Port Wentworth Channel - Upper Savannah River/ATON/ATON Changes	ATON Changes	ATON/ATON Changes 20881 Location: 33.47695° N / 81.95834° W Aid Name: Upper Savannah River Obstruction Buoy E LLNR: 5577 Action: ESTABLISH Position: 33-28-37.026N, 081-57-30.013W	Lat: 33° 28' 37" Lon: -081° 57' 30'
Port Wentworth Channel - Upper Savannah River/ATON/ATON Changes	ATON Changes	ATON/ATON Changes 20883 Location: 33.47806° N / 81.96056° W Aid Name: Upper Savannah River Obstruction Buoy F LLNR: 5578 Action: ESTABLISH Position: 33-28-41.033N, 081-57-38.007W	Lat: 33° 28' 41" Lon: -081° 57' 38'
Port Wentworth Channel - Upper Savannah River/General/Miscellaneous	Miscellaneous	General/Miscellaneous 20921 Location: 33.3492° N / 81.93818° W Delete: Upper Savannah River Buoy 92	Lat: 33° 20' 57" Lon: -081° 56' 17'

Vernon River

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Ossabaw Sound - Vernon	Advanced Notice	ATON/Advanced Notice of Change Location: 31.87195° N / 81.07605° W Aid Name: Vernon River Light Wreck 86 LLNR: 36260 Action: CHANGE	Lat:
River/ATON/Advanced Notice	of Change	Action Type Change Light Characteristic The following change has been approved to the Aid to Navigation system in the Intracoastal Waterway	31° 52' 19"
of Change		the Vernon River, part of the Intracoastal Waterway (ICW). The nominal range permanently reduced from 5NM to 4NM. The current nominal	Lon:
		range of 5NM is not necessary. Based on the design of the Short-Range Aids System (SRA), mariners should be able to see two lighted aids to	-081° 04'
		navigation forward of the aid from which they are alongside. Based on this data, a nominal range of 4NM is more than adequate.	34"

Villas Continental Club

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Villas Continental Club Daybeacon 2	7790	STRUCT DEST/HAZ NAV	PA
Villas Continental Club Daybeacon 3	7795	STRUCT DEST	PA
Villas Continental Club Daybeacon 4	7800	STRUCT DEST	PA
Villas Continental Club Daybeacon 5	7805	STRUCT DEST	PA

<u>Volusia</u>

Federal Discrepancies

47"

NAME	LLNR	STATUS	AID TYPE
Volusia Light 23	8820	STRUCT DEST/TRLB	FD

Wadmalaw River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wadmalaw River Light 82	34870	STRUCT MISSING/TRLB	FD
Wadmalaw River Daybeacon 87	34890	STRUCT DEST/TRUB	FD
Wadmalaw River Daybeacon 95	34915	STRUCT MISSING/TRUB	FD
Wadmalaw River Daybeacon 96	34920	STRUCT DEST/TRUB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATIO
North Edisto River -	Advanced Notice	ATON/Advanced Notice of Change Location: 32.69507° N / 80.22075° W Aid Name: Wadmalaw River Daybeacon 87 LLNR: 34890 Action:	Lat:
Wadmalaw	of Change	CHANGE Action Type Change Aid Subtype The following changes have been approved in the Wadmalaw River to improve aids to navigation	32° 41' 42
River/ATON/Advanced Notice		reliability. Wadmalaw River DBN 87 (LLNR 34890) and Wadmalaw River DBN 96 (LLNR 34920) will be changed to Wadmalaw River Buoy 87	Lon:
of Change		(Same LLNR) and Wadmalaw River Buoy 96 (Same LLNR). Both aids to navigation are currently destroyed and have a Temporary Unlighted Buoy	-080° 13'
		on station. Both assigned positions are presenting depths of over 28 feet. This depth makes it impossible for a CG asset to rebuild the structures.	15"
		Changing the aids to navigation from fixed to floating allows the CG primary servicing unit the flexibility to relocate the aid to mark safe water.	
North Edisto River -	Advanced Notice	ATON/Advanced Notice of Change Location: 32.66553° N / 80.23956° W Aid Name: Wadmalaw River Daybeacon 96 LLNR: 34920 Action:	Lat:
Wadmalaw	of Change	CHANGE Action Type Change Aid Subtype The following changes have been approved in the Wadmalaw River to improve aids to navigation	32° 39' 56'
River/ATON/Advanced Notice		reliability. Wadmalaw River DBN 87 (LLNR 34890) and Wadmalaw River DBN 96 (LLNR 34920) will be changed to Wadmalaw River Buoy 87	Lon:
of Change		(Same LLNR) and Wadmalaw River Buoy 96 (Same LLNR). Both aids to navigation are currently destroyed and have a Temporary Unlighted Buoy	-080° 14'
		on station. Both assigned positions are presenting depths of over 28 feet. This depth makes it impossible for a CG asset to rebuild the structures.	22"
		Changing the aids to navigation from fixed to floating allows the CG primary servicing unit the flexibility to relocate the aid to mark safe water.	

Walls Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Walls Cut Light 42	35840	STRUCT MISSING/TRLB	FD

Wappoo Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wappoo Creek Daybeacon 5	34615	STRUCT DEST/TRUB	FD

Wassaw Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wassaw Sound Lighted Buoy 8	5595	MISSING	FD

Waterway Name Not Found

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Channel Daybeacon A1	35920	STRUCT MISSING/TRUB	FD
South Channel Daybeacon A8	35940	STRUCT DMGD	FD
North River Light 178A	36800	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wexford Harbour Daybeacon 3	4420	MSLD SIG	PA
Wexford Harbour Daybeacon 4	4425	MSLD SIG	PA
Wexford Harbour Daybeacon 8	4445	MSLD SIG	PA
Palmetto Dunes Marina West Light 22	4520	DAYMK IMCH	PA

Western Gulf Intracoastal Waterway

NAME	LLNR	STATUS	AID TYPE
South Seas Boat Basin Daybeacon 3	55650	HAZ NAV/DAYMK MISSING	PA
Dunedin Pass Daybeacon 2	25850	STRUCT DEST	PA

Maritime Safety Information Products | Navigation Center

Dunedin Pass Daybeacon 3	25855	STRUCT DEST	PA
Dunedin Pass Daybeacon 9	25875	STRUCT DEST	PA
Dunedin Pass Daybeacon 12	25885	STRUCT MISSING	PA

Whale Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Whale Harbor Channel Daybeacon 6	12720	STRUCT DEST/HAZ NAV/TRLB	FD
· · · · · · · · · · · · · · · · · · ·		1	

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Holiday Isle Marina Daybeacon 1	12765	STRUCT DEST	PA
Holiday Isle Marina Daybeacon 2	12770	STRUCT DEST	PA

White Shells Cut

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
White Shells Cut Lighted Buoy 27	7315	RELOCATED FOR DREDGING	FD
White Shells Temporary Range Rear Light	7325.2	ESTABLISHED	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Johns River - White Shells	Advanced Notice	White Shells Cut LB 27 (LLNR 7315) will be permanently relocated to 30-23-36.040N/081-28-48.780W. This change calls to relocate (6) lighted	Lat:
Cut/ATON/Advanced Notice	of Change	buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are	30° 23' 36"
of Change		needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe navigation	Lon:
		for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this change. All	-081° 28'
		positions listed are approximate. Permanent positions will be advertised when the work is completed.	49"
St Johns River - White Shells	Advanced Notice	White Shells Cut LB 29 (LLNR 7316) will be permanently relocated to 30-23-32.900N/081-29-05.750W. This change calls to relocate (6) lighted	Lat:
Cut/ATON/Advanced Notice	of Change	buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are	30° 23' 33'
of Change		needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe navigation	Lon:
		for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this change. All	-081° 29'
		positions listed are approximate. Permanent positions will be advertised when the work is completed.	06"

Wilmington River

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Skidaway Island - Wilmington	Bridges	General/Bridges/Conversion From: 2024-10-29 To: 2025-04-27 Location: 32.062044° N / 81.02951° W Bridge Name: CR 787 (Island	Lat:
River/General/Bridges/Conversion		Expressway) Drawbridges Construction on the first of the two high level fixed bridges is complete and now spans the waterway providing 65	32° 03' 43"
		feet of vertical clearance and 100 feet of horizontal clearance between the fender systems. Construction of the second high level fixed bridge	Lon:
		has begun. Work hours are 7 am 7 p.m., Monday through Saturday. During this time, there will be intermittent work inside and outside the	-081° 01'
		federal channel. Mariners operating commercial/recreational vessels greater than 50ft in breath/beam requiring full width of the federal	46"
		navigational channel, are strongly encouraged to call Myrick Marine at 912-210-6778 up to 24 hours in advance, but not less than one hour	
		before arrival to the construction area to coordinate safe passage. Once in the vicinity of the Causton Bluff Bridge, please contact the LONA	
		MYRICK or GRACE MYRICK by VHF to verify your scheduled passage. If applicable, please have your Automated Information System (AIS)	
		energized. In addition, there will be a Myrick Marine safety boat in the vicinity of the construction area for traffic management. The safety	
		boat can be reached on channel 10 or 13. The old bascule bridges have been removed from the waterway. Mariners are reminded to	
		proceed through the construction area at a safe speed, always maintain situational awareness, and monitor VHF radio channel 16 when in	
		the vicinity of the Causton Bluff Bridge. For further information regarding this MSIB, please contact the U.S. Coast Guard MSU Savannah	
		Waterways Management Division at SMB-MSUSavannah-WWM@uscg.mil or the Command Duty Officer at (912) 247-0073.	

Windward Passage

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Johnson Reef Lighted Buoy JD	32680.3	LT EXT	PA

Winyah Bay Channel

NAME	LLNR	STATUS	AID TYPE
Winyah Bay Range A Front Light	1875	LT EXT	FD
Winyah Bay Range A Rear Light	1880	LT EXT	FD
Winyah Bay Range B Rear Light	1915	STRUCT DEST/HAZ NAV/TRLT	FD
Winyah Bay Channel Lighted Buoy 13	1950	OFF STATION	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - Winyah	Advanced Notice of	The Coast Guard Mooring Buoy WB (LLNR 1958) will be permanently relocated to approximate position 33-14-	Lat:
Bay Channel/ATON/Advanced Notice of Change	Change	59.160N/079-12-47.580W. The new location will provide a more protected environment from the previous exposed	33° 13' 54"
		location for CG assets when moored to this buoy.	Lon:
			-079° 11'
			30"
Sector Charleston, Submerged Land Act (SLA) - Winyah	Advanced Notice of	Winyah Bay Channel LB 4 (LLNR 1885) will have the bell permanently removed.	Lat:
Bay Channel/ATON/Advanced Notice of Change	Change		33° 11' 37"
			Lon:
			-079° 07'
			13"

Winyah Bay Charleston Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Winyah Bay-Charleston Harbor Daybeacon 19	34180	STRUCT MISSING/TRUB	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - Winyah Bay Charleston	Marine Construction	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2025-02-25 To: 2026-11-13 Location: 32.7602° N / 79.86088° W 32.75736° N / 79.85803° W 32.7566° N / 79.85931° W 32.75944° N /	
Harbor/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	(Excluding Bridges)	79.86219° W 32.7602° N / 79.86088° W Cape Romain Contractors will be replacing Fort Sumter and Fort Moultrie Docks and rehabilitate Liberty Square Pier. They will have a crane barge starting March 3, 2025, until May 31, 2026, at Fort Moultrie and crane barges at Fort Sumter and Liberty Square Pier as the project progresses. Estimated completion date of the entire project is 310ctober 31, 2026. All Vessels should use caution when transiting the work area. The crew at Fort Moultrie will monitor VHF-FM channels 13 and 16.	

Withlacoochee River

NAME	LLNR	STATUS	AID TYPE
Withlacoochee River Entrance Daybeacon 8	29410	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 16	29455	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 26	29520	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 29	29535	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 30	29545	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 31	29550	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Light 32	29555	STRUCT MISSING/TRLB	FD
Withlacoochee River Entrance Daybeacon 32B	29565	STRUCT DEST/TRUB	FD