

Local Notice to Mariners for Heartland (MRS) District 05/06/2026

Arkansas River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Milligan Bend Light	990	STRUCT DEST	FD
Webber Falls Jetty Light	1010	STRUCT DEST	FD
Bluff View Light	1020	STRUCT DEST	FD
Hisaw Bottom Light	1055	LT EXT	FD
Sandtown Bottom Light	1077	STRUCT DEST	FD
Black Rock Daybeacon	1200	STRUCT DEST	FD
Gans Light	1205	STRUCT DEST	FD
Onion Creek Daybeacon	1220	STRUCT DMGD	FD
Non Lateral Mark 328.5	1223	STRUCT DMGD	FD
Tucker Lake Light	1225	STRUCT DEST	FD
Mcnabb Bottom Daybeacon	1230	STRUCT DEST	FD
Deadman Slough Light	1240	STRUCT DEST	FD
Wilson's Rock Light	1255	STRUCT DMGD	FD
Peno Point Daybeacon	1265	DAYMK DMGD	FD
Garrison Creek Daybeacon	1315	DAYMK MISSING	FD
Crawford County Daybeacon	1360	STRUCT DEST	FD
Jeffrey Light	1365	DAYMK MISSING	FD
Fort Chaffee Light	1390	STRUCT DEST	FD
Haroldton Light	1395	DAYMK MISSING	FD
New Haroldton Light	1400	STRUCT DEST	FD
Gun Club Lake Daybeacon	1420	DAYMK MISSING	FD
Big Creek Daybeacon	1427	DAYMK MISSING	FD
Clear Creek Light	1435	DAYMK MISSING	FD
Crooked Slough Light	1445	STRUCT DEST	FD
Mulberry River Daybeacon	1455	STRUCT DEST	FD
Moores Creek Light	1510	LT IMCH/STRUCT DMGD	FD
Roseville Daybeacon	1515	DAYMK MISSING	FD
O'Kane Island Light	1520	LT IMCH/STRUCT DMGD	FD
Alix Bottom Light	1525	STRUCT DEST	FD
County Line Daybeacon	1530	STRUCT DEST	FD
Non Lateral Mark 246.3	1532	DAYMK MISSING	FD
Non Lateral Mark 236.3	1562	DAYMK MISSING	FD
Spadra Creek Light	1605	DAYMK IMCH/STRUCT DMGD	FD
Dublin Daybeacon	1615	STRUCT DEST	FD
Bunker Hill Upper Daybeacon	1650	STRUCT DEST	FD
Bunker Hill Lower Daybeacon	1660	STRUCT DEST	FD
Non Lateral Mark 201.4	1697	STRUCT DEST	FD
Elberta Light	1700	DAYMK MISSING	FD
Non Lateral Mark 197.9	1708	STRUCT DEST	FD
Hola Bend Cutoff Light	1715	DAYMK MISSING	FD
Carden Bottoms Light	1720	DAYMK IMCH/STRUCT DMGD	FD
Sweedeen Island Light	1735	LT EXT/DAYMK MISSING	FD
Wilson Light	1745	STRUCT DEST	FD
Willow Bend Lower Daybeacon	1770	DAYMK MISSING	FD
Louisburg Light	1795	DAYMK IMCH/STRUCT DMGD	FD
Non Lateral Mark 175.6	1798	DAYMK MISSING	FD
Ellis Island Light	1815	STRUCT DEST	FD
Stane Reach Upper Daybeacon	1845	DAYMK DMGD	FD
Stane Reach Light	1850	DAYMK DMGD	FD
Cadron Creek Light	1860	DAYMK IMCH/STRUCT DMGD	FD
Belk Corner Light	1890	DAYMK MISSING/STRUCT DMGD	FD
Non Lateral Mark 150.9	1903	DAYMK MISSING	FD
Bigelow Middle Daybeacon	1915	DAYMK DMGD	FD
Bigelow Lower Light	1920	DAYMK MISSING	FD
Tri County Light	1930	STRUCT DEST	FD
Non Lateral Mark 138.8	1948	DAYMK MISSING	FD

Non Lateral Mark 137.6	1953	DAYMK MISSING	FD
Palarm Light	1960	DAYMK MISSING	FD
Maumelle River Upper Daybeacon	1975	STRUCT DEST	FD
Burns Park Light	2030	STRUCT DEST	FD
Peach Orchard Bend Light	2110	LT IMCH/DAYMK IMCH	FD
Fourche Place Cutoff Light	2125	DAYMK IMCH	FD
Non Lateral Mark 106.5	2143	DAYMK MISSING	FD
Fourche Bayou Light	2150	DAYMK IMCH/STRUCT DMGD	FD
Chenault Island Light	2155	DAYMK IMCH/STRUCT DMGD	FD
Estes Place Light	2160	DAYMK IMCH/STRUCT DMGD	FD
Jim Brown Island Light	2170	DAYMK IMCH/STRUCT DMGD	FD
Non Lateral Mark 92.0	2199	STRUCT DEST	FD
Ste. Marie Bend Lower Daybeacon	2370	STRUCT DEST	FD
Richland Bend Middle Daybeacon	2435	STRUCT DEST	FD
Little Bayou Meto Lower Daybeacon	2485	DAYMK DMGD	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Oakley Light	2100	LT EXT	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Arkansas Post Canal - Arkansas River/General/Bridges/Maintenance	Bridges	Garrison Street Bridge: Continuing until further notice, maintenance will be conducted on the bridge. A containment system will be in place and will hang 3 feet below low steel. Mariners are advised to transit the area with caution.	Lat: 35° 23' 33" Lon: -094° 25' 59"
Arkansas Post Canal - Arkansas River/General/Bridges/Construction	Bridges	Mariners are advised that bridge construction falsework is located in the river at approximate Mile 291.6, downstream of James W. Trimble L/D (No. 13). These obstructions will be in place intermittently during the I-49 Bridge construction and may be submerged depending on river conditions. Although the obstructions are located outside of the navigation channel, mariners should exercise caution when transiting the area and remain aware of potential changes to navigation due to construction activities. Updates and further notices will be issued as needed. Mariners may contact Little Rock District Office at (501) 324-5739 or by email at CESWL-OP-OM@usace.army.mil, for further information.	Lat: 35° 20' 36" Lon: -094° 16' 51"
Arkansas Post Canal - Arkansas River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	Continuing through June 15, 2026, mariners may experience intermittent delays at the Toad Suck Ferry L/D (Nr. 8), in the vicinity of Mile 155.9. Intermittent delays are required to facilitate dredging and dive inspections in preparation of the 110' stoplog conversions. Work will be conducted from 7:00 a.m. until 5:30 p.m., daily. Mariners may contact the USACE Little Rock District Office, at (501) 324-5096 or you may email ceswl-op-om@usace.army.mil, for additional information.	
Arkansas Post Canal - Arkansas River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	Continuing through June 15, 2026, mariners may experience intermittent delays at the Murray L/D (Nr. 7), in the vicinity of Mile 125.4. Intermittent delays are required to facilitate dredging and dive inspections in preparation of the 110' stoplog conversions. Work will be conducted from 7:00 a.m. until 5:30 p.m., daily. Mariners may contact the USACE Little Rock District Office, at (501) 324-5096 or you may email ceswl-op-om@usace.army.mil, for additional information.	

Bay Springs Lake

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
General/Hazards To Navigation/Obstructions	Hazards To Navigation	Tennessee Tombigbee River - Aids to Navigation --- From: 2025-11-26 To: 2025-12-31 --- A can buoy has been reported off station towards the red side of the channel near Mile 408.5. Mariners are urged to transit the area with caution.	Lat: 34° 28' 34" Lon: -088° 20' 13"

Clinch River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Solway Lower Daybeacon	3017	STRUCT DMGD	FD
DBO Straight Daybeacon	3052	STRUCT DEST	FD

Cumberland River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Watkins Daybeacon	3965	STRUCT DEST	FD
Cotton Gin Bar Daybeacon	4040	STRUCT DEST	FD

Mannings Landing Light	4280	Status Unreported	FD
Saline Creek Light	4285	STRUCT DEST/TRUB	FD
Pryors Creek Light	4315	STRUCT DEST	FD
Devils Elbow Light	4340	STRUCT DEST	FD
Bleidt Landing Light	4365	STRUCT DEST/TRUB	FD
Crooked Creek Light	4390	STRUCT DEST/TRUB	FD
Commerce Landing Light	4425	STRUCT DEST	FD
Metal Landing Light	4435	STRUCT DEST/TRUB	FD
Big Eddy Light	4450	STRUCT DEST/TRUB	FD
Prison Farm Landing Light	4455	STRUCT DEST	FD
Kuttawa Bar Light	4500	STRUCT DEST	FD
Money Cliff Light	4505	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Ohio River - Cumberland River/General/Bridges/Closure (Scheduled Or Emergency)	Bridges	Bordeaux Railroad Drawbridge; Continuing until May 6, 2026, the bridge will be closed due to maintenance work. Work will be conducted from 7:00 a.m. until 4:00 p.m., daily. The bridge will open temporarily on April 30, 2026. Mariners are urged to transit the area with caution. Mariners are advised to contact the maintenance supervisor at (854) 304-0667, for additional information.	Lat: 36° 10' 58" Lon: -086° 49' 54"

Illinois River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lacon Light	6885	STRUCT DEST	FD
Sand Point Lower Light	6985	STRUCT DEST	FD
Circle Light	6990	STRUCT DMGD	FD
Spring Bay Daybeacon	6995	STRUCT DEST	FD
Drolls Point Light	7035	STRUCT DEST/TRLB	FD
Frederick Light	7585	STRUCT DEST	FD
Twin Island Light	7943	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cargill Terminal Lights (2)	7725	LT IMCH	PA
Adm Growmark Grain Elevator Lights (2)	7760	LT IMCH	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Lacon Light	6885	TRUB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Lower Mississippi River - Illinois River/General/Bridges/Inspection	Bridges	I-80 Bridge; Commencing April 20, 2026, and continuing until May 15, 2026, bridge inspections are being conducted. Work will be conducted from 6:00 a.m. to 6:00 p.m., Monday through Friday. Vertical clearance may be reduced due to snooper trucks hanging below the bridge deck. A vessel will be on-scene conducting scour inspections on the bridge piers. Mariners are urged to exercise caution while transiting under the bridge.	Lat: 41° 15' 39" Lon: -089° 20' 48"
Lower Mississippi River - Illinois River/General/Bridges/Maintenance	Bridges	Continuing through May 15, 2025, bridge cleaning will be conducted on the I-474 Dual Bridges. Work will be conducted from 7:00 a.m. to 7:00 p.m., Monday through Friday. Vertical clearance may be reduced, due to snooper trucks hanging below the bridge deck. Mariners are urged to use extreme caution while transiting the bridge.	Lat: 40° 38' 06" Lon: -089° 37' 21"

Kanawha River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dam 10 Light	8795	LT EXT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

Ohio River - Kanawha River/General/Bridges/Rehabilitation	Bridges	Virginia Street and Quarrier Street Bridges: Continuing until December 2026, vertical clearance may be reduced by up to 3 feet due to work platforms hanging below the bridges. Mariners are urged to maintain a proper lookout and exercise caution in the area.	Lat: 38° 21' 20" Lon: -081° 38' 37"
Ohio River - Kanawha River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	Continuing until approximately April 24, 2026, Amherst Madison is conducting sewer main sub-crossing replacement operations in the vicinity of Mile 0.05. Work will be conducted from 6:30 a.m. until 4:30 p.m., Monday through Friday. The contractors floating plant will consist of the M/Vs TOM COOK and LUCEDALE, a barge mounted crane, excavator barge and jumbo deck barge. The M/Vs TOM COOK and LUCEDALE will monitor VHF-FM Channel 13 or 16. During non-working hours, the contractors floating plant will be moored at the worksite and lighted accordingly. Mariners are urged to transit the area at their slowest safe speed to minimize their wake and proceed with caution.	
General/Miscellaneous	Miscellaneous	Commencing January 11, 2026, London L/D will decrease hours of operations. The lock will operate from 7:00 a.m. to 5:00 p.m. and from 7:00 p.m. and 5:00 a.m., 7-days a week. Mariners may contact the Lockmaster at (304) 442-8422, for further information.	
Ohio River - Kanawha River/General/Miscellaneous	Miscellaneous	Commencing May 7, 2026, and continuing until December 2026, Union Carbide Corporation South Charleston Facility will deploy a 75-foot by 50-foot sorbent boom alongside Blaine Island's south bank, in the vicinity of Mile 55.3. The boom will be in place 24-hours a day, 7-days a week and lighted accordingly. Mariners are urged to exercise caution in the area.	

Lake St Croix

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Houden Point Daybeacon	29845	STRUCT DEST	FD

Lower Mississippi River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Island 30 Light	10090	STRUCT DEST	FD
Randolph Light	10150	STRUCT DEST	FD
Cedar Point Light	10185	REDUCED INT	FD
Cedar Point Light	10185	STRUCT DEST	FD
Dean Island Light	10195	REDUCED INT	FD
Brandywine Chute Light	10210	REDUCED INT	FD
Island 40 Foot Light	10225	STRUCT DEST	FD
Stumpy Point Light	10545	STRUCT DEST	FD
Williamson Light	10605	LT EXT	FD
Ludlow Bar Light	10710	DAYMK DMGD	FD
Riverton Middle Bar Light	10815	STRUCT DEST	FD
Cypress Bend Light	10885	STRUCT DEST	FD
Eutaw Bar Light	10895	STRUCT DEST	FD
Mounds Crevasse Lower Light	10905	STRUCT DEST	FD
Boliver Light	10910	STRUCT DEST	FD
Miller Bend Light	10955	STRUCT DEST	FD
La Grange Towhead Light	10965	STRUCT DEST	FD
Vaucluse Bend Light	11050	STRUCT DEST	FD
Anconia Point Light	11070	STRUCT DEST	FD
Lakeport Light	11080	STRUCT DEST	FD
Walnut Point Light	11085	STRUCT DEST	FD
Sarah Island Light	11130	STRUCT DEST	FD
Stack Island Light	11170	STRUCT DEST	FD
STACK ISLAND LOWER LIGHT	11180	STRUCT DEST	FD
Chinaman Light	11195	STRUCT DEST	FD
Coggins Light	11407	STRUCT DEST	FD
Buckridge Light	11455	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Consolidated Grain and Barge Loading Dock Piling Lights (2)	10114	MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
New Orleans To Baton Rouge - Lower Mississippi River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	Continuing until May 9, 2026, a USACE mat revetment project will be ongoing along the LDB, in the vicinity of Miles 744.2, from 6:00 a.m. to 6:00 p.m., daily. The M/V OSCAR WALTERS will monitor VHF-FM Channels 13 and 16. Mariners are urged to transit the area at their slowest safe speed to minimize their wake and proceed with caution.	

New Orleans To Baton Rouge - Lower Mississippi River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	Commencing April 27, 2026, and continuing through May 18, 2026, M/V MR. LEON is conducting construction operations along the LDB, in the vicinity of Mile 364.0. Work will be conducted from 6:00 a.m. until 6:00 p.m., daily. M/V MR. LEON will monitor VHF-FM Channel 8. Mariners are urged to transit the area at their slowest safe speed and proceed with caution after passing arrangements have been made.	
---	---	---	--

Lower Old River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Barbre Daybeacon	29780	STRUCT DEST	FD
Torras Daybeacon	29785	STRUCT DEST	FD
Oak Grove Daybeacon	29795	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Lower Mississippi River - Lower Old River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	Commencing May 4, 2026, and continuing until May 8, 2026, mariners may be subject to delays of up to 12 hours at the Old River L/D, in the vicinity of Mile 304.0. Delays will occur during daylight hours only. Mariners may contact the lock wall at (225) 492-2301, for updated information/current status or lockmaster, Mr. Anthony Lindsly at (225) 492-3333, for up-to-date information. The point of contact at the USACE New Orleans District is Russell Beauvais at (225) 492-2169 (work) (225) 202-3851 (Cell).	

Minnesota River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Black Dog Lights (5)	9440	LT EXT	PA

Missouri River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fitzhugh Daybeacon	17970	STRUCT DEST	FD
Lower Blencoe Bend Daybeacon	17975	STRUCT DEST	FD
Wahle Daybeacon	17985	STRUCT DEST	FD
Little Sioux Reach Daybeacon	18010	STRUCT DEST	FD
Bullard Bend Daybeacon	18025	STRUCT DEST	FD
Peterson Cut-Off Upper Daybeacon	18040	STRUCT DEST	FD
Sandy Point Daybeacon	18055	DAYMK IMCH	FD
Tysons Bend Daybeacon	18065	DAYMK IMCH	FD
California Cut-Off Daybeacon	18075	DAYMK MISSING	FD
Dodds Daybeacon	18140	DAYMK IMCH	FD
Lower Calhoun Bend Daybeacon	18160	DBD DEST	FD
Boyer River Daybeacon	18170	STRUCT DEST	FD
Pottawattamie Daybeacon	18185	DAYMK IMCH	FD
Lower Rockport Bend Daybeacon	18190	STRUCT DMGD	FD
Pigeon Creek Bend Daybeacon	18200	STRUCT DEST	FD
Thornton Daybeacon	18205	DAYMK IMCH	FD
Lower Pigeon Creek Bend Daybeacon	18210	DAYMK IMCH	FD
Douglas County Daybeacon	18215	DAYMK IMCH	FD
Florence Bend Lower Daybeacon	18250	DBD DEST	FD
Council Bend Upper Daybeacon	18270	DAYMK IMCH	FD
Carter Lake Daybeacon	18290	DBD DEST	FD
Omaha Bend Daybeacon	18305	DBD DEST	FD
Omaha Bend Lower Daybeacon	18320	STRUCT DEST	FD
Gibson Bend Daybeacon	18325	DAYMK IMCH	FD
Jones Point Daybeacon	18520	STRUCT DEST	FD
Civil Bend Upper Daybeacon	18530	STRUCT DEST	FD
Nebraska Bend Daybeacon	18580	DAYMK IMCH	FD
Iatan Bend Daybeacon	19345	DBD DMGD	FD
Weston Daybeacon	19375	DBD DMGD	FD
Waldrons Quarry Daybeacon	19485	DBD DMGD	FD
Missouri City Daybeacon	19775	STRUCT DEST	FD
Clay County Daybeacon	19790	DBD DMGD	FD
Little Blue Upper Daybeacon	19795	STRUCT DEST	FD

Fishing River Bend Daybeacon	19850	DBD DEST	FD
Camden Bend Dike Daybeacon	19880	DAYMK IMCH	FD
Mine Dump Daybeacon	19910	STRUCT DEST	FD
Berlin Bend Daybeacon	19975	STRUCT DEST	FD
Baltimore Bend Daybeacon	19990	STRUCT DEST	FD
Waverly Bend Daybeacon	20050	DBD DEST	FD
Chariton Daybeacon	20220	DBD DEST	FD
Little Missouri Bend Daybeacon	20250	DAYMK MISSING	FD
Cambridge Bend Lower Daybeacon	20290	STRUCT DEST	FD
Chariton River Daybeacon	20300	DAYMK IMCH	FD
Glasgow Daybeacon	20310	DAYMK IMCH	FD
Hurricane Creek Daybeacon	20340	STRUCT DEST	FD
Euphrase Bend Lower Daybeacon	20365	DBD DEST	FD
Diana Bend Daybeacon	20510	DBD DMGD	FD
Perchee Creek Daybeacon	20600	DBD DEST	FD
Providence Bend Daybeacon	20605	DBD DEST	FD
Sandy Hook Lower Daybeacon	20620	DBD DEST	FD
Morrison Daybeacon	20890	DBD DEST	FD
Sheltons Island Daybeacon	21075	DBD DMGD	FD
Hancock Bottom Daybeacon	21155	DBD DMGD	FD
Chesterfield Daybeacon	21275	DBD DMGD	FD
Cora Daybeacon	21430	DBD DMGD	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
U.E. Callaway Intake Lights (2)	20870	LT EXT	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Lower Mississippi River - Missouri River/General/Bridges/Repairs, Painting, Or Fender Replacement	Bridges	Discovery Bridge; Continuing through December 31, 2027, the vertical clearance will be reduced by 3 feet by the installed safespan. Mariners are urged to transit the area with caution.	Lat: 38° 47' 54" Lon: -090° 28' 01"

Monongahela River

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Ohio River - Monongahela River/General/MSIB	MSIB	The U.S. Coast Guard COTP Pittsburgh has issued the following Safety Advisory due to high water/flow conditions at Point Marion L/D, in the vicinity of Mile 90.8. The gate opening is greater than 20 feet. Mariners are urged to exercise caution when transiting between approximate Miles 95.0 and 93.0, Coburn Bend.	

Ohio River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Forked Run Daybeacon	24565	DAYMK MISSING	FD
Sciotoville Light	25355	LT EXT	FD
Dayton Bar Light	25895	DAYMK IMCH	FD
Water Works Light	27540	STRUCT DMGD	FD
Graham Varble Light	27855	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bens Run Light	24005	LT EXT	PA
Ohio Power Coal Dock Light	24580	LT EXT	PA
Transmontaige Dock Lights (2)	26833	LT EXT	PA
Dupont Chemical Lights (2)	26860	LT EXT	PA
Transmontaigne Dock Lights (4)	27590	LT EXT	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

Lower Mississippi River - Ohio River/General/Bridges/Maintenance	Bridges	I-24 Bridge: A scaffold deck system has been installed and will hang 8 feet below low steel. Mariners are advised to transit the bridge with caution.	Lat: 37° 08' 04" Lon: -088° 41' 13"
Lower Mississippi River - Ohio River/General/Bridges/Lighting and Other Signals	Bridges	Ravenswood Highway Drawbridge: The bridge navigation lights have been reported extinguished. Mariners are advised to transit the area with caution at night and during periods of reduced visibility.	Lat: 38° 56' 11" Lon: -081° 45' 26"
Lower Mississippi River - Ohio River/General/Bridges/Lighting and Other Signals	Bridges	Cairo Bridge: The upbound and downbound lights have been reported extinguished. Mariners are advised to transit the bridge with extreme caution.	Lat: 36° 59' 36" Lon: -089° 08' 47"
Lower Mississippi River - Ohio River/General/Hazards To Navigation/Wrecks	Hazards To Navigation	A 24ft crew boat has been reported to have sunk in the vicinity of the Olmstead Boat Launch, near Mile 966.0, RDB, on April 16, 2026. The sunk crew boat is reportedly not marked. Mariners are urged to avoid this area, keep a sharp lookout and report any sighting to the nearest U.S. Coast Guard Unit.	Lat: 37° 10' 04" Lon: -089° 05' 01"
Lower Mississippi River - Ohio River/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	Mid-channel shoaling has been reported in the vicinity of Mile 925.0. Mariners are urged to exercise caution in the area.	
Lower Mississippi River - Ohio River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	Commencing April 7, 2026, and continuing through April 8, 2026, transmission line operations are being conducted between approximate Miles 943.5 and 947.5. The M/V GENERAL will be on scene monitoring VHF-FM Channels 13 and 16. U.S. Coast Guard Sector Ohio Valley will monitor VHF-FM Channel 16. Mariners are urged to transit the area at their slowest safe speed and proceed with caution after passing arrangements have been made.	
Lower Mississippi River - Ohio River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	Commencing May 5, 2026, and continuing through June 19, 2026, the Cannelton L/D Auxiliary 600-foot chamber will be closed for repairs. All traffic will pass through the Primary 1200-foot chamber, during this time. Both chambers will be closed, not to exceed 4 hours a day, from May 5, 2026, until May 7, 2026. Mariners may contact the Lockmaster at (812) 547-2962, for additional information.	
Lower Mississippi River - Ohio River/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	Commencing May 23, 2026, and continuing until July 17, 2026, Foertsch Marine Services LLC., will be conducting dredging operations at Summit Terminal Facility, in the vicinity of Mile 743.0. Work will be conducted from 5:00 a.m. until 9:00 p.m., Monday through Saturday. The floating plant will monitor VHF-FM Channels 13 and 16. Mariners are urged to transit the area at their slowest safe speed to minimize their wake and proceed with caution.	
Lower Mississippi River - Ohio River/General/Miscellaneous	Miscellaneous	Continuing until August 13, 2026, Expand Water Resources LLC., installed a spud barge along the LDB, in the vicinity of Mile 97.1. A 16-inch waterline and gangway will extend from the barge to the shoreline. Mariners may contact Mike Tuttle at (304) 266-3900, for further information. Mariners are urged to transit the area with caution.	

Red River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Westdale Middle Daybeacon	29231.34	STRUCT DEST/TRUB	FD
Smith Island Lower Daybeacon	29241.25	STRUCT DEST	FD
Deloges Middle Daybeacon	29272	DAYMK IMCH	FD
Hog Lake Daybeacon	29467	STRUCT DEST	FD
Dry Cypress Daybeacon	29665	STRUCT DEST	FD
Bayou Cocodrie Upper Daybeacon	29690	STRUCT DEST	FD
Bayou Cocodrie Daybeacon	29695	STRUCT DEST	FD
Grassy Lake Daybeacon	29710	DAYMK MISSING	FD
Alligator Bayou Daybeacon	29725	STRUCT DEST	FD
Timber Lake Daybeacon	29750	STRUCT DEST	FD
Naples Daybeacon	29755	STRUCT DEST	FD

Red River Old River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bear Industries Barge Dock Lights (4)	11943	LT EXT	PA

Sans Bois Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Washita Point Light	9150	LT EXT	FD
Preston Peninsula Light	9185	REDUCED INT	FD

St Croix River**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Upper Mississippi River - St Croix River/General/Bridges/Public Notice	Bridges	Highway 243 Bridge: There is a Public Notice available for a proposed replacement of the existing truss bridge with a prestressed concrete beam bridge. The Public Notice can be found at: https://www.navcen.uscg.gov/sites/default/files/pdf/bridges/publicNotices/D08_PN929-26_OsceolaHighwayBridge_StCroixRiver_WI.pdf .	Lat: 45° 19' 17" Lon: -092° 42' 36"

Tennessee River**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Lanter Light	30325	STRUCT DEST	FD
Chambers Daybeacon	32140	STRUCT DEST	FD
Diamond Island Lower Daybeacon	32170	STRUCT DEST	FD
Savannah Bend Upper Daybeacon	32190	STRUCT DEST	FD
Hardin Creek Daybeacon	32245	DAYMK IMCH	FD
Brodies Landing Light	32335	STRUCT DEST	FD
Crooked Creek Light	32350	STRUCT DEST	FD
Sales Light	32445	STRUCT DEST/TRUB	FD
Reynoldsburg Island Light	32460	STRUCT DEST/TRUB	FD
Shirley Light	32465	STRUCT DEST	FD
Hurricane Creek Light	32510	STRUCT DEST	FD
Standing Rock Upper Light	32530	STRUCT DEST	FD
Fort Henry Light	32570	STRUCT DEST	FD
Blood River Light	32595	STRUCT DEST/TRUB	FD
W. L. Berry Light	32825	STRUCT DEST	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Twenty-One Mile Light	32710	DISCONTINUED	FD
Chottes Creek Light	32715	DISCONTINUED	FD
Haddock Ferry Light	32750	DISCONTINUED	FD
Big Chain Light	32765	DISCONTINUED	FD
Mud Creek Light	32780	DISCONTINUED	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Ohio River - Tennessee River/General/Bridges/Maintenance	Bridges	I-65 Highway Bridge; Due to maintenance work, vertical clearance may be reduced by 2 feet. Mariners are urged to exercise caution while transiting the bridge.	Lat: 34° 34' 48" Lon: -086° 54' 25"
Ohio River - Tennessee River/General/Bridges/Maintenance	Bridges	Walnut Street Bridge; Continuing through September 24, 2026, repair work will be conducted on the bridge. Work will be conducted 7a.m. to 7 p.m., daily. There will be a containment system set up that will reduce vertical clearance by 4 feet. All mariners are reminded to transit the bridge with caution and report any unsafe conditions to the United States Coast Guard.	Lat: 35° 03' 30" Lon: -085° 18' 26"
General/Marine Events/Other	Marine Events	On December 20, 2025, from 7:00 p.m. until 8:00 p.m., the Christmas on the River event will be held in the vicinity of Mile 334.0. Mariners are urged to transit the area with caution and maintain a proper lookout. Mariners may contact the event manager at (256) 604-0986, for additional information.	
Ohio River - Tennessee River/General/Miscellaneous	Miscellaneous	A nun buoy has been reported off station, in the vicinity of Mile 194.2. Mariners are urged to exercise caution in the area.	
Ohio River - Tennessee River/General/Miscellaneous	Miscellaneous	A nun buoy has been reported off station along the RDB, in the vicinity of Mile 208.5. Mariners are urged to exercise caution in the area.	

Upper Mississippi River**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Lock 5A Light	13165	STRUCT MISSING	FD
Root River Upper Light	13430	STRUCT DEST	FD
Perry Ruby Light	13510	STRUCT DEST	FD
Warners Landing Light	13525	LT EXT/DAYMK MISSING	FD

Warners Landing Light	13525	STRUCT DEST	FD
Cassville Upper Daybeacon	14010	STRUCT DEST	FD
Maquoketa Island Light	14105	STRUCT DEST	FD
Nine-Mile Island Light	14230	STRUCT DEST	FD
Stone Slough Light	14260	STRUCT DEST	FD
Fever River Light	14275	STRUCT DEST/TRUB	FD
Pulaski Light	14295	STRUCT DEST	FD
Arnold Light	14380	LT EXT	FD
Arnold Towhead Light	14385	STRUCT DEST	FD
Sabula Lower Light	14445	STRUCT DEST	FD
Smith Bay Light	14460	STRUCT DEST	FD
Elk River Light	14475	DAYMK DMGD	FD
Andalusia Island Light	14960	STRUCT DEST/TRUB	FD
Edwards Island Upper Light	15170	STRUCT DEST/TRUB	FD
Waggoner PT Lighted Buoy	15475	MISSING	FD
Sny River Light	15785	DBD DEST	FD
Mulheron Field Light	16010	DAYMK MISSING	FD
Hastings Landing Daybeacon	16110	STRUCT DMGD	FD
Ste. Genevieve Island Light	16910	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Newport Terminal Lights (2)	12320	LT EXT	PA
Shiely Dock Lights (2)	12385	LT IMCH	PA
City of Red Wing Metering Station Special Light	12712	MISSING	PA
Alma City Dock Light/Daymarks (3)	12930	MISSING	PA
G. Heileman Brewery Dock Light	13405	MISSING	PA
Hall Towing Light	15425	STRUCT DEST	PA
Hannibal Intake Light	15822	LT EXT	PA
Jersey County Grain Dock Lights (2)	16100	LT EXT	PA
Commodore Meyer Light	16215	LT EXT/STRUCT DEST	PA
Con-Agra Mooring Lights (2)	16220	LT EXT	PA
Union Electric Coal Dock Lights (2)	16430	LT EXT	PA
Consolidation Coal Dock Lights (3)	16890	LT EXT	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Lower Mississippi River - Upper Mississippi River/General/Bridges/Lighting and Other Signals	Bridges	I-57 Bridge; The bridge navigation lights have been reported extinguished. Mariners are advised to transit the area with caution at night and during periods of reduced visibility.	Lat: 37° 01' 28" Lon: -089° 12' 39"
Lower Mississippi River - Upper Mississippi River/General/Bridges/Construction	Bridges	Lansing Bridge; Continuing through May 11, 2026, from 6:30 a.m. to 5:30 p.m., the channel will be restricted to 350 feet. Mariners shall contact M/V MISS KARA PATRICIA on VHF-FM Channel 13 or 16 to coordinate passing arrangements. Vessels are urged to transit the area at their slowest safe speed and proceed with caution after passing arrangements have been made.	Lat: 43° 21' 55" Lon: -091° 12' 52"
Lower Mississippi River - Upper Mississippi River/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	Mid-channel shoaling has been reported in the vicinity of Mile 729.7. Mariners are urged to exercise caution in the area.	
Lower Mississippi River - Upper Mississippi River/General/LAA/RNA/Temporary Regulated Navigation Zone	LAA/RNA	Continuing until further notice, construction activities are being conducted on the Dam at L/D 24, at Mile 273.4. Tainter gate 1 will not be operational and Tainter gate 2 may be potentially closed as well. Due to the construction, there is potential for stronger than normal outdraft conditions at the lower end of the lock. Mariners may contact the Lockmaster via VHF-FM Channel 12, or at (573) 242-3524, for further information.	
Lower Mississippi River - Upper Mississippi River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	Continuing through October 2026, construction will be conducted for a new 50 ft diameter guide cell downstream of Lock and Dam 25. The new guide cell will be constructed approximately 340 ft downstream of the existing guide cell. Intermittent periods of active construction will take place adjacent to the navigation channel throughout the duration of the project. Additional Lock closures may be required as construction of the guide cell continues. Mariners should be on the lookout for construction activities and related equipment to include barges, cranes, and work boats that will be operating in the area. All vessels should be alert for, and abide by, any special instructions that may be issued by the Lockmaster.	
Lower Mississippi River - Upper Mississippi River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	Recent inspection of the Lock and Dam 25 downstream protection cell has revealed a large amount of fill material has been displaced. Effective immediately and until further notice, vessels will be required to use an assist vessel so as not to land on the protection cell northbound or create excess wheel wash when exiting the Lock southbound. All vessels should be alert for, and abide by, any special instructions that may be issued by the Lockmaster. Mariners may contact the Lockmaster via VHF-FM Channel 14, or at (636) 566-8120 for further information.	

Lower Mississippi River - Upper Mississippi River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	Continuing until July 6, 2026, mooring cells are being installed along the RDB at Mile 498.0 and along the LDB at Mile 495.0. Work will be conducted from 7:00 a.m. until 5:00 p.m., daily. M/V THOMAS KENNEDY will be on scene monitoring VHF-FM Channel 13 or 16. Mariners are urged to transit the area at their slowest safe speed to minimize their wake and proceed with caution.	
Lower Mississippi River - Upper Mississippi River/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	Continuing until further notice, the M/V MARY J., is conducting dredging operations in the vicinity of Mile 818.9. Work will be conducted from 7:00 a.m. until 7:00 p.m., Monday through Friday. The M/V MARY J., will monitor VHF-FM Channel 12 or 13 and request 30 minutes' advance notice of passage. Mariners are urged to transit the area at their slowest safe speed and proceed with caution after passing arrangements have been made.	
Lower Mississippi River - Upper Mississippi River/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	Continuing until further notice, the M/V BRAND MARIE, is conducting dredging operations in the vicinity of Mile 801.8. Work will be conducted from 7:00 a.m. until 7:00 p.m., Monday through Friday. The M/V BRAND MARIE, will monitor VHF-FM Channel 12 or 13 and request 30 minutes' advance notice of passage. Mariners are urged to transit the area at their slowest safe speed and proceed with caution after passing arrangements have been made.	
Lower Mississippi River - Upper Mississippi River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	L/D 25 will be closed for 12-hours on each of the following days for damaged protection cell removal: May 5 and 7, 2026, from 7:00 a.m. to 7:00 p.m. The requirement for an assist vessel remains in place and until further notice, vessels will be required to use an assist vessel so as not to land on the protection cell northbound or create excess wheel wash when exiting the Lock southbound. Mariners should be alert for and abide by any special instructions that may be issued by the Lockmaster.	
Lower Mississippi River - Upper Mississippi River/General/MSIB	MSIB	The U. S. Coast Guard COTP has issued the following Safety Advisory due to high water/high flow conditions at Grays Point and Thebes Railroad Bridge, in the vicinity of Mile 43.2. Mariners are urged to exercise caution due to hazardous conditions associated with strong currents, increased drift and severe outdrafts. Mariners are advised to consider horsepower capability and tow size. Fleet operators should regularly check their fleets and immediately report barge breakaways to the U.S. Coast Guard. Mariners are urged to exercise caution in the area.	
Lower Mississippi River - Upper Mississippi River/General/MSIB	MSIB	Due to extreme high water, the COTP Ohio Valley has issued a Safety Advisory for the Upper Mississippi River between Miles 46.0 and 43.5. It is recommended that vessels do not meet, pass or overtake in these areas. Downbound tows greater than 140 feet are restricted to daylight transit only and red flag barges should be placed in a protected location in the tow. Mariners should exercise caution and report navigation hazards to the U.S. Coast Guard via VHF-FM Channel 16.	
Lower Mississippi River - Upper Mississippi River/General/MSIB	MSIB	The U.S. Coast Guard COTP has issued the following Safety Advisory due to high water/high flow conditions at Chester Bridge, in the vicinity of Mile 109.9. Mariners are urged to exercise caution due to hazardous conditions associated with strong currents, increased drift and severe outdrafts. Mariners are advised to consider horsepower capability and tow size. Fleet operators should regularly check their fleets and immediately report barge breakaways to the U.S. Coast Guard. Mariners are urged to exercise caution in the area.	Lat: 37° 54' 10" Lon: -089° 50' 12"